

Safety Audit 5

Delayed repair of V-102 identified. Medium risk.