

# INVOICE

Charlie Melnarik  
159 Kendra Way, Hamilton, MT 59840  
(406) 360-6324

Invoice #: 2025000003

Date: December 24, 2025

Date In: March 12, 2025

## BILL TO

Judy Banks

## JOB DETAILS

Vehicle: 2007 Volvo xc90

Rate/Hour: \$65.00

Total Hours: 10.8 hrs

## Labor

Description	Time	Line Total
Brake Booster Pump: Replaced	1 hrs	\$65.00
Brakes: Replace Pads and Rotors (all four)	2.8 hrs	\$182.00
ABS sensor Front Left: Replaced	0.5 hrs	\$32.50
Brake lines both front: Replaced and Bleed	1 hrs	\$65.00
Rear Left ABS sensor: Replaced	1.5 hrs	\$97.50
Rear Right ABS sensor: Replaced	2 hrs	\$130.00
Fuel Filter: Replaced	0.5 hrs	\$32.50
Front Right ABS sensor: Replaced	0.5 hrs	\$32.50
Differential Fluids: Drained and Refilled	0.5 hrs	\$32.50
Middle Row Right Seat Belt Buckle: Replaced	0.5 hrs	\$32.50

## Parts

Part	Price
Fuel filter	\$35.79
Brake Hose	\$17.60
Vacuum Pump	\$119.79
ABS wheel speed sensors	\$216.34
Brake pads and Rotors	\$304.58
Freight	\$19.98
Right Middle Row Buckle(used)	\$43.89
Differential Fluid	\$18.99

## NOTES

Found Right front ABS sensor bad as well  
in addition to the other 3 already diagnosed by M&M  
Traction control light is still on due to "Steering Angle Sensor" bad  
All ABS sensors are functioning as they should

## SUMMARY

Parts:	\$776.96
Labor:	\$702.00
Supplies:	\$19.00
<b>Total:</b>	<b>\$1,497.96</b>
<b>Paid:</b>	<b>\$1,497.96</b>

**AMOUNT DUE: \$0.00**

Thank you for your business.