Prelab 5

Aseda Gyeke Aboagye

Joe Orr

Doug Hewitt

20 October 2012

DAC Pins 1

DAC0: Pin 64 (our JTAG connector: C26)

DAC1: Pin 63 (our JTAG connector: B25)

There appears to be no bits in the XBRn that control the DAC.

$\mathbf{2}$ VREF Configuration

- 1. VREFD is on pin C28. It should be connected to B32.
- 2. The Reference Control Register, REF0CN enables/disables the internal reference generator and the internal temperature sensor on all devices.

Bits 0 and 1 should be set to 1. (SFRPAGE 0)

3 Timing

Solving for the Timer 2 overflow count:

$$SYSCLOCK = 12.25 \ MHz$$

$$T_2 = {}^{SYSCLOCK}\!/_{12} = 1.0208\overline{3}~MHz$$

$$\frac{T_2}{8\ KHz} = 127.6041\overline{6} \Longrightarrow count = -128$$

$$Error = \frac{128 - 127.6041\overline{6}}{128} = 0.3092\%$$

Using a count of -128, we can use the following assembly code for our Timer 2 setup:

mov RCAP2H, #HIGH(-128)

mov RCAP2L, #LOW(-128)

DAC SFR Configuration

Bits 4 and 3 and DACnCN need to bet set to 1.