



2000 S Main Street
McPherson, KS 67460

620-241-2340
chsinc.com/refining

April 1, 2025

Ms. Connie Ellis
Air Compliance & Enforcement Section
Kansas Dept. of Health and Environment
1000 SW Jackson, Suite 310
Topeka, KS 66612-1366

Re: J-01 Primary and Secondary Seal Failure
CHS McPherson Refinery (CHS)
Source I.D. 1130003

Dear Ms. Ellis:

This letter is to satisfy the reporting requirements of 40 CFR 63.1066(b)(2) regarding a primary and secondary seal failure on a portion of the floating roof on Tank J-01. On March 25, 2025, a CHS contract inspection company identified approximately 10 feet of the primary mechanical shoe seal, and two feet of the secondary wiper seal that were not in contact with the tank wall. The same contract company was hired to repair the compromised seals. Both seals were fixed on March 28, 2025. Thus, per 40 CFR 63.1063(e)(2), the repairs were completed within 45 days from when the issues were discovered. A copy of the inspection report has been included with this letter.

If you have any questions, please feel free to contact me at (620) 241-9295 or via e-mail at Andrew.Vogelsberg@chsinc.com.

Sincerely,
CHS

Andy Vogelsberg
Environmental Scientist

Attachments

Efile: G:\Environmental\Recordkeeping\Refinery\Air\Tanks\Investigative Seal Inspections\2025

CHS Floating Roof Tank-Seal Inspections

Tank Identification J-01 IFR/EFR EFR Diameter 134 ft. Height 48 ft.

Applicable Regulation Kb/MACT Construction Date _____

Seal Inspection (check one) ☐ Primary ☐ Secondary ☒ Both Seals

Reason for Inspection Inspection after Repair

Name of Inspector (print) Andy Vogelsberg

Inspection Summary

Primary Seal Type: mss

Seal Gap Measurements:

Gap Length L (in.)	Maximum Gap Width W_{max} (in.)	Average Gap Width W_{avg} (in.) = $(W_{max} + 1/8) / 2$	Gap Area A (in ²) = $W_{avg} L$	Tank Diameter (ft.) D	Seal Gap Ratio R $R = A_{tot}/D$
0	0	0	0	134	0

Check one:

☒ Primary seal passed visual inspection, NO corrective action required.

☐ Primary seal failed visual inspection, corrective action IS required.

Secondary Seal Type: Wiper

Seal Gap Measurements:

Gap Length L (in.)	Maximum Gap Width W_{max} (in.)	Average Gap Width W_{avg} (in.) = $(W_{max} + 1/8) / 2$	Gap Area A (in ²) = $W_{avg} L$	Tank Diameter (ft.) D	Seal Gap Ratio R $R = A_{tot}/D$
0	0	0	0	134	0

Check one:

☒ Secondary seal passed visual inspection, NO corrective action required.

☐ Secondary seal failed visual inspection, corrective action IS required.

List any failure type(s) and corrective action taken/to be taken (i.e. liquid on roof, detached seals, visible seal gaps, floating roof/fitting failure, etc. If no failures are listed, all components are compliant)

Signature of Inspector: Andy Vogelsberg

Date of Inspection: 3/31/25