

FRIMS Assam



Flood Reporting And Information Management System

					d Report as on	31-07-2	2022 a	at 4:00 PM				
Particulars	Situation as	on 31-07-2	97-2022 (in last 24 hours)									
Rivers flowing above Danger	Rivers flowi level	ng above d	anger	Disang (Nanglamuraghat)								
Level (as per CWC bulletin issued at 8 AM)	Rivers flowi flood level	ng above h	Nil									
District Affected	No. of Districts Affected	Name of	Flood Aff	ected Distr	icts		Name of Urban Flood Districts					
	5	Dhemaji,	Jorhat, La	khimpur, M	lorigaon, Tam	ulpur						
No. Of Revenue Circles Affected	7											
	District	Total										
Name Of	Dhemaji	2		, Gogamukl	1							
Revenue Circles	Jorhat	2	Titabor, Teok									
	Lakhimpur	1	Subansiri									
Affected	Morigaon	1	Morigaon									
	Tamulpur	1	Goreswa	ır								
	Total	7										
	District	Total	Revenue Circle									
	Dhemaji	36			gamukh 31)							
Villages	Jorhat	5	(Titabor 1), (Teok 4)									
Affected	Lakhimpur	2	(Subansiri 2)									
111100100	Morigaon	5	(Morigaon 5)									
	Tamulpur	1	(Goresv	var 1)								
	Total	49										
	District	Male	Femal e	Childre n	Total Populatio n	Population Details		Crop Area (in Hect.)	Crop Area Details			
Population And Crop	Dhemaji	6099	6084	2694	14877	(Dhemaji 2335), (Gogamukh 12542)		381.00	(Dhemaji 181.00), (Gogamukh 200.00)			
Area	Jorhat	39	45	28	112	(Titabor 0), (Teok 112)		98.70	(Titabor 20.00), (Teok 78.70)			
Affected	Lakhimpur	14	16	5	35	(Suba	ansiri	35)	20.00	(Subansiri 20.00)		
	Morigaon	27	28	21	76		(Morigaon 76)		55.00	(Morigaon 55.00)		
	Tamulpur	195	153	57	405		(Goreswar 405)		0.00	(Goreswar 0.00)		
	Total	6374	6326	2805	15505		1 - /		554.70			
Relief	District	Total	Relief C		Relief Distribution Centres							
Camps /	Dhemaji	5	2(Dhem			3(Dhemaji						
Centres	Morigaon	2	2(Morigaon 2)			0(Morigao		0(Morigaor	on 0)			
Opened	Total	7	4				3					
Inmates In Relief Camps	District	Total	Revenue Circlewise			Male		Female	Children	Pregnant / Lactating Mother	Person with Disabilit y	
	Dhemaji	344	(Gogamukh 0), (Dhemaji 344)			77		112	137	18	0	
	Morigaon	76	(Morigaon 76)			27		28	21	0	0	
	Total	420				104		140	158	18	0	
Human Lives Lost - Confirmed	Nil											
Human Lives Lost	Nil											

Death Type	C " 1													
Missing Mis	Confirmed -													
Harman Missing Harman Missing Harman Missing Harman Missing Harman Missing Harman Missing														
Missing Nil		NEI .												
Human Christics Doctor District Total Big Small Poultry Denning Affected Total Big Small Poultry Denning Agency Denning Boats Denning Denning Denning Denning Total Big Small Denning Boats Boats Boats Denning Denning Denning Denning Denning Denning Bistrict Denning Bistrict Denning Bistrict Denning Bistrict Denning Bistrict Denning Den		N ₁ I												
Missing - Type	-													
Missing														
Special Spec		Nil												
Maintaise Main	_													
Adimals Adim	Type	District	Total	D:-	Consti	Davilton								
Allement	Animala					•								
Mainake Maked Ma														
Maistrict Polemaji 33.46 6.26 1.87 187.00 0.0	Affected													
Maska Mask	A:1-	Total	3642 2197 1009 436											
Mouses District Agency District Agency District Agency District Agency District Distric		NGI												
Boass Damaged District Agency		INII												
District Agency														
Rescue Operation District Agency		Nil												
Rescue Operation	Damaged	Darcon												
Part							Person		Heliconter					
Deptoyed		District	Agency						_					
Operation	Rescue	District	Agency			Deployed	d By	d By			Deploye			
Dhemaji SDRF	Operation						Boats	Boats	Deployed	-	d			
Total		Dhemaii	SDBE			2	50	0	0		1			
Relief Distributed Pistrict Pistributed District Pistributed District Distributed District Numbe Teok - Left ring bund of river Mudoijan at Tangami Tangami Date-30-07-2022 Approx. 25 feets (Long 94.4194.2, Lat 26.7990.30), Left ring bund of river Mudoijan at Pirakata Habi Claun Pirakata Habi Gaon Date-30-07-2022 Length-Approx. 25 feets (Long 94.4194.73, Lat 26.7990.30), Left ring bund of river Mudoijan at Pirakata Habi Claun Pirakata Habi Gaon Date-30-07-2022 Length-Approx. 20 feets (Long 94.4194.73, Lat 26.804.732) Total 3 Infrastructure Damaged-Infrastructure Damaged-Bridge District			SDKI											
Relief District District Size (in OJ Color OJ Color OJ OJ OJ OJ OJ OJ OJ O		Total				2			U	0	_ <u> </u>			
Relief Distributed Dist														
Relief Distributed Distr		District	Rice (in	Dal	Salt (in	M. Oil (in			Cottle Food	Dias Puon (~ (0)			
Distributed Dhemaji 33.46 6.26 1.87 187.00 0.00 0.00 0.00 0.00 Total 33.46 6.26 1.87 187.00 0.00 0.00 0.00 0.00 Relief Distributed Dhemaji 0.00-Q 0.00-Q 0.00-Q District Demaji 0.00-Q 0.00-Q 0.00-Q District Numbe Details	Relief	District	Q)	(in Q)	Q)	L)			Cattle reed	- Rice Draii (n Q)			
District	Distributed							`						
Relief Distributed Others		Dhamaii	22.46	6.26	1 07	197.00			0.00					
Relief Distributed Others District Distributed Others District Distributed Others District Distributed Others District Distributed Others District Distributed Others District District Numbe r Details														
Distributed Others District Dimenaji 0.00-Q	D-1:-£	Total			1.8/	187.00	0.00	0.00	0.00					
Dhemaji O.00-Q O.00-Q O.00-Q O.00-Q		District												
Infrastructur e Damaged - Embankment Breached Jorhat Jorhat Jorhat Brached Jorhat Brached Jorhat Jorhat Brached Jorhat Jorhat Brached Jorhat Jorhat Jorhat Brached Jorhat Jorhat Jorhat Jorhat Jorhat Brached Jorhat		Dhomaii	_		0.00.0									
Infrastructur e Damaged - Embankment Breached Jorhat Jorhat Jorhat Jorhat Brached Jorhat Jorh	Others	Bhemaji	_		0.00 Q									
Infrastructur e Damaged - Embankment Breached Infrastructur e Damaged - Embankment Breached Infrastructur e Damaged - Embankment Breached Infrastructur e Damaged - Embankment s Affected Infrastructur e Damaged - Embankment s Affected Infrastructur e Damaged - Brown Embankment s Affected Infrastructur e Damaged - Brown Embankment s Affected Infrastructur e Damaged - Bridge Infrastructur e Damaged - Wildlife Infrastr		District	Details											
Infrastructure Damaged - Embankment Breached Jorhat Jorh			-	Teok - I	eft ring bur	nd of river Mu	doiian at Tans	gani Tangani	i Date- 30-07-	2022 Approx.	25 feets l			
Embankment Breached Jorhat J								5	, –					
Length-Approx. 25 feets (Long - 94.413473, Lat - 26.799030), Left ring bund of river Mudoijan at Pirakata Habi Gaon Pirakata Habi Gaon near Padam TE Date-30-07-2022 Length- Approx. 20 feets (Long - 94.409329, Lat - 26.804732)	-	Jorhat		Left ring bund of river Mudoijan at Pirakata Habi Chuk Pirakata Habi Gaon Date- 30-07-2022 Length- Approx. 25 feets (Long - 94.413473, Lat - 26.799030),										
Left ring bund of river Mudoijan at Pirakata Habi Gaon Pirakata Habi Gaon near Padam TE Date-30-07-2022 Length- Approx. 20 feets (Long - 94.409329, Lat - 26.804732)			3											
Infrastructur e Damaged - Embankment s Affected Infrastructur e Damaged - Road Infrastructur e Damaged - Bridge Infrastructur e Damaged - Will Infrastructur e Damaged - Damaged	Breached													
Infrastructur e Damaged - Embankment s Affected Infrastructur e Damaged - Road Infrastructur e Damaged - Road Infrastructur e Damaged - Bridge Infrastructur e Damaged - Bridge Infrastructur e Damaged - Bridge Infrastructur e Damaged - Will Infrastructur e Damaged - Other Details Infrastructur e Damaged - District Other Details Infrastructur e Damaged - District Other Details Infrastructur e Damaged - Niil Infrastruc														
e Damaged - Embankment s Affected Infrastructur e Damaged - Road Infrastructur e Damaged - Bridge Infrastructur e Damaged - Will Wildlife District Other Details Baska Power Dept. Poles 2 nos. of HT Pole uprooted at village Doomni (Sonapur) on 31/07/2022 (Coordinate: 26.708897, 91.304457, 1 no. of LT pole uprooted at village Barimukh on 31/07/2022. Co-ordinate: 26.630536, 91.343940 District District Titabor - Protection Bundh Damaged Left Bank of the river Kason at Kachari Gaon length approx 10ft. Dated 31/07/2022 GPS Lat26.579811 Long94.132554 Lakhimpur Lakhimpur Power Dept. Poles 23 Nos Pole Damaged at Near Champara River on 30/07/2022 as reported by APDCL		Total												
Embankment s Affected Infrastructur e Damaged - Road Infrastructur e Damaged - Bridge Infrastructur e Damaged - Will Infrastructur e Damaged - Wildlife Infrastructur e Damaged - Other Details Baksa Power Dept. Poles 2 nos. of HT Pole uprooted at village Doomni (Sonapur) on 31/07/2022 Coordinate: 26.708897, 91.304457, 1 no. of LT pole uprooted at village Barimukh on 31/07/2022. Co-ordinate: 26.630536, 91.343940 Jorhat Jitabor - Protection Bundh Damaged Left Bank of the river Kason at Kachari Gaon length approx 10ft. Dated 31/07/2022 GPS Lat26.579811 Long94.132554 Subansiri - Power Dept. Conductors 8km Conductor Damaged at Near Champara River on 30/07/2022 as reported by APDCL Power Dept. Poles 23 Nos Pole Damaged at Near Champara River on 30/07/2022 as reported by APDCL	Infrastructur													
Embankment s Affected Infrastructur e Damaged - Road Infrastructur e Damaged - Bridge Infrastructur e Damaged - Will Infrastructur e Damaged - Wildlife Infrastructur e Damaged - Other Details Baksa Power Dept. Poles 2 nos. of HT Pole uprooted at village Doomni (Sonapur) on 31/07/2022 Coordinate: 26.708897, 91.304457, 1 no. of LT pole uprooted at village Barimukh on 31/07/2022. Co-ordinate: 26.630536, 91.343940 Jorhat Jitabor - Protection Bundh Damaged Left Bank of the river Kason at Kachari Gaon length approx 10ft. Dated 31/07/2022 GPS Lat26.579811 Long94.132554 Subansiri - Power Dept. Conductors 8km Conductor Damaged at Near Champara River on 30/07/2022 as reported by APDCL Power Dept. Poles 23 Nos Pole Damaged at Near Champara River on 30/07/2022 as reported by APDCL	e Damaged -	Damaged -												
Infrastructur e Damaged - Road Infrastructur e Damaged - Bridge Infrastructur e Damaged - Wildlife District Baksa District Baksa - Power Dept. Poles 2 nos. of HT Pole uprooted at village Doomni (Sonapur) on 31/07/2022 Coordinate: 26.708897, 91.304457, 1 no. of LT pole uprooted at village Barimukh on 31/07/2022. Co-ordinate: 26.630536, 91.343940 Titabor - Protection Bundh Damaged Left Bank of the river Kason at Kachari Gaon length approx 10ft. Dated 31/07/2022 GPS Lat26.579811 Long94.132554 Subansiri - Power Dept. Conductors 8km Conductor Damaged at Near Champara River on 30/07/2022 as reported by APDCL	Embankment Nil													
e Damaged - Road Infrastructur e Damaged - Bridge Infrastructur e Damaged - Wildlife District District	s Affected													
Road Infrastructur e Damaged - Bridge Infrastructur e Damaged - Wildlife District Baska - Power Dept. Poles 2 nos. of HT Pole uprooted at village Doomni (Sonapur) on 31/07/2022 Coordinate: 26.708897, 91.304457, 1 no. of LT pole uprooted at village Barimukh on 31/07/2022. Co-ordinate: 26.630536, 91.343940 Titabor - Protection Bundh Damaged Left Bank of the river Kason at Kachari Gaon length approx 10ft. Dated 31/07/2022 GPS Lat26.579811 Long94.132554 Subansiri - Power Dept. Conductors 8km Conductor Damaged at Near Champara River on 30/07/2022 as reported by APDCL Division, Ghilamara, Power Dept. Poles 23 Nos Pole Damaged at Near Champara River on 30/07/2022 as reported by APDCL	Infrastructur		Nil											
Infrastructur e Damaged - Bridge Infrastructur e Damaged - Wildlife Nil	e Damaged -	Nil												
e Damaged - Bridge Infrastructur e Damaged - Wildlife District Other Details	Road													
Bridge Infrastructur e Damaged - Wildlife District Baska - Power Dept. Poles 2 nos. of HT Pole uprooted at village Doomni (Sonapur) on 31/07/2022 Coordinate: 26.708897, 91.304457, 1 no. of LT pole uprooted at village Barimukh on 31/07/2022. Co-ordinate: 26.630536, 91.343940 Jorhat Jorhat Jorhat Lakhimpur Lakhimpur Baska - Power Dept. Poles 2 nos. of HT Pole uprooted at village Barimukh on 31/07/2022. Co-ordinate: 26.630536, 91.343940 Titabor - Protection Bundh Damaged Left Bank of the river Kason at Kachari Gaon length approx 10ft. Dated 31/07/2022 GPS Lat26.579811 Long94.132554 Subansiri - Power Dept. Conductors 8km Conductor Damaged at Near Champara River on 30/07/2022 as reported by APDCL Division, Ghilamara, Power Dept. Poles 23 Nos Pole Damaged at Near Champara River on 30/07/2022 as reported by APDCL	Infrastructur													
Infrastructur e Damaged - Wildlife District Baska - Power Dept. Poles 2 nos. of HT Pole uprooted at village Doomni (Sonapur) on 31/07/2022 Coordinate: 26.708897, 91.304457, 1 no. of LT pole uprooted at village Barimukh on 31/07/2022. Co-ordinate: 26.630536, 91.343940 Jorhat Jorhat Jorhat Titabor - Protection Bundh Damaged Left Bank of the river Kason at Kachari Gaon length approx 10ft. Dated 31/07/2022 GPS Lat26.579811 Long94.132554 Subansiri - Power Dept. Conductors 8km Conductor Damaged at Near Champara River on 30/07/2022 as reported by APDCL Division, Ghilamara, Power Dept. Poles 23 Nos Pole Damaged at Near Champara River on 30/07/2022 as reported by APDCL	e Damaged -	Nil												
e Damaged - Wildlife District Other Details	Bridge													
Wildlife District Other Details	Infrastructur													
District Other Details		Nil												
Baksa Baksa Power Dept. Poles 2 nos. of HT Pole uprooted at village Doomni (Sonapur) on 31/07/2022 Coordinate: 26.708897, 91.304457, 1 no. of LT pole uprooted at village Barimukh on 31/07/2022. Co-ordinate: 26.630536, 91.343940 Jorhat Titabor - Protection Bundh Damaged Left Bank of the river Kason at Kachari Gaon length approx 10ft. Dated 31/07/2022 GPS Lat26.579811 Long94.132554 Subansiri - Power Dept. Conductors 8km Conductor Damaged at Near Champara River on 30/07/2022 as reported by APDCL Division, Ghilamara, Power Dept. Poles 23 Nos Pole Damaged at Near Champara River on 30/07/2022 as reported by APDCL	Wildlife													
Baksa Coordinate: 26.708897, 91.304457, 1 no. of LT pole uprooted at village Barimukh on 31/07/2022. Co-ordinate: 26.630536, 91.343940 Jorhat Jorhat Titabor - Protection Bundh Damaged Left Bank of the river Kason at Kachari Gaon length approx 10ft. Dated 31/07/2022 GPS Lat26.579811 Long94.132554 Subansiri - Power Dept. Conductors 8km Conductor Damaged at Near Champara River on 30/07/2022 as reported by APDCL Division, Ghilamara, Power Dept. Poles 23 Nos Pole Damaged at Near Champara River on 30/07/2022 as reported by APDCL	Infrastructur e Damaged - Others	District												
Infrastructur e Damaged - Others 26.630536, 91.343940 Titabor - Protection Bundh Damaged Left Bank of the river Kason at Kachari Gaon length approx 10ft. Dated 31/07/2022 GPS Lat26.579811 Long94.132554 Subansiri - Power Dept. Conductors 8km Conductor Damaged at Near Champara River on 30/07/2022 as reported by APDCL Division, Ghilamara, Power Dept. Poles 23 Nos Pole Damaged at Near Champara River on 30/07/2022 as reported by APDCL														
Intrastructure Damaged - Others Titabor - Protection Bundh Damaged Left Bank of the river Kason at Kachari Gaon length approx 10ft. Dated 31/07/2022 GPS Lat26.579811 Long94.132554 Subansiri - Power Dept. Conductors 8km Conductor Damaged at Near Champara River on 30/07/2022 as reported by APDCL Division, Ghilamara, Power Dept. Poles 23 Nos Pole Damaged at Near Champara River on 30/07/2022 as reported by APDCL		Baksa				457, 1 no. of I	T pole uproo	ted at village	Barimukh on 3	1/07/2022. Co	-ordinate:			
e Damaged - Others Jorhat														
Others Subansiri - Power Dept. Conductors 8km Conductor Damaged at Near Champara River on 30/07/2022 as reported by APDCL Division, Ghilamara, Power Dept. Poles 23 Nos Pole Damaged at Near Champara River on 30/07/2022 as reported by APDCL		Inrhat				- '		ver Kason at I	Kachari Gaon le	ength approx 1	0ft. Dated			
Lakhimpur Subansiri - Power Dept. Conductors 8km Conductor Damaged at Near Champara River on 30/07/2022 as reported by APDCL Division, Ghilamara, Power Dept. Poles 23 Nos Pole Damaged at Near Champara River on 30/07/2022 as reported by APDCL		Joinat												
Power Dept. Poles 23 Nos Pole Damaged at Near Champara River on 30/07/2022 as reported by APDCL			-											
Power Dept. Poles 23 Nos Pole Damaged at Near Champara River on 30/0//2022 as reported by APDCL		Lakhimpur												
Division, Ghilamara,		Power Dept. Poles 23 Nos Pole Damaged at Near Champara River on 30/07/2022 as reported by APDCL									DCL			
			Division,	Ghilamar	a,									

		Bamboo Foot Bridge as reported by the Dhakuakhana Territorial Road Division, Ghilamar the Bamboo							
		on Dorge Gaon tiniali to Kaligaon Tiniali is damaged (L- 30 Mtr) on 30/07/2022							
	District	Details							
Erosion	Bongaigao n	Manikpur - Bashbari Part 2 Erosion of around 1300 mtr. had occurred w.ef 17/06/2022 to 30/06/2022.Two (2) Nos of Relief camp opened due to the said erosion (1) Tilpukhuri ME Madrasa "Male=179 Female=165 Child=124 Pregnant=1 Disability=1 Total=470(Latitude-26.39971 Longitude-90.753438) (2)3 no. Bashbari LP School, Male=86 Female=83 Child=77 Pregnant=2 Total=248(Latitude-26.426476 Longitude-90.759589) since 17.06.2022 to till date 01.07.2022/Total Inmates 718. Medical Team- 2 Nos. date- 31.07.2022 718							
	Lakhimpur	Bihpuria - Madhupur-Dahgharia area Active erosion was observed at Madhupur-Dahgharia area near the Dikrong R/B embankment from 30th July 2022. About 1000m sq. of land has been eroded as reported by officials of WRD, Bihpuria SD. 0							
	Tinsukia	Sadiya - Na lakhimpuria River bank erosion is reported at Na- lakhimpuria village by Kundil river. Stretch 200m. From date 25/07/2022 to 31/07/2022. (27.92386♠, 95.785844♠) 0							
	Udalguri	Udalguri - Hajaragaon Erosion Occurred on the R/B of Golandi river at Hajaragaon around 400m on 30.07.2022. 0							
Landslide	Nil								
Urban Flood	Nil								