

FRIMS Assam



Flood Reporting And Information Management System

Assam Daily Flood Report as on 10-06-2022 at 4:00 PM											
Particulars	Situation as on 10-06-2022 (in last 24 hours)										
Rivers											
flowing											
above											
Danger											
Level (as	Nil										
per CWC											
bulletin											
issued at 8 AM)											
Aivi)	No. of										
District	Districts	Name of	Flood Aff	ected Distri	cts	Name of Urban Flood Districts					
Affected	Affected	1 (61110 01	- 1004 1111	2 10111		1144110 01 010411 11004 2	15011005				
	4	Dhemaji, Morigaon, South Salmara Kamrup (M)									
No. Of			Maintup (191)								
Revenue	6										
Circles											
Affected											
	District	Total	Revenue								
	Dhemaji	3	Dhemaji	, Gogamukh	, Sissiborgaor	<u> </u>					
Name Of Revenue	Kamrup (M)	1	Dispur								
Circles	Morigaon	1	Morigaon								
Affected	South	1	Mankacl	nar							
	Salmara	1	Withintaci	iui							
	Total	6									
	District	Total	Revenue								
	Dhemaji	8			gamukh 6), (Sissiborgaon 1)					
Villages	Morigaon	9	(Moriga	on 9)							
Affected	South Salmara	20	20 (Mankachar 20)								
	Total	37									
	District	Male	Femal e	Childre n	Total Populatio n	Population Details	Crop Area (in Hect.)	Crop Area Details			
Population And Crop Area	Dhemaji	1127	1083	629	2839	(Gogamukh 1834), (Sissiborgaon 422), (Dhemaji 583)	101.00	(Gogamukh 35.00), (Sissiborgaon 60.00), (Dhemaji 6.00)			
Affected	Morigaon	0	0	0	0	(Morigaon 0)	750.00	(Morigaon 750.00)			
	South Salmara	2	2	3	7	(Mankachar 7)	199.00	(Mankachar 199.00)			
	Total	1129	1085	632	2846		1050.00				
Relief Camps / Centres Opened	Nil		1000	002	2010		200000				
Inmates In Relief Camps	Nil										
Human Lives Lost - Confirmed	Nil										
Human Lives Lost Confirmed - Death Type	Nil										
Human Lives Lost - Missing	Nil										
Human	Nil			_				-			

Lives Lost										
Missing -										
Type										
Animals	District	Total	Big	Small	Poultry					
Affected	Dhemaji Total	700 700	360 360	340 340	0					
Animals	Total	700	300	340	U					
Washed Away	Nil									
Houses Damaged	District	Fully Kuccha	Fully Pukka	Fully Total	Partially Kuccha	Partially Pukka	Partially Total	Others Huts	Others Cattle Shed	Others Total
	South Salmara	1	0	1	0	0	0	0	0	0
	Udalguri	1	0	1	0	0	0	0	0	0
	Total	2	0	2	0	0	0	0	0	0
Rescue Operation	District	Agency			Boats Deployed	Person Evacuate d By Boats	Animal Evacuate d By Boats	Helicopter s Deployed	Person Evacuated By Helicopter s	Medical Team Deploye d
	South Salmara				0	0	0	0	0	1
	Total				0	0	0	0	0	1
Relief Distributed	Nil									•
Relief Distributed Others	Nil									
Infrastructur	Nil									
e Damaged - Embankmen t Breached	Nil									
e Damaged - Embankmen	Nil District	Numbe	Details							
e Damaged - Embankmen t Breached Infrastructur e Damaged -		Numbe r	Badarpu area of E stating th 3650m to Dyke ald 09-06-20 due to hi affecting Patherk Resource right bar Kachuba rainfall o	Badarpur Onat on 19-05 of 6100 m af ong L/B of I 022, the EE, gh rise of fl the said dy andi - Tapa e, Patharkar uk of river Luri Left Banlon 09/06/20	on 09-06-2022, 5-2022, due to fecting the said River Barak fro Cachar Invs. V lood water, Ove ke., darpara Right adi, due to ince longai at Villag k Kachubari	the EE, Cach high rise of flo d dyke., om Badarpur t WR Division, er topping rea Bank Tapade essant rainfall ge-Tapadarpar As reported b (slump down)	ar Invs. WR I pood water, Ov o Bhanga Ph-Badarpur sub ched at Bhair arpara, Pathar on 09/06/2022 a. Approx stroy AEE, Wate	Bhanga Ph-II Division, Badar er topping reac I Bhairab Bar mitted report st ab Bari Umarpt kandi As repo 2 an erosion (sle etch is 22 meter r Resource, Pat it bank of river	pur submitted in the dat Naharpur to Srating that on 1 ar at Ch 4945 to treed by AEE, Valump down) occur.,	report ur at Ch rigouri On 9-05-2022, 0 5200 m Water cured at o incessant
e Damaged - Embankmen t Breached Infrastructur e Damaged - Embankmen	District Karimgan	4	Badarpu area of E stating th 3650m to Dyke ald 09-06-20 due to hi affecting Patherk Resource right bar Kachuba rainfall o	Badarpur Onat on 19-05 of 6100 m af ong L/B of I 022, the EE, gh rise of fl the said dy andi - Tapa e, Patharkar uk of river Luri Left Banlon 09/06/20	on 09-06-2022, 5-2022, due to fecting the said River Barak fro Cachar Invs. V lood water, Ove ke., darpara Right adi, due to ince Longai at Villag k Kachubari 22 an erosion (the EE, Cach high rise of flo d dyke., om Badarpur t WR Division, er topping rea Bank Tapade essant rainfall ge-Tapadarpar As reported b (slump down)	ar Invs. WR I pood water, Ov o Bhanga Ph-Badarpur sub ched at Bhair arpara, Pathar on 09/06/2022 a. Approx stroy AEE, Wate	Division, Badar fer topping reach I Bhairab Bar mitted report stab Bari Umarpu kandi As repo 2 an erosion (sle etch is 22 meter r Resource, Pat	pur submitted in the dat Naharpur to Srating that on 1 ar at Ch 4945 to treed by AEE, Valump down) occur.,	report ur at Ch rigouri On 9-05-2022, 0 5200 m Water cured at o incessant
e Damaged - Embankmen t Breached Infrastructur e Damaged - Embankmen	District Karimgan j	4 Numbe	Badarpu area of E stating th 3650m to Dyke ald 09-06-20 due to hi affecting Patherk Resource right bar Kachuba rainfall o	Badarpur Onat on 19-05 of 6100 m af ong L/B of I 022, the EE, gh rise of fl the said dy andi - Tapa e, Patharkar uk of river Luri Left Banlon 09/06/20	on 09-06-2022, 5-2022, due to fecting the said River Barak fro Cachar Invs. V lood water, Ove ke., darpara Right adi, due to ince Longai at Villag k Kachubari 22 an erosion (the EE, Cach high rise of flo d dyke., om Badarpur t WR Division, er topping rea Bank Tapade essant rainfall ge-Tapadarpar As reported b (slump down)	ar Invs. WR I pood water, Ov o Bhanga Ph-Badarpur sub ched at Bhair arpara, Pathar on 09/06/2022 a. Approx stroy AEE, Wate	Division, Badar fer topping reach I Bhairab Bar mitted report stab Bari Umarpu kandi As repo 2 an erosion (sle etch is 22 meter r Resource, Pat	pur submitted in the dat Naharpur to Srating that on 1 ar at Ch 4945 to treed by AEE, Valump down) occur.,	report ur at Ch rigouri On 9-05-2022, 0 5200 m Water cured at o incessant
e Damaged - Embankmen t Breached Infrastructur e Damaged - Embankmen	District Karimgan j Total	4	Badarpi area of E stating the 3650m to Dyke ald 09-06-20 due to his affecting Patherk Resource right bar Kachuba rainfall of Kachuba Details RK Nag approach rains and Gamaria damaged nearby of Dullebol length 3 area, C.R. Roa upto length	Badarpur Onat on 19-05 on 6100 m af ong L/B of I on 19-22, the EE, gh rise of fly the said dy andi - Tapae, Patharkarak of river Lari Left Banlon 09/06/20 uri. Approx ar - Gambin washed out to Rakhalb I on date 06 atchment ar narra veterbil 0 m due to ad at Ramar	on 09-06-2022, due to 5-2022, due to 5-2022, due to 6-2022, due to 6-206-206-206-206-206-206-206-206-206-20	the EE, Cach high rise of fle d dyke., om Badarpur t WR Division, er topping rea Bank Tapada ssant rainfall ge-Tapadarpar As reported b (slump down) eter. and to Daulatp and side length ed rain water maria to Rakh to incessant ra lebcharra vete s and drained . Road at Ram	ar Invs. WR I pood water, Over the pood water, Over the pood water, Over the pood of the p	Division, Badar fer topping reach I Bhairab Bar mitted report stab Bari Umarpu kandi As repo 2 an erosion (sle etch is 22 meter r Resource, Pat	pur submitted in the dat Naharpur to Situ the dat Naharpur to Situ the date of	report ur at Ch rigouri On 9-05-2022, o 5200 m Water cured at o incessant age- Bridge ncessant h 164 m ter from maged up to catchment h damaged
e Damaged - Embankmen t Breached Infrastructur e Damaged - Embankmen t Affected Infrastructur e Damaged -	District Karimgan j Total District Karimgan	4 Number	Badarpi area of E stating the 3650m to Dyke ald 09-06-20 due to hi affecting Patherk Resource right bar Kachuba Tainfall of Kachuba Details RK Nag approach rains and Gamaria damaged nearby c Dullebel length 3 area, C.R. Roa upto leng from near	Badarpur Onat on 19-05 on 6100 m af ong L/B of I of	on 09-06-2022, due to 5-2022, due to 5-2022, due to 5-2022, due to 5-2022 due to 6-2022 due to 6-202	the EE, Cach high rise of fle d dyke., om Badarpur t WR Division, er topping rea Bank Tapada sssant rainfall ge-Tapadarpar As reported b (slump down) eter. ad to Daulatp d side length ed rain water maria to Rakh to incessant ra lebcharra vete s and drained . Road at Ram (22 due to ince	ar Invs. WR I pood water, Over the pood water, Over the pood water, Over the pood of the p	Division, Badar Per topping reacher topping reacher topping reacher topping reacher topping reacher topping reacher topping the second of the	pur submitted in the dat Naharpur to Situ the dat Naharpur to Situ that on 1 ar at Ch 4945 to set date by AEE, Varied down) occir., that and it does not be a set of	report ur at Ch rigouri On 9-05-2022, o 5200 m Water cured at o incessant age- Bridge ncessant th 164 m ter from maged up to catchment h damaged rain water

Infrastructur		
e Damaged -	Nil	
Bridge	1111	
Infrastructur		
e Damaged -	Nil	
Wildlife	1111	
** Haire	District	Other Details
	District	Dhemaji - Anganwadi Centres Affected Today on 10/06/2022, No 2 Baruah 1 no. of AWC of Baruah Lalung
		submerged due to flood water,
Infrastructur e Damaged - Others	Dhemaji Karimgan j	Sissiborgaon - Washed away Culverts As on 10/06/2022, 1 no. of culvert was damaged on Lahram khuti to
		Chekaimajgaon road at Ch 500.0 M
		Badarpur - Irrigation Canal/Scheme Damaged On 09-06-2022, Executive Engineer, Irrigation Karimganj
		submitted report that on 18-05-22, the underground Hume Pipe Canal of size 1.22 m dia was affected at Malua
		Srigouri area due to flood water. The Location of the site is Latitude- 24.8642 and Longitude- 92.5216
	South	Mankachar - Fisheries/Pond As per report submitted Fisheries Department there are 93 nos Fisheries damaged
	Salmara	due to flash flood.
	District	Details
	Biswanat	Halem - Paken As reported by Water Resources Gohpur, mild erosion observed at Paken area on R/B of river
	h	Brahmaputra since 06/06/22 till 10/06/2022. Length 1400m 0
		Morigaon - 2 no Naramari (01-06-2022) As per Water Resources Dept., Erosion at 2 No. Naramari area with
		receding of water level of the river, massive erosion took place due to flow concentration because of restriction of
		water way for a reach length of about 200m and half of the crest of the embankment has already been eroded
	Morigaon	away threatening breach of the embankment. 0,
		Laharighat - Leruamukh, Goroimari , Bhajaikhati gaon & Barchapori As per report received from the Water
		Resources Dept. on 10-06-2022. Maximum erosion occured at Leruamukh is 1 m, Goroimari is 0 m, Barchapori is
		2 m & Bhajaikhati gaon is 3 m. 0
		Barkhetri - Larkuchi and Mukalmua Due to erosion damage have occurred in B/dyke at larkuchi, length 500m
	Nalbari	approx, as reported by AEE, WRD, MUKALMUA on 10/06/2022 Due to incessant rain AR to M.Mukalmua
	Ivaibaii	chowk to Rajiv Gandhi complex road damaged at mukalmua creating one big pot hole and surface damage, length
		20m approx, as reported by PWRD, barkhetri Teritorial sub div. on 10/06/2022. 0
		Sivsagar - Near Cherekapar under Sivasagar Revenue Circle Electrical 33 KV Line (Gargaon - sivasagar)
		damaged due to erosion near Cherekapar on 05-06-2022 . The Damages are :- 1.33 KV SP- Pole :- 2 Nos. 2. 33
	Sivasagar	KV PSC Pole 9.7 M:- 1 No 3. 33 KV pin insulator :- 12 Nos. 4.33 KV Disc insulator with H/F:- 6 Set 5 33 KV GI
		Channel :-02 Nos. 6. 33 KV V cross arm:- 1 No 7. 33 KV wole Conductor:5 CKM As per report received from
		APDCL, Sivasagar 0
Erosion	Sonitpur	Tezpur - Da-Parbatia Dated: 10.06.2022. As reported by Water Resource Department erosion is observed on the
		R/B of river Brahmaputra at Da-Parbatia (Lenga Chuburi). Length: 100 m 0
	South	Mankachar - 1. Darua 2. Chirakhawa Bengarvita As per report submitted water resource department Darua and
	Salmara	Chirakhawa Bengarvita river side erosion due to kaloo river for flash flood. Appx-Darua Length- 50M, Breadth- 5M and Chirakhawa Bengarvita Leangth-40M, Breadth-3M. dated: 10-06-2022 36
		Goreswar - 1. Village - No.1 Suagpur 2. Village - Balabari 1. Dated 09/06/2022. As reported by Water
		Resource department erosion occurred at East Bank of River Puthimari approximately 200 m. at Village No
		1.Suagpur .No active erosion reported on 10/06/2022. 2. 09/06/2022, As reported by Water Resource department
	Tamulpur	erosion occurred at West Bank of River Puthimari Village Balabari approximately 500m palliative measures like
		bamboo screening is done by concerned WRD department. Lat: 26. 557709 Long: 91.664876. No active erosion
		reported on 10/06/2022 0
		Doomdooma - 1. Village: No. 1 Kordoiguri(Darjijan), 2. Village : No. 2 Kordoiguri (Simoluguri Satra). 1.
	Tinsukia	River Bank erosion is being observed at No. 1 Kordoiguri (Darjijan)on the left Bank of River Brahmaputra
		(Ananta Nallah) since 19/05/2022 till 10/06/2022. As per information received from concerned Lot Mandal and
		WR department officials the affected stretch is about 410 m in length. (Long: 95.450531, Lati: 27.651217),
		population affected 37. 2. River Bank erosion is being observed at No.2 Kordoiguri (Simoluguri Satra)on the left
		Bank of River Brahmaputra (Ananta Nallah) since 19/05/2022 till 10/06/2022. As per information received from
		concerned Lot Mandal and WR department officials, the affected stretch is about 462 m in length. (Long:
		954505, Lati: 27.65196) 0
	Udalguri	Udalguri - Ambagaon (Alikash) Erosion Occured on the R/B of Kalyani river at Alikash Ambagaon around 140m on 09.06.2022. 0
Landslide	Nil	140III 0II 07.00.2022. U
Lanusnue	District	Details
Urban Flood	Kamrup	
Oluan Flood	(M)	Dispur - Hatigaon, Keraikuchi, Sijubari, Beharbari Due to rainfall waterlogging took place on 10/06/2022 0
<u> </u>	(/	