Differential





NOTE: If the * mark parts were replaced, the bearing preload must be adjusted (page 8-23).

