VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

## **CONTAINER 3317 DETAILS**

PO# I	ITEM	DESCRIPTION	VPART NO.	SHIP OTV	LOCATION	FOB	EXT COST
	112.11	Description (	MAKE	SIII QII			
3317 <b>1076FI</b>	1076FE	64-70 DOOR LOCK STRIKER ALL		16	A126	\$87.20	\$87.20
3317	3317 10/0FE	CHEVY65-72 A BODY CARS	CAMARO	10			
3317	1076FG	67-69 DOOR HANDLE RELAY RH	CAMARO	1	A126	\$7.07	\$7.07
3317	1076FH	67-69 DOOR HANDLE RELAY LH	CAMARO	2	A126	\$13.42	\$13.42
3317	1076FZ	71-81 DOOR GLASS LH CLEAR	CAMARO	1	N131 / G1	\$47.24	\$47.24
3317	3317 <b>1076JA</b>	68-69 QUARTER GLASS RH		1	B101	\$15.00	\$15.00
		CONVT CLEAR	CAMARO			+	+
		67-69 VENT WINDOW					
3317	3317 <b>1076K</b>	ASSEMBLY LHCONVT QUARTER VENT	CAMARO	2	B113	\$178.62	\$178.62
2215	40=5774	68-69 QUARTER GLASS LH		_	2101		
3317 <b>1076KA</b>	CONVT CLEAR	CAMARO	1	B101	\$14.61	\$14.61	
3317	1076P	70-73 DOOR SHELL RH	CAMARO	1	C102	\$270.00	\$270.00
2217	105(0)	70-73 DOOR HINGE LOWER		3	D111	002.16	<b>002.16</b>
3317	1076QA	RH=LH	CAMARO		D111	\$83.16	\$83.16
3317	1076QC	70-73 DOOR HINGE UPPER RH	CAMARO	1	D111	\$32.25	\$32.25
3317	1076QD	70-73 DOOR HINGE UPPER LH	CAMARO	2	D111	\$65.94	\$65.94
2217	105CD	70-73 DOOR SKIN RH CAMARO			G112	ф101 <i>7</i> 4	Φ101.774
3317 <b>1076R</b>	1076K	ONLY	CAMARO	2	C112	\$101.74	\$101.74
221=	10=40	70-73 DOOR SKIN LH CAMARO		1	2114	<b></b>	# <b>#</b> 00 ===
3317	1076S	ONLY	CAMARO		C112	\$39.75	\$39.75
		70-73 DOOR WINDOW GUIDE &					
3317	1076T	STOP4PC / SET	CAMARO	4	C82	\$64.00	\$64.00
3317	1076YA	70-81 DOOR SKIN RH	FIREBIRD	1	J172	\$47.37	\$47.37

PAGE:21