VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

## **CONTAINER 3318 DETAILS**

PO# ITEM	ITEM	DESCRIPTION	VPART NO.	CHID OTV	LOCATION	FOB	EXT COST
	TIENI	DESCRIPTION	MAKE	Shir Q11			
3318 <b>1102CJ</b>	55-59 DOOR HINGE PILLAR		2	B45	\$32.24	\$32.24	
3316	5516 1102CJ	POCKET RHLOWER INNER	CHEVY PU	2	D45	\$32.24	\$32.24
3318 <b>1102CK</b>	55-59 DOOR HINGE PILLAR		2	B45	\$32.24	\$32.24	
3316	3310 1102CK	POCKET LHLOWER INNER	CHEVY PU		D43	\$32.24	\$32.24
3318	1102H	47-55 DOOR ARM REST BLACK		_ 2	B92	\$38.64	\$38.64
3316	110211	RH=LH1 ST SERIES	CHEVY PU		D92	φ36.04	φ36.04
3318	3318 <b>1102J</b>	55-59 DOOR ARM REST BLACK		2	B92	\$38.64	\$38.64
3310	11025	RH=LH	CHEVY PU		D72	φ36.04	φ36.04
3318	3318 <b>1102K</b>	64-67 DOOR ARM REST BLACK		_ 2	B92	\$21.84	\$21.84
3310	11021	RH=LH	CHEVY PU		D92	φ41.04	φ21.04
3318	1102L	68-71 DOOR ARM REST BLACK		4	B92	\$30.36	\$30.36
3310	3316 1102L	RH=LH	CHEVY PU	<b>-</b>	10/2	φ30.50	Ψ50.50
3318	1102SA	47-50 DOOR WINDOW INNER		1	B103	\$28.15	\$28.15
3310	3316 1102SA	FRAME RH	CHEVY PU		DIOS	φ26.13	Ψ20.13
3318	3318 <b>1102TA</b>	47-50 DOOR WINDOW INNER		1	B103	\$28.06	\$28.06
3310		FRAME LH	CHEVY PU		D103	Ψ20.00	Ψ20.00
3318	1102X	47-50 DOOR WINDOW FRAME LH	CHEVY PU	<b>-</b>   1	B103	\$19.84	\$19.84
			CHEVITO				
3318	1102XB	47-51 DOOR LATCH STRIKER PR	CHEVY PU	2	B92	\$19.62	\$19.62
3318	1102XD	64-66 DOOR LATCH STRIKER PR	CHEVY DI	1	F162	\$13.86	\$13.86
	-		CHEVY PU	1		,	,
3318	1102XE	67-72 DOOR LATCH STRIKER PR	CHEVY PU		C82	\$16.80	\$16.80
3318 <b>1103</b>	DOOR SHELL LH 67-7172 HAS		1	021	Φ1.55.02	Φ155 0 <b>2</b>	
	1103	HOLE FOR VENT WINDOW	CHEVY PU	1	031	\$155.82	\$155.82
3318 1103	11022DT	60-66 WINDSHIELD SUNVISOR		1		<b>#0.00</b>	фо оо
	11033DT	BRACKETLH	CHEVY PU	1		\$0.00	\$0.00
3318	1103B	DOOR SHELL LH 72		1	031	\$154.64	\$154.64
3310 <b>1103D</b>		DOOK SHEEL EH 72	CHEVY PU			ψ154.04	Ψ154.04

PAGE:6