| VENDOR | SHIP DATE | SHIP VIA | F.O.B | FREIGHT |
|--------|------------|----------|-------|---------|
| CORV | 2017-06-28 | 1 | ORGIN | 1 |

CONTAINER ENCOUNTERED DETAILS

| PO# | ITEM | DESCRIPTION | VPART NO. | MAKE | SHIP QTY | LOCATION |
|------|----------|--|--------------|-----------|-------------|----------|
| 3291 | 10 | | | | 16 | |
| 3291 | 100 | 67 IGNITION LOCK LATER | | CAMARO | 8 | 1-1 |
| 3291 | 1000C | 67-69ANTENNA MAST*FIXED WHIP STYLE* | | CAMARO | 4 | B74 |
| 3291 | 1011 | 47-54 FRONT SHOCK ABSORBERS PR | | CHEVY PU | 8 | |
| 3291 | 1011B | 47-54 SHOCK ABSORBER BRACKET | | CHEVY PU | 4 | G102 |
| 3291 | 1012 | 55-59 FRONT SHOCK ABSORBERS PR | | CHEVY PU | 12 | A133 |
| 3291 | 1012A | DISCONTINUED | | CHEVY PU | 20 | A133 |
| 3291 | 1015 | 67-82 VALVE COVER POLISHED ALUMINUM | | CAMARO | 4 | A26 |
| 3291 | 1021A | 67 QUARTER/DOOR FRAME ASSEMBLY RH | | CAMARO | 4 | |
| 3291 | 1023B | 69 QUARTER/DOOR FRAME ASSEMBLY LH | | CAMARO | 4 | |
| 3291 | 1041 | FENDER LH 70-77 | | CAMARO | 4 | E32 |
| 3291 | 1052B | 67-68 SEAT FRAME SUPPORT LH CONVT | | CAMARO | 4 | G115 |
| 3291 | 1112A | FRONT BUMPER BRACE LH 67-70 CHEVY | | CHEVY PU | 4 | B92 |
| 3291 | 1112E | 67-70 FRONT BUMPER BRACKET SET | | CHEVY PU | 4 | B92 |
| 3291 | 1143B | FRNT DOOR TOP WEATHERSTRIP RH 73-80 | CV01-R03 | CHEVY PU | 4 | C33 |
| 3291 | 1473E | 66-67 QUARTER LIP PATCH PANEL RH | | CHEVELLE | 4 | B35 |
| 3291 | 1477A | 66-67 FENDER PATCH PANEL LH | | CHEVELLE | 4 | A136 |
| 3291 | 14B53132 | 73-77 CARPET BLACK 80/20 LOOP | | EL CAMINO | 8 | |
| 3291 | 1502 | INNER FENDER RH 68-69 | | GTO | 8 | J161 |
| 3291 | 1541 | DOOR LATCH ASSY 68-69 LH GTO | | GTO | 4 | A103 |

PAGE:1