

The application is not able to keep up with the hardware acquisition. Increasing the buffer size, reading the data more frequently, or specifying a fixed number of samples to read instead of reading all available samples might correct the problem.

Property: NationalInstruments.DAQmx.DaqStream.ReadRelativeTo

Corresponding Value:

National Instruments. DAQmx. Read Relative To. Current Read Position

Property: NationalInstruments.DAQmx.DaqStream.ReadOffset

Corresponding Value: 0

Task Name: \_unnamedTask<2>

Status Code: -200279