- Hole for roller wheel is not big enough, will need to expand it
- The thumb divot is at too steep of an angle, it is blocking the snap pins from accepting the mouse top
- In an ideal world, the back part of my mouse would be higher so it could meet my palm (represented by the "topographical lines" drawn on the mouse)







