MILITARY SPECIFICATION

TRIPOD ASSEMBLY, DEMOLITION KIT, M180,
METAL PARTS FOR AND ASSEMBLY

This amendment forms a part of military specification MIL-T-50595C(AR), dated 23 September 1979, and is approved for use within the U.S. Army Armament, Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 5

Table I: Change "M57 Firing Device, Modified (Dwg. 9244458)" to "Firing Device, Antipersonnel Mine, Electrical M57 (Dwg. 8800924)"

Add the following to Table I:

"Cover, Protective (Dwg. 12598668)

Examination for Defects 10 100% 3.1 4.4.2.13A"

PAGE 20

4.4.2.13: Change TITLE to "Firing Device, Antipersonnel Mine, Electrical M57"

Change DRAWING NUMBER to "8800924"

Under "Critical" change "1 Safety pin missing or loose 100% 3.1 Visual" to "None defined".

PAGE 20A

4.4.2.13A: Add new 4.4.2.13A included.

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:30Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.13A	Cover, Protective	1 OF 1	12598668
			NEXT HIGHER ASSEMBLY
			9244403

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Largest height		0.40%	3.1	Gage
102	Top width		0.40%	3.1	Gage
103	Angle between top and largest height		0.40%	3.1	Gage
104	Angle between top and slanted side		0.40%	3.1	Gage
105	Height from top to bottom of rivet tabs		0.40%	3.1	Gage
106	Height of top lip		0.40%	3.1	Gage
107	True position of bolt slots		0.40%	3.1	Gage
108	True position of rivet holes		0.40%	3.1	Gage
109	Inside depth		0.40%	3.1	Gage
110	Material thickness		0.40%	3.1	Gage
111	Presence of rivets		0.40%	3.1	Visual
112	Markings present & properly located		0.40%	3.1	Visual
Minor					
201	Protective finish missing or imcomplete		0.65%	3.1	Visual
202	Poor workmanship		1.0%	3.5	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:30Z
Check the source to verify that this is the current version before use.

PAGE 29

4.4.2.22: Add the following under "Critical":

"1 M57 Protective Cover missing 100% 3.1 Visual"

Add the following under "Major":

"109 Bail visible (1) 100% 3.1 Visual"

Add the following under NOTES:

(1) If bail is visible, the protective cover should be removed, the bail placed in the safe/vertical position and the cover reinstalled."

PAGE 30

4.5.4: Change "(Dwg. 9244458)" to "(Dwg. 8800924)"

Custodian
Army-AR

Preparing activity
Army-AR

(Project 1375-A388)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:30Z
Check the source to verify that this is the current version before use.