MILITARY SPECIFICATION

FUZE, ROCKET, M412
LOADING, ASSEMBLING AND PACKING

This amendment forms a part of Military Specification MIL-F-60010 (MU), dated 16 December 1963 and is approved for use by the US Army Armament Research and Development Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

Add the following preamble underneath the title:

"This specification is approved for use by the US Army Armament Research and Development Command ans is available for use by all Departments and Agencies of the Department of Defense."

PAGE 2

Add new paragraph 3.4 and 3.5 as follows:

"3.4 Position of locking shaft. The locking shaft shall bear on the graze lever as illustrated in drawing 10048786 as evidenced by 0.350 inches minimum distance between the inside bottom surface of the firing pin and the bottom surface of the mounting base when the firing pin is inserted into the fuze cavity of the mounting base.

3.5 Electrical resistance. The maximum electrical resistance indicative of an unarmed fuze, shall not exceed ten ohms when measured between the telltale contact in the cover assembly and the cover and shall be not less than one megohm when measured between the terminal and the cover."

PAGE 4

4.2.2.2, Critical defect: Delete in its entirety and substitute the following:

"1. One or more electrical test marks missing (telltale contact-cover, terminal-cover) Visual 02001.

FSC: 1340

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:03Z
Check the source to verify that this is the current version before use.

2. Fuze in armed or partially armed position (see 3.5) Test (see 4.2.4 and 4.3.2) 02011."

PAGE 5

4.2.3.2: Delete in its entirety and substitute the following:

"4.2.3.2 Position of locking shaft (see 3.4) - Code No. 02010 - Major defect. In the event that the graze functioning elements of the fuze (less booster pellet) are received at the loading plant unassembled or if the graze elements have for any reason been removed, the following inspection shall be performed 100 percent. The inspection shall be performed following the insertion of the firing pin into the firing pin cavity and immediately prior to the insertion of the firing pin spring into the firing pin and the assembly of the base plug into the firing pin cavity. The inspection shall consist of gaging to determine if the fuze meets the applicable requirements. Fuzes failing to meet the requirement as determined using the inspection equipment specified in 4.2.4 shall be classed defective and removed from the lot subject to repositioning of the locking shaft and reinspection prior to reentry into the lot."

Add new paragraph 4.2.3.3 as follows:

4.2.3.3 Explosive graze functioning (see 3.11.1 of Specification MIL-F-60005, MU), Functioning during non-functioning test - Code No. 02012, Major defect, average functioning g level - Code No. 02013, Major defect, and non-functioning during functioning test - Code No. 02014 - Major defect. In the event that the graze functioning elements of the fuze (less booster pellet) are received at the loading plant unassembled or if the graze elements have been disturbed during shipment, a sample of eighteen (18) complete fuze assemblies shall be selected from each lot and subjected to the test specified in 4.3.3, using test equipment specified in 4.2.4. The lot shall be rejected if one or more fuzes function during the non-functioning portion of test, or if the average functioning g level, plus or minus the product of 1.1 and the standard deviation fail to conform to the requirement contained in paragraph 3.11.1 of Specification MIL-F-60005 (MU), or if one or more fuzes fail to function explosively within the required g limits."

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:03Z
Check the source to verify that this is the current version before use.

4.3.2: Delete in its entirety and substitute the following:

"4.3.2 Fuze safety. The electrical resistance shall be measured between the terminal and the cover and between the telltale contact and the cover. The fuze shall be classed defective if the resistance between the terminal and the cover is less than the requirement. A low voltage ohmmeter shall be used in determining the terminal-cover resistance. If the reading between the telltale contact and the cover exceeds the requirement and the fuze is not classed defective on the terminal cover electrical test, visual examination to determine the actual condition of the leaves of the setback assembly is permitted. The fuze shall be classed defective if during the telltale contact cover electrical test, the fuze exhibits in excess of the specified maximum electrical resistance and upon visual examination one or more leaves are found in any position other than the fully safe position. The fully safe position, as illustrated in drawing 10048786, is defined as follows:

(1) Leaf Number 1 shall press against the rotor pin of the rotor assembly and shall retain it from rotational movement toward the armed position.

(2) Leaf Number 2 shall be supported under spring tension against the telltale contact and shall be positioned so as to interfere with the rearward (towards the mounting base) movement of Leaf Number 2.

(3) Leaf Number 3 shall be supported under spring tension against the sidewall of the step provided for it in the Number 2 leaf so as to interfere with the rearward (towards the mounting base) movement of Leaf Number 2.

WARNING: When measuring the resistance between the terminal and the cover, the test equipment shall limit the current to 20 microamperes to prevent inadvertent functioning of the detonator. This test may be dangerous and should be performed behind a suitable barricade. Prior to removing the cover to perform the visual inspection for fully safe positioning of the leaves the base plug, the firing pin and the firing pin spring shall be removed to assure fuze safety during the inspection. These parts shall remain separated until the cover is completely resecured onto the fuze and while they are

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:03Z
Check the source to verify that this is the current version before use.

separated, they shall be identified for replacement into the fuze from which they were separated. The parts shall be handled carefully and kept free from contamination and upon reinsertion of the firing pin into the fuze, the inspection for position of the locking shaft of paragraph 4.2.3.2 of MIL-F-60010 as added by engineering orders dated later than EO 31969-S dated October 1964 shall be performed 100 percent. Fuzes failing to meet the applicable requirements or the position of the locking shaft inspection shall be classed defective and removed from the lot."

4.3.3, line 6: Add the following statement after "specified":

"and maintained for the minimum time period specified."

Custodian:
Army-AR

Preparing Activity:
Army-AR

Project No: 1340-A611

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:03Z
Check the source to verify that this is the current version before use.