MIL-C-48237 (PA)
Amendment 3
1 December 1976
Superseding
Amendment 2
3 June 1975

MILITARY SPECIFICATION

CARTRIDGE, 105MM, APDS-T, M728

LOADING, ASSEMBLING AND PACKING

This Amendment forms a part of Military Sepcification MIL-C-48237 (PA), dated 27 July 1973, and is approved for use by all Departments and Agencies of the Department of Defense.

Paragraph 2.1, delete drawing number 9278419 and 9278417 and substitute:

" 8835039 - Box, Packing, Ammunition for Cartridge, 105MM, APDS-T, M392A1, M392A2 and M728 in Fiber Container M431.

8835040 - Container, Ammunition, Fiber M431, for Cartridge 105MM, APDS-T, M392A1, M392A2 and M728 for Gun M68. "

Paragraph 3.6.1, delete and substitute:

" 3.6.1 Muzzle Velocity - The corrected muzzle velocity of the cartridge, when fired at 70°F, shall not be more than 4730 feet per second (fps) nor less than 4630 (fps), and the standard deviation of the lot shall not be greater than 12 fps maximum. "

Paragraph 3.8, delete in its entirety.

Paragraph 4.2.2.3, delete drawing number " 9276809 " and substitute " 9287564. "

*Paragraph 4.2.2.3, add the following defect:

" 100% Major

103. Base plug assembly not properly seated.....Visual/Manual 03006 "

FSC: 1315

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:18Z
Check the source to verify that this is the current version before use.

Paragraph 4.2.2.4, Add "major defect no. 103-100 percent inspection Primer above Flush - Gage (CD) Code No. 04006."

Paragraph 4.2.2.5, delete drawing number "9278416" and substitute "8835040."

Paragraph 4.2.2.6, delete drawing number "9278417" and substitute "8835040."

Paragraph 4.2.2.7, delete drawing number "9278419" and substitute "8835039."

Add the following paragraph:

"4.2.2.8, Case Cartridge and Liner Assembly 105MM, M115B1 (see dwg. 9282950).

Categories	Defects	Method of Inspection	Code No.
Critical: None defined			
Major:	AQL 0.65 percent		
101.	Location of liner assembly	Gage (CD)	08001
102.	Adhesive missing	Visual	08002
103.	Liner assembly improperly assembled	Visual	08003
Minor:	AQL 0.65 percent		
201.	Evidence of poor workmanship	Visual	08004"

Paragraph 4.2.3.8.3, add the following sentence:

"Sub-projectile spin rate shall also be recorded."

Paragraph 4.2.3.8.5, add:

To Title: "...and Spin Rate"

End of Sentence: "...and spin rate."

Paragraph 4.3.4.1, delete last sentence and substitute:

"This test shall be conducted using M68 gun tubes which have fired APDS type rounds only and have at least 60 percent life remaining."

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:18Z
Check the source to verify that this is the current version before use.

Paragraphs 4.3.4.1 and 4.3.4.3, add the following sentence:

"Sub-projectile spin rate shall also be recorded for informational purposes only."

Paragraph 5.1.1, delete drawing number "9278417" and substitute "8835040."

Paragraph 5.2.1, delete drawing number "9278419" and substitute "8835039."

Paragraph 5.3, delete drawing numbers "9278417 and 9278419" and substitute "8835039 and 8835040."

Paragraph 6.5, delete "SMUPA" and substitute "SARPA-."

Paragraph 6.7.2, delete the following requirement and note:

Test	Requirement	Sampling Para.	Test Procedure Para
Muzzle Velocity	"e. Pressure (info-Note 1)	4.2.3.8.1.1	4.3.4.1"

Paragraph 6.7.2, add the following requirements:

Test	Requirements	Sampling Para	Test Procedure Para
Muzzle Velocity	"e. Spin Rate (Info)	4.2.3.8.5	4.3.4.1"
Extreme Temp Firing	"e. Spin Rate (Info)	4.2.3.8.3	4.3.4.3"

*Asterisks indicate changes or additions to Amendment 2.

Custodian:
ARMY-PA

Preparing Activity:
ARMY-PA

Project Number: 1315-A122

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:18Z
Check the source to verify that this is the current version before use.