INCH-POUND

MIL-D-50868A (AR)
AMENDMENT 3
25 June 2001
SUPERCEDING
AMENDMENT 2
16 JUNE 1993

MILITARY SPECIFICATION

DETONATOR, FLASH, M85
PARTS AND LOADING, ASSEMBLING AND PACKING

MIL-D-50868A was inactivated after 15 July 1996 for new design.

This amendment forms a part of MIL-D-50868A (PA), dated 05 February 1974, and is approved for use by the U.S. Army Armament Research, Development and Engineering Center, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 2

2.1 Under inspection equipment, add "12912871 - M104 Primer holder".

Page 10

Add new paragraph

"4.3.2.9 Cup (See dwg. 12929269)

| CATEGORIES | DEFECTS | METHOD OF INSPECTION |
|---|---|---|
| Critical: | None defined | |
| Major: | AQL = 0.65 percent | |
| 101 | Thickness of thin section at bottom | Gage |
| 102 | Length | Gage |
| 103 | Outside Diameter | Gage |
| 104 | Inside Diameter | Gage |
| Minor: | None defined" | |


DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:41Z
Check the source to verify that this is the current version before use.

* 4.4.3.1, Delete in its entirety and substitute the following:

"4.4.3.1 Sensitivity and energy output. - The detonator shall be assembled to the applicable test fixture. A steel ball 1 3/16 inch in diameter and weighing 3.95 ounces, maximum, shall be dropped on the firing pin to function the M104 primer, from a height of 8 inches, maximum. The height of drop shall be measured as the height from the top of the firing pin to the bottom of the ball. A detonator that fails to fire or fails to create a depression in the aluminum disc of the required depth shall be classed defective. Method of inspection shall be in accordance with Drawings 12977395, 12977393, 8827829, 8827934, 12977392, 9200012, 12977396, and 12977397.

* 4.4.3.2, Delete in its entirety and substitute the following:

"4.4.3.2 Waterproofness. - Within one hour after removal from the water the detonator shall be subjected to the sensitivity and energy output test specified in 4.4.3.1. Any detonator which fails to fire or fails to create a minimum depth of indentation in the aluminum disc as specified in 3.4.1 shall be classed defective.

The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assume no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army - AR

Preparing activity:
Army – AR

(Project 1375-0096)



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:41Z
Check the source to verify that this is the current version before use.