MIL-F-50780(MU)
AMENDMENT 2
22 March 1973

SUPERSEDING
AMENDMENT 1
14 December 1972

MILITARY SPECIFICATION

FUZE, MT, M565 ASSEMBLY (ALTERNATE)

This amendment forms a part of Military Specification MIL-F-50780(MU) dated 16 June 1972.

Paragraph 3.4.2, line 4, delete "180 plus 5 feet" and substitute "150 plus 5 feet".

Paragraph 3.4.3, add "Table I" above "Fuze Setting".

Add Paragraph 3.4.7:

"3.4.7 High and Low Temperature Conditioning.-For the high and low temperature firings only the fuze shall be temperature conditioned. The elapsed time for the conditioning chamber to the firing in the weapon shall not exceed five (5) minutes. Reconditioning is not permitted".

Paragraph 3.5.1, delete the word "porosity".

Paragraph 4.2, line 7, after "20", delete "D.A.M." and substitute "Delay Arming Mechanism (D.A.M)," line 8 after 4.4.13.1 add "(see 6.8)".

Paragraph 4.2.3.2, delete "(3)" and substitute "(2)".

Paragraph 4.2.1, delete "450" and substitute "425".

Paragraph 4.2.6, under "Test Method" for 4.4.13.1 add "(see 6.8)".

Paragraph 4.2.6, under "Quantity" for "Time-to-Burst (Ambient Temperature)". delete "5" and substitute "20".

Paragraph 4.3.2.11 after "MAJOR", add "AQL = 1.0%" and delete "MAJOR" characteristic "101".

Paragraph 4.3.2.15, delete drawing letter "D" and substitute "F".
Add "MAJOR" characteristic "108" and "109".

"108.	Profile of external surface, incorrect	Gage
109.	Threads damaged	Visual"

FSC 1390

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:37Z
Check the source to verify that this is the current version before use.

Paragraph 4.3.2.16, in heading, delete "(Faze)" and substitute "(Fuze)".
Add "MAJOR" characteristic "108".
"108. Profile of external surface, incorrect Gage"

Paragraph 4.3.2.27, for "CRITICAL" characteristic "3", delete "Riming" and substitute "Timing".

Delete the following paragraphs:

* "4.3.2.29 "101. Length from shoulder to top of pin less than min. allowable (to be checked after the load test, see 4.3.3.6.1) Gage"

* 4.3.2.31 "3. Delay arming mechanism rotor armed or partially armed as viewed through the flash hole (to be checked immediately prior to assembly of the lead charge)".

Paragraph 4.3.2.33, line 1, after the word "Periodic" add "(at least once during each 8 hours shift)".

Paragraph 4.3.2.33, f., delete drawing number "F10523008" and substitute "F11743960".

Paragraph 4.3.2.33, h., delete "(3)" in its entirety.

Add new paragraphs 4.3.2.34, 4.3.2.35, 4.3.2.36, 4.3.2.37 and 4.3.2.38.

"4.3.2.34 Pallet Assembly, Drawing D11743962 covering a detail of Drawing F11738602.

CRITICAL

None defined

MAJOR AQL = 1.0%

101.	Broken, deformed, or bent assembly	Visual
102.	Balance, staff inadequately staked or seated	Visual
103.	Metal defective	Visual

4.3.2.35 Wheel and Pinion Escapement Drawing D11743967 covering a detail of Drawing F11738602.

CRITICAL

None defined

MAJOR AQL = 1.0%

101.	Circular runout of escape wheel and pinion	Gage
102.	Perpendicularity of escape wheel and pinion, incorrect	Gage

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:37Z
Check the source to ensure that this is the current version before use.

4.3.2.35 (Cont'd)

MAJOR (Cont'd)

103.	Broken or missing teeth	Visual

4.3.2.36 No. 1 Gear and Pinion Assembly, Drawing D10523167 covering a detail of Drawing F11738602.

CRITICAL

None defined

MAJOR AQL = 1.0%

101.	Circular runout of gear and pinion	Gage
102.	Perpendicularity of gear and pinion, incorrect	Gage
103.	Broken or missing teeth, improper assembly	Visual

4.3.2.37 Rotor Assembly, Drawing D10551356 covering a detail of drawing F11738602.

CRITICAL

None defined

MAJOR AQL = 1.0%

101.	Circular runout of rotor assembly	Gage
102.	Perpendicularity of rotor assembly, incorrect	Gage
103.	Broken or missing teeth, improper assembly	Visual

4.3.2.38 Escape Wheel, Drawing C8595539 covering a detail of Drawing F11738602.

CRITICAL

None defined

MAJOR AQL = 1.0%

101.	Escape wheel profile, incorrect	Gage

Paragraph 4.3.3.1, delete drawing numbers "D10523171" and substitute "C8595539", "B10523175" and substitute "B11743965" and "C10520951" and substitute "C10520664".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:37Z
Check the source to verify that this is the current version before use.

Delete "Arbor, escapement D10534857".

Paragraph 4.3.3.4.1, delete drawing numbers "D10523170" and substitute "D11743967" and "D10523174" and substitute "D11743962".

Paragraph 4.3.3.4.2, delete "Escapement Gear and Pinion Assembly C10521112".

Add the following paragraph:

* "4.3.3.9.3 Spin, 3000 ± 50 r.p.m. with setback assembly (nondestructive).- Each D.A.M. assembly produced shall be tested to determine that the rotor is restricted from moving into the armed position when spun at 3000 r.p.m. Failure of setback mechanism assembly to restrict movement of the rotor with both spring loaded blocks in the fully open position shall be cause for rejection of that assembly (see 4.4.9.3)."

Delete paragraphs, 4.3.3.11, 4.4.11 and 4.4.11.1 in their entirety.

Paragraph 4.3.3.13, line 1, delete "Sixty (60)" and substitute "Forty (40)" and after the word "fuzes" add "plus 20 D.A.M.'s".

Add the following paragraph:

* "4.4.9.3 Spin, 3000 ± 50 r.p.m. with setback assembly.-The unarmed D.A.M. shall be spun in a counterclockwise direction when viewed from movement plate end at a constant r.p.m., as specified. The duration of spin shall be three (3) seconds minimum. At the conclusion of the test, the rotor and blocks shall be returned to the unarmed position".

Paragraph 4.4.10.1, line 3, delete "lower cap" and substitute "head".

Paragraph 4.4.13.1, line 2, after "subassemblies" add "(see 6.8)".

* The margins of this amendment are marked with an asterisk to indicate where changes (additions, modifications, corrections, deletions) from the previous issue were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective on the marginal notations and relationship to the last previous issue.

Custodian:

Army - MU

Preparing activity:

Army - MU(FA)

Project No. 1390-A121

Source: https://assist.dla.mil - Downloaded: 2026-10-22T20:37Z
Check the source to verify that this is the current version before use.