MIL-P-63142A (AR)
AMENDMENT 4
17 January 1983
SUPERSEDING
AMENDMENT 3
29 March 1982

MILITARY SPECIFICATION

PROJECTILE, 8 INCH, HE, RA, M650
LOADING, ASSEMBLING AND PACKING

This amendment forms a part of Military Specification MIL-P-63142A (AR) dated 08 February 1981, and is approved for use by the U.S. Army Armament Research and Development Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 12

4.4.2.1, change title to read: "Delay Assy and Motor Body prior to Assembly".

Add the following Major defect:

103. Rocket motor body protective cap missing or improper 100% 3.2 Visual.

PAGE 16

* 4.4.2.5, delete: "Critical 1: Nozzle insert missing, loose, inverted, or damaged" and substitute the following:

"Critical 1: "Nozzle insert missing, loose, or damaged."

PAGE 19

4.4.2.8, add the following Major defects:

"102. Forward protective cap missing or improper 100% 3.2 Visual.
103. Aft protective cap missing or improper 100% 3.2 Visual".

FSC 1320

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:20Z
Check the source to verify that this is the current version before use.

PAGE 20

4.4.2.9, Major category:

Major 102, Inspecton Method column: Delete "Gage" and substitute "Visual".

Major 104, Inspection Method column: Delete "Visual" and substitute "Gage"

Add the following Major defects:

"107. Pellet cavity depth incorrect 0.40% 3.2 Gage
108. Pellet cavity diameter incorrect 0.40% 3.2 Gage".

PAGE 26

4.4.2.14, Critical defect 1: Delete "O-ring groove"

Major defect 106: Delete in its entirety.

Add the following major defects:

"106. Forward grain cushion improper, missing or improperly lubricated, prior to application of sealant 0.40% 3.2 Visual.
108. Aft protective cap missing or improper on aft warhead 100% 3.2 Visual."

PAGE 28

4.4.2.15, add the following Minor defect:

"205. Lifting plug improperly lubricated 0.65% 3.2 Visual".

PAGE 29

4.4.2.16, Major defect 103:

Delete in its entirety and substitute the following:

"103. Strapping or staples missing or loose 0.40% 3.2 Visual.

Minor defect 203:

Delete in its entirety and substitute the following:

"203. Strapping or staples improperly engaged 0.65% 3.2 Visual".

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:20Z
Check the source to verify that this is the current version before use.

PAGE 31

4.4.3.2, add the following:

"As an alternate to the once an hour torque check sample, a verification check may be made on the torque assembly machine. In this case, the torque readout from the assembly machine shall be verified for transducer accuracy at the beginning and end of the operating shift and after each four hour production interval. If the torque assembly machine fails the verification test, all the projectiles assembled during that production interval shall be rejected. In the event of two consecutive gap rejects, the torque assembly machine shall be checked for proper calibration and operation at that time. Failure of these checks will reject those projectiles assembled since the last acceptable verification test. If the torque display mechanism indicates a torque not within the specified range, the torque assembly machine shall automatically shut down and require appropriate corrections to restore its operation."

PAGE 34

4.4.3.7, add the following:

"As an alternate to the once an hour torque check sample, a verification check may be made on the torque assembly machine. In this case, the torque readout from the assembly machine shall be verified for transducer accuracy at the beginning and end of the operating shift and after each four hour production interval. If the torque assembly machine fails the verification test, all the projectiles assembled during that production interval shall be rejected. In the event of two consecutive gap rejects, the torque assembly machine shall be checked for proper calibration and operation at that time. Failure of these checks will reject those projectiles assembled since the last acceptable verification test. If the torque display mechanism indicates a torque not within the specified range, the torque assembly machine shall automatically shut down and require appropriate corrections to restore its operation."

The margins of this amendment are marked with an asterisk to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army - AR

Preparing activity:
Army - AR

(Project 1320-A662)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:20Z
Check the source to verify that this is the current version before use.