MIL-L-45935A(AR)
AMENDMENT 2
29 JUNE 1987
SUPERSEDING
AMENDMENT 1
11 APRIL 1978

MILITARY SPECIFICATION

LAUNCHER, GRENADE, 40MM: DETACHABLE M203

This amendment forms a part of Military Specification MIL-L-45935A, dated 5 September 1974, and is approved for use by all Departments and Agencies of the Department of Defense.

PAGE 1

* 1.1 Change "the M16 and M16A1, 5.56mm Rifle to "the M16 and M16A1 or M16A2, 5.56mm Rifle".

PAGE 4

* 3.2.3.2 Change "2.75 pounds minimum to 6.75 pounds maximum" to "0.65 pounds minimum to 1.62 pounds maximum".

3.2.3.4 Add: testing shall be as specified in 4.5.3.10."

3.2.3.5 Delete and substitute:

"3.2.3.5 Breech insert. The breech insert shall be securely seated and torqued to 50 pounds-inches ± 5 pounds-inches so that the breech insert face is flush to 0.007 inch below the breech surface of the receiver. After the breech insert has been securely seated and torqued, the sealing compound shall be allowed to cure for not less than 24 hours. The loosening torque of the breech insert from the receiver shall not be less than 130 pounds-inches - 10 pounds-inches. The firing pin hole shall be free of residue that would affect firing pin movement or freedom of other moving parts. Testing shall be as specified in 4.5.3.8.".

PAGE 6

* 3.3.3 Change "an M16 or M16A1 rifle" to "an M16 or M16A1 or M16A2 Rifle".

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://apps.dtic.mil - Downloaded: 2026-10-22T04:12Z
Check the source to verify that this is the current version before use.

3.3.3.2 Change "an M16 or M16A1 rifle" to "an M16 or M16A1 or M16A2 Rifle".

Add 3.5.1 as shown below:

"3.5.1 Definition of reliability failure.

3.5.1.1 The occurence of a malfunction which cannot be cleared in 10 seconds. A malfunction is any cessation of any ability of the system or any of its components to perform its intended function. A system is the item or combination of items which are under test.

3.5.1.2 The occurence of a launcher condition which causes an unwarranted safety hazard to personnel.

3.5.1.3 The occurence of a broken or unserviceable part which renders the launcher inoperable or unsafe if firing is continued.

3.5.1.4 Failures which are attributable to ammunition shall not be charged against the launcher; they will however, be recorded."

PAGE 8

4.5.2.2.1 Delete "F1183800 and add "F11838246".

* Change "the M16 or M16A1 rifle" to "the M16 or M16A1 or M16A2 Rifle".

PAGE 10

* 4.5.3.4 Delete in its entirety and substitute:

"4.5.3.4 Trigger pull, safety actuating torque, pressure resistance and functioning and breech insert loosening torque. Each launcher shall be tested for trigger pull (see 3.2.3.9), safety actuation torque (see 3.2.3.11.2), pressure resistance and functioning (see 3.3.1) and breech insert loosening torque (see 3.2.3.5) using the test methods specified in 4.7.2.4, 4.7.2.5, 4.7.4 and 4.7.7.1.1.1 respectively. Failure of the launcher to pass any of these tests shall be cause for rejection."

PAGE 11

4.5.3.8.1.1.1 Delete in its entirety and substitute the following:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T04:20Z
Check the source to verify that this is the current version before use.

"4.5.3.10 Trigger sear and secondary sear testing. A sample of 50 launchers shall be randomly selected from each inspection lot for trigger sear and secondary sear requirements of 3.2.3.4 using the test method specified in 4.7.2.6. Failure of the launcher to pass the above test shall be cause for rejection of the represented lot. Reconditioned launchers or reconditioned lots shall be tested using the procedures and test methods specified above."

PAGE 12

* 4.6 Change "on a rifle, 5.56mm, M16 or M16A1" to "on an M16, M16A1 or M16A2 Rifle".

PAGE 14

Add paragraph 4.7.2.6 as shown below:

"4.7.2.6 Trigger sear and secondary sear test. Launchers shall be tested for trigger sear and secondary sear requirements (see 3.2.3.4) utilizing inspection equipment in accordance with drawing F11836899 and Cartridge, 40MM, XM387B2 (Dummy, Completely Inert). With the launcher mounted to the fixture, the barrel latch shall be depressed and the launcher barrel exercised to cock the launcher with the left hand. Parital trigger pull shall be evenly applied to the trigger by the index finger of the right hand until movement of the trigger occurs without releasing the firing pin. The trigger shall then be released. The trigger shall return to the original position under spring action after partial trigger pull. The trigger will then be pulled to cause the firing pin to fall. The launcher shall then be opened in the manner previously cited and a fired cartridge case inserted into the breech of the barrel. The hook of the fixture will be placed over the trigger and 20 lb. pressure applied to depress the trigger. The barrel will then be moved to the closed position, left hand on the hand guard, at a speed to simulate actual loading and firing of 5 to 10 rounds per 2 minutes. When the barrel is closed, the firing pin shall be retained by the secondary sear until the trigger is released and allowed to return to its forward position. When the trigger is pulled with the index finger of the right hand, the firing pin shall fall."

* 4.7.5.1 Change "to and M16 or M16A1 rifle" to "to an M16, M16A1 or M16A2 Rifle".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T04:20Z
Check the source to verify that this is the current version before use.

4.7.7.1.1.1 Delete in its entirety and substitute:

* "4.7.7.1.1.1 The launcher receiver, prior to reassembly, shall be securely held, and using a torque wrench, shall withstand a torque of 130-10 pound-inches applied to the breech insert without movement or loosening of the breech insert."

PAGE 16

* Table titled: GROUPS OF NONMATING PARTS. Group V Change "Spring, Ejector (8448307)" to "Spring, Ejector (12006355)".

PAGE 17

4.7.8.1 Change "to an M16 or M16A1 rifle" to "to an M16, M16A1 or M16A2 Rifle".

PAGE 18

6.1.1 Delete "4.7.11.7" and substitute: "4.7.8.7".

* 6.2 Change "and interchangeability and breech insert removal, etc.)" to "and interchangeability)".

The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR
Navy-OS

Preparing activity:
Army-AR

Review activity:
Navy-OS

(Project 1010-0135)

User activity:
Navy-MC

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T04:20Z
Check the source to verify that this is the current version before use.