# MILITARY SPECIFICATION
# BATTERY, SINGLE CELL, PRIMARY RESERVE

This Amendment forms a part of Military Specification MIL-M-48761(AR), dated 17 March 1978, and is approved for use by the U.S. Army Armament Research and Development Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 2

Inspection Equipment Drawings - Delete "8841278 - Firing Pin" and substitute "9275628 - Firing Pin".

PAGE 9

4.4.2.2, Terminal Plate Assy, Machined 9275568:

Delete: Minor Defect 203 in its entirety.

Add:

| | "Minor | Exam or Test | AQL | Reqm't Para | Insp Method |
|---|---|---|---|---|---|
| | 203. | Height of terminal pin above inside shoulder, improper | 0.65% | 3.2 | Gage |
| * | 205. | Height of terminal pin above outside shoulder, improper | 0.65% | 3.2 | Gage" |

PAGE 10

* 4.4.2.3, Pin, Terminal 9275569:

Delete: Minor Defect 201 in its entirety.

FSC: 1345



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:39Z
Check the source to verify that this is the current version before use.

PAGE 11

4.4.2.4, Plate, Terminal, 9275570:

Change Next Higher Assembly from "9275603" to "9375568".

Add:

| "Minor | Exam or Test | AQL | Reqm't Para | Insp Method |
|---|---|---|---|---|
| 204 | Taper not present | 1.0% | 3.2 | Visual" |

PAGE 12

4.4.2.5 Cell Assembly, 9275571, Major Defect 101 is revised as follows:

Change Major Defect 101 from "Anode lead not positioned....." to "Screen lead not positioned....."

PAGE 14

4.4.2.7, Screen Assembly, Anode 9275574. Change next higher assembly; from "9275576" to "9275572".

Add:

| "Major | Exam or Test | AQL | Reqm't Para | Insp Method |
|---|---|---|---|---|
| 104 | Length of lead from screen, improper | 0.40% | 3.2 | Gage |
| 105 | Length of lead overlap on screen, improper | 0.40% | 3.2 | Gage" |

Delete Minor Defects 201, 203, 204, and 205 in their entirety. Delete Notes 1, 2. and 3.

PAGE 15

4.4.2.8, Lead, 9275575. Under Minor Defects, delete "None defined", add:

| "Minor | Exam or Test | AQL | Reqm't Para | Insp Method |
|---|---|---|---|---|
| 201 | Lead thickness improper | 0.65% | 3.2 | Gage |
| 202 | Lead width improper | 0.65% | 3.2 | Gage" |



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:39Z
Check the source to verify that this is the current version before use.

PAGE 26

4.4.2.19, Plate Assembly, Terminal, 9275603: Delete paragraph in its entirety.

PAGE 34

4.4.6.2.1 - Delete "(Dwg. 8841278)" and substitute "(Dwg. 9275628)".

PAGE 38

Add "-A204" after project number.

NOTE: The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the previous amendment.

Custodian:
Army-AR

Preparing Activity:
Army-AR

Project No.: 1345-A188



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:39Z
Check the source to verify that this is the current version before use.