MIL-S-45428D (AR)
AMENDMENT 2
1 NOVEMBER 1982
SUPERSEDING
AMENDMENT 1
6 OCTOBER 1978

MILITARY SPECIFICATION

SQUIB, ELECTRIC, M2
PARTS FOR AND LOADING, ASSEMBLING AND PACKING

This Amendment forms a part of Military Specification MIL-S-45428D(MU), dated 7 May 1969, and is approved by the US Army Armament Research and Development Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 3

3.6 Workmanship. Add the following to end of this paragraph:

"The soldered joints shall be flushed of all residual flux by means of a cleaning solvent approved by the Contracting Officer. There shall be no chlorides present at the soldered joints when tested in accordance with 4.4.8.5.

PAGE 8

4.3.2.5 Squib assembly. In table for Major Defects add the following under the headings shown below, as they appear on Page 8:

Categories	Defects	Method of Inspection	Code No.
Major			
"105	Presence of chloride at soldered joints	See 4.3.3.9	05007"

PAGE 10

Add an additional paragraph, and number it 4.3.3.9:

"4.3.3.9 Presence of chloride at soldered joints (see dwg. 8799892 and 4.3.2.5 category 105 - major defect, Code No. 05007).

FSC 1375

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:58Z
Check the source to verify that this is the current version before use.

The sampling plan for this test shall be in accordance with MIL-STD-105 and 100 percent inspection. The lot shall be rejected if it fails to comply with this sampling plan. The test shall be performed as specified in 4.4.8.5."

PAGE 14

Add an additional paragraph, and number it 4.4.8.5:

"4.4.8.5 Chloride contamination test. CAUTION - Proper laboratory procedures and practices must always be followed. Since nitric acid and silver nitrate are corrosive to skin, the use of eye and face protection as well as rubber gloves should be mandatory. Additional safety rules of individual laboratories or operating areas should be observed."

4.4.8.5.1 Material and equipment.

a. Assorted laboratory beakers.
b. Deionized and/or distilled water.
c. ACS reagent grade isopropyl alcohol.
d. Nitric acid (70%, for trace metal analysis).
e. Silver nitrate solution (0.1N).
f. Nitric acid solution (35%). Prepare a diluted nitric acid solution by carefully adding a volume of the 70% nitric acid to an equal volume of water. For safety reasons, add the acid to the water. NOTE: The acid may be stored in a proper bottle for later use. The acid solution should be at room temperature before use.

4.4.8.5.2 Additional instructions.

a. Ensure that beakers as well as the water are free of chloride ion contamination prior to use. Laboratory apparatus should be pre-rinsed with distilled or deionized water prior to use.

b. Only deionized or distilled water shall be used.

c. Beaker and water used should be tested by adding a few drops of diluted nitric acid and then a few drops of silver nitrate solution and mix. The presence of any chlorides or other halides will cloud the solution..

4.4.8.5.3 Test procedure. Take 200 plug assemblies and rinse the bridge portion of the plug assembly in a beaker containing 100ml of rinse solution. This solution shall consist of 75% by

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:58Z
Check the source to verify that this is the current version before use.

volume of isopropyl alcohol and 25% deionized and/or distilled water. Add a few drops of diluted nitric acid and then a few drops of silver nitrate solution to the rinse solution. Mix the solution by swirling the beaker. Any milky cloudiness of the solution indicates the presence of halide (Chlorides, bromide or iodide) ions."

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1375-A250)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:58Z
Check the source to verify that this is the current version before use.