MIL-I-48110B(AR)
11 May 1982
SUPERSEDING
MIL-I-48110A(AR)
7 April 1977

MILITARY SPECIFICATION

IGNITER ASSEMBLY, ROCKET,
FOR DEMOLITION KIT, CRATERING, M180

This specification is approved for use by the US Army Armament Research and Development Command, and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 Scope. This specification covers quality assurance provisions and preparation for delivery for the igniter assembly for the Rocket Motor for Demolition Kit, Cratering, M180.

2. APPLICABLE DOCUMENTS

2.1 Government documents.

2.1.1 Specifications and standards. Unless otherwise specified (see 6.2), the following specifications and standards of the issue listed in that issue of the Department of Defense Index of Specifications and Standards (DoDISS) specified in the solicitation, form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-S-45428 - Squib, Electric, M2, Parts For and Loading, Assembling and Packing.

MIL-A-48078 - Ammunition, Standard Quality Assurance Provisions, General Specification For.

STANDARDS

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes.

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, US Army Armament Research and Development Command, Attn. DRDAR-QA, Dover, New Jersey 07801 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

FSC 1375

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:13Z
Check the source to verify that this is the current version before use.

2.1.2 Other Government documents, drawings, and publications. The following other Government documents, drawings, and publications form a part of this specification to the extent specified herein.

DRAWINGS (see 6.6)

US ARMY ARMAMENT RESEARCH AND DEVELOPMENT COMMAND

9244405 - Igniter Assembly, Rocket.
9244411 - Retainer, Nozzle Closure, Igniter.

(Copies of specifications, standards, handbooks, drawings, and publications required by manufacturers in connection with specific acquisition functions should be obtained from the contracting activity or as directed by the contracting officer.)

CODE OF FEDERAL REGULATIONS

Title 49 - Transportation, parts 100-199.

(Application for copies should be addressed to the Superintendent of Documents, Government Printing Office, Washington, D. C. 20402. Orders should specify, "49-CFR 100-199 (latest revision).")

2.1.3 Order or precedence. In the event of a conflict between the text of this specification and the references cited herein, the text of this specification shall take precedence.

3. REQUIREMENTS

3.1 Materials and parts. Materials and parts shall be in accordance with applicable drawings, specifications and standards.

3.2 Igniter assembly. The igniter assembly shall comply with all the requirements specified on Drawing (Dwg.) 9244405, all associated drawings, and with all the requirements specified in applicable specifications and standards.

3.3 Parallel splice pull test. The parallel splice shall not allow the leads to slip when subjected to a minimum static load of eight (8) pounds when tested as specified in 4.5.1.

3.4 Electrical resistance. The electrical resistance of the igniter shall be no less than 0.40 ohm nor greater than 0.66 ohm when tested as specified in 4.5.2.

3.5 Functioning.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:13Z
Check the source to verify that this is the current version before use.

3.5.1 Ignition delay time. The ignition delay time of the igniter assembly, when conditioned at minus $40^{\circ}\pm5^{\circ}$F., shall be no greater than 0.10 seconds when tested as specified in 4.5.3. Ignition delay time is defined as the elapsed time from when the current is applied to the appearance of the flash of the igniter charge.

3.6 First article inspection. This specification contains technical provisions for first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

3.7 Workmanship.

3.7.1 Plastic parts. All components shall be fabricated in a thorough, workmanlike manner and shall be free of porosity, twist, warpage, heat marks, sinks, checks, cracks, chipped edges, burrs, blisters, scratches, excess flash, and other defects which would affect their serviceability.

3.7.2 Assemblies. Igniter assemblies, components, and materials shall be free from dirt, chips, grease and other foreign matter. There shall be no cracks, scratches, dents, gouges, holes porous areas, distortion, or undesirable characteristics which would in any way detract from the useability of the product for its intended purpose. Parts and assemblies shall be free from all contaminants and damage after cleaning. All soldering shall be performed in a thorough, workmanlike manner with no evidence of burning or charring. All required marking shall be neat and sharply defined.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection and standard quality assurance provisions. Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of inspections. The inspection requirements specified herein are classified as follows:

a. First article inspection (see 4.3).

b. Quality conformance inspection (see 4.4).

4.3 First article inspection.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:13Z
Check the source to verify that this is the current version before use.

4.3.1 Submission. The contractor shall submit a first article sample as designated by the Contracting Officer for evaluation in accordance with provisions of 4.3.2. The first article sample shall consist of the following items in sample quantities as indicated below and Table I.

Part Description	Drawings	Quantity
Igniter Assembly Rocket, Prior to Loading	9244405	10
Igniter Assembly Rocket	9244405	10
Retainer, Nozzle Closure, Igniter	9244411	10
Closure, Nozzle, Igniter	9244415	10
Igniter Squib Assembly	9244416	10
Sheet, Polyethylene	9270809	10

4.3.2 Inspections to be performed. See MIL-A-48078 and Table I specified herein.

4.3.3 Rejection. See MIL-A-48078.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:13Z
Check the source to verify that this is the current version before use.

TABLE 1. First article inspection.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
	Igniter Assembly	1 OF 1	See Below
			NEXT HIGHER ASSEMBLY --

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Closure, Nozzle, Igniter (Dwg. 9244415)				
	Examination for Defects	10	-	3.2	4.4.2.1
	Retainer, Nozzle Closure, Igniter (Dwg. 9244411)				
	Examination for Defects	10	-	3.2	4.4.2.2
	Igniter Squib Assembly (Dwg. 9244416)				
	Examination for Defects	10	-	3.2	4.4.2.3
	Parallel-splice pull test	10	-	3.2	4.5.1
	Sheet, Polyethylene (Dwg. 9270809)				
	(Inspect for all dimensions specified on drawing and plastic workmanship)	10	- -	3.2, 3.7.1	Gage-Visual

NOTES:

DRDAR-QA Form 160 Jul 77

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:13Z
Check the source to verify that this is the current version before use.

TABLE 1. First article inspection. (Cont'd)

CLASSIFICATION OF DEFECTS & TESTS MIL-I-48110B(AR)

PARAGRAPH	TITLE: Igniter Assembly (Cont'd)		SHEET 2 OF 2		DRAWING NUMBER: See Below NEXT HIGHER ASSEMBLY: --
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Igniter Assembly, Rocket, prior to loading (Dwg. 9244405)				
	Examination for Defects	10	-	3.2	4.4.2.4
	Igniter Assembly, Rocket, prior to sealing Polyethylene Sheet (Dwg. 9244405)				
	Examination for Defects	10	-	3.2	4.4.2.5
	Igniter Assembly Rocket (Dwg. 9244405)				
	Examination for Defects	10	-	3.2	4.4.2.6
	Resistance test	10	-	3.5	4.5.2
	Functioning test	10	-	3.6	4.5.3
	Ignition delay time	10	-	3.6.1	4.5.3

NOTES:

DRDAR-QA Form 160 Jul 77

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:13Z
Check the source to verify that this is the current version before use.

4.4 Quality conformance inspection.

4.4.1 Inspection lot formation. Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition, each lot of igniter assemblies shall contain:

a. Parts of one lot interfix number from one manufacturer.

b. Pellets of one lot interfix number from one manufacturer.

c. Squibs of one lot interfix number from one manufacturer. (See 4.4.6 for check test for deterioration.)

4.4.1.1 Cavity identification (plastic parts). The contractor shall maintain an approved cavity identification system. Components shall be grouped and identified until all inspections have been completed.

4.4.2 Examination. See MIL-A-48078.

a. Sampling plans. Unless otherwise specified in the Classification of Defects and Tests Tables, sampling plans and procedures for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:13Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-48110B(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.1	Closure, Nozzle, Igniter		9244415
			NEXT HIGHER ASSEMBLY 9244405

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Outside diameter of flange		0.40%(a)	3.2	Gage
102	Pitch diameter of threads		0.40%(a)	3.2	Gage
103	Major diameter of threads, min.		0.40%(a)	3.2	Gage
104	Total length		0.40%(a)	3.2	Gage
105	True position of major diameter of thread with datum A		0.40%(a)	3.2	Gage
106	Plastic workmanship unsatisfactory		0.40%(a)	3.7.1	Visual
Minor					
201	Inside diameter		0.65%(a)	3.2	Gage
202	Major diameter of threads, max.		0.65%(a)	3.2	Gage
203	Depth of cavity		0.65%(a)	3.2	Gage
204	Diameter of small hole		0.65%(a)	3.2	Gage
205	Countersink missing (2 places)		0.65%(a)	3.2	Visual
206	Poor workmanship		1.00%(a)	3.7.2	Visual

NOTES: a. See 4.4.5 for alternative inspection procedure for plastic parts.

DRDAR-QA Form 160 Jul 77

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:13Z
Check the source to verify that this is the current version before use.

Quality conformance inpsection

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-48110B(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.2	Retainer, Nozzle Closure, Igniter				9244411
					NEXT HIGHER ASSEMBLY
					9244401
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of 0 ring groove		0.40%(a)	3.2	Gage
102	Width of 0 ring groove		0.40%(a)	3.2	Gage
103	Pitch diameter (P.D) of threads		0.40%(a)	3.2	Gage
104	Runout of 0 ring groove with datum A		0.40%(a)	3.2	Gage
105	Minor diameter of threads, max.		0.40%(a)	3.2	Gage
106	15° chamfer incorrect		0.40%(a)	3.2	Gage
107	Outside diameter		0.40%(a)	3.2	Gage
108	Runout of P.D of threads with datum A		0.40%(a)	3.2	Gage
109	Plastic workmanship unsatisfactory		0.40%(a)	3.7.1	Visual
Minor					
201	Length of web		0.65%(a)	3.2	Gage
202	Thickness of web		0.65%(a)	3.2	Gage
203	Minor diameter of threads, min.		0.65%(a)	3.2	Gage
204	Poor workmanship		1.00%(a)	3.7.2	Visual

NOTES: a. See 4.4.5 for alternative inspection procedure for plastic parts.

DRDAR-QA Form 160 Jul 77

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:13Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-48110B(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.3	Igniter Squib Assembly				9244416
					NEXT HIGHER ASSEMBLY 9244405
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Igniter lead wires not shorted		100%	3.2	Visual
Major					
101	Parallel splice pull test		100%	3.3	4.5.1
102	Wiring improper		0.40%	3.2	Visual
103	Incorrect trim at M2 squib leads and wire leads-prior to crimping		0.40%	3.2	Visual
104	M2 squibs not connected in parallel		0.40%	3.2	Visual
105	Base wire exposed at parallel splice		0.40%	3.2	Visual
106	Broken or damaged wire or insulation		0.40%	3.2	Visual
107	Crimp missing or unsatisfactory		0.40%	3.2	Visual
Minor					
201	Length from edge of parallel splice to twisted end		0.65%	3.2	Gage
202	Poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77

Source: https://assist.dla.mil - Downloaded: 2026-10-22T19:13Z
Check the source to verify that this is the current version before use.

Quality conformance inspection

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.4	Igniter Assembly, Rocket (prior to loading)				9244405
					NEXT HIGHER ASSEMBLY --
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Igniter Squib Assembly leads not shorted		100%	3.2	Visual
Major					
101	Squib damaged, improperly connected or positioned		0.40%	3.2	Visual
102	Seal at nozzle closure hole at thread end missing or inadequate		0.40%	3.2	Visual
103	Foreign matter on interior surface		0.40%	3.2	Visual
104	Nozzle closure or polyethylene sheet damaged		0.40%	3.2	Visual
Minor					
201	Poor workmanship (excl. 103 and 104)		1.0%	3.7.2	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:13Z
Check the source to verify that this is the current version before use.

Quality conformance inspection

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-48110B(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.5	Igniter Assembly, Rocket (prior to sealing sheet)				9244405
					NEXT HIGHER ASSEMBLY --
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Igniter Squib Assembly leads not shorted		100%	3.2	Visual
Major					
101	Weight of charge		0.40%	3.2	Balance
102	Insulation on lead wire missing or damaged		0.40%	3.2	Visual
103	Charge bag damaged		0.40%	3.2	Visual
104	Mating surfaces of polyethylene sheet and nozzle closure not clean		0.40%	3.2	Visual
Minor					
201	Poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:13Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-48110B(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.6	Igniter Assembly, Rocket				9244405
					NEXT HIGHER ASSEMBLY --
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Igniter Squib Assembly leads not shorted		100%	3.2	Visual
Major					
101	Resistance test		100%	3.4	4.5.2
102	Seal improper		100%	3.2	Visual
103	Functioning-Ignition Delay Time at-40°F		0.40%	3.5.1	4.5.3
104	Sheet to nozzle closure seal missing, peeling, loose or inadequate		0.40%	3.2	Visual
105	Threads damaged		0.40%	3.2	Visual
106	Polyethylene sheet damaged (cracked, punctured, torn, etc. so that sealing is inadequate or lost)		0.40%	3.2	Visual
107	Twisted wires not taped		0.40%	3.2	Visual
Minor				3.7.1	
201	Poor workmanship		1.00%	3.7.2	Visual

NOTES:

DRDAR-QA Form 160 Jul 77

Source: https://assist.dla.mil - Downloaded: 2026-10-22T19:13Z
Check the source to verify that this is the current version before use.

4.4.3 Testing. Testing is described in the First article and Quality conformance inspection tables.

4.4.4 Inspection Equipment. The inspection equipment required to perform the inspections and tests prescribed in this specification is identified in the "Paragraph Reference/Inspection Method" column in the tables starting with paragraph 4.4.2.1, and the test method paragraph (See 4.5). The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and 6.3 herein.

4.4.5 Dimensional Control of molded parts. In place of the normal sampling associated with the Classification of Defects, and with the approval of the Contracting Officer, and after a curing time for the parts has been approved (See Note), a sample of three (3) parts (as molded) from each cavity shall be dimensionally inspected to qualify a new or reworked cavity for use in production or as a control of each cavity during production.

The inspection of the parts shall be performed only when the curing time for the parts has been reached. The inspection for control of each cavity during production shall be performed on the above quantities from each cavity after production of each 5000 parts or at the end of each shift, providing the number of parts produced during that shift is less than 5000 parts. Of the three (3) samples, one (1) sample shall be the last part produced. Parts that fail to comply with dimensional requirements after dimensional stability has been attained shall be classed defective.

If any defective parts are found during qualification of the cavity, the cavity producing the defective part shall not be used in production. If any defective parts are found when inspection is performed for control of the cavity, the cavity producing the defective part shall be removed from production. Further, that portion of production since the last control check shall be returned to the contractor for corrective action.

All cavities formerly removed from production because of some fault may, after reworking, be returned to production providing they pass the qualification test as above. The contractor may request a change of inspection frequency providing he presents objective evidence to substantiate the request to the Contracting Officer.

NOTE: To establish a curing time, dimensionally check ten (10) parts from each cavity at periodic intervals (e.g., every 30 min, 60 min, etc.), until dimensional stability is attained. The curing time will be from the time the part comes out of the mold until dimensional stability is attained. The inspection data used in determining the curing time shall be sent to: ARRADCOM, Dover, NJ 07801, ATTN: DRDAR-QAT-M. If there is a change in material, cycle time, or if a cavity is reworked, or a new cavity is used, a new curing time shall be established and approved.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:13Z
Check the source to verify that this is the current version before use.

4.4.6 Check test for deterioration of M2 Squibs (See MIL-S-45428). If the total time between original acceptance of any lot and the assembly of that lot into the Igniter Assemblies exceeds two years, or if the squibs have been subjected to adverse conditions, however brief, at any time since previous test, the squib lot shall be subjected to and must satisfactorily pass, the check test for deterioration specified in MIL-S-45428 immediately before the squib lot is assembled into the Igniter Assemblies. This test shall be performed by the contractor on squibs selected by the Government Inspector at the facility assembling the squibs into the Igniter Assemblies. (See 6.7)

4.5 Methods of inspection.

4.5.1 Parallel splice pull test. The lead wires from the opposite ends of each parallel splice shall be attached to the applicable test fixture. The required force shall be applied to each splice in a smooth gradual manner. Observation shall be made for evidence of slippage of the lead wires in the parallel splice. Any assembly which fails to comply with the requirement shall be classed defective and removed from the lot.

NOTE: When performing this test, do not pull on holder assembly of squibs.

4.5.2 Electrical resistance test.

WARNING: This test is conducted on assemblies containing explosive components and shall be performed behind a suitable barricade.

The igniter assemblies selected for this test shall have the short removed from the lead wires. The Igniter Assembly shall be connected to the applicable test equipment which shall limit the current to 10 milliamperes (.010 amps) maximum. Any unit exhibiting a resistance outside the permitted range specified shall be classed defective. The lead wires shall be shorted immediately after this test.

4.5.3 Functioning test.

WARNING: This test is conducted on assemblies containing explosive components and shall be performed behind a suitable barricade.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:13Z
Check the source to verify that this is the current version before use.

The sample igniter assemblies selected for this test shall be conditioned in a conditioning chamber at minus 40 degrees F+5°F for a minimum of sixteen (16) hours. The Igniter Assembly shall be removed from the chamber, the short shall be removed from the lead wires, and the assembly connected to the applicable test equipment. The Igniter Assembly shall be fired within 30 seconds using a current of 1.1 + .2 amperes. The ignition delay time shall be observed and recorded. Any unit which fails to function or which exceeds the ignition delay time specified shall be classed defective.

5. PACKAGING

5.1 Preservation - packaging.

5.1.1 Level B. The igniter assembly and retainer (Dwg. 9244411) shall be preserved and packaged in accordance with the Code of Federal Regulations, Title 49, Parts 100-199.

5.2 Packing.

5.2.1 Level B. The igniter assembly and retainer (Dwg. 9244411). preserved and packaged as specified in 5.1.1, shall be packed in accordance with the Code of Federal Regulations, Title 49, Parts 100-199. Packing shall be in a manner that will assure safe delivery from the manufacturer's plant to the first receiving activity.

5.3 Marking. Marking shall be in accordance with the Code of Federal Regulations, Title 49, Parts 100-199.

5.4 Shipping. When assemblies from more than one lot are shipped at one time, each lot shall be kept separate, and the division between lots clearly indicated to prevent mixing of the lots in transit.

6. NOTES

6.1 Intended use. The components covered by this specification are intended for use in the Rocket Motor for Demolition Kit, Cratering: M180.

6.2 Ordering data. See MIL-A-48078.

6.3 Submission of inspection equipment designs for approval. (See MIL-A-48078). Equipment designs shall be submitted as required to: Commander, U.S. Army Armament Research and Development Command, ATTN: DRDAR-QAT-I, Dover, New Jersey 07801. Request letter of submittal should state contractor, contract number, specification number, item nomenclature, and classification of defects and test paragraph number.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:13Z
Check the source to verify that this is the current version before use.

6.4 Submission of test data. When required by incorporation of DD Form 1423 into the contract, all test data required in Section 4 of this specification shall be submitted in accordance with Data Item Description DI-R-1724. In addition to the normal distribution of records, one copy of all test data shall be forwarded to the following:

Commander
US Army Armament Research and Development Command
ATTN: DRDAR-QAT-M
Dover, New Jersey 07801

6.5 Data cards. (See MIL-A-48078). Distribution of data cards shall include the address specified in 6.4.

6.6 Drawings. Drawings listed in Section 2 of this specification under the heading US Army Armament Research and Development Command (ARRADCOM) may also include drawings prepared by, and identified as, Edgewood Arsenal, Frankford Arsenal, Rock Island Arsenal or Picatinny Arsenal drawings. Technical data originally prepared by these activities are now under the cognizance of ARRADCOM.

6.7 Cost of check test. The contracting officer will arrange for the contractor to be reimbursed for the expense incurred in the performance of the check test for deterioration of the M2 Squibs. The tests shall be conducted at Government expense without cost to the contractor who loaded the squibs or to the contractor assembling the squibs into the igniter assemblies, and shall not constitute a basis for rejection against either contractor except where deterioration has occurred as a direct result of carelessness in handling, storage, etc., permitted while the squib lot was under the jurisdiction of either contractor.

6.8 Check test for possible deterioration. The following test is designed to prevent igniter assemblies that have deteriorated from being assembled into major ammunition items. The test shall be performed on igniter assemblies from each lot which have been stored under normal conditions for more than two (2) years, or under adverse conditions for any period of time. If the specification for the ammunition item into which igniters are assembled does not require that the check test be performed, the Contracting Officer should insert in the contract a provision for the performance of the check test. The Contracting Officer will arrange for the contractor to be reimbursed for expense incurred in his performance of the check tests for possible deterioration. Igniter assemblies shall be selected from each lot and tested as specified in 4.5.3.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:13Z
Check the source to verify that this is the current version before use.

6.8.1 Functioning test. Igniter assemblies shall be selected for this test in accordance with MIL-STD-105, Inspection Level II. using an AQL of 0.65%. Test equipment shall be as specified in 4.4.4 and 4.5.3.

6.9 Changes from previous issue. Asterisks are not used in this revision to identify changes with respect to the previous issue, due to the extensiveness of the changes.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1375-A231)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:13Z
Check the source to verify that this is the current version before use.