MIL-C-707D
AMENDMENT-2
9 March 1977
SUPERSEDING
Amendment-1
10 January 1974

MILITARY SPECIFICATION

CASE, SLEEPING BAG, M-1945, WATER REPELLENT

This amendment forms a part of Military Specification MIL-C-707D, dated 27 January 1971, and is approved for use by all Departments and Agencies of the Department of Defense.

PAGE 1

2.1, under Federal Specifications: Delete title of PPP-B-636 and substitute "Boxes, Shipping, Fiberboard".

Under Military Specifications: Add "MIL-E-20652/3 - Eyelets, Metallic, Telescopic Type" and "MIL-C-43482 - Cloth, Boplin, Cotton and Polyester (Water Repellent)".

PAGE 2

2.1, under Military Standards: Delete title of MIL-STD-147 and substitute "Palletized Unit Loads for 40" x 48" Pallets".

2.2, line 12: Delete "Room 202, Union Station, 516 W. Jackson Blvd." and substitute "Room 1106, 222 South Riverside Plaza".

PAGE 3

* 3.3.1, line 1: Delete "Cloth, wind resistant oxford, cotton" and substitute "Base fabric".

Line 3, after "MIL-C-484": Add "or class 1 of MIL-C-43482".

3.3.2 and 3.3.2.1: Delete in entirety and substitute:

"3.3.2 Eyelets and washers. The eyelets and washers shall conform to dash numbers ABT313 and ABT314 respectively of MIL-E-20652/3."

FSC 8465

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T11:19Z
Check the source to verify that this is the current version before use.

PAGE 4

* 3.4.1 After line 7: Add "For overedge stitching - Type 503 or 504 or 602, 8 to 12 stitches per inch with 3/16 inch minimum gage."

3.4.1.1.1 and 3.4.1.2. Delete in entirety and substitute:

"3.4.1.1.1 Repairs of type 301 stitching. Repairs of type 301 stitching shall be as follows:

a. When thread breaks or bobbin run-outs occur during sewing, the stitching shall be repaired by restarting the stitching a minimum of one inch back of the end of the stitching. 1/

b. Thread breaks, or two or more consecutive skipped stitches or run-offs noted during inspection or the item (in-process or end item) shall be repaired by overstitching. The stitching shall start a minimum of one inch in back of the defective area, continue over the defective area and continue a minimum of one inch beyond the defective area onto the existing stitching. Loose or excessively tight stitching shall be repaired by removing the defective stitching, without damaging the materials and restitching in the required manner. 1/

1/ When making the above repairs, the ends of the stitching are not required to be backstitched.

* 3.4.1.2 Type 401, 503, 504 or 602 stitching. Thread tension shall be maintained so that there will be no loose stitching. All repairs shall be in accordance with 3.4.1.1.1a and 3.4.1.1.1b. For the 401 stitching, the looper portion of the stitching shall be on the inside of the case."

PAGE 5

Add the following new paragraphs:

"3.4.8 Repairs. Except as otherwise specified herein, repairs are not allowed to be made to the case.

3.4.9 Replacement of defective components. During the spreading, cutting and manufacturing process, components having material defects or damages that are classified as defects in 4.3.3.1 shall be removed from production and replaced with non-defective and properly matched components."

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T11:19Z
Check the source to verify that this is the current version before use.

PAGE 6

4.1.1 and 4.3.1.1: Delete in entirety.

PAGE 10

* 4.3.1.1, opposite "Stitching indicated by "Z" on drawing": Delete "Chain portion" and substitute "Looper portion".

PAGE 12

4.3.4.1, line 5: Delete "sealed" and substitute "closed".

Under "Defect", line 3: Add "or not as specified".
Line 7: Add "or improper taping".

PAGE 13

5.2.1, line 3: Delete "taped".

Delete last sentence and substitute: "Each shipping container shall be closed in accordance with method III, waterproofed in accordance with method V, and reinforced as specified in the appendix of PPP-B-636".

5.2.2, line 4: Delete "taped".

5.2.2.1, line 3, after "with": Insert "method III as specified in".

PAGE 14

5.3, line 1: Delete "Unless otherwise" and substitute "When".

6.2 (f): Delete "not".

NOTE: The margins of this amendment are marked with an asterisk to indicate where changes (additions, modifications, corrections, deletions) from the previous issue were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and suppliers are cautioned to evaluate the requirements of this specification based on the entire content irrespective of the marginal notations and relationship to the last previous issue.

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T11:19Z
Check the source to verify that this is the current version before use.

Custodians:

Army - GL
Navy - MC
Air Force - 99

Review activities:

Army - MD
Navy - SA
DSC - CT

Preparing activity:

Army - GL

Project No. 8465-0748

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T11:19Z
Check the source to verify that this is the current version before use.