**NOTICE OF INACTIVATION**

**NOT MEASUREMENT SENSITIVE**

**TOP-10-2-060**
**NOTICE 1**
**03-Apr-2026**

# TEST OPERATIONS PROCEDURE

## Fuel Thickeners, Flamethrower

TOP-10-2-060, dated 19-May-1969, is inactive for new design and is no longer used, except for replacement purposes.

**Custodians:**
Army - TE

**Preparing Activity:**
Army - TE

**NOTE:** The activities above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at https://assist.dla.mil

**AMSC** N/A

**AREA ENVR**

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T14:54Z
Check the source to verify that this is the current version before use.