MIL-W-50259 (AR)
AMENDMENT 1
16 April 1982

MILITARY SPECIFICATION

WARHEAD SECTION, 762MM ROCKET,
PRACTICE, M38
LOADING, ASSEMBLING AND PACKING

This amendment forms a part of Military Specification MIL-W-50259 (MU), dated 28 February 1969, and is approved for use by the US Army Armament Research and Development Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

Add the following preamble underneath the title:

"This specification is approved for use by the US Army Armament Research and Development Command and is available for use by all Departments and Agencies of the Department of Defense."

2.1 Specifications, Military: Add "MIL-P-116" as follows:

"MIL-P-116 - Preservation, Method of."

PAGE 3

Add new paragraph 3.6 as follows:

"Heat-sealed Seam Test. - The heat-sealed seam may evidence partial separation within the first two (2) minutes of the test. No additional separation permitted in the heat-sealed area during the final three (3) minutes of the test. The test shall be performed as specified in 4.4.1."

4.3.2.3: Delete Major defect 101 and substitute the following:

"Major	AQL 1.00 Percent		
101.	Container for fuze missing or damaged	Visual	03001

FSC 1340

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:18Z
Check the source to verify that this is the current version before use.

102.	Nose strap missing	Visual	03007
103.	Bolts missing	Visual	03008
104.	Desiccant bags missing or insecure	Visual	03009
105.	Barrier bag assembly torn or perforated	Visual	03010
106.	Humidity indicator missing	Visual	03011."

PAGE 7

4.3.2.4: Delete Major and Minor defects and substitute the following:

"Major	AQL 0.40 Percent		
101.	Quicklock missing	Visual	04006
102.	Hardware missing or damaged	Visual	04007
Minor	AQL 2.50 Percent		
201.	Wood damaged or loose	Visual	04001
202.	Side, end or top improperly	Visual	04002
203.	Socket head screw key	Visual	04003
204.	Marking misleading or unidentifiable	Visual	04004
205.	Evidence of poor workmanship (See 3.3)."	Visual	04005

4.3.3: Delete in its entirety and substitute the following:

"4.3.3 Testing.

4.3.3.1 Heat-sealed Seam Test (See 3.6 and Dwg. 8824941) Major Defect, Code No. 05001. - Sampling for this test shall be one coupon approximately 6" x 12" of barrier bag material, heat-sealed at the beginning of each lot and one coupon heat-sealed at the end of each lot. If the

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:18Z
Check the source to verify that this is the current version before use.

heat-sealed sample at the beginning of the lot fails to meet the heat sealed seam test requirement, production shall not begin until a satisfactory heat-seal has been accomplished. If the heat-sealed seam test fails on sample heat-sealed at the end of the lot, the entire lot shall be rejected and the items in that lot shall be re-heat-sealed, including sample coupon. If second (2nd) heat-sealed seam test fails, entire lot shall be rejected. The test shall be performed as specified in 4.4.1."

4.4: Delete in its entirety and substitute the following:

"4.4 Test methods and procedures.

4.4.1 Heat-sealed Seam Test. - The heat-sealed seam test shall be performed as specified in MIL-P-116, Section 4.4.4. Equipment shall be as specified on the Equipment List."

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1340-A623)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:18Z
Check the source to verify that this is the current version before use.