QUALIFICATIONS CERTIFIED
EVERY TWO YEARS

QPL-25027-17
7 FEBRUARY 2000
SUPERSEDING
QPL-25027-16
10 June 1998

QUALIFIED PRODUCTS LIST

OF

PRODUCTS QUALIFIED UNDER MILITARY SPECIFICATION

MIL-N-25027

NUT, SELF-LOCKING, 250 DEG. F, 450 DEG. F, AND 800 DEG.F

This list has been prepared for use by or for the Government in the acquisition of products covered by the subject specification and such listing of a product is not intended to and does not connote endorsement of the product by the Department of Defense. All products listed herein have been qualified under the requirements for the product as specified in the latest effective issue of the applicable specification. This list is subject to change without notice; revision or amendment of this list will be issued as necessary. The listing of a product does not release the supplier from compliance with the specification requirements.

Changes from previous issue. The margins of this specification are marked with Vertical lines to indicate where changes (additions) from the previous issue were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous issue.

THE ACTIVITY RESPONSIBLE FOR THIS QUALIFIED PRODUCTS LIST IS THE DEFENSE SUPPLY CENTER PHILADELPHIA (CODE: DISC-ILEA), 700 ROBBINS AVENUE, PHILADELPHIA, PA 19111-5096.

AMSC N/A FSC 5310

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS14144 NUT, SELF-LOCKING, LIGHTWEIGHT, CASTELLATED, 450 DEG F.			
MS14144L3	RME9868-3	NADC Report No.	ESNA
MS14144L4	RME9868-4	305Q7051 of	Division of Harvard Industries
MS14144L5	RME9868-5	18 Jun 1979*	
MS14144L6	RME9868-6		
MS14144L7	RME9868-7	*MUST BE MANUFACTURED	
MS14144L8	RME9868-8	AFTER 10 MAY 94	
MS14144L9	RME9868-9	DISC-E-94130 LTR	
MS14144L10	RME9868-10		
MS14144L12	RME9868-12		
MS14144L14	RME9868-14		
MS14144L16	RME9868-16		
MS14144L18	RME9868-18		
Note: "RM" designates Molybdenum Disulfide Lubricant Coating.			
MS14144-4	HC54631X4	NAWCADWAR	Kaynar Technologies, Inc.
MS14144L4	HC54631-4	Report No.	Kaynar Division
MS14144-5	HC54631X5	435Q9622 of	800 S. State College Blvd.
MS14144-L5	HC54631-5	1 Jul 1996	Fullerton, CA 92631
			Plant: Same address
MS14144-3	HC54631X3	NAWCAD	
MS14144L3	HC54631-3	Report No.	
MS14144-6	HC54631X6	435Q9811 of	
MS14144-L6	HC54631-6	13 MAY 1998	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS14144-3	PHCR-353	NADC Report	Simmonds Mecaero Fasteners, Inc
MS14144-4	PHCR-354	601Q8414 of	1734 Sequoia Avenue
MS14144-5	PHCR-355	26 Sep 1984	Orange, CA 92668
MS14144-6	PHCR-356		
MS14144-7	PHCR-357		
MS14144-8	PHCR-3S8		Plant:
MS14144-9	PHCR-359		Simmonds
MS14144-10	PHCR-3510		Usine De Champaissant
MS14144-12	PHCR-3512		72110 Saint-Cosme En Vairais
			France
MS14144L3	PHCR-353M		
MS14144L4	PHCR-354M		
MS14144L5	PHCR-355M		
MS14144L6	PHCR-356M		
MS14144L7	PHCR-357M		
MS14144L8	PHCR-358M		
MS14144L9	PHCR-359M		
MS14144L10	PHCR-3510M		
MS14144L12	PHCR-3512M		

Note: 1. Manufacturing process: Cold formed
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS14144-4	73781-428	NADC Report	SPS Technologies
MS14144L4	73781M-428	601Q8506 of	Highland Avenue
		17 Jun 1985	Jenkintown, PA 19046
			Plant: Same address

MS14144L14	73781M-1414	NAWC Report 601Q9210 of 2 Sep 1992

Note: 1. Manufacturing process: Forged
2. Lubricant: Everlube 620C per MIL-L-46010 Type I

MS14144L4	RME9868-4	Report No.
MS14144L14	RME9868-14	435Q9505 of
		31 Mar 1995

Note: "RM" designates Molybedenum Disulfide Lubricant Coating.

MS14144L20	73781M-2012	NAWCADWAR
	RME9868-20	Report No.
		435Q9601 of
		11 Jan 1996

Notes: 1. Manufacturing Process: Forged
2. Lubricant: Everlube 620C per MIL-L-46010, Type I

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS14144L8	73781M-820 RME9868-8	NAWCADWAR Letter 4955 Ser 435200R08/006030	
MS14144L16	73781M-1612 RME8968-16	of 30 Jan 1996	
MS14144L18	73781M-1812 RME9868-18		
MS14144-20	78781M-2012 RME9868-20		

MS14144L7	73781M-720 RME9868-7	NAWCADWAR Report No. 435Q9618 of	
MS14144L10	73781M-1018 RME9868-10	16 Apr 1996	

Notes: (1) Manufacturing Process: Forged
(2) Lubricant: Everlube 620C per MIL-L-46010, Type I

MS14144L12	73781M-1216 RME9868-12	NAWCADWAR Report No. 435Q9617 of 12 Apr 1996	

Notes: (1) Manufacturing Process: Forged
(2) Lubricant: Everlube 620C per MIL-L-46010, Type I

MS141414L6	73781M-624 RME9868-6	NAWCADWAR Report No. 435Q9620 of 26 Apr 1996	

Notes: (1) Manufacturing Process: Forged
(2) Lubricant: Everlube 620C per MIL-L-46010, Type I

MS14144L9	73781M-918 RME9868-9	NAWCADWAR Report No. 435Q9624 of 25 Jul 1996	

Notes: 1. Manufacturing Process: Forged
2. Lubricant: Everlube 620C per MIL-L-46010, Type I

MS14144L5	73781M-524 RMC9868-5	NAWCAD Report No.	SPS Technologies Aerospace Products Div.
MS14144-18	73781-1812 E9868-18	435Q9812 of 19 MAY 1998	Highland Avenue Jenkintown, PA 19046 Plant: Same address

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS14145 NUT, SELF-LOCKING, LIGHTWEIGHT, THIN, CASTELLATED, 450 DEG F

MS14145L3	RMTE9868-3	NADC Report No.	ESNA
MS14145L4	RMTE9868-4	305Q79051 of	Division of Harvard Industries
MS14145L5	RMTE9868-5	18 June 1979*	
MS14145L6	RMTE9868-6		
MS14145L7	RMTE9868-7		
MS14145L8	RMTE9868-8		
MS14145L9	RMTE9868-9		
MS1414SL10	RMTE9868-10		
MS14145L12	RMTE9868-12		
MS14145L14	RMTE9868-14		
MS14145L16	RMTE9868-16		
MS14145L18	RMTE9868-18		
MS14145-3	TE9868-3		
MS14145-4	TE9868-4		
MS14145-5	TE9868-5		
MS14145-6	TE9868-6		
MS14145-7	TE9868-7	*MUST BE MANUFACTURED	
MS14145-8	TE9868-8	AFTER 10 MAY 1994	
MS14145-9	TE9868-9	DISC-E-94130 LTR	

Note: "RM" designates Molybdenum Disulfide Lubricant Coating.

MS14145-4	HC54632X4	NAWCADWAR	Kaynar Technologies, Inc.
MS14145L4	HC54632-4	Report No.	Kaynar Division
MS14145-5	HC54632X5	435Q9622 of	800 S. State College Blvd.
MS14145-L5	HC54632-5	1 Jul 1996	Fullerton, CA 92631
			Plant: Same address

MS14145-3	HC54632X3	NAWCAD
MS14145L3	HC54632-3	Report No.
MS14145-6	HC54632X6	435Q9811 of
MS14145-L6	HC54632-6	13 MAY 1998

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS14145-3	THCR-3S3	NADC Report	Simmonds Mecaero
MS14145-4	THCR-354	601Q8415 of	Fasteners, Inc.
MS14145-5	THCR-355	24 Sep 1984	1734 Sequoia Avenue
MS14145-6	THCR-356		Orange, CA 92668
MS14145-7	THCR-357		
MS14145-8	THCR-358		Plant:
MS14145-9	THCR-359		Simmonds
MS14145-10	THCR-3510		Usine De Champaissant
MS14145-12	THCR-3512		72110 Saint-Cosme En Vairais
			France
MS14145L3	THCR-353M		
MS14145L4	THCR-354M		
MS14145L5	THCR-355M		
MS14145L6	THCR-356M		
MS14145L7	THCR-357M		
MS14145L8	THCR-358M		
MS14145L9	THCR-359M		
MS14145L10	THCR-3510M		
MS14145L12	THCR-3512M		

Note: 1. Manufacturing process: Cold formed
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS14145L14	THCR-3514M	NADC Report 601Q8516 of 12 Nov 1985	

Note: 1. Manufacturing process: Machined
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS14145-14	THCR-3514	NADC Report 601Q8606 of 12 May 1986	

Note: 1. Manufacturing process: Cold forging
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS14145L18	73783M-1812	Report No. 601Q8804 of 20 May 1988	SPS Technologies Highland Ave. Jenkintown, PA 19046
MS14145L16	73783M-1612	Report No. 601Q8806 of 11 Oct 1988	Plant: Same address

Note: Manufacturing process: Forged

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS14145-20	73783-2012	NAWD Report 601Q9417 of 7 Dec 94

Note: 1. Manufcturing Process: Forged
2. Lubricant: Carbowax (soluble lubricant)

MS14145-4	73783M-820	NADC Report No. 601Q8905 of 28 April 1989
MS14145L8	73783A-428	

MS14145-4	TE9868-4	Report No. 435Q9505 of 31 Mar 1995
MS14145L8	RMTE9868-8	
MS14145L16	RMTE9868-16	
MS14145L18	RMTE9868-18	

Note: "RM" designates Modybedenum Disulfide Lubricant Coating

---

MS14145L20	73783M-2012 RMTE9868-20	NAWCADWAR Report No. 435Q9601 of 11 Jan 1996

Notes: 1. Manufacturing Process: Forged
2. Lubricant: Everlube 620C per MIL-L-46010, Type I

MS14145L7	78783M-720 RMTE9868-7	NAWCADWAR Report No. 435Q9618 of 16 Apr 1996
MS14145L10	73783M-1018 RMTE9868-10	

Notes: (1) Manufacturing Process: Forged
(2) Lubricant: Everlube 620C per MIL-L-46010, Type I

MS14145L4	73783M-428 RMTE9868-4	NAWCADWAR Report No. 435Q9617 of 12 Apr 1996

Notes: (1) Manufacturing Process: Forged
(2) Lubricant: Everlube 620C per MIL-L-46010, Type I

MS14145L9	73783M-918 RMTE9868-9	NAWCADWAR Report No. 435Q9624 of 25 Jul 1996

Notes: 1. Manufacturing Process: Forged
2. Lubricant: Everlube 620C per MIL-L-46010, Type I

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS14145-18	73783A-1812 TE9868-18	NAWCAD Report No. 435Q9812 of 19 MAY 1998	SPS Technologies Aerospace Products Div. Highland Avenue Jenkintown, PA 19046 Plant: Same address

---

MS14146 NUT, SELF-LOCKING, CASTELLATED, HEXAGON, C-BORED, CAPTIVE WASHER, 450 DEG F

MS14146-3 MS14146-4 MS14146-5 MS14146-6 MS14146-7 MS14146-8	E10361-3 E10361-4 E10361-5 E10361-6 E10361-7 E10361-8	NADC Report No. 305Q81066 of 15 Oct 1981 * *MUST BE MANUFACTURED AFTER 10 MAY 94 DISC-E-94130 LTR	ESNA Division of Harvard Industries

Note: Manufacturing process: Forged

MS14146-4	CR-5952-4	NADC Report No. 601Q8609 of 8 Aug 1986	Simmonds Mecaero Fasteners, Inc. 1734 Sequoia Avenue Orange, CA 92668 Plant: Simmonds Usine De Champaissant 72110 Saint-Cosme En Vairais France

Note: 1. Manufacturing process: Cold stamping
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specia1ity). The contractor should include these provisions in every subcontract and purchase order.

MS14146-5	83352-525 E10361-5	NAWCADWAR Report No. 435Q9624 of 25 Jul 1996	SPS Technologies Highland Avenue Jenkintown, PA 19046

Notes: 1. Manufacturing Process: Forged
2. Lubricant: Everlube 620C per MIL-L-46010, Type I

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS14200 NUT, FLOATING, SELF-LOCKING, ATTACHED RETENTION ELEMENT (A.R.E.), 450 DEG F, STEEL, 125 KSI Ftu, REPLACEABLE NUT ELEMENT

MS14200-04	FF 6010(L)-4.	NADC Report	Huck International, Inc.
MS14200-06	FF 6010(L)-(6)	601Q8607 of	Deutsch Operations
MS14200-08	FF 6010(L)-(8)	9 Jun 1986	3969 Paramount Blvd.
MS14200-3	FF 6010(L)-(10)		Lakewood, CA 90712-4193
MS14200-4	FF 6010(L)-(12)		
			Plant: Same address

Note: Lubricant: QPL-8937.

MS14210 NUT PLATE ASSEMBLY, SELF LOCKING, 125 KSI Ftu; CRES (A-286) OR CARBON STEEL

MS14210-04	GFP 6010(L)-4.	NADC Report	Huck International, Inc.
MS14210-06	GFP 6010(L)-(6)	601Q8607 of	Deutsch Operations
MS14210-08	GFP 6010(L)-(8)	9 Jun 1986	3969 Paramount Blvd.
MS14210-3	GFP 6010(L)-(10)		Lakewood, CA 90712-4193
MS14210-4	GFP 6010(L)-(12)		
			Plant: Same address

N0TE: Lubricant: QPL-8937.

MS14213 NUT, ELEMENT, REPLACEABLE ATTACHED RETENTION ELEMENT (A.R.E), 450 DEG F CRES (A-286), 125 KSI Ftu

---

MS14213-04	DNCD 6050L4	NADC Report	Huck International, Inc.
MS14213-06	DNCD 6050L6	601Q8607 of	Deutsch Operations
MS14213-08	DNCD 6050L8	9 Jun 1986	3969 Paramount Blvd.
MS14213-3	DNCD 6050L10		Lakewood, CA 90712-4193
MS14213-4	DNCD 6050L12		
			Plant: Same address

Note: 1. Lubricant: QPL-8937.
2. The MS14213L4 nut elements can be produced by SPS Technologies or Republic Fastener Manufacturi Corporation for Deutsch Fastener Corporation.

MS14214 NUT ELEMENT, ATTACHED RETENTION ELEMENT (A.R.E.), 450 DEG F, STEEL (AISI 1050 OR 4130), 125 KSI Ftu

---

MS14214-04	DND 6050L4	NADC Report	Huck International, Inc.
MS14214-06	DND 6050L6	601QB607 of	Deutsch Operations
MS14214-08	DND 6050L8	9 Jun 1986	3969 Paramount Blvd.
MS14214-3	DND 6050L10		Lakewood, CA 90712-4193
MS14214-4	DND 6050L12		
			Plant: Same address

Note: 1. Lubricant: QPL-8937.
2. The MS14213L4 nut elements can be produced by SPS Technologies or Republic Fastener Manufacturi Corporation for Deutsch Fastener Corporation.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS14222 NUT, SELF-LOCKING, 450 DEG F, HEXAGON, REDUCED HEAD HEIGHT, RING BASE, CRES

MS14222-04	BH 14222-04	Report No.	Bristol Industries
MS14222-06	BH 14222-06	601Q8719 of	630 E. Lambert Road
MS14222-08	BH 14222-08	13 Nov 19B7	P.0. Box 630
MS14222-3	BH 14222-3		Brea, CA 92621
MS14222-4	BH 14222-4		
MS14222-5	BH 14222-5		Plant: Same address
MS14222-6	BH 14222-6		

Note: Manufacturing process: Forged

MS14222-08	RH30C08D	Report No.	Republic Fastener Mfg. Corp.
MS14222-3	RH30C3D	601Q8714 of	1300 Rancho Conejo Blvd.
MS14222-4	RH30C4D	24 Aug 1987	Newbury Park, CA 91320
MS14222-5	RH30C5D		
MS14222-6	RH30C6D		Plant: Same address

MS14222-04	RH30C04D	Report No.
MS14222-06	RH30C06D	601Q9019
		of 22 Aug 1990

Note: Manufacturing process. Forged

MS14493 NUT, SELF-LOCKING, CHANNEL, FLOATING, CARBON STEEL, 125 KSI Ftu

MS14493A-3	BGC14493N-3	Report No.	Bristol Industries
MS14493AL-3	BGC14493NL3	601Q8723 of	P.0. Box 630
MS14493C-3	BGC14493C-3	11 Dec 1987	East Lambert Road
MS14493CL-3	BGC14493CL3		Brea, CA 92621
			Plant: Same address

MS14493C3	F52G214-3	NADC Report No.	ESNA
MS14493CL3	RM52G214-3	601Q8725 of	Division of Harvard Industries
MS14493A3	F52G214-3J	11 Dec 1987*	
MS14493AL3	RM52G214-3J		
		*MUST BE MANUFACTURED AFTER 10 MAY 94 DISC-E-94130 LTR	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS14493CL3	G19431-3	Report No.	Kaynar Technologies, Inc.
MS14493C3	G19431x3	601Q8724 of	Kaynar Division
MS14493AL3	G53152-3	11 Dec 1987	P.O. Box 3001
MS14493A3	G53152x3		800 S. State College Blvd.
			Fullerton, CA 92634
			Plant: Same address

MS16228 NUT, SELF-LOCKING, HEXAGON, THIN, UNC 3B (NONMETALLIC INSERT), AUSTENITIC, CORROSION-RESISTANT STEEL, NONMAGNETIC, 250 DEG F

MS16228-4C	L79NTU-420	AMD Report No.	Greer Stop Nut, Inc.
MS16228-5C	L79NTU-518	MA669027 of	481 McNally Drive
MS16228-6C	L79NTU-616	6 Mar 1969	Nashville, TN 37211
MS16228-8C	L79NTU-813		
			Plant: Same address
MS16228-12C	L79NTU-1210	NADC Report No.	
MS16228-16C	L79NTU-1608	305Q79055 of	
		24 Aug 1979	

MS16228-4C	79NTU-040	NAWCADWAR	MacLean-ESNA
MS16228-5C	79NTU-058	Report No.	A MacLean-Fogg Co.
MS16228-6C	79NTU-066	435Q9519 of	611 Country Club Road
MS16228-7C	79NTU-074	20 Oct 1995	P. O. Box 988
MS16228-8C	79NTU-083		Pocahontas, AR 72455
MS16228-10C	79NTU-101		
MS16228-12C	79NTU-120		Plant: Same address
MS16228-16C	79NTU-168		

MS17825 NUT, SELF-LOCKING, CASTELLATED, HEXAGON, 250 DEG F, NONMETALLIC INSERT

MS17825-5	F12NE4753-054	NAMC-AML-1571	ESNA
		of Dec 1962*	Division of Harvard Industries
MS17825-3	FNE4753-02	NAEC-AML-1583	
MS17825-6	F12NE4753-064	of 17 Dec 1962*	
MS17825-7	F12NE4753-070	NAEC-AML-1825	
		of 4 Dec 1963*	
MS17825-8	F12NE4753-080	NAEC-AML-2016	
		of 20 Aug 1964*	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS17825-9	F12NE4753-098	AMD Report No.	
MS17825-10	F12NE4753-108	MA770504A of	
MS17825-12	F12NE4753-126	25 Nov 1969*	
MS17825-14	F12NE4753-144		
MS17825-16	F12NE4753-162	*MUST BE MANUFACTURED	
MS17825-18	F12NE4753-182	AFTER 10 MAY 94	
MS17825-20	F12NE4753-202	DISC-E-94130 LTR	

Note: Manufacturing process: Machined

MS17825-3	F12NMC-1032	AMD Report No.	Greer Stop Nut, Inc.
MS17825-8	F12NEC-820	MA768758 of	481 McNally Drive
		30 Nov 1967	Nashville, TN 37211
			Plant: Same addrress
MS17825-7	F12NEC-720	AMD Report No.	
		MA768771 of	
		29 Nov 1967	

MS1782S-9	F12NEC-918	NADC Report No.	
MS17825-10	F12NEC-1018	305Q78043 of	
MS17825-12	F12NEC-1216	12 Apr 1978	

Notes: 1. Locking insert: Green, nylon-zytel 101
2. Manufacturing process: Machined

MS17825-4	F12NEC-428	AML Report No.	Kaynar Technologies, Inc.
MS17825-5	F12NEC-524	78608-67 of	Kaynar Div.
MS17825-6	F12NEC-624	9 Jun 1967	P.0. Box 3001
			800 S. State College Blvd.
			Fullerton, CA 92634
			Plant: Same address

MS17825-3	F12NE4753-02	NAWCADWAR	MacLean-ESNA
MS17825-4	F12NE4753-048	Report No.	A MacLean-Fogg Co.
		435Q9519 of	611 Country Club Road
		20 Oct 1995	P. O. Box 988
			Pocahontas, AR 72455

Note: Manufacturing process for all nuts listed: Machined Plant: Same address

---

MS17825-14	F12NE4753-14	NAWCAD	MacLean-ESNA
MS17825-16	F12NE4753-16	Report No.	611 Country Club Road
		435Q9801 of	Pocahontas, AR 72455
		29 JAN 1998	
			Plant: Same address

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS17825-3	PCR63	Report No.	Simmonds Mecaero
MS17825-4	PCR64	601Q8718 of	Fasteners, Inc.
MS17825-5	PCR65	16 Oct 1987	1734 Sequoia Avenue
MS17825-6	PCR66		Orange, CA 92668
		NADC Ltr 02872	
		5 April 1988	
			Plant:
			Simmonds
			Usine De Champaissant
			72110 Saint-Cosme En Vairais
			France

Notes: 1. Manufacturing process: Machined
2. Locking insert: Blue or gold nylon until 31 December 1990, gold thereafter
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordanc with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Meta The contractor should include these provisions in every subcontract and purchase order.

MS17825-3	F12NE4753-02	DISC-E MEMORANDUM	SPS Technologies
MS17825-4	F12NE4753-048	JANUARY 4, 1996	Highland Avenue
MS17825-7	F12NE4753-070		Jenkintown, PA 19046
MS17825-9	F12NE4753-098		
MS17825-10	F12NE4753-108		Plant: Same address
MS17825-12	F12NE4753-126		
MS17825-14	F12NE4753-144		
MS17825-18	F12NE4753-182		
MS17825-16	F12NE4753-162	NAWCADWAR	
MS17825-20	F12NE4753-202	Report No.	
		435Q9602 of	
		24 Jan 1996	

MS17825-14	F12NE4753-144	NAWCADWAR	
		Report No.	
		435Q9615 of	
		5 Apr 1996	

MS17825-5	F12NE4753-054	NAWCADWAR	
MS17825-8	F12NE4753-080	Report No.	
		435Q9617 of	
		12 Apr 1996	

MS17825-6	F12NE4753-064	NAWCADWAR	
		Report No.	
		435Q9620 of	
		26 Apr 1996	

NOTE: Manufacturing process: Machined

MS17826 NUT, SELF-LOCKING, CASTELLATED, HEXAGON, 250 DEG F, THIN NONMETALLIC INSERT

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS17826-5	F12NE4717-054	NAMC-AML-1523	ESNA
MS17826-6	F12NE4717-064	of 27 Nov 1962*	Division of Harvard Industries
MS17826-7	F12NE4717-070	NAEC-AML-1932	
MS17826-8	F12NE4717-080	of 9 Apr 1964*	
MS17826-9	F12NE4717-098	AMD Report No.	
MS17826-10	F12NE4717-108	MA770504B of	
MS17826-12	F12NE4717-126	8 Dec 1969*	
MS17826-14	F12NE4717-144		
MS17826-16	F12NE4717-162	*MUST BE MANUFACTURED	
MS17826-18	F12NE4717-182	AFTER 10 MAY 94	
MS17826-20	F12NE4717-202	DISC-E-94130 LTR	

Note: Manufacturing process: Machined

MS17826-3	F12NTMC-1032	AMD Report No.	Greer Stop Nut, Inc.
MS17826-7	F12NTEC-720	MA768771 of	481 McNally Drive
MS17826-8	F12NTEC-820	29 Nov 1967	Nashville, TN 37211
			Pla

Same address

MS17826-5	F12NTEC-524	AMD Report No.	
MS17826-6	F12NTEC-624	MA768758 of	
		30 Nov 1967	
MS17826-9	F12NTEC-918	NADC Report No.	
MS17826-10	F12NTEC-1018	30SQ78043 of	
MS17826-12	F12NTEC-1216	12 Apr 1978	

Notes: 1. Locking insert: Green, nylon-zytel 101
2. Manufacturing process: Machined

MS17826-4	F12NTEC-428	AML Report No.	Kaynar Technologies, Inc.
		78608-67 of	Kaynar Div.
		9 Jun 1967	P.0. Box 3001
			800 S. State College Blvd.
			Fullerton, CA 92634
			Plant: Same address

MS17826-3	F12NE4717-02	NAWCADWAR	MacLean-ESNA
MS17826-4	F12NE4717-048	Report No.	A MacLean-Fogg Co.
		435Q9519 of	611 Country Club Road
		20 Oct 1995	P. O. Box 988
			Pocahontas, AR 72455
			Plant: Same address

Note: Manufacturing process for all nuts listed: Machined

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS17826-5	F12NE4717-5	NAWCAD	MacLean-ESNA
MS17826-6	F12NE4717-6	Report No.	611 Country Club Road
MS17826-7	F12NE4717-7	435Q9809 of	Pocahontas, AR 72455
MS17826-8	F12NE4717-8	17 APR 1998	
MS17826-9	F12NE4717-9		Plant: Same address
MS17826-10	F12NE4717-10		
MS17826-12	F12NE4717-12		
MS17826-14	F12NE4717-14		
MS17826-16	F12NE4717-16		
MS17826-18	F12NE4717-18		
MS17826-20	F12NE4717-20		

MS17826-3	TCR63	Report No.	Simmonds Mecaero
MS17826-4	TCR64	601Q8718 of	Fasteners, Inc.
MS17826-5	TCR65	16 Oct 1987	1734 Sequoia Avenue
MS17826-6	TCR66		Orange, CA 92668
		NADC Ltr 02872	
		5 April 1988	

Notes: 1. Manufacturing process: Machined
2. Locking insert: Blue or gold nylon until 31 December 1990, gold thereafter
3. Provisions Governing Procurement. Procurement of these self-locking shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

Plant: Simmonds
Usine De Champaissant
72110 Saint-Cosme En Vairais
France

MS17826-18	F12NE4717-182	NAWCADWAR	SPS Technologies
		Report No.	Highland Avenue
		435Q9527 of	Jenkintown, PA 19046
		7 Dec 1995	

Note: Manufacturing Process: Machined

Plant: Same address

MS17826-14	F12NE4717-144	NAWCADWAR
MS17826-20	F12NE4717-202	Report No.
		435Q9621 of
Note: Manufacturing Process: Machined		19 Jun 1996

MS17826-3	F12NE4717-02	DISC-E MEMORANDUM
MS17826-4	F12NE4717-048	JANUARY 4, 1996
MS17826-7	F12NE4717-070	
MS17826-9	F12NE4717-098	
MS17826-10	F12NE4717-108	
MS17826-12	F12NE4717-126	
MS17826-16	F12NE4717-162	

Note: Manufacturing process: Machined

MS17826-5	F12NE4717-054	NAWCADWAR
MS17826-8	F12NE4717-080	Report No.
		435Q9617 of
Note: Manufacturing process: Machined		12 Apr 1996

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS17826-6	F12NE4717-064	NAWCADWAR Report No. 435Q9620 of 26 Apr 1996	
Note: Manufacturing process: Machined			

MS17828 NUT, SELF-LOCKING, HEXAGON, REGULAR HEIGHT, (NONMETALLIC INSERT) 250 DEG F, NICKEL-COPPER ALLOY

MS17828-8C	AD-09NE-813	Report No. 601Q8717 of 21 Sep 1987	Automatic Screw Machine Products Co. 709 2nd Avenue P.0. Box 1608 Decatur, AL 35602
MS17828-10C	AD-09NE-1011		
MS17828-12C	AD-09NE-1210		
MS17828-14C	AD-09NE-1409		
Note: Manufacturing process: Machined			Plant: Same address

MS17828-4C	09NE-420	AMD Report No. MA669027 of 6 Mar 1969	Greer Stop Nut, Inc. 481 McNally Drive Nashville, TN 37211
MS17828-5C	09NE-518		
MS17828-6C	09NE-616		
MS17828-8C	09NE-813		
MS17828-10C	09NE-1011		Plant: Same address
MS17828-12C	09NE-1210		

MS17828-14C	09NE-1409	Report No. MA772020 of 2 Dec 1971	
Note: 1. Manufacturing process: Machined			

MS17828-16C	09NE-1608	Report No. MA772005 of 26 Jan 1972	
MS17828-18C	09NE-1807		
MS17828-20C	09NE-2007		
MS17828-22C	09NE-2206		
MS17828-24C	09NE-2406		
Note: 1. Manufacturing process: Machined			

MS17828-3C	09NM-1024	NADC Report No. 305Q79055 of 24 Aug 1979	
MS17828-28C	09NU-2805		
MS17828-32C	09NU-3204.5		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS17828-04C	09NM-40 (Monel)	NAWCADWAR	MacLean-ESNA
MS17828-06C	09NM-62 "	Report No.	A MacLean-Fogg Co.
MS17828-08C	09NM-82 "	435Q9519 of	611 Country Club Road
MS17828-3C	09NM-04 "	20 Oct 1995	P. O. Box 988
MS17828-3F	09NM-02 "		Pocahontas, AR 72455
MS17828-4C	09NE-040 "		
MS17828-4F	09NE-048 "		Plant: Same address
MS17828-5C	09NE-058 "		
MS17828-5F	09NE-054 "		
MS17828-6C	09NE-066 "		
MS17828-6F	09NE-064 "		
MS17828-7C	09NE-074U "		
MS17828-7F	09NE-070U "		
MS17828-8C	09NE-083 "		
MS17828-8F	09NE-080 "		
MS17828-9C	09NE-092 "		
MS17828-9F	09NE-098 "		
MS17828-10C	09NE-101 "		
MS17828-10F	09NE-108 "		
MS17828-12C	09NE-120 "		
MS17828-12F	09NE-126 "		
MS17828-14C	09NE-149 "		
MS17828-14F	09NE-144 "		
MS17828-16C	09NE-168 "		
MS17828-16F	09NE-162 "		
MS17828-18C	09NE-187 "		
MS17828-18F	09NE-182 "		
MS17828-20C	09NE-207 "		
MS17828-20F	09NE-202 "		
MS17828-22C	09NE-226 "		
MS17828-22F	09NE-222 "		
MS17828-24C	09NE-246 "		
MS17828-24F	09NE-242 "		
MS17828-28C	09NU-285 "		
MS17828-32C	09NU-324 "		
MS17828-36C	09NU-364 "		
MS17828-40C	09NU-404 "		

Note: Manufacturing process: Machined or Forged
Lubricant: Carbowax

MS17829 NUT, SELF-LOCKING, HEXAGON, REGULAR HEIGHT, 250 DEG F, (NONMETALLIC INSERT), NONCORROSION-RESISTANT STEEL

MS17829-5C	F52N7582-518	AMD Report No.	Greer Stop Nut, Inc.
MS17829-8C	F52N7582-813	MA669027 of	481 McNally Drive
MS17829-4C	F52N7582-420	6 Mar 1969	Nashville, TN 37211
MS17829-6C	F52N7582-616		
MS17829-7C	F52N7582-714U		Plant: Same address
MS17829-10C	F52N7582-1011		
MS17829-12C	F52N7582-1210		
MS17829-14C	F52N7582-1409		
MS17829-16C	F52N7582-1608		
MS17829-20C	F52N7582-2007		

MS17829-22C	F52N7582-2206	Report No.	
MS17829-24C	F52N7582-2406	MA772021 of	
		25 May 1972	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS17829-18C	F52N7582-1807	Report No. MA772027 of 30 Jun 1972

MS17829-28C	F52N7582-2805	Report No. 305Q74017 of 3 Jan 1975
MS17829-32C	F52N7582-32045	
MS17829-36C	F52N7582-36045	

Note: 1. Manufacturing process: Machined

MS17829-9C	F52N7582-912	NADC Report No. 305Q79055 of 24 Aug 1979
MS17829-40C	F52N7582-4004	

MS17829-3C	F52N1610-04	NAWCADWAR Report No. 435Q9519 of 20 Oct 1995	MacLean-ESNA A MacLean-Fogg Co. 611 Country Club Road P. O. Box 988 Pocahontas, AR 72455
MS17829-4C	F52N1610-040		
MS17829-4F	F52N1610-048		
MS17829-5C	F52N1610-058		
MS17829-5F	F52N1610-054		
MS17829-6C	F52N1610-066		
MS17829-6F	F52N1610-064		Plant: Same address
MS17829-7C	F52N1610-074U		
MS17829-7F	F52N1610-070U		
MS17829-8C	F52N1610-083		
MS17829-8F	F52N1610-080		
MS17829-9C	F52N1610-092		
MS17829-9F	F52N1610-098		
MS17829-10C	F52N1610-101		
MS17829-10F	F52N1610-108		
MS17829-12C	F52N1610-120		
MS17829-12F	F52N1610-126		
MS17829-14C	F52N1610-149		
MS17829-14F	F52N1610-144		
MS17829-16C	F52N1610-168		
MS17829-16F	F52N1610-162		
MS17829-18C	F52N1610-187		
MS17829-18N08	F52N1610-1808		
MS17829-18F	F52N1610-182		
MS17829-20C	F52N1610-207		
MS17829-20N08	F52N1610-2008		
MS17829-20F	F52N1610-202		
MS17829-22C	F52N1610-226		
MS17829-22N08	F52N1610-2208		
MS17829-22F	F52N1610-222		
MS17829-24C	F52N1610-246		
MS17829-24N08	F52N1610-2408		
MS17829-24F	F52N1610-242		
MS17829-28C	F52NU1610-285		
MS17829-28N08	F52NU1610-2808		
MS17829-32C	F52NU1610-324		
MS17829-32N08	F52NU1610-3208		
MS17829-36C	F52NU1610-364		
MS17829-36N08	F52NU1610-3608		
MS17829-40C	F52NU1610-404		
MS17829-40N08	F52NU1610-4008		

Note: Manufacturing process: Forged or machined for 1-12 size and smaller; machined for 11/8-7 size and larger.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS17829Z3C	54N1610-04	NAWCAD	MacLean-ESNA
MS17829Z4C	54N1610-040	Report No.	611 Country Club Road
MS17829Z4F	54N1610-048	435Q9809 of	Pocahontas, AR 72455
MS17829Z5C	54N1610-058	17 APR 1998	
MS17829Z5F	54N1610-054		Plant: Same address
MS17829Z6C	54N1610-066		
MS17829Z6F	54N1610-064		
MS17829Z7C	54N1610-074U		
MS17829Z7F	54N1610-070U		
MS17829Z8C	54N1610-083		
MS17829Z8F	54N1610-080		
MS17829Z9C	54N1610-092		
MS17829Z9F	54N1610-098		
MS17829Z10C	54N1610-101		
MS17829Z10F	54N1610-108		
MS17829Z12C	54N1610-120		
MS17829Z12F	54N1610-126		
MS17829Z14C	54N1610-149		
MS17829Z14F	54N1610-144		
MS17829Z16C	54N1610-168		
MS17829Z16F	54N1610-162		
MS17829Z18C	54N1610-187		
MS17829Z18F	54N1610-182		
MS17829Z20C	54N1610-207		
MS17829Z20F	54N1610-202		

MS17830 NUT, SELF-LOCKING, HEXAGON, REGULAR HEIGHT, 250 DEG F, (NONMETALLIC INSERT), 300 SERIES CORROSION-RESISTANT STEEL

MS17830-4C	L79NE-420	AMD Report No.	Greer Stop Nut, Inc.
MS17830-5C	L79NE-518	MA669027 of	481 McNally Drive
MS17830-6C	L79NE-616	6 Mar 1969	Nashville, TN 37211
MS17830-8C	L79NE-813		
MS17830-10C	L79NE-1011		Plant: Same address
MS17830-12C	L79NE-1210		

MS17830-14C	L79NE-1409	NADC Report No.	
MS17830-16C	L79NE-1608	305Q79055 of	
		24 Aug 1979	

MS17830-3C	L79NM-1024	NADC Report No.	
		305Q82084 of	
Note: Manufactured process: Machined		22 Sep 1982	

MS17830-04C	L79NM-440	NADC Report	
MS17830-06C	L79NM-632	601Q8605 of	
MS17830-08C	L79NM-832	14 Mar 1986	

Note: 1. Manufacturing process: Machined
2. Locking Insert: Green Nylon

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS17830-04C	79NM-40	NAWCADWAR	MacLean-ESNA
MS17830-06C	79NM-62	Report No.	A MacLean-Fogg Co.
MS17830-08C	79NM-82	435Q9519 of	611 Country Club Road
MS17830-3C	79NM-04	20 Oct 1995	P. O. Box 988
MS17830-4C	79NE-040		Pocahontas, AR 72455
MS17830-5C	79NE-058		
MS17830-6C	79NE-066		Plant: Same address
MS17830-7C	79NE-074U		
MS17830-8C	79NE-083		
MS17830-9C	79NE-092		
MS17830-10C	79NE-101		
MS17830-12C	79NE-120		
MS17830-14C	79NE-149		
MS17830-16C	79NE-168		
MS17830-18C	79NE-187		
MS17830-20C	79NE-207		
MS17830-22C	79NE-226		
MS17830-22F	79NE-222		
MS17830-24C	79NE-246		
MS17830-24F	79NE-242		
MS17830-28C	79NU-285		
MS17830-32C	79NU-324		
MS17830-36C	79NU-364		
MS17830-40C	79NU-404		

Note: Manufacturing process: Forged or machined for 9/16-12 size and smaller; machined for 5/8-11 size and larger.

MS20365 NUT, SELF-LOCKING, 250 DEG F

Note: 1. MS20365 Canceled.
2. See interchangeability table on MS21042, MS21044 and MS21045 for substitute parts.

MS21040 NUT, SELF-LOCKING, 500 DEG F , HEXAGON, REDUCED HEIGHT

Note: 1. MS21040 Canceled.
2. See interchangeability table on MS21042 for substitute parts.

MS21042 NUT, SELF-LOCKING, 450 DEG F, REDUCED HEXAGON, REDUCED HEIGHT, RING BASE, NONCORROSION-RESISTANT STEEL

MS21042-02	T98S256CPC	Report No.	Boots Nut Division of
MS21042L02	T98S256	601Q9002 of	Republic Fastener
MS21042-04	T98S440CPC	8 Jan 90	1300 Rancho Conejo Blvd.
MS21042L04	T98S440		Newbury Park, CA 91320
MS21042-06	T98S632CPC		
MS21042L06	T98S632		Plant: Same address

Note: 1. Manufacturing Process: Forged
2. Dry Film Lubricant: MIL-L-46010, Type I
3. "CPC" Series: Cadmium plated with no lubricant

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21042L08	T98S832	NAWC Report
MS21042-08	T98S832CPC	601Q9004 of
MS21042L3	T98S1032	22 Jan 90
MS21042-3	T98S1032CPC	
MS21042L4	T98S428	
MS21042-4	T98S428CPC	
MS21042L5	T98S524	
MS21042L6	T98S624	
MS21042-6	T98S624CPC	

Notes: 1. Manufacturing Process: Forged
2. Dry Film Lubricant: MIL-L-46010, Type I
3. CPC series: Cadmium plated with no lubricant

MS21042-06	BH21042-06	NADC Report No.	Bristol Industries
MS21042L06	BH21042L06	305Q79052 of	630 E. Lambert Road
MS21042-08	BH21042-08	30 Jul 1979	P.O. Box 630
MS21042L08	BH21042L08		Brea, CA 92621
MS21042-3	BH21042-3		
MS21042L3	BH21042L3		Plant: Same address
MS21042-4	BH21042-4		
MS21042L4	BH21042L4		

MS21042-04	BH21042-04	NADC Report No.	
MS21042L04	BH21042L04	305Q80061 of	
		17 Nov 1980	

MS21042L06	T97S632	Report No.	Cherry/Textron
MS21042-06	T97S632 CPF	NAMC-AML-AE 6201.40	Cherry Div. of
MS21042-06	T97S632 CPC	Part XXII of	Textron Inc.
MS21042L08	T97S832	10 Aug 1961	P.0. Box 2157
MS21042-08	T97S832 CPF		1224 East Warner Ave.
MS21042-08	T97S832 CPC		Santa Ana, CA 92707
MS21042L3	T97S1032		
MS21042-3	T97S1032 CPF		Plant: Same address
MS21042-3	T97S1032 CPC		
MS21042L4	T97S428		
MS21042-4	T97S428 CPF		
MS21042-4	T97S428 CPC		
MS21042L5	T97S524		
MS21042-5	T97S524 CPF		
MS21042-5	T97S524 CPC		
MS21042L6	T97S624		
MS21042-6	T97S624 CPF		
MS21042-6	T97S624 CPC		

Note: 1. Manufacturing process forged for MS21042L04 and MS21042-04.
2. Manufacturing process for all other nuts: Machined
3. Molybdenum disulfide dry film lubricant as approved by NAMATCEN ltr XM-621-FTR:mlp 10410(2510) of 9 Feb 1960.
4. The CPF series is cadmium-plated and lubricated with Ferrocote.
5. The CPC series is cadmium-plated with no lubricant.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21042L04	T98S440	AML Report No.
MS21042-04	T98S440 CPF	78569-67 of
MS21042-04	T98S440 CPC	17 Mar 1967

MS21042L06	T98S632	Report No. NAMC-
MS21042-06	T98S632 CPF	AML-1313 of
MS21042-06	T98S632 CPC	16 Nov 1961
MS21042L3	T98S1032	
MS21042-3	T98S1032 CPF	
MS21042-3	T98S1032 CPC	
MS21042L4	T98S428	
MS21042-4	T98S428 CPF	
MS21042-4	T98S428 CPC	

Note: 1. Manufacturing process for all nuts: Forged
2. Molybdenum disulfide dry film lubricant as approved by NAMC ltr XM-621-FTR:mlp 10410 of 9 Feb 1960.
3. The CPF series is cadmium-plated and lubricated with Ferrocote.
4. The CPC series is cadmium-plated with no lubricant.

MS21042L08	T98S832	Report No. NAEC-
MS21042-08	T98S832 CPF	AML-1554 of
MS21042-08	T98S832 CPC	7 Feb 1963

Note: 1. Manufacturing process: Forged
2. T98S832 is cadmium-plated, and lubricated with Molybdenum disulfide as approved by NAMATCEN ltr XM-621-FTR:mlp 10410(2510) of 9 February 1960.
3. T98S832 CPF is cadmium-plated and lubricated with Ferrocote.
4. T98S832 CPC is cadmium-plated with no lubrication.

MS21042-5	T98S524 CPF	AMD Report No.
MS21042L5	T98S524	MA768806 of
MS21042L6	T98S624	30 Jan 1969
MS21042-6	T98S624 CPF	
MS21042-6	T98S624 CPC	

MS21042L02	T98S256	NADC Report No.
MS21042-02	T98S256 CPC	305Q82074 of
		29 Mar 1982

Note: Manufacturing process: Forged

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21042L04	RM52LH3324-40	NAMC-AML-AE 16201.40	ESNA
MS21042-04	LF52LH3324-40	Part VIII	Div of
MS21042-04	F52LH3324-40	of 8 Dec 1959*	Harvar
MS21042L06	RM52LH3324-62		
MS21042-06	LF52LH3324-62		
MS21042-06	F52LH3324-62		
MS21042L08	RM52LH3324-82		
MS21042-08	LF52LH3324-82		
MS21042-08	F52LH3324-82		
MS21042L3	RM52LH3324-02		
MS21042-3	LF52LH3324-02		
MS21042-3	F52LH3324-02		
MS21042L4	RM52LH3324-048		
MS21042-4	LF52LH3324-048		
MS21042-4	F52LH3324-048		
MS21042L5	RM52LH3324-054		
MS21042-5	LF52LH3324-054		
MS21042-5	F52LH3324-054		
MS21042L6	RM52LH3324-064		
MS21042-6	LF52LH3324-064		
MS21042-6	F52LH3324-064		
MS21042L04	RM52LH3324-40		
MS21042-04	LF52LH3324-40		
MS21042-04	F52LH3324-40		
MS21042L06	RM52LH3324-62		
MS21042-06	LF52LH3324-62		
MS21042-06	F52LH3324-62		
MS21042L08	RM52LH3324-82		
MS21042-08	LF52LH3324-82		
MS21042-08	F52LH3324-82		
MS21042L3	RM52LH3324-02		
MS21042-3	LF52LH3324-02		
MS21042-3	F52LH3324-02		
MS21042L4	RM52LH3324-048		
MS21042-4	LF52LH3324-048		
MS21042-4	F52LH3324-048		

Note: 1. Manufacturing process for all nuts listed: Forged
2. "RM" designates molybdenum disulfide dry film lubricant as approved by NAMATCEN ltr XM-621-FTR:mlp J9(1423) of Jul 1959.
3. Prefix "LF" designates cadmium-plated and lubricated with Ferrocote 348
4. Prefix "F" designates cadmium-plated with no lubrication.

MS21042L5	RM52LH3324-054	NAMC-AML-1540
MS21042-5	LF52LH3324-054	of 31 Oct 1962*
MS21042-5	F52LH3324-054	

Note: 1. Manufacturing process: Stamped
2. RM52LH3324-054 (with molybdenum disulfide dry film lubricant).
3. LF52LH3324-054 (with Ferrocote 348 lubricant).
4. F52LH3324-054 (no lubrication).

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21042L02	RM52LH3324-26	NAEC-AML-1851	
MS21042-02	LF52LH3324-26	of 20 Dec 1963*	
		*MUST BE MANUFACTURED AFTER 10 MAY 94 DISC-E-94130 LTR	

Note: 1. Manufacturing process: Stamped
2. RM52LH3324-26 (with molybdenum disulfide dry film lubricant).
3. LF52LH3324-26 (with Ferrocote 348 lubricant).

MS21042-06	MN16-06	NADC Report No.	Hi-Shear Corp.
MS21042L06	MN16PJ-06	305Q77035 of	2600 SkyPark Drive
MS21042-08	MN16-08	30 March 1977	Torrance, CA 90509
MS21042L08	MN16PJ-08		
MS21042-3	MN16-3		Plant: Same address
MS21042-4	MN16-4		

MS21042L04	H14L04	Report No. NAMC-	Kaynar Technologies, Inc.
MS21042-04	H14L04CW	AML-AE 6201.40,	Kaynar Div.
MS21042-04	H14LX04	Part XXI of	P.0. Box 3001
MS21042L06	H14L06	9 May 1961	800 S. State College Blvd.
MS21042-06	H14L06CW		Fullerton, CA 92634
MS21042-06	H14LX06		
MS21042L08	H14L08		Plant: Same address
MS21042-08	H14L08CW		
MS21042-08	H14LX08		

MS21042L3	H14-3	Report No. NAMC-
MS21042-3	H14X3	AML-AE 6201.40,
MS21042-3	H14-3CW	Part IX of
MS21042L4	H14-4	8 Dec 1959
MS21042-4	H14x4	
MS21042-4	H14-4CW	
MS21042L5	H14-5	
MS21042-5	H14X5	
MS21042-5	H14-SCW	
MS21042L6	H14-6	
MS21042-6	H14X6	
MS21042-6	H14-6CW	

Note: 1. Manufacturing process for all nuts listed: Forged
2. Molybdenum disulfide dry film lubricant as approved by BUAER ltr AER-AE-6337/25 of 2 Mar 1959.
3. "CW" suffix in the Kaynar P/N designates lubricated with Kaywax which consists of a synthetic wa corrosion inhibitor and an aromatic so1vent.
4. "X" designates cadmium-plated with no lubrication.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21042L02 MS21042-02	H14L02 H14L02CW	Report No. NAEC AML-1743 of 29 Aug 1963	

Note: 1. Manufacturing process: Forged
2. H14L02 (with Molybdenum disulfide dry film lubricant).
3. H14L02CW (With Kaywax lubricant).

MS21042-3 MS21042L3	180000-3 180000-3L	NAWC Report 601Q9110 of 14 Feb 1992	The Monadnock Company 18301 East Arenth Ave. City of Industry, CA 91749
			Plant: Same address
MS21042-08 MS21042L08 MS21042-4 MS21042L4	180000-08 180000-08L 180000-4 180000-4L	NAWC Report 601Q9208 of 15 Jun 1992	

Note: Manufacturing Process: Forged

MS21042-06 MS21042L06	180000-06 180000-06L	NAWC Report 601Q9213 of 27 Aug 1992	
MS21042-02 MS21042L02	180000-02 180000-02L	NAWC Report 601Q9313 of 11 Jun 93	
MS21042-04 MS21042L04	180000-04 180000-04L	NAWC Report 601Q9319 of 15 Nov 93	

Note: 1. Manufacturing process: Forged
2. Lubricant: Lube-Lok 5306 per MIL-L-46010 Type I

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21042-08	RH30X08	NADC Report	Republic Fastener
MS21042-08	RH30X08CN	601Q8503 of	Manufacturing Corp.
MS21042L08	RH30A08	8 Apr 1985	1300 Rancho Conejo Blvd.
MS21042-3	RH30X3		Newbury Park, CA 91320
MS21042-3	RH30X3CN		
MS21042L3	RH30A3		Plant: Same address
MS21042-4	RH30X4		
MS21042-4	RH30X4CN		
MS21042L4	RH30A4		
MS21042-5	RH30X5		
MS21042-5	RH30X5CN		
MS21042L5	RH30A5		
MS21042-6	RH30X6		
MS21042-6	RH30X6CN		
MS21042L6	RH30XA6		

Note: 1. Manufacturing process: Forged
2. "CW" denotes CARBO WAX
3. "X" denotes Cadmium P1ating
4. "A" denotes Dry Film Lubricant

MS21042L3	PLH-353M	Report No.	Simmonds Mecaero
MS21042L4	PLH-354M	305Q83101 of	Fasteners, Inc.
		5 May 1983	1734 Sequoia Avenue
			Orange, CA 92668
MS21042L04	PLH-3504M	Report No.	Plant:
		305Q83111 of	Simmonds
		19 Oct 1983	Usine De Champaissant
			72110 Saint-Cosme En Vairais
			France
MS21042L5	PLH-335M	Report No.	
		305Q83112 of	
		28 Nov 1983	
MS21042-04	PLH-3504	Report No.	
MS21042-06	PLH-3506	601Q8401 of	
MS21042L06	PLH-3506M	24 Feb 1984	
MS21042-08	PLH-3508		
MS21042L08	PLH-3508M		
MS21042-3	PLH-353		
MS21042-4	PLH-354		
MS21042-5	PLH-35S		
MS21042-6	PLH-356	NADC Report No.	
MS21042L6	PLH-356M	601Q8407 of	
		20 Apr 1984	

Note: 1. Manufacturing process: Cold formed
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance
FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals)
The contractor should include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21042-02	PLH-3502	NADC Report	
MS21042L02	PLH-3502M	601Q8505 of	
		30 May 1985	

Note: 1. Manufacturing process: Cold stamping
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance
FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals
The contractor should include these provisions in every subcontract and purchase order.

MS21042L04	FN12M-40	Report No. NAMC-	SPS Technologies
MS21042-04	FN12A-40	AML-AE 6201.40,	Highland Ave.
MS21042-04	FN12X-40	Part VII of	Jenkintown, PA 19046
MS21042L06	FN12M-62	8 Dec 1959	
MS21042-06	FN12A-62		Plant: Same address
MS21042-06	FN12X-62		
MS21042L08	FN12M-82		
MS21042-08	FN12A-82		
MS21042-08	FN12X-82		
MS21042L3	FN12M-02		
MS21042-3	FN12A-02		
MS21042-3	FN12X-02		
MS21042L4	FN12M-048		
MS21042-4	FN12A-048		
MS21042-4	FN12X-048		
MS21042L5	FN12M-054		
MS21042-5	FN12A-054		
MS21042-5	FN12X-054		
MS21042L6	FN12M-064		
MS21042-6	FN12A-064		
MS21042-6	FN12X-064		

Note: 1. Manufacturing process for all nuts listed: Forged
2. Molybdenum disulfide dry film lubricant as approved by NAMATCEN
ltr XM-621-FTR:mlp (1428) of 29 July 1959.
3. The FN12A series is cadmium-plated and lubricated with Carbo Wax.
4. The FN12X series is cadmium-plated with no lubricant.
5. The FN12M series is molybdenum disulfide lubricated.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21042L04	RM52LH3324-40	Report No.
MS21042-04	LF52LH3324-40	435Q9505 of
MS21042-04	F52LH3324-40	31 Mar 1995
MS21042L06	RM52LH3324-62	
MS21042-06	LF52LH3324-62	
MS21042-06	F52LH3324-62	
MS21042L08	RM52LH3324-82	
MS21042-08	LF52LH3324-82	
MS21042-08	F52LH3324-82	
MS21042L3	RM52LH3324-02	
MS21042-3	LF52LH3324-02	
MS21042-3	F52LH3324-02	
MS21042L4	RM52LH3324-048	
MS21042-4	LF52LH3324-048	
MS21042-4	F52LH3324-048	
MS21042L5	RM52LH3324-054	
MS21042-5	LF52LH3324-054	
MS21042-5	F52LH3324-054	
MS21042L6	RM52LH3324-064	
MS21042-6	LF52LH3324-064	
MS21042-6	F52LH3324-064	

Note: 1. Manufacturing process: Forged
2. "RM" designates Molybdenum Disulfide Lubricant Coating
3. "LF" designates cadmium-plated and lubricated with Carbowax
4. "F" designates cadmium-plated with no lubricant

MS21042L3	VN300-A-02	Report No. NAMC-	VOI-SHAN
MS21042-3	VN300-C-02	AML-AE 6201.40,	Fairchild Aerospace Fastener Div
MS21042-3	VN300-CN-02	Part XV of	2950 W. Lomita Blvd.
MS21042L4	VN300-A-048	5 Aug 1960	Torrance, CA 90505-5103
MS21042-4	VN300-C-048		
MS21042-4	VN300-CN-048		Plant: Same address

Note: 1. Manufacturing process for all nuts listed: Forged
2. Molybdenum disulfide dry film lubricant designation "A" approved by NAMATCEN ltr XM-621:FTR:mlp J9(1421) of 20 July 1959.
3. Cadmium-plated parts designated "C" are lubricated with Carbo Wax.
4. "CN" designates cadmium-plated having no lubrication.

MS21042L06	VN300-A-62	Report No. NAEC-
MS21042-06	VN300-C-62	AML-1686 of
MS21042-06	VN300-CN-62	29 May 1963

Note: 1. Manufacturing process: Forged
2. Molybdenum disulfide dry film lubricant as approved by NAMATCEN ltr XM-621-FTR:mlp(2510) of 9 February 1960.
3. The "C" series is cadmium-plated and lubricated with 11 Carbo Wax.
4. The "CN" series is cadmium-plated with no lubrication.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21042L08	VN300-A-82	Report No.
MS21042-08	VN300-C-82	NAMC-AML-1348
MS21042-08	VN300-CN-82	of 2 Jan 1962

Note: 1. Manufacturing process for all nuts: Forged
2. Molybdenum disulfide dry film lubricant as approved by NAMATCEN ltr XM-621-FTR:mlp 10410 (2510) of 9 February 1960.
3. Tne "C" series is cadmium-plated, and lubricated with Carbo Wax.
4. The "CN" series is cadmium-plated with no lubrication.

MS21042L04	VN300-A-40	Report No.
MS21042-04	VN300-C-40	NAMC-AML-1569
MS21042-04	VN300-CN-40	of 7 Dec 1962

Note: 1. Manufacturing process for all nuts: Forged
2. The "A" series is cadmium-plated, and lubricated with Molybdenum disulfide as approved by NAVAIRMATCEN ltr XM-621-FTR:mlp 10410(2510) of 9 February 1960.
3. The "C" series is cadmium-plated, and lubricated with Carbo Wax.
4. The "CN" series is cadmium-plated With no lubrication.

MS21043-04	T99C440	NADC Report	Boots Nut Division of
MS21043-06	T99C632	602Q9002 of	Republic Fastener Mfg Corp
		8 Jan 90	1300 Rancho Conejo Blvd.
			Newbury Park, CA 91320
Note: 1. Manufacturing Process: Forged			
2. "CPC" Denotes Dry Film Lubricant per MIL-L-46010, Type I			Plant: Same address

---

MS21043-08	T99C832	NAWC Report
MS21043-3	T99C1032	601Q9004 of
MS21043-4	T99C428	22 Jan 90
MS21043-5	T99C524	
MS21043-6	T99C624	

Note: Manufacturing Process: Forged

MS21043-06	BH21043-06	NADC Report No.	Bristol Industries
MS21043-08	BH21043-08	305Q79052 of	630 E. Lambert Road
MS21043-3	BH21043-3	30 Jul 1979	P.0. Box 630
MS21043-4	BH21043-4		Brea, CA 92621
MS21043-5	BH21043-5		
MS21043-6	BH21043-6		Plant: Same address

MS21043-04	BH21043-04	NADC Report No.
		305Q80061 of
		17 Nov 1980

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21043-04	T99C440	Report No.	Cherry/Textron
MS21043-06	T99C632	NAMC-AML-AE	Cherry Div. of
MS21043-08	T99C832	6201.40, Part XVII	Textron Inc.
MS21043-3	T99C1032	of 10 May 1961	P.0. Box 2157
MS21043-4	T99C428		1224 East Warner Ave.
MS21043-5	T99C524		Santa Ana, CA 92707

Note: Manufacturing process for all nuts listed: Machined Plant: Same address

---

MS21043-06	T99C632	Report No.
MS21043-3	T99C1032	NAMC-AML-1416
MS21043-4	T99C428	of 23 Apr 1962

Note: Manufacturing process for all nuts listed: Forged

MS21043-08	T99C832	Report No.
		NAMC-AML-1556
Note: Manufacturing process: Forged		of 27 Nov 1962

MS21043-04	T99C440	AMD Report No.
MS21043-5	T99C524	MA768806 of
		30 Jan 1969

Note: Manufacturing process: Forged

MS21043-6	T99C624	Report No.
		305Q73008 of
Note: 1. Manufacturing process: Forged		29 Aug 1973
2. Lubrication: None		
3. Plating: Silver		

MS21043-04	LH3858-40	NAMC-AML-AE	ESNA
MS21043-06	LH3858-62	6201.40, Part XVIII	Division of Harvard Industries
MS21043-08	LH3858-82	of 9 May 1961*	
MS21043-3	LH3858-02		
MS21043-4	LH3858-048		
MS21043-5	LH3858-054		
MS21043-6	LH3858-064		

Note: Manufacturing process for all nuts listed: Forged

MS21043-04	LH3858-40	*MUST BE MANUFACTURED
MS21043-06	LH3858-62	AFTER 10 MAY 94
MS21043-08	LH3858-82	DISC-E-94130 LTR
MS21043-3	LH3858-02	

Note: Manufacturing process for all nuts listed: Stamped

MS21043-04	MN-19-04	NADC Report No.	Hi-Shear Corp.
MS21043-06	MN-19-06	305Q76025 of	2600 SkyPark Dr.
MS21043-08	MN-19-08	15 Oct 1976	Torrance, CA 90509
MS21043-3	MN-19-3		
			Plant: Same Address

Note: Nuts are forged.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21043-04	H41L-04	Report No.	Kaynar Technologies, Inc.
MS21043-06	H41L-06	NAMC-AML-AE	Kaynar Div.
MS21043-08	H41L-08	6201.40, Part XXIII	P.0. Box 3001
MS21043-3	H41-3	of 29 Jun 1981	800 S. State College Blvd.
MS21043-5	H41-5		Fullerton, CA 92634
MS21043-6	H41-6		
			Plant: Same address

Note: Manufacturing process for all nuts listed: Forged

MS21043-4	H41-4	Report No.	
		NAMC-AML-AE	
		6201.40, Part XX	
		of 10 May 1961	

Note: Manufacturing process for all nuts listed: Forged

MS21043-3	180000-3	NAWC Report	The Monadnock Company
		601Q9110 of	18301 East Arenth Ave.
		14 Feb 1992	City of Industry, CA 91749
			Plant: Same address
MS21043-4	180001-4	NAWC Report	
		601Q9302 of	
		5 Feb 1993	
MS21043-04	180001-04	NAWC Report	
		601Q9319 of	
		15 Nov 93	
MS21043-06	180001-06	NAWC Report	
		601Q9213 of	
		27 Aug 1993	
MS21043-08	180001-08	NAWC Report	
		601Q9208 of	
		15 June 1992	

Note: Manufacturing Process: Forged

MS21043-08	RH30C08	NADC Report	Republic Fastener
MS21043-3	RH30C3	601Q8503 of	Manufacturing Corp.
MS21043-4	RH30C4	8 Apr 1985	1300 Rancho Conejo Blvd.
MS21043-5	RH30C5		Newbury Park, CA 91320
MS21043-6	RH30C6		
			Plant: Same address

Note: 1. Manufacturing process: Forged

MS21043-04	PLH-504	NADC	Simmonds Mecaero
MS21043-06	PLH-506	Report No.	Fasteners, Inc.
MS21043-3	PLH-53	305Q3111 of	1734 Sequoia Avenue
MS21043-4	PLH-54	19 Oct 1983	Orange, CA 92668

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

			Plant:
MS21043-5	PLH-55	NADC Report 305Q83112 of 28 Nov 1983	Simmonds Usine De Champaissant 72110 Saint-Cosme En Vairais France
MS21043-08	PLH-508	NADC Report 601Q8401 of 24 Feb 1984	
MS21043-6	PLH-56	NADC Report 601Q8417 of 25 Oct 1984	

Note: 1. Manufacturing process: Cold formed
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance
FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals)
The contractor should include these provisions in every subcontract and purchase order.

MS21043-04	FN1014-440	Report No.	SPS Technologies
MS21043-06	FN1014-632	NAMC-AML-AE	Highland Ave.
MS21043-08	FN1014-832	6201.40, Part XIX	Jenkintown, PA 19046
MS21043-3	FN1014-1032	of 9 May 1961	
MS21043-4	FN1014-428		Plant: Same address
MS21043-5	FN1014-524		
MS21043-6	FN1014-624		

Note: Manufacturing process for all nuts listed: Forged

MS21043-04	LH3858-40	Report No.	
MS21043-06	LH3858-62	435Q9505	
MS21043-08	LH3858-82	31 Mar 1995	
MS21043-3	LH3858-02		
MS21043-4	LH3858-048		
MS21043-5	LH3858-054		
MS21043-6	LH3858-064		

Note: Manufacturing Process: Forged

MS21043-3	VN300-B-02	Report No.	VOI-SHAN
MS21043-4	VN300-B-048	NAMC-AML-140B of 26 Mar 1962	Fairchild Aerospace Fastener Div 2950 W. Lomita Blvd. Torrance, CA 90505-5103
Note: Manufacturing process for both nuts listed: Forged			Plant: Same address
MS21043-08	VN300-B-82	Report No. NAEC-AML-16B7	
Note: Manufacturing process: Forged		of 29 May 1963	

MS21043-04	T99C440	NADC Report	Boots Nut Division of
MS21043-06	T99C632	602Q9002 of	Republic Fastener
Mfg Corp			
		8 Jan 90	1300 Rancho Conejo Blvd. Newbury Park, CA 91320
Note: 1. Manufacturing Process: Forged			
2. "CPC" Denotes Dry Film Lubricant per MIL-L-46010, Type I			Plant: Same address

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21043-08	T99C832	NAWC Report	
MS21043-3	T99C1032	601Q9004 of	
MS21043-4	T99C428	22 Jan 90	
MS21043-5	T99C524		
MS21043-6	T99C624		

Note: Manufacturing Process: Forged

MS21043-06	BH21043-06	NADC Report No.	Bristol Industries
MS21043-08	BH21043-08	305Q79052 of	630 E. Lambert Road
MS21043-3	BH21043-3	30 Jul 1979	P.0. Box 630
MS21043-4	BH21043-4		Brea, CA 92621
MS21043-5	BH21043-5		
MS21043-6	BH21043-6		Plant: Same address

MS21043-04	BH21043-04	NADC Report No. 305Q80061 of 17 Nov 1980

MS21043-04	T99C440	Report No.	Cherry/Textron
MS21043-06	T99C632	NAMC-AML-AE	Cherry Div. of
MS21043-08	T99C832	6201.40, Part XVII	Textron Inc.
MS21043-3	T99C1032	of 10 May 1961	P.0. Box 2157
MS21043-4	T99C428		1224 East Warner Ave.
MS21043-5	T99C524		Santa Ana, CA 92707

Note: Manufacturing process for all nuts listed: Machined — Plant: Same address

---

MS21043-06	T99C632	Report No.
MS21043-3	T99C1032	NAMC-AML-1416
MS21043-4	T99C428	of 23 Apr 1962

Note: Manufacturing process for all nuts listed: Forged

MS21043-08	T99C832	Report No. NAMC-AML-1556
Note: Manufacturing process: Forged		of 27 Nov 1962

MS21043-04	T99C440	AMD Report No.
MS21043-5	T99C524	MA768806 of 30 Jan 1969

Note: Manufacturing process: Forged

MS21043-6	T99C624	Report No. 305Q73008 of 29 Aug 1973

Note: 1. Manufacturing process: Forged
2. Lubrication: None
3. Plating: Silver

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21043-04	LH3858-40	NAMC-AML-AE	ESNA
MS21043-06	LH3858-62	6201.40, Part XVIII	Division of Harvard Industries
MS21043-08	LH3858-82	of 9 May 1961*	
MS21043-3	LH3858-02		
MS21043-4	LH3858-048		
MS21043-5	LH3858-054		
MS21043-6	LH3858-064		

Note: Manufacturing process for all nuts listed: Forged

MS21043-04	LH3858-40	*MUST BE MANUFACTURED
MS21043-06	LH3858-62	AFTER 10 MAY 94
MS21043-08	LH3858-82	DISC-E-94130 LTR
MS21043-3	LH3858-02	

Note: Manufacturing process for all nuts listed: Stamped

MS21043-04	MN-19-04	NADC Report No.	Hi-Shear Corp.
MS21043-06	MN-19-06	305Q76025 of	2600 SkyPark Dr.
MS21043-08	MN-19-08	15 Oct 1976	Torrance, CA 90509
MS21043-3	MN-19-3		
			Plant: Same Address

Note: Nuts are forged.

MS21043-04	H41L-04	Report No.	Kaynar Technologies, Inc.
MS21043-06	H41L-06	NAMC-AML-AE	Kaynar Div.
MS21043-08	H41L-08	6201.40, Part XXIII	P.0. Box 3001
MS21043-3	H41-3	of 29 Jun 1981	800 S. State College Blvd.
MS21043-5	H41-5		Fullerton, CA 92634
MS21043-6	H41-6		
			Plant: Same address

Note: Manufacturing process for all nuts listed: Forged

MS21043-4	H41-4	Report No.	
		NAMC-AML-AE	
		6201.40, Part XX	
		of 10 May 1961	

Note: Manufacturing process for all nuts listed: Forged

MS21043-3	180000-3	NAWC Report	The Monadnock Company
		601Q9110 of	18301 East Arenth Ave.
		14 Feb 1992	City of Industry, CA 91749
			Plant: Same address
MS21043-4	180001-4	NAWC Report	
		601Q9302 of	
		5 Feb 1993	
MS21043-04	180001-04	NAWC Report	
		601Q9319 of	
		15 Nov 93	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21043-06	180001-06	NAWC Report 601Q9213 of 27 Aug 1993	
MS21043-08	180001-08	NAWC Report 601Q9208 of 15 June 1992	

Note: Manufacturing Process: Forged

MS21043-08 MS21043-3 MS21043-4 MS21043-5 MS21043-6	RH30C08 RH30C3 RH30C4 RH30C5 RH30C6	NADC Report 601Q8503 of 8 Apr 1985	Republic Fastener Manufacturing Corp. 1300 Rancho Conejo Blvd. Newbury Park, CA 91320 Plant: Same address

Note: 1. Manufacturing process: Forged

MS21043-04 MS21043-06 MS21043-3 MS21043-4	PLH-504 PLH-506 PLH-53 PLH-54	NADC Report No. 305Q3111 of 19 Oct 1983	Simmonds Mecaero Fasteners, Inc. 1734 Sequoia Avenue Orange, CA 92668 Plant:
MS21043-5	PLH-55	NADC Report 305Q83112 of 28 Nov 1983	Simmonds Usine De Champaissant 72110 Saint-Cosme En Vairais France
MS21043-08	PLH-508	NADC Report 601Q8401 of 24 Feb 1984	
MS21043-6	PLH-56	NADC Report 601Q8417 of 25 Oct 1984	

Note: 1. Manufacturing process: Cold formed
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance
FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals)
The contractor should include these provisions in every subcontract and purchase order.

MS21043-04 MS21043-06 MS21043-08 MS21043-3 MS21043-4 MS21043-5 MS21043-6	FN1014-440 FN1014-632 FN1014-832 FN1014-1032 FN1014-428 FN1014-524 FN1014-624	Report No. NAMC-AML-AE 6201.40, Part XIX of 9 May 1961	SPS Technologies Highland Ave. Jenkintown, PA 19046 Plant: Same address

Note: Manufacturing process for all nuts listed: Forged

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21043-04	LH3858-40	Report No.	
MS21043-06	LH3858-62	435Q9505	
MS21043-08	LH3858-82	31 Mar 1995	
MS21043-3	LH3858-02		
MS21043-4	LH3858-048		
MS21043-5	LH3858-054		
MS21043-6	LH3858-064		

Note: Manufacturing Process: Forged

MS21043-3	VN300-B-02	Report No.	VOI-SHAN
MS21043-4	VN300-B-048	NAMC-AML-140B	Fairchild Aerospace Fastener Div
		of 26 Mar 1962	2950 W. Lomita Blvd.
			Torrance, CA 90505-5103

Note: Manufacturing process for both nuts listed: Forged

Plant: Same address

MS21043-08	VN300-B-82	Report No.	
		NAEC-AML-16B7	
Note: Manufacturing process: Forged		of 29 May 1963	

MS21044 NUT, SELF-LOCKING, HEXAGON, REGULAR HEIGHT, 250 DEG F, 125 KSI Ftu AND 60 KSI Ftu

---

MS21044N04	F22NM-40	AMD Report No.	Abbott Interfast Corp.
MS21044N06	F22NM-62	MA769358 of	190 Abbott Drive
MS21044N08	F22NM-82	7 Feb 1969	Wheeling, IL 60090
MS21044N3	F22NM-02		
MS21044N4	F52NE-048		Plant: Same address
MS21044N5	F52NE-054		
MS21044N6	F52NE-064		
MS21044N7	F52NE-070U		
MS21044N8	F52NE-080		
MS21044N9	F52NE-098		
MS21044N10	F52NE-108		
MS21044N12	F52NE 126		
MS21044N14	F52NE-144		
MS21044N16	F52NE-162		

Note: 1. Manufacturing process: Machined or forged
2. Material: Zytel 101 (yellow color).

MS21044B06	Y92NM-632	Report No.	Greer Stop Nut, Inc.
MS21044B6	Y92NE-624	NAEC-AML-1918	481 McNally Drive
MS21044B7	Y92NE-720U	of 30 Mar 1964	Nashville, TN 37211
		and NAEC-AML ltr	
		M-62-BRS 10410(7701)	Plant: Same address
Note: Manufactur1ng process: Machined		of 13 Apr 1966	

MS21044B8	Y92NE-820	Report No.	
		NAEC-AML-2269	
Note: Manufacturing process: Machined		of 3 Sep 1968	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21044-C06	L79NM-632	Report No.
MS21044-B08	Y92NM-832	NAEC-AML-1935
MS21044-N7	F52NE-720U	of 24 Apr 1964
MS21044-N8	F52NE-820	

Note: Manufacturing process: Machined

MS21044-N08	F22NM-832	Report No.
MS21044-D4	NMJ-428	NAEC-AML-1941
MS21044-B5	Y92NE-524	of 4 May 1964
MS21044-D5	68NE-524	
MS21044-N5	F42NE-524	
MS21044-N6	F52NE-624	

Note: Manufacturing process: Machined

MS21044-N12	F52NE-1216	Report No.
MS21044-N10	F52NE-1018	NAEC-AML-2086
MS21044-N9	P52NE-918	of 25 Nov 1964
MS21044-D6	68NE-624	

Note: Manufacturing process: Machined except for
MS21044-N10, which can be machined or forged.

MS21044N3	F22NM-1032	Report No.
MS21044N4	F42NE-428	NAEC-AML-2480
MS21044N5	F42NE-524	of 5 Jul 1966
MS21044N6	F52NE-624	

Note: Manufacturing process: Forged

MS21044N14	F52NE-1414	AML Report No.
		78496-67
		of 15 Sep 1966

MS21044-N04	F22NM-440	Report No.
MS21044-D04	NMJ-440	NAEC-AML-1777
MS21044-B04	Y92NM-440	of 25 Oct 1963
MS21044-C04	L79NM-440	and NAEC-AML ltr
MS21044-N06	F22NM-632	M-62-BRS 10410(7701)
MS21044-D06	NMJ-632	of 13 Apr 1966
MS21044-N3	F22NM-1032	
MS21044-D3	NMJ-1032	
MS21044-B3	Y92NM-1032	
MS21044-C3	L79NM-1032	
MS21044-N4	F42NE-428	
MS21044-B4	Y92NE-428	
MS21044-C4	L79NE-428	

Note: Manufacturing process: Machined

MS21044D08	NMJ-832	Report No.
		NAEC-AML-2457
		of 10 May 1966

Note: Manufactur1ng process: Machined

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21044D8	68NE-820	Report No. NAEC-AML-1866 of 3 Feb 1964	
Note: Manufacturing process: Machined			
MS21044C08	L79NM-832	Report No. NAEC-AML-1916 of 18 Mar 1964	
Note: Manufacturing process: Machined			
MS21044D7	68NE-720U	Report No. NAEC-AML-1908 of 18 Mar 1964	
Note: Manufacturing process: Machined			
MS21044C5	L79NE-524	NADC Report No. 305Q79055 of 24 Aug 1979	
MS21044C6	L79NE-624		
MS21044C8	L79NE-820		
MS21044C10	L79NE-1018		
MS21044C12	L79NE-1216		
MS21044N16	F52NE-1612		
MS21044N20	F52NE-2012		
MS21044D10	68NE-1018	AML Report No. 78601-67 of 24 May 1967	
MS21044N8	F52NE-820	NAWCAD Report No. 435Q8905 of 11 MAR 1998	Greer Stop Nut, Inc. 481 McNally Drive Nashville, TN 37211 Plant: Same address
MS21044-N04	F22NM-40	NAEC-AML-2561 of 11 Jan 1967	MacLean-ESNA A MacLean-Fogg Co. 611 Country Club Road P. O. Box 988 Pocahontas, AR 72455
MS21044-N06	F22NM-62		
Note: Manufacturing process: Machined			
MS21044-N08	FF22NM-82		Plant: Same address
MS21044-N3	F22NM-02		
MS21044-N4	F42NE-048		
MS21044-N5	F42NE-054		
MS21044-N6	F52NE-064		
Note: Manufacturing process: Forged or machined			

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21044-N7	F52NE-070U	NAMC-AML-1496
MS21044-N8	F52NE-080	of 9 Aug 1962
MS21044-N9	F52NE-098	
MS21044-N10	F52NE-108	
MS21044-N12	F52NE-126	
MS21044-N14	F52NE-144	
MS21044-N16	F52NE-162	
MS21044-N18	F52NE-182	
MS21044-N20	F52NE-202	

Note: Manufacturing process: Forged or machined

MS21044N10	F52CE-108	NADC Report No. 305Q81067 of 25 Nov 1981

Note: Manufacturing process: Machined

MS21044-B04	Y92NM-40	NAMC-AML-1496
MS21044-B06	Y92NM-62	of 9 Aug 1962
MS21044-B08	Y92NM-82	
MS21044-B3	Y92NM-02	
MS21044-B4	Y92NE-048	
MS21044-B5	Y92NE-054	
MS21044-B6	Y92NE-064	
MS21044-B7	Y92NE-070U	
MS21044-B8	Y92NE-080	
MS21044-B9	Y92NE-098	
MS21044-B10	Y92NE-108	
MS21044-B12	Y92NE-126	
MS21044-B14	Y92NE-144	
MS21044-B16	Y92NE-162	
MS21044-B18	Y92NE-182	
MS21044-B20	Y92NE-202	
MS21044-D04	NMJ-40	
MS21044-D06	NMJ-62	
MS21044-D08	NMJ-82	
MS21044-D3	NMJ-02	
MS21044-D4	NMJ-048	
MS21044-D5	68NE-054	
MS21044-D6	68NE-064	
MS21044-D7	68NE-070U	
MS21044-D8	68NE-080	
MS21044-D9	68NE-098	
MS21044-D10	68NE-108	
MS21044-D12	68NE-126	
MS21044-D14	68NE-144	
MS21044-D16	68NE-162	
MS21044-D18	68NE-182	
MS21044-D20	68NE-202	
MS21044-E08	1804-82	
MS21044-E3	1804-02	
MS21044-E4	1804-048	
MS21044-E5	1804-054	
MS21044-E6	1804-064	
MS21044-E7	1804-070U	
MS21044-E8	1804-080	

Note: Manufacturing process for all nuts listed: Machined

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21044C04	79NM-40	NAEC-AML-1860	
MS21044C06	79NM-62	of 10 Feb 1964	
MS21044C08	79NM-82		
MS21044C3	79NM-02		
MS21044C4	79NE-048		
MS21044C5	79NE-054		
MS21044C6	79NE-064		
MS21044C7	79NE-070U		
MS21044C8	79NE-080		
MS21044C9	79NE-098		

Note: (1) Manufacturing process: Forged or machined
(2) All parts are passivated plus waxed

MS21044C10	79NE-108	NAEC-AML-2075	
MS21044C12	79NE-126	of 12 Nov 1964	
MS21044C14	79NE-144		
MS21044C16	79NE-162		
MS21044C18	79NE-182		
MS21044C20	79NE-202		

Notes: 1. Manufacturing process: Forged or machined
2. All parts are passivated Plus waxed

MS21044H04	75FS-440	Report No.	SPS Technologies
MS21044H06	75FS-632	NAEC-AML-1774	Highland Ave.
MS21044H08	75FS-832	of 31 Oct 1963	Jenkintown, PA 19046
MS21044H3	75FS-1032		
MS21044H4	75FS-428		Plant: Same address
MS21044H5	75FS-524		
MS21044H6	75FS-624		
MS21044H8	75FS-820		
MS21044H9	75FS-918		
MS21044H10	75FS-1018		
MS21044H12	75FS-1216		
MS21044H14	75FS-1414		

Note: Manufacturing process: Machined

MS21044N5	PA0524-SCN3	AML Report No.
MS21044N6	PA0624-SCN3	78373-66 of
		1 Jul 1965

Note: Manufacturing process: Machined

MS21044-N04	PA0440-SCN3	Report No.
MS21044-N06	PA0632-SCN3	NAEC-AML-1834
MS21044-N08	PA0832-SCN3	of 11 Dec 1963
MS21044-N3	PA1032-SCN3	and NAEC-AML ltr
MS21044-N4	PA0428-SCN3	M-62-BRS:ma 10410(7052)
		of 25 May 1966

Note: Manufacturing process: Machined

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21045 NUT, SELF-LOCKING, HEXAGON, REGULAR HEIGHT, 450 DEG F, 125 KSI Ftu

MS21045-04	F1801-40	NAMC-AML-1514	ESNA
MS21045-06	F1801-62	of 3 Dec 1962*	Division of Harvard Industries
MS21045-08	F1801-82		
MS21045-3	F1801-02		
MS21045-4	F1801-048		
MS21045-5	F1801-054		
MS21045-6	F1801-064		
MS21045-7	F1801-070U		
MS21045-8	F1801-080		
MS21045-9	F1801-098		
MS21045-10	F1801-108		
MS21045-12	F1801-126		
MS21045-14	F1801-144		
MS21045-16	F1801-162		

Note: Manufacturing process for all nuts listed: Machined

MS21045L04	RM1801-40	NAEC-AML-2467
MS21045L06	RM1801-62	of 2 Jun 1966*
MS21045L08	RM1801-82	
MS21045L3	RM1801-02	
MS21045L4	RM1801-048	
MS21045L5	RM1801-054	
MS21045L6	RM1801-064	
MS21045L7	RM1801-070U	
MS21045L9	RM1801-098	
MS21045L10	RM1801-108	
MS21045L12	RM1801-126	
MS21045L14	RM1801-144	
MS21045L16	RM1801-162	

MS21045C08	SM1813-82	NAEC-AML-1886
MS21045C3	SM1813-02	of 19 Feb 1964*
MS21045C4	SM1813-048	
MS21045C5	SM1813-054	
MS21045C6	SM1813-064	

Note: 1. Manufacturing process: Machined
2. All parts are passivated Plus molybdenum disulfide (ESNALUBE 382).

MS21045-8	F52VE-080	AML Report No.
MS21045L8	RM52VE-080	78468-67 of
MS21045C8	RM79VE-080	4 Apr 1967*

MS21045C3	SMLH1813-02	AMD Report No.
MS21045C4	SMLH1813-048	MA669013 of
MS21045C5	SMLH1813-054	21 Nov 1968*

Note: 1. Finish: Passivated Plus Moly (ESNALUBE 382).
2. Manufacturing process: Forged

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21045C7	SM1813-070U	AMD Report No.
MS21045C8	SM1813-080	MA669030 of
MS21045C9	SM1813-098	21 Nov 1968*
MS21045C10	SM1813-108	

Note: 1. Manufacturing process: Machined or forged
2. Passivated Plus Molybdenum disulfide (ESNALUBE 382).

MS21045-08	LFLH1801-82 (Machined)	AMD Report No.
MS21045-6	LFLH1801-064	MA770504A of
MS21045-7	LFLH1801-070U	25 Nov 1969*
MS21045L08	RMLH1801-82	
MS21045L6	RMLH1801-064 (Forged)	
MS21045L7	RMLH1801-070U	
MS21045C08	SMLH1813-82 (Forged)	
MS21045L3	RMLH1801-02	NAEC-AML-2060
MS21045L4	RMLH1801-048	of 3 Nov 1964*
MS21045L5	RMLH1801-054	
MS21045-3	LFLH1801-02	
MS21045-4	LFLH1801-048	
MS21045-5	LFLH1801-054	

Note: 1. Manufacturing process: Forged or machined
2. RM prefix designates molybdenum disulfide dry film lubricant.
3. LF prefix designates Carbowax.

MS21045L8	RM1801-080	NAEC-AML-2203 of 24 May 1965*

*MUST BE MANUFACTURED AFTER 10 MAY 1994 DISC-E-94130 LTR

Note: 1. Manufacturing process: Machined
2. "RM" designates molybdenum disulfide dry film lubricant as approved by NAMATCEN ltr XM-621-FTR:mlp J9 (1423) of 20 July 1959.

MS21045-04	F22MXM-440	Report No.	Greer Stop Nut, Inc.
MS21045-06	F22MXM-632	305Q81068 of	481 McNally Drive
MS21045-3	F22MXM-1032	9 Dec 1981	Nashville, TN 37211
MS21045-4	F22MXE-428		
MS21045-5	F22MXE-524	Plant: Same address	
MS21045-6	F22MXE-624		
MS21045-7	F52MXE-720U		
MS21045-8	F52MXE-820		
MS21045-9	F52MXE-918		
MS21045-10	F52MXE-1018		
MS21045-12	F52MXE-1216		
MS21045-14	F52MXE-1414		
MS21045-16	F52MXE-1612		
MS21045-18	F52MXE-1812		
MS21045-20	F52MXE-2012		

Note: Manufactured process: Forged or machined for 3/4-16 size and smaller; machined for 7/8-14 size and larger.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21045-08	F22MXM-832	Report No. 305Q83094 of 10 Mar 1983	

Note: Manufacturing process:Forged or machined

MS21045L04 MS21045L06 MS21045L08	H55-04 H55-06 H55-08	Report No. NAEC-AML-1605 of 6 Feb 1963	Kaynar Technologies, Inc. Kaynar Div. P.0. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
MS21045L3 MS21045L4	H55-3 H55-4	Report No. NAEC-AML-1671 of 10 May 1963	

Note: 1. Manufacturing process for all nuts: Forged
2. Molybdenum disulfide dry film lubricant as approved by BUAER ltr AER-AE-6337/25 of 2 March 1959.

MS21045C08 MS21045C5	H57-08 H57-5	Report No. NAEC-AML-1892 of 24 Apr 1964	
MS21045C04 MS21045C06	H57-04 H57-06	Report No. NAEC-AML-1931 of 24 Apr 1964	
MS21045C3 MS21045C4	H57-3 H57-4	Report No. NAEC-AML-1990 of 6 Jul 1964	

Note: 1. Manufacturing process: Forged
2. Lubricant: Molybdenum disulfide dry film lubricant as approved by BUAER ltr AER-AE-6337/25 of 2 March 1959.

MS21045-04 MS21045-06 MS21045-08 MS21045-3 MS21045-4	H55-04CN H55-06CN H55-08CW H55-3CW H55-4CW	Report No. NAEC-AML-1998 of 3 Aug 1964	

Note: 1. Manufacturing process: Forged
2. Lubricant: Kaywax.

MS21045-10	H55-10CW	AML Report No. 78601-67 of 24 May 1967	
MS21045-8	H55-8CN	AMD Report No. MA769434B of 4 Mar 1970	

NOTE: 1. Forged
2. "CW": Cad plated and Kaywax added.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21045L5(4)(2)	H55-5	AMD Report No.	
MS21045-5(2)(3)	H55-5CW	MA769434A of	
MS21045L6(2)(4)	H55-6	19 Feb 1970	
MS21045-6(3)(2)	H55-6CN		
MS21045L7(1)(4)	H55-7		
MS21045C6(5)(1)	H57-6		

Note: 1. Machined.
2. Forged.
3. "CW": Cad plated with Kaywax.
4. Cad plated with Kaylube.
5. Kaylube only.

MS21045C3	RH50C3M	NADC Report No.	Republic Fastener Mfg. Corp.
MS21045C4	RH50C4M	305Q7904B of	1300 Rancho Conejo Blvd.
MS21045C5	RH50C5M	15 Feb 1979	Newbury Pk., CA 91320
MS21045C6	RH50C6M		
			Plant: Same address

Note: Parts machined or forged.

MS21045-4	YE3180	Report No.	Russell, Burdsall &
MS21045-5	YE3181	NAEC-AML-1896	Ward Corp.
MS21045-6	YE3182	of 25 Feb 1964	5970 Heisley Rd.
MS21045-7	YE3183		Mentor, OH 44060
MS21045-8	YE3184		
			Plant: 800 Mogadore Rd.
			Kent, OH 44240

Note: 1. Manufacturing process: Machined
2. Lubricant: Ferrocote #348

MS2104S-4	YE3180	Report No.	
MS21045-5	YE3181	NAEC-AML-78418-66	
MS21045-6	YE3182	of 10 Oct 1966	
MS21045-7	YE3183		
MS21045-8	YE3184		

Note: 1. Manufacturing process: Cold forged
2. Lubrication: Ferrocote #348

MS21045-9	YE3185	AML Report No.	
MS21045-10	YE3186	78397-66 of	
MS21045-12	YE3187	24 Feb 1966	
MS21045-14	YE3188		

Note: 1. Manufacturing process: MS21045-9 machined or Cold forged.
All others machined.
2. Lubrication: Ferrocote #348

MS21045-3	YE3179	AMD Report No.	
		MA768792 of	
		12 Dec 1967	

Note: 1. Manufacturing process: Cold forged
2. Lubricant: Ferrocote #348

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21045C3	YE3219	AMD Report No.	
MS21045C4	YE3220	MA768848 of	
MS21045C5	YE3221	19 Jun 1968	
MS21045C6	YE3222		
MS21045C7	YE3223		
MS21045C8	YE3224		

Note: 1. Manufacturing process: Machined
2. Lubricant: Dry Film - "VYDAX" "AR"

MS21045L3	YE3199	AMD Report No.	
MS21045L4	YE3200	MA770517 of	
MS21045L5	YE3201	18 Dec 1970	

MS21045L6	YE3202	AMD Report No.	
MS21045L8	YE3204	MA770517 of	
MS21045L10	YE3206	18 Dec 1970	

Note: 1. "L" denotes "VYDAX": "AR" dry film.
2. Ferrocote #348 Lubricant.

MS21045L08	YE3198	Report No.	
MS21045L7	YE3203	MA772002 of	
		27 Aug 1971	

Note: 1. "L" denotes "VYDAX": "AR" dry film.
2. Lubricant: Ferrocote #348.

MS21045L3	SL2374-3	NADC Report No.	Shur-Lok Corp.
MS21045L4	SL2374-4	305Q77036 of	P.0. Box 19584
MS21045L5	SL2374-5	5 May 1977	2541 White Road
MS21045L6	SL2374-6		Irvine, CA 92713
MS21045L7	SL2374-7		
MS21045L8	SL2374-8		Plant: Same address

Note: 1. Manufactured machined or forged.
2. Dry Film, "TIO-LUBE 460."
3. "L" designates dry film

MS21045C06	PZ-506M	NADC Report	Simmonds Mecaero
MS21045C3	P2-53M	601Q8606 of	Fasteners, Inc.
MS21045C4	PZ-54M	12 May 1986	1734 Sequoia Avenue
			Orange, CA 92668
			Plant:
			Simmonds
			Usine De Champaissant
			72110 Saint-Cosme En Vairais
			France

Note: 1. Manufacturing process: Screw cutting
2. Lubricant: QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21045-04	27FH-440	Report No.	SPS Technologies
MS21045-06	27FH-632	NAMC-AML-1567	Highland Ave.
MS21045-08	27FH-832	of 3 Dec 1962	Jenkintown, PA 19046
MS21045-3	27FH-1032		
MS21045-4	27FH-428		Plant: Same address
MS21045-5	27FH-524		
MS21045-6	27FH-624		
MS21045-7	27FH-720UN		
MS21045-8	27FH-820		
MS21045-9	37FH-918		
MS21045-10	37FH-1018		
MS21045-12	37FH-1216		
MS21045-14	37FH-1414		
MS21045-16	37FH-1612		
MS21045-18	37FH-1812		
MS21045-20	37FH-2012		

Note: Manufacturing process for all nuts listed: Machined

MS21045C04	58FH-440	Report No.
MS21045C06	58FH-632	NAEC-AML-2112
MS21045C08	58FH-832	of 4 Jan 1965
MS21045C3	58FH-1032	
MS21045C4	58FH-428	
MS21045C5	58FH-524	
MS21045C6	58FH-624	

Note: 1. Manufacturing process: Machined
2. Molybdenum disulfide dry film lubricant as previously approved by NAMATCEN ltr XM-621-FTR:mlp of 29 July 1959.

MS21045C7	SM1813-070U	NAWCADWAR
	58FH-720UN	Report No.
		435Q9516 of
		27 Sep 1995

Notes: 1. Manufacturing Process: Machined
2. Lubricant: Everlube 620C per MIL-L-46010, Type I

MS21045C16	93885-1612	Report No.
		601Q9401 of
		23 Feb 94

Note: 1. Manufacturing Process: Machined
2. Dry Film Lubricant: Everlube 260C per MIL-L-46010, Type I

MS21045L4	RM1801-048	NAWCADWAR
	28FH-428	Report No.
		435Q9522 of
		26 Oct 1995

MS21045L5	28FH-524	Report No.
	RM1801-054	435Q9502 of
		21 Mar 1995

Notes: 1. Manufacturing Process: Forged
2. Lubricant: Everlube 620C per MIL-L-46010, Type I

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21045L8	SPS28GH-820	AMD Report No. MA769379 of 7 Feb 1969

Note: 1. Manufacturing process: Machined
2. Molybdenum disulfide dry film lubricant as approved by NAVMATCEN ltr XM-621-FTR:mlp.

MS21045L4	SPS28GH-428	AMD Report No. MA669025 of 25 Feb 1969

Note: Manufacturing process: Machined or forged

MS21045-04	27GH-440	AMD Report No. MA796417 of 17 Jul 1969
MS21045-06	27GH-632	
MS21045-08	27GH-832	
MS21045-3	27GH-1032	

MS21045-4	27GH-428	AMD Report No. MA796417 of 17 Jul 1969
MS21045-5	27GH-524	
MS21045-6	27GH-624	
MS21045-7	27GH-720	
MS21045-8	27GH-820	

Note: 1. Manufacturing process: Machined or forged
2. Cadmium plated.

MS21045C10	SM1813-108 58FH-1018	NAWCADWAR Report No. 435Q9523 of 6 Nov 1995

Notes: 1. Manufacturing Process: Machined
2. Lubricant: Everlube 620C per MIL-L-46010, Type I

MS21045C12	58FH-1216	Report No. 305Q82073 of 18 Feb 1982
MS21045L12	38FH-1216	

Note: Manufacturing process. Forged for MS21045L12, machined for others

---

MS21045L16	38FH-1612	Report No. 305Q83107 of 1 Sep 1983

Note: Manufacturing process: Machined

MS21045L08	28FH-832	NAWC Report 601Q9210 of 2 Sep 1992
MS21450L9	38FH-918	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21045L10	38FH-1018	NAWC Report 601Q9406 of 28 Oct 1994

Notes: 1. Manufacturing Process: Forged
2. Lubricant: Everlube 620C per MIL-L-46010, Type I

MS21045-04	F1801-40	Report No. 435Q9505 of 31 Mar 1995
MS21045-04S	F1801-40	
MS21045-06	F1801-62	
MS21045-06S	F1801-62	
MS21045-08	F1801-82	
MS21045-08S	F1801-82	
MS21045-3	F1801-02	
MS21045-3S	F1801-02	
MS21405-4	F1801-048	
MS21045-4S	F1801-048	
MS21045-5	F1801-054	
MS21045-5S	F1801-054	
MS21045-6	F1801-064	
MS21045-6S	F1801-064	
MS21045-7	F1801-070U	
MS21045-7S	F1801-070U	
MS21045-8	F1801-080	
MS21045-8S	F1801-080	
MS21045-9	F1801-098	
MS21045-9S	F1801-098	
MS21045-10	F1801-108	
MS21045-10S	F1801-108	
MS21045-12	F1801-126	
MS21045-12S	F1801-126	
MS21045-14	F1801-144	
MS21045-14S	F1801-144	
MS21045-16	F1801-162	
MS21045-16S	F1801-162	

Notes: Manufacturing Process: Machined for MS21045-16 and MS21045-16S, Machined or Forged for all others

---

MS21045-08E	LFLH1801-82
MS21045-3E	LFLH1801-02
MS21045-4E	LFLH1801-048
MS21045-5E	LFLH1801-054
MS21045-6E	LFLH1801-064
MS21045-7E	LFLH1801-070U

Notes: Manufacturing Process: Machined or Forged

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21045L08	RM1801-82
MS21045L08S	RM1801-82
MS21045L3	RM1801-02
MS21045L3S	RM1801-02
MS21045L6	RM1801-064
MS21045L6S	RM1801-064
MS21045L7	RM1801-070U
MS21045L7S	RM1801-070U
MS21045L8	RM1801-080
MS21045L8S	RM1801-080
MS21045L9	RM1801-098
MS21045L9S	RM1801-098
MS21045L10	RM1801-108
MS21045L10S	RM1801-108
MS21045L12	RM1801-126
MS21045L12S	RM1801-126
MS21045L16	RM1801-162
MS21045L16S	RM1801-162

MS21045C08	SM1813-82
MS21045C3	SM1813-02
MS21045C4	SM1813-048
MS21045C5	SM1813-054
MS21045C6	SM1813-064

Notes: 1. Manufacturing Process: Machined or Forged
2. Finish: Passivated Plus Molybdenum Disulfide (Everlube 620C)

MS21045C8	58FH-820 SM1813-080	NAWCAD Report No. 435Q9803 of 13 FEB 1998	SPS Technologies Highland Ave. Jenkintown, PA 19046
MS21045C9	58FH-918 SM1813-098		Plant: Same address
MS21045L18	38FH-1812	NAWCAD Report No. 435Q9819 of 9 JUL 1998	SPS Technologies Highland Ave. Jenkintown, PA 19046 Plant: Same address

---

MS21046 NUT, SELF-LOCKING HEXAGON, REGULAR HEIGHT 800 DEG F, 125 KSI, Ftu

---

MS21046C4	BH21046-4	Report No. 305Q82076 of 3 May 1982	Bristol Industries 630 E. Lambert Rd. P.0. Box 630 Brea, CA 92621
Note: Manufacturing process: Forged			Plant: Same address

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21046C04	1803-40	NAMC-AML-1423	ESNA
MS21046C06	1803-62	of 15 June 1962*	Division of Harvard Industries
MS21046C08	1803-82	and XM-62-MJZ:jem	
MS21046C6	1803-064	10410(8886) of	
MS21046C7	1803-070U	16 Aug 1963*	
MS21046C8	1803-080		
MS21046C9	1803-098		
MS21046C10	1803-108		

MS21046C3	1803-02		
MS21046C4	1803-048		
MS21046C5	1803-054		

MS21046C3	LH1803-02	NAEC-AML-1922	
MS21046C4	LH1803-048	of 7 Apr 1964*	
MS21046C5	LH1803-054		

Note: Manufacturing process: Forged

MS21046C12	1803-126	NAEC-AML-1942	
MS21046C14	1803-144	of 29 Apr 1964*	

Note: Manufacturing process: Machined

MS21046C6	LH1803-064	AMD Report No.	
MS21046C7	LH1803-070U	MA77050A of	
		21 Apr 1970*	
		*MUST BE MANUFACTURED AFTER 10 MAY 1994 DISC-E-94130 LTR	

MS21046C04	70MXM-440	Report No.	Greer Stop Nut, Inc.
MS21046C06	70MXM-632	601Q9005	481 McNally Drive
MS21046C08	70MXM-832	of 22 Mar 90	Nashville, TN 37211
MS21046C3	70MXM-1032		
MS21046C4	70MXE-428		Plant: Same address
MS21046C5	70MXE-524		
MS21046C6	70MXE-624		
MS21046C7	70MXE-720U		
MS21046C8	70MXE-820		

MS21046C06	H56-06	Report No.	Kaynar Technologies, Inc.
		NAMC-AML-1575	Kaynar Div.
		of 12 Dec 1962	P.O. Box 3001
			800 S. State College Blvd
			Fullerton, CA 92634
Note: Manufacturing process: Forged			Plant: Same address

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21046C04	H56-04	Report No.	
MS21046C08	H56-08	NAEC-AML-1611	
		of 29 Jan 1963	

Note: Manufacturing process: Forged

MS21046C3	H56-3	Report No.	
		NAMC-AML-1506	
		of 13 Sep 1962	

Note: Manufacturing process: Forged

MS21046C4	H56-4	Report No.	
		NAMC-AML-1561	
		of 14 Nov 1962	

Note: Manufacturing process: Forged

MS21046C5	H56-5	Report No.	
		NAEC-AML-1744	
		of 30 Aug 1963	

Note: Manufacturing process: Forged

MS21046C3	RH40C3	NADC Report No.	Republic Fastener Mfg. Corp.
MS21046C4	RH40C4	305Q79048 of	1300 Rancho Conejo Blvd
MS21046C5	RH40C5	15 Feb 1979	Newbury Park, CA 91320
MS21046C6	RH40C6		
			Plant: Same address

Note: Parts machined or forged.

MS21046C3	YE3702	AMD Report No.	Russell, Burdsall &
MS21046C4	YE3703	MA769406 of	Ward Corp.
MS21046C6	YE3705	27 May 1969	5970 Heisley Rd.
MS21046C7	YE3706		Mentor, OH 44060
MS21046C8	YE3707		
			Plant: 800 Mogadore Rd.
			Kent, OH 44240

Note: 1. Manufacturing process: Machined
2. Finish: Passivated-silver plated

MS21046C04	59FH-440	Report No.	SPS Technologies
MS21046C06	59FH-632	NAEC-AML-1486	Highland Ave.
MS21046C08	59FH-832	of 22 Jan 1963	Jenkintown, PA 19046
MS21046C3	59FH-1032		
MS21046C4	59FH-428		Plant: Same address
MS21046C5	59FH-524		

MS21046C6	59FH-624	Report No.	
MS21046C7	59FH-720	NAEC-AML-1656	
MS21046C8	59FH-820	of 4 Apr 1963	
MS21046C9	59FH-918		
MS21046C10	59FH-1018		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21046C12	59FH-1216	Report No.
MS21046C14	59FH-1414	NAEC-AML-1656
MS21046C16	59FH-1612	of 4 Apr 1963

Note: Manufacturing process: Machined

MS21046C16	93360-1612	NAWC Report 601Q9416 of 6 Dec 1994

Note: 1. Manufacturing Process: Machined
2. Lubricant: Ferrocote 5815 (soluble lubricant)

MS21046C20	93360-2012	NAWC Report 601Q9301 of 7 Jan 1993

Note: Manufacturing Process: Machined

MS21046C04	1803-40	Report No.
MS21046C04S	1803-40	435Q9505 of
MS21046C06	1803-62	31 Mar 1995
MS21046C06S	1803-62	
MS21046C08	1803-82	
MS21046C08S	1803-82	
MS21046C3	1803-02	
MS21046C3S	1803-02	
MS21046C4	1803-048	
MS21046C4S	1803-048	
MS21046C5	1803-054	
MS21046C5S	1803-054	
MS21046C6	1803-064	
MS21046C6S	1803-064	
MS21046C7	1803-070U	
MS21046C7S	1803-070U	
MS21046C8	1803-080	
MS21046C8S	1803-080	
MS21046C9	1803-098	
MS21046C9S	1803-098	

MS21046C10	1803-108	Report No.
MS21046C10S	1803-108	435Q9505 of
MS21046C12	1803-126	31 Mar 1995
MS21046C12S	1803-126	
MS21046C14	1803-144	
MS21046C14S	1803-144	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21047 NUT, SELF-LOCKING, PLATE, TW0 LUG, LOW HEIGHT, STEEL, 125 KSI Ftu, 450 DEG F

MS21047-04	T2S440	NAWC Report	Boots Nut Division
MS21047-06	T2S632	601Q9004 of	Republic Fasteners
MS21047-08	T2S832	22 Jan 90	1300 Rancho Conejo Blvd
MS21047-3	T2S1032		Newbury Park, CA 91320
MS21047-4	T2S428		
MS21047-5	T2S524		Plant: Same address
MS21047-6	T2S624		
MS21047L04	T2S440		
MS21047L06	T2S632		
MS21047L08	T2S832		
MS21047L3	T2S1032		
MS21047L4	T2S428		
MS21047L5	T2S524		
MS21047L6	T2S624		
MS21047-04K	T2S440BCCPC		
MS21047-06K	T2S632BCCPC		
MS21047-08K	T2S832BCCPC		
MS21047-3K	T2S1032BCCPC		
MS21047-4K	T2S428BCCPC		
MS21047-5K	T2S524BCCPC		
MS21047L04K	T2S440BC		
MS21047L06K	T2S632BC		
MS21047L08K	T2S832BC		
MS21047L3K	T2S1032BC		
MS21047L4K	T2S428BC		
MS21047L5K	T2S524BC		

Notes: Manufacturing Process: Forged

MS21047-04	T2S440CPC	Report No.	Cherry/Textron
MS21047-06	T2S632CPC	NAEC-AML-2428	Cherry Div. of
MS21047-08	T2S832CPC	of 15 Mar 1966	Textron Inc.
MS21047-3	T2S1032CPC		P.0. Box 2157
MS21047-4	T2S428CPC		1224 East Warner Ave.
MS21047-5	T2S524CPC		Santa Ana, CA 92707
MS21047-6	T2S624CPC		
MS21047L04	T2S440		Plant: Same address
MS21047L06	T2S632		
MS21047L08	T2S832		
MS21047L3	T2S1032		
MS21047L4	T2S428		
MS21047L5	T2S524		
MS21047L6	T2S624		
MS21047-04K	T2S440BCCPC		
MS21047-06K	T2S632BCCPC		
MS21047-08K	T2S832BCCPC		
MS21047-3K	T2S1032BCCPC		
MS21047-4K	T2S428BCCPC		
MS21047-5K	T2S524BCCPC		
MS21047L04K	T2S440BC		
MS21047L06K	T2S632BC		
MS21047L08K	T2S832BC		
MS21047L3K	T2S1032BC		
MS21047L4K	T2S428BC		
MS21047L5K	T2S524BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21047-04	F52LHTA51-40	NAEC-AML-2429	ESNA
MS21047-06	F52LHTAS1-62	of 15 Mar 1966*	Division of Harvard Industries
MS21047-08	F52LHTA51-A-82		
MS21047-3	F52LHTA51-A-02		
MS21047-4	F52LHTA51-A-048		
MS21047-5	F52LHTA51-054		
MS21047-6	F52LHTA51-B-064		
MS21047-6	F52LHTA51-064		
MS21047L04	RM52LHTA51-40		
MS21047L06	RM52LHTA51-62		
MS21047L08	RM52LHTA51-A-82		
MS21047L3	RM52LHTA51-A-02		
MS21047L4	RM52LHTA51-A-048		
MS21047L5	RM52LHTA51-054		
MS21047L6	RM52LHTA51-B-064		
MS21047L6	RM52LHTA51-064		
MS21047-04K	F52LHTA51-40BC		
MS21047-06K	F52LHTA51-62BC		
MS21047-08K	F52LHTA51-A-82BC		
MS21047-3K	F52LHTA51-A-02BC		
MS21047-4K	F52LHTA51-A-048BC		
MS21047-5K	F52LHTA51-054BC		
MS21047L04K	RM52LHTA51-40BC		
MS21047L06K	RM52LHTA51-62BC		
MS21047L08K	RM52LHTA51-A-82BC		
MS21047L3K	RM52LHTA51-A-02BC	*MUST BE MANUFACTURED	
MS21047L4K	RM52LHTA51-A-048BC	AFTER 10 MAY 1994	
MS21047L5K	RM52LHTA51-054BC	DISC-E-94130 LTR	

MS21047-04	K1000-04CW	Report No.	Kaynar Technologies, Inc.
MS21047-06	K1000-06CW	NAEC-AML-2474	Kaynar Div.
MS21047-08	K1000-08CW	of 15 Jun 1966	P. O. Box 3001
MS21047-3	K1000-3CW		800 S. State College Blvd.
MS21047-4	K1000-4CW		Fullerton, CA 92634
MS21047-5	K1000-5CW		
MS21047-6	K1000-6CW		Plant: Same address
MS21047-04K	K1000-04BCCW		
MS21047-06K	K1000-06BCCW		
MS21047-08K	K1000-08BCCW		
MS21047-3K	K1000-3BCCW		
MS21047-4K	K1000-4BCCW		
MS21047-5K	K1000-5BCCW		
MS21047L04	K1000-04		
MS21047L06	K1000-06		
MS21047L08	K1000-08		
MS21047L3	K1000-3		
MS21047L4	K1000-4		
MS21047L5	K1000-5		
MS21047L6	K1000-6		
MS21047L04K	K1000-04BC		
MS21047L06K	K1000-06BC		
MS21047L08K	K1000-08BC		
MS21047L3K	K1000-3BC		
MS21047L4K	K1000-4BC		
MS21047L5K	K1000-5BC		

MS21047L7	K1000-7	Report No. 305Q83097 of 22 Mar 1983	

Note: Manufacturing process: Machined

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21047-04	R2000X04	Report No.	Republic Fastener Mfg. Corp.
MS21047L04	R2000A04	305Q73001 of	1300 Rancho Conejo Blvd.
MS21047-04K	R2000X04K	6 Feb 1973	Newbury Park, CA 91320
MS21047L04K	R2000A04K		
MS21047-06	R2000X06		Plant: Same address
MS21047L06	R2000A06		
MS21047-06K	R2000X06K		
MS21047L06K	R2000A06K		
MS21047-08	R2000X08		
MS21047L08	R2000A08		
MS21047-08K	R2000X08K		
MS21047L08K	R2000A08K		
MS21047-3	R2000X3		
MS21047L3	R2000A3		
MS21047-3K	R2000X3K		
MS21047L3K	R2000A3K		
MS21047-4	R2000X4		
MS21047L4	R2000A4		
MS21047-4K	R2000X4K		
MS21047L4K	R2000A4K		
MS21047-5	R2000X5		
MS21047L5	R2000A5		
MS21047-5K	R2000X5K		
MS21047L5K	R2000A5K		

Note: "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124.

MS21047-6	R2000X6	Report No.	
MS21047L6	R2000A6	305Q83088 of	
		26 Jan 1983	

MS21047-04	12600NM-40	Report No.	SPS Technologies
MS21047-06	12600NM-62	NAEC-AML-2429	2701 S. Harbor Blvd.
MS21047-08	12600NM-82	of 15 Mar 1966	Santa Ana, CA 92702
MS21047-3	12600NM-02		
MS21047-4	12600NM-048		Plant: Same address
MS21047-5	12600NM-054		
MS21047-6	12600NM-064		
MS21047L04	12600-40		
MS21047L06	12600-62		
MS21047L08	12600-82		
MS21047L3	12600-02		
MS21047L4	12600-048		
MS21047L5	12600-054		
MS21047L6	12600-064		
MS21047-04K	12600NM-40BC		
MS21047-06K	12600NM-62BC		
MS21047-08K	12600NM-82BC		
MS21047-3K	12600NM-02BC		
MS21047-4K	12600NM-048BC		
MS21047-5K	12600NM-054BC		
MS21047L04K	12600-40BC		
MS21047L06K	12600-62BC		
MS21047L08K	12600-82BC		
MS21047L3K	12600-02BC		
MS21047L4K	12600-048BC		
MS21047L5K	12600-054BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21047L3	G-93M	NADC Report No.	Simmonds Mecaero
MS21047L3K	G-93MK	305Q83112 of	Fasteners, Inc.
MS21047L4	G-94M	28 Nov 1983	1734 Sequoia Avenue
MS21047L4K	G-94MK		Orange, CA 92668
			Plant:
MS21047L08	G-908M	305Q83111 of	Simmonds
MS21047L08K	G-908MK	19 Oct 1983	Usine De Champaissant
MS21047-3	G-93	601Q8407 of	72110 Saint-Cosme En Vairais
MS21047-4	G-94	20 Apr 1984	France

Note: 1. Manufacturing process: Cold formed
2. Lubricant: (For Government Designation With "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordanc FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals The contractor should include these provisions in every subcontract and purchase order.

MS21047-08	G-908	NADC Report
MS21047-08K	G-908K	601Q8502 of
		11 Mar 1985

MS21047-06	G-906	NADC Report
MS21047-06K	G-906K	601Q8510 of
MS21047L06	G-906M	10 Jun 1985
MS21047L06K	G-906MK	

Note: 1. Manufacturing process: Cold formed
2. Lubricant: (For Government Designation With "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordanc FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals The contractor should include these provisions in every subcontract and purchase order.

MS21047-04	VN102-C1-40	Report No.	VOI-SHAN
MS21047-06	VN102-C1-62	NAEC-AML-2425	Fairchild Aerospace Fastener Div
MS21047-08	VN102-C1-82	of 15 Mar 1966	2950 W. Lomita Blvd.
MS21047-3	VN102-C1-02		Torrance, CA 90505-5103
MS21047-4	VN102-C1-048		
MS21047-5	VN102-C1-054		Plant: Same address
MS21047-6	VN102-C1-064		
MS21047L04	VN102-A1-40		
MS21047L06	VN102-A1-62		
MS21047L08	VN102-A1-82		
MS21047L3	VN102-A1-02		
MS21047L4	VN102-A1-048		
MS21047L5	VN102-A1-054		
MS21047L6	VN102-A1-064		
MS21047-04K	VN102-C2-40		
MS21047-06K	VN102-C2-62		
MS21047-08K	VN102-C2-B2		
MS21047-3K	VN102-C2-02		
MS21047-4K	VN102-C2-048		
MS21047-5K	VN102-C2-054		
MS21047L04K	VN102-A2-40		
MS21047L06K	VN102-A2-62		
MS21047L08K	VN102-A2-82		
MS21047L3K	VN102-A2-02		
MS21047L4K	VN102-A2-048		
MS21047L5K	VN102-A2-054		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21048 NUT, SELF-LOCKING, PLATE, TW0 LUG, LOW HEIGHT, CRES, 125 KSI Ftu, 450 DEG F & 800 DEG F

MS21048-04	T2C440	NAWC Report	Boots Nut Division
MS21048-06	T2C632	601Q9004 of	Republic Fasteners
MS21048-08	T2C832	22 Jan 90	1300 Rancho Conejo Blvd
MS21048-3	T2C1032		Newbury Park, CA 91320
MS21048-4	T2C428		
MS21048-5	T2C524		Plant: Same address
MS21048-6	T2C624		
MS21048-04K	T2C440BC		
MS21048-06K	T2C632BC		
MS21048-08K	T2C832BC		
MS21048-3K	T2C1032BC		
MS21048-4K	T2C428BC		
MS21048-5K	T2C524BC		
MS21048-04W	T2C440P		
MS21048-06W	T2C632P		
MS21048-08W	T2C832P		
MS21048-3W	T2C1032P		
MS21048-4W	T2C428P		
MS21048-5W	T2C524P		
MS21048-6W	T2C624P		
MS21048L04	T2C440M		
MS21048L06	T2C632M		
MS21048L08	T2C832M		
MS21048L3	T2C1032M		
MS21048L4	T2C428M		
MS21048L5	T2C524M		
MS21048L6	T2C624M		
MS21048L04K	T2C440BCM		
MS21048L06K	T2C632BCM		
MS21048L08K	T2C832BCM		
MS21048L3K	T2C1032BCM		
MS21048L4K	T2C428BCM		
MS21048L5K	T2C524BCM		
MS21048L04W	T2C440PM		
MS21048L06W	T2C632PM		
MS21048L08W	T2C832PM		
MS21048L3W	T2C1032PM		
MS21048L4W	T2C428PM		
MS21048L5W	T2C524PM		
MS21048L6W	T2C624PM		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21048-04	T2C440	Report No.	Cherry/Textron
MS21048-06	T2C632	NAEC-AML-2428	Cherry Div. of Textron Inc.
MS21048-08	T2C832	of 15 Mar 1966	P.0. Box 2157
MS21048-3	T2C1032		1224 East Warner Ave.
MS21048-4	T2C428		Santa Ana, CA 92707
MS21048-5	T2C524		
MS21048-6	T2C624		Plant: Same address
MS21048-04K	T2C440BC		
MS21048-06K	T2C632BC		
MS21048-08K	T2C832BC		
MS21048-3K	T2C1032BC		
MS21048-4K	T2C428BC		
MS21048-5K	T2C524BC		
MS21048-04H	T2C440P		
MS21048-06H	T2C632P		
MS21048-08W	T2C832P		
MS21048-3W	T2C1032P		
MS21048-4W	T2C428P		
MS21048-5W	T2C524P		
MS21048-6W	T2C624P		
MS21048L04	T2C440M		
MS21048L06	T2C632M		
MS21048L08	T2C832M		
MS21048L3	T2C1032M		
MS21048L4	T2C428M		
MS21048L5	T2C524M		
MS21048L6	T2C624M		
MS21048L04K	T2C440BCM		
MS21048L06K	T2C632BCM		
MS21048L08K	T2C832BCM		
MS21048L3K	T2C1032BCM		
MS21048L4K	T2C428BCM		
MS21048L5K	T2C524BCM		
MS21048L04W	T2C440PM		
MS21048L06W	T2C632PM		
MS21048L08W	T2CB32PM		
MS21048L3W	T2C1032PM		
MS21048L4W	T2C428PM		
MS21048L5W	T2C524PM		
MS21048L6W	T2C624PM		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21048L04	RMLHTA51-2860-40	NAEC-AML-2429	ESNA
MS21048L06	RMLHTA51-2860-62	of 15 Mar 1966*	Division of Harvard Industries
MS21048L08	RMLHTA51-2860-82		
MS21048L3	RMLHTA51-2860-02		
MS21048L4	RMLHTA51-2860-048		
MS21048L5	RMLHTA51-2860-054		
MS21048L6	RMLHTA51-2860-064		
MS21048L04K	RMLHTA51_2860-40BC		
MS21048L06K	RMLHTA51-2860-62BC		
MS21048L08K	RMLHTA51-2860-82BC		
MS21048L3K	RMLHTA51-2860-02BC		
MS21048L4K	RMLHTA51-2860-048BC		
MS21048L5K	RMLHTA51-2860-054BC		
MS21048L04W	RMLHTA51-2860P-40		
MS21048L06W	RMLHTA51-2B60P-62		
MS21048L08W	RMLHTA51-2860P-82		
MS21048L3W	RMLHTA51-2860P-02		
MS21048L4W	RMLHTA51-2860P-048	*MUST BE MANUFACTURED	
MS21048L5W	RMLHTA51-2860P-054	AFTER 10 MAY 1994	
MS21048L6W	RMLHTAS1-2860P-064	DISC-E-94130 LTR	
MS21048-04	LHTA51-2860-40		
MS21048-06	LHTA51-2860-62		
MS21048-08	LHTA51-2860-82		
MS21048-3	LHTA51-2860-02		
MS21048-4	LHTA51-2860-048		
MS21048-5	LHTA51-2860-054		
MS21048-6	LHTA51-2860-064		
MS21048-04K	LHTA51-2860-40BC		
MS21048-06K	LHTA51-2860-62BC		
MS21048-08K	LHTA51-2860-82BC		
MS21048-3K	LHTA51-2860-02BC		
MS21048-4K	LHTA51-2860-048BC		
MS21048-5K	LHTA51-2860-054BC		
MS21048-04W	LHTA51-2B60P-40		
MS21048-06W	LHTA51-2B60P-62		
MS21048-08W	LHTA51-2860P-82		
MS21048-3W	LHTA51-2860P-02		
MS21048-4W	LHTA51-2B60P-04B		
MS21048-5W	LHTA51-2860P-054		
MS21048-6W	LHTA51-2860P-064		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21048-04	K1031-04	Report No.	Kaynar Technologies, Inc.
MS21048-06	K1031-06	NAEC-AML-2474	Kaynar Div.
MS21048-08	K1031-08	of 15 Jun 1966	P.0. Box 3001
MS21048-3	K1031-3		800 S. State College Blvd.
MS21048-4	K1031-4		Fullerton, CA 92634
MS21048-5	K1031-5		
MS21048-6	K1031-6		Plant: Same address
MS21048-04K	K1031-04BC		
MS21048-06K	K1031-06BC		
MS21048-08K	K1031-08BC		
MS21048-3K	K1031-3BC		
MS21048-4K	K1031-4BC		
MS21048-5K	K1031-5BC		
MS21048-04W	K1031-04P		
MS21048-06W	K1031-06P		
MS21048-08W	K1031-08P		
MS21048-3W	K1031-3P		
MS21048-4W	K1031-4P		
MS21048-5W	K1031-SP		
MS21048-6W	K1031-6P		
MS21048L04	K1001-04		
MS21048L06	K1001-06		
MS21048L08	K1001-08		
MS21048L3	K1001-3		
MS21048L4	K1001-4		
MS21048L5	K1001-5		
MS21048L6	K1001-6		
MS21048L04K	K1001-04BC		
MS21048L06K	K1001-06BC		
MS21048L08K	K1001-08BC		
MS21048L3K	K1001-3BC		
MS21048L4K	K1001-4BC		
MS21048L5K	K1001-5BC		
MS21048L04W	K1001-04P		
MS21048L06W	K1001-06P		
MS21048L08W	K1001-08P		
MS21048L3W	K1001-3P		
MS21048L4W	K1001-4P		
MS21048L5W	K1001-5P		
MS21048L6W	K1001-6P		

MS21048L08	R2000C08M	Report No.	Republic Fastener Mfg. Corp.
MS21048L08K	R2000C08MK	305Q73001 of	1300 Rancho Conejo Blvd
MS21048L08W	R2000C08MW	6 Feb 1973	Newbury Park, CA 91320
MS21048-08	R2000C08		
MS21048-08K	R2000C08K		Plant: Same address
MS21048-08W	R2000C08W		
MS21048L3	R2000C3M		
MS21048L3K	R2000C3MK		
MS21048L3N	R2000C3MW		
MS21048-3	R2000C3		
MS21048-3K	R2000C3K		
MS21048-3W	R2000C3W		
MS21048L4	R2000C4M		
MS21048L4K	R2000C4MK		
MS21048L4W	R2000C4MW		
MS21048-4	R2000C4		
MS21048-4K	R2000C4K		
MS21048-4W	R2000C4W		

Note: "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124 of 20 November 1970.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21048-04	R2000C04	Report No.	
MS21048L04	R2000C04M	305Q76023 of	
MS21048-04K	R2000C04K	14 May 1976	
MS21048L04K	R2000C04MK		
MS21048-04W	R2000C04W		
MS21048L04W	R2000C04MW		
MS21048-06	R2000C06		
MS21048L06	R2000C06M		
MS21048-06K	R2000C06K		
MS21048L06K	R2000C06MK		
MS21048-06M	R2000C06W		
MS21048L06W	R2000C06MW		
MS21048-5	R2000C5		
MS21048L5	R2000C5M		
MS21048-5K	R2000C5K		
MS21048L5K	R2000C5MK		
MS21048-5W	R2000C5W		
MS21048L5W	R2000C5MW		
MS21048-6	R2000C6	Report No.	
MS21048L6	R2000C6M	305Q83088 of	
MS21048-6W	R2000C6W	26 Jan 1983	
MS21048L6W	R2000C6MW		
MS21048-3	G-53	NADC Report No.	Simmonds Mecaero
MS21048-3K	G-53K	305Q83112 of	Fasteners, Inc.
		28 Nov 1983	1734 Sequoia Avenue
			Orange, CA 92668
MS21048-4	G-54	NADC Report No.	Plant:
MS21048-4K	G-54K	305Q83111 of	Simmonds
		19 Oct 1983	Usine De Champaissant
			72110 Saint-Cosme En Vairais
			France
MS21048-08	G-508	NADC Report No.	
MS21048-08K	G-508K	601Q8401 of	
		24 Feb 1984	

Note: 1. Manufacturing process: Cold formed
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance
FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals)
The contractor should include these provisions in every subcontract and purchase order.

MS21048-04	12700-40	Report No.	SPS Technologies
MS21048-06	12700-62	NAEC-AML-2369	2701 S. Harbor Blvd.
MS21048-08	12700-82	of 15 Mar 1966	Santa Ana, CA 92702
MS21048-3	12700-02		
MS21048-4	12700-048		Plant: Same address
MS21048-5	12700-054		
MS21048-6	12700-064		
MS21048-04K	12700-40BC		
MS21048-06K	12700-62BC		
MS21048-08K	12700-82BC		
MS21048-3K	12700-02BC		
MS21048-4K	12700-048BC		
MS21048-5K	12700-054BC		
MS21048-04W	12700-40PH		
MS21048-06W	12700-62PW		
MS21048-08W	12700-82PW		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21048-3W	12700-02PW
MS21048-4W	12700-048PW
MS21048-5W	12700-054PW
MS21048-6W	12700-064PW
MS21048L04	12700E-40
MS21048L06	12700E-62
MS21048L08	12700E-82
MS21048L3	12700E-02
MS21048L4	12700E-048
MS21048L5	12700E-054
MS21048L6	12700E-064
MS21048L04K	12700E-40BC
MS21048L06K	12700E-62BC
MS21048L08K	12700E-82BC
MS21048L3K	12700E-02BC
MS21048L4K	12700E-048BC
MS21048L5K	12700E-054BC
MS21048L04W	12700E-40PW
MS21048L06W	12700E-62PW
MS21048L08W	12700E-82PW
MS21048L3W	12700E-02PW
MS21048L4W	12700E-048PW
MS21048L5W	12700E-0S4PW
MS21048L6W	12700E-064PW

MS21048-04	VN102-B1-40	Report No.	VOI-SHAN
MS21048-06	VN102-B1-62	NAEC-AML-2425	Fairchild Aerospace Fastener Div
MS21048-08	VN102-B1-82	of 15 Mar 1966	2950 W. Lomita Blvd.
MS21048-3	VN102-B1-02		Torrance, CA 90505-5103
MS21048-4	VN102-B1-048		
MS21048-5	VN102-B1-054		Plant:
MS21048-6	VN102-B1-064		Same address
MS21048-04K	VN102-B2-40		
MS21048-06K	VN102-B2-62		
MS21048-08K	VN102-B2-82		
MS21048-3K	VN102-B2-02		
MS21048-4K	VN102-B2-048		
MS21048-5K	VN102-B2-054		
MS21048-04W	VN102-B3-40		
MS21048-06W	VN102-B3-62		
MS21048-08W	VN102-B3-82		
MS21048-3W	VN102-B3-02		
MS21048-4W	VN102-B3-048		
MS21048-5W	VN102-B3-054		
MS21048-6W	VN102-B3-064		
MS21048L04	VN102-D1-40		
MS21048L06	VN102-D1-62		
MS21048L08	VN102-D1-82		
MS21048L3	VN102-D1-02		
MS21048L4	VN102-D1-048		
MS21048L5	VN102-D1-054		
MS21048L6	VN102-D1-064		
MS21048L04K	VN102-D2-40		
MS21048L06K	VN102-D2-62		
MS21048L08K	VN102-D2-82		
MS21048L3K	VN102-D2-02		
MS21048L4K	VN102-D2-048		
MS21048L5K	VN102-02-054		
MS21048L04W	VN102-D3-40		
MS21048L06W	VN102-D3-62		
MS21048L08W	VN102-D3-82		
MS21048L3W	VN102-D3-02		
MS21048L4W	VN102-D3-048		
MS21048L5W	VN102-D3-054		
MS21048L6W	VN102-D3-064		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21049 NUT, SELF-LOCKING, PLATE, TWO LUG, 100° CSK, LOW HEIGHT, STEEL, 125 KSI Ftu, 450 DEG F

MS21049-08	T2SH832CPC	Report No.	Cherry/Textron
MS21049-3	T2SH1032CPC	NAEC-AML-2428	Cherry Div. of
MS21049-4	T2SH428CPC	of 15 Mar 1966	Textron Inc.
MS21049-5	T2SH524CPC		P.0. Box 2157
MS21049L08	T2SH832		1224 East Warner Ave.
MS21049L3	T2SH1032		Santa Ana. CA 92707
MS21049L4	T2SH428		
MS21049L5	T2SH524		Plant: Same address
MS21049-08K	T2SH832BCCPC		
MS21049-3K	T2SH1032BCCPC		
MS21049-4K	T2SH428BCCPC		
MS21049-5K	T2SH524BCCPC		
MS21049L08K	T2SH832BC		
MS21049L3K	T2SH1032BC		
MS21049L4K	T2SH428BC		
MS21049L5K	T2SH524BC		

MS21049-08	F52LHTA58-82	NAEC-AML-2429	ESNA
MS21049-3	F52LHTA58-02	of 15 Mar 1966*	Division of Harvard Industries,
MS21049-4	F52LHTA58-048		
MS21049-5	F52LHTA58-054	*MUST BE MANUFACTURED	
MS21049L08	RM52LHTA58-82	AFTER 10 MAY 1994	
MS21049L3	RM52LHTA58-02	DISC-E-94130 LTR	
MS21049L4	RM52LHTA58-048		
MS21049L5	RM52LHTA58-054		
MS21049-08K	F52LHTA58-82BC		
MS21049-3K	F52LHTA58-02BC		
MS21049-4K	F52LHTA58-048BC		
MS21049-5K	F52LHTA58-054BC		
MS21049L08K	RM52LHTA58-82BC		
MS21049L3K	RM52LHTA58-02BC		
MS21049L4K	RM52LHTA58-048BC		
MS21049L5K	RM52LHTA58-054BC		

MS21049-08	K1100-08CW	Report No.	Kaynar Technologies, Inc.
MS21049-3	K1100-3CW	NAEC-AML-2474	Kaynar Div.
MS21049-4	K1100-4CW	of Jun 1966	P.0. Box 3001
MS21049-5	K1100-5CW		800 S. State College Blvd.
MS21049-08K	K1100-08BCCW		Fullerton, CA 92634
MS21049-3K	K1100-3BCCW		
MS21049-4K	K1100-4BCCW		Plant: Same address
MS21049-5K	K1100-5BCCW		
MS21049L08	K1100-08		
MS21049L3	K1100-3		
MS21049L4	K1100-4		
MS21049L5	K1100-5		
MS21049L08K	K1100-08BC		
MS21049L3K	K1100-3BC		
MS21049L4K	K1100-4BC		
MS21049L5K	K1100-5BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21049-08	R2100X08	Report No.	Republic Fastener Mfg. Corp.
MS21049-08K	R2100X08K	305Q73001 of	1300 Rancho Conejo Blvd.
MS21049L08	R2100A08	6 Feb 1973	Newbury Park, CA 91320
MS21049L08K	R2100A08K		
MS21049-3	R2100X3		Plant: Same address
MS21049-3K	R2100X3K		
MS21049L3	R2100A3		
MS21049L3K	R2100A3K		

.

Note: "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124 of 20 November 1970.

.

MS21049-4	R2100X4	Report No.	
MS21049L4	R2100A4	305Q76023 of	
MS21049-4K	R2100X4K	14 May 1976	
MS21049L4K	R2100A4K		
MS21049-5	R2100X5		
MS21049L5	R2100A5		
MS21049-5K	R2100X5K		
MS21049L5K	R2100A5K		

MS21049-08	H-908	NADC Report	Simmonds Mecaero
MS21049-08K	H-908K	601QB417 of	Fasteners, Inc.
MS21049L08	H-908M	25 Oct 1984	1734 Sequoia Avenue
MS21049L08K	H-908MK		Orange, CA 92668
			Plant:
MS21049-3	H-93	NADC Report	Simmonds
MS21049L3	H-93M	601Q8609 of	Usine De Champaissant
		8 Aug 1986	72110 Saint-Cosme En Vairais
			France

Note: 1. Manufacturing process: Cold stamping
2. Lubricant: (For Government Designat1on with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordanc FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Meta The contractor should include these provisions in every subcontract and purchase order.

MS21049-08	15600NM-82	Report No.	SPS Technologies
MS21049-3	15600NM-02	NAEC-AML-2369	2701 S. Harbor Blvd.
MS21049-4	15600NM-048	of 15 Mar 1966	Santa Ana, CA 92702
MS21049-5	15600NM-054		
MS21049L08	15600-82		Plant: Same address
MS21049L3	15600-02		
MS21049L4	15600-048		
MS21049L5	15600-054		
MS21049-08K	15600NM-82BC		
MS21049-3K	15600NM-02BC		
MS21049-4K	15600NM-048BC		
MS21049-5K	15600NM-054BC		
MS21049L08K	15600-B2BC		
MS21049L3K	15600-02BC		
MS21049L4K	15600-048BC		
MS21049L5K	5600-054BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21050 NUT, SELF-LOCKING, PLATE, TWO LUG, 100 DEG CSK, LOW HEIGHT, CRES, 125 KSI Ftu, 450 DEG AND 800 DE

MS21050-08	T2CH832	NAWC Report	Boots Nut Division
MS21050-3	T2CH1032	601Q9004 of	Republic Fasteners
MS21050-4	T2CH428	22 Jan 90	1300 Rancho Conejo Blvd
MS21050-5	T2CH524		Newbury Park, CA 91320
MS21050-08K	T2CH832BC		
MS21050-3K	T2CH1032BC		Plant: Same address
MS21050-4K	T2CH428BC		
MS21050-5K	T2CH524BC		
MS21050-08W	T2CH832P		
MS21050-3W	T2CH1032P		
MS21050-4W	T2CH428P		
MS21050-5W	T2CH524P		
MS21050L08	T2CH832M		
MS21050L3	T2CH1032M		
MS21050L4	T2CH428M		
MS21050L5	T2CH524M		
MS21050L08K	T2CH832BCM		
MS21050L3K	T2CH1032BCM		
MS21050L4K	T2CH428BCM		
MS21050L5K	T2CH524BCM		
MS21050L08W	T2CH832PM		
MS21050L3W	T2CH1032PM		
MS21050L4W	T2CH428PM		
MS21050L5W	T2CH524PM		

MS21050-08	T2CH832	Report No.	Cherry/Textron
MS21050-3	T2CH1032	NAEC-AML-2428	Cherry Div. of
MS21050-4	T2CH428	of 15 Mar 1966	Textron Inc.
MS21050-5	T2CH524		P.0. Box 2157
MS21050-08K	T2CH832BC		1224 East Warner Ave.
MS21050-3K	T2CH1032BC		Santa Ana, CA 92707
MS21050-4K	T2CH428BC		
MS21050-5K	T2CH524BC		Plant: Same address
MS21050-08W	T2CH832P		
MS21050-3W	T2CH1032P		
MS21050-4W	T2CH428P		
MS21050-5W	T2CH524P		
MS21050L08	T2CH832M		
MS21050L3	T2CH1032M		
MS21050L4	T2CH428M		
MS21050L5	T2CH524M		
MS21050L08K	T2CH832BCM		
MS21050L3K	T2CH1032BCM		
MS21050L4K	T2CH428BCM		
MS21050LSK	T2CHS24BCM		
MS21050L08W	T2CH832PM		
MS21050L3W	T2CH1032PM		
MS21050L4W	T2CH428PM		
MS21050L5W	T2CH524PM		

MS21050L08	RMLHTA58-2860-82	NAEC-AML-2429	ESNA
MS21050L3	RMLHTA58-2860-02	of 15 Mar 1966*	Division of Harvard Industries
MS21050L4	RMLHTA58-2860-048		
MS21050L5	RMLHTA58-2860-054	*MUST BE MANUFACTURED	
MS21050L08K	RMLHTA58-2860-82BC	AFTER 10 MAY 1994	
MS21050L3K	RMLHTA58-2860-02BC	DISC-E-94130 LTR	
MS21050L4K	RMLHTA58-2860-048BC		
MS21050L5K	RMLHTA58-2860-054BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21050L08W	RMLHTA58-2860P-82
MS21050L3N	RMLHTA58-2860P-02
MS21050L4N	RMLHTA58-2860P-048
MS21050L5W	RMLHTA58-2860P-054
MS21050-08	LHTA58-2860-82
MS21050-3	LHTA58-2860-02
MS21050-4	LHTA58-2860-048
MS21050-5	LHTA58-2860-054
MS21050-08K	LHTA58-2860-82BC
MS21050-3K	LHTAS8-2860-02BC
MS21050-4K	LHTA58-2860-048BC
MS21050-5K	LHTA58-2860-054BC
MS21050-08W	LHTA5B-2860P-82
MS21050-3W	LHTA58-2860P-02
MS21050-41	LHTA58-2860P-048
MS21050-5W	LHTA58-2860P-054

MS21050-08	K1131-08	Report No.	Kaynar Technologies, Inc.
MS21050-3	K1131-3	NAEC-AML-2474	Kaynar Div.
MS21050-4	K1131-4	of 15 Jun 1966	P.0. Box 3001
MS21050-08K	K1131-0BBC		800 S. State College Blvd.
MS21050-3K	K1131-3BC		Fullerton, CA 92634
MS21050-4K	K1131-4BC		
MS21050-08W	K1131-0BP		Plant: Same address
MS21050-3W	K1131-3P		
MS21050-4W	K1131-4P		
MS21050L08	K1101-08		
MS21050L3	K1101-3		
MS21050L4	K1101-4		
MS21050L08K	K1101-08BC		
MS21050L3K	K1101-3BC		
MS21050L4K	K1101-4BC		
MS21050L08W	K1101-08P		
MS21050L3W	K1101-3P		
MS21050L4W	K1101-4P		

MS21050-08	R2100C08	Report No.	Republic Fastener Mfg. Corp.
MS21050-08K	R2100C08K	305Q73001 of	1300 Rancho Conejo Blvd.
MS21050-08W	R2100C08W	6 Feb 1973	Newbury Park, CA 91320
MS21050L08	R2100C08M		
MS21050L08K	R2100C08MK		Plant: Same address
MS21050L08W	R2100C08MN		
MS21050-3	R2100C3		
MS21050-3K	R2100C3K		
MS21050-3W	R2100C3W		
MS21050L3	R2100C3M		
MS21050L3K	R2100C3MK		
MS21050L3W	R2100C3MW		

Note: "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124 of 20 November 1970.

MS21050-4	R2100C4	Report No,
MS21050L4	R2100C4M	305Q76023 of
MS21050-4K	R2100C4K	14 May 1976
MS210S0L4K	R2100C4MK	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21050-4W	R2100C4W
MS21050L4W	R2100C4MW
MS21050-5	R2100C5
MS21050LS	R2100C5M
MS21050-5K	R2100C5K
MS21050L5K	R2100C5MK
MS21050-5W	R2100C5W
MS21050L5W	R2100C5MW

MS21050-08	15700-82	Report No.	SPS Technologies
MS21050-3	15700-02	NAEC-AML-2369	2701 S. Harbor Blvd.
MS21050-4	15700-048	of 15 Mar 1966	Santa Ana, CA 92702
MS21050-5	15700-054		
MS21050-08K	15700-82BC		Plant: Same address
MS21050-3K	15700-02BC		
MS21050-4K	15700-048BC		
MS21050-5K	15700-054BC		
MS21050-08W	15700-82PW		
MS21050-3W	15700-02PW		
MS21050-4W	15700-048PW		
MS21050-5W	15700-054PH		
MS21050L08	15700E-82		
MS21050L3	15700E-02		
MS210S0L4	15700E-048		
MS21050L5	15700E-054		
MS21050L08K	15700E-82BC		
MS21050L3K	15700E-02BC		
MS21050L4K	15700E-048BC		
MS21050L5K	15700E-054BC		
MS21050L08W	15700E-B2PW		
MS21050L3W	15700E-02PW		
MS21050L4W	5700E-048PW		
MS21050L5W	15700E-054PW		

MS21051 NUT, SELF-LOCKING, PLATE, ONE LUG, LOW HEIGHT, ALLOY STEEL, 125 KSI Ftu, 450 DEG F

MS21051-08	T12S832CPC	NAWC Report	Boots Nut Division
MS21051-3	T12S1032CPC	601Q9004 of	Republic Fasteners
MS21051-4	T12S428CPC	22 Jan 90	1300 Rancho Conejo Blvd
MS21051L08	T12S832		Newbury Park, CA 91320
MS21051L3	T12S1032		
MS21051L4	T12S428		Plant: Same address
MS21051-08K	T12S832BCCPC		
MS21051-3K	T12S1032BCCPC		
MS21051-4K	T12S428BCCPC		
MS21051L08K	T12S832BC		
MS21051L3K	T12S1032BC		
MS210514K	T12S428BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21051-08	T12S832CPC	Report No.	Cherry/Textron
MS21051-3	T12S1032CPC	NAEC-AML-2428	Cherry Div. of
MS21051-4	T12S428CPC	of 16 Mar 1966	Textron Inc.
MS21051L08	T12S832		P.0. Box 2157
MS21051L3	T12S1032		1224 East Warner Ave.
MS21051L4	T12S428		Santa Ana, CA 92707
MS21051-08K	T12S832BCCPC		
MS21051-3K	T12S1032BCCPC		Plant: Same address
MS21051-4K	T12S428BCCPC		
MS21051L08K	T12S832BC		
MS21051L3K	T12S1032BC		
MS21051L4K	T12S428BC		

MS21051-06	F52LHTA57-62	NAEC-AML-2429	ESNA
MS21051-08	F52LHTA57-82	of 15 Mar 1966*	Division of Harvard Industries
MS21051-3	F52LHTA57-02		
MS21051-4	F52LHTA57-048	*MUST BE MANUFACTURED	
MS21051-5	F52LHTA57-054	AFTER 10 MAY 1994	
MS21051-6	F52LHTA57-064	DISC-E-94130 LTR	
MS21051L06	RM52LHTA57-62		
MS21051L08	RM52LHTA57-82		
MS21051L3	RM52LHTA57-02		
MS21051L4	RM52LHTA57-048		
MS21051L5	RM52LHTA57-054		
MS21051L6	RM52LHTA57-064		
MS21051-06K	F52LHTA57-62BC		
MS21051-08K	F52LHTA57-82BC		
MS21051-3K	F52LHTA57-02BC		
MS21051-4K	F52LHTA57-048BC		
MS21051-5K	F52LHTA57-054BC		
MS21051L06K	RM52LHTA57-62BC		
MS21051L08K	RM52LHTA57-82BC		
MS21051L3K	RM52LHTA57-02BC		
MS21051L4K	RM52LHTA57-04BBC		
MS21051L5K	RM52LHTA57-0S4BC		

MS21051-06	K2000-06CW	Report No.	Kaynar Technologies, Inc.
MS21051-08	K2000-08CW	NAEC-AML-2474	Kaynar Div.
MS21051-3	K2000-3CW	of 15 Jun 1966	P.0. Box 3001
MS21051-4	K2000-4CW		800 S. State College Blvd.
MS21051-5	K2000-5CW		Fullerton, CA 92634
MS21051-6	K2000-6CW		
MS21051-06K	K2000-06BCCW		Plant: Same address
MS21051-08K	K2000-08BCCW		
MS21051-3K	K2000-3BCCW		
MS21051-4K	K2000-4BCCW		
MS21051-5K	K2000-5BCCW		
MS21051L06	K2000-06		
MS21051L08	K2000-08		
MS21051L3	K2000-3		
MS21051L4	K2000-4		
MS21051L5	K2000-5		
MS21051L6	K2000-6		
MS21051L06K	K2000-06BC		
MS21051L08K	K2000-08BC		
MS21051L3K	K2000-3BC		
MS21051L4K	K2000-4BC		
MS21051L5K	K2000-5BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21051-08 MS21051L08 MS21051-08K MS21051L08K MS21051-3 MS21051L3 MS21051-3K MS21051L3K MS21051-4 MS21051L4 MS21051-4K MS21051L4K	R1000X08 R1000A08 R1000X08K R1000A08K R1000X3 R1000A3 R1000X3K R1000A3K R1000X4 R1000A4 R1000X4K R1000A4K	Report No. 30SQ76023 of 14 May 1976	Republic Fastener Mfg. Corp. 1300 Rancho Conejo Blvd. Newbury Park, CA 91320 Plant: Same address
MS21051-06 MS21051L06 MS21051-06K MS21051L06K	R1000X06 R1000A06 R1000X06K R1000A06K	Report No. 305Q83088 of 26 Jan 1983	
MS21051L3 MS21051L3K MS21051L4 MS21051L4K	AJ-93M AJ-93MK AJ-94M AJ-94MK	Report No. 305Q83104 of 12 Aug 1983	Simmonds Mecaero Fasteners, Inc. 1734 Sequoia Avenue Orange, CA 92668
MS21051L08 MS21051L08K	AJ-908M AJ-908MK	Report No. 601Q8401 of 24 Feb 1984	Plant: Simmonds Usine De Champaissant 72110 Saint-Cosme En Vairais France
MS21051-08 MS21051-3	AJ-908 AJ-93	Report No. 601Q8407 of 20 Apr 1984	

Note: 1. Manufacturing process: Cold formed
2. Lubricant: (For Government Designation with "L") QPL-B937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21051-4 MS21051L4	AJ-94 AJ-94M	NADC Report 601Q8507 of 31 May 1985	

Note: 1. Manufacturing process: Cold stamping
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21051-06	12610NM-62	Report No.	SPS Technologies
MS21051-08	12610NM-82	NAEC-AML-2369	2701 S. Harbor Blvd.
MS21051-3	12610NM-02	of 15 Mar 1966	Santa Ana, CA 92702
MS21051-4	12610NM-048		
MS21051-5	12610NM-054		Plant: Same address
MS21051-6	12610NM-064		
MS21051L06	12610-62		
MS21051L08	12610-82		
MS21051L3	12610-02		
MS21051L4	12610-048		
MS21051L5	12610-054		
MS21051L6	12610-064		
MS21051-06K	12610NM-62BC		
MS21051-08K	12610NM-82BC		
MS21051-3K	12610NM-02BC		
MS21051-4K	12610NM-048BC		
MS21051-5K	12610NM-054BC		
MS21051L06K	12610-62BC		
MS21051L08K	12610-82BC		
MS21051L3K	12610-02BC		
MS21051L4K	12610-048BC		
MS21051L5K	12610-054BC		

MS210S1-06	VN101-C1-62	Report No.	VOI-SHAN
MS21051-08	VN101-C1-82	NAEC-AML-2425	Fairchild Aerospace Fastener Div
MS21051-3	VN101-C1-02	of 15 Mar 1966	2950 W. Lomita Blvd.
MS21051-4	VN101-C1-048		Torrance, CA 90505-5103
MS21051-5	VN101-C1-054		
MS21051-6	VN101-C1-064		Plant: Same address
MS21051L06	VN101-A1-62		
MS21051L08	VN101-A1-82		
MS21051L3	VN101-A1-02		
MS21051L4	VN101-A1-048	Report No.	
MS21051L5	VN101-A1-054	NAEC-AML-2425	
MS21051L6	VN101-A1-064	of 15 Mar 1966	
MS21051-06K	VN101-C2-62		
MS21051-08K	VN101-C2-82		
MS21051-3K	VN101-C2-02		
MS21051-4K	VN101-C2-048		
MS21051-5K	VN101-C2-054		
MS21051L06K	VN101-A2-62		
MS21051L08K	VN101-A2-82		
MS21051L3K	VN101-A2-02		
MS21051L4K	VN101-A2-048		
MS21051L5K	VN101-A2-054		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21052 NUT, SELF-LOCKING, PLATE, ONE LUG, LOW HEIGHT, CRES, 125 KSI Ftu, 450 DEG F AND 800 DEG F

MS21052-08	T12C832	NAWC Report	Boots Nut Division
MS21052-3	T12C1032	601Q9004 of	Republic Fasteners
MS21052-4	T12C428	22 Jan 90	1300 Rancho Conejo Blvd
MS21052-08K	T12C832BC		Newbury Park, CA 91320
MS21052-3K	T12C1032BC		
MS21052-4K	T12C428BC		Plant: Same address
MS21052-08W	T12C832P		
MS21052-3W	T12C1032P		
MS21052-4W	T12C428P		
MS21052L08	T12C832M		
MS21052L3	T12C1032M		
MS21052L4	T12C428M		
MS21052L08K	T12C832BCM		
MS21052L3K	T12C1032BCM		
MS21052L4K	T12C428BCM		
MS21052L08W	T12C832PM		
MS21052L3W	T12C1032PM		
MS21052L4W	T12C428PM		

MS21052-08	T12C832	Report No.	Cherry/Textron
MS21052-3	T12C1032	NAEC-AML-2428	Cherry Div. of
MS21052-4	T12C428	of 15 Mar 1966	Textron Inc.
MS21052-08K	T12C832BC		P.0. Box 2157
MS21052-3K	T12C10328C		1224 East Warner Ave.
MS21052-4K	T12C428BC		Santa Ana, CA 92707
MS21052-08W	T12C832P		
MS21052-3W	T12C1032P		Plant: Same address
MS21052-4W	T12C428P		
MS21052L08	T12C832M		
MS21052L3	T12C1032M		
MS21052L4	T12C428M		
MS21052L08K	T12C832BCM		
MS21052L3K	T12C1032BCM		
MS21052L4K	T12C428BCM		
MS21052L08W	T12C832PM		
MS21052L3W	T12C1032PM		
MS21052L4W	T12C428PM		

MS21052-5	T98S524CP	AMD Report No. MA768806 of 30 Jan 1969	

MS21052L06	RMLHTA57-2860-62	NAEC-AML-2429	ESNA
MS21052L08	RMLHTA57-2860-82	of 15 Mar 1966*	Division of Harvard Industries
MS21052L3	RMLHTA57-2860-02		
MS21052L4	RMLHTA57-2860-048	*MUST BE MANUFACTURED	
MS21052L5	RMLHTA57-2860-054	AFTER 10 MAY 1994	
MS21052L6	RMLHTA57-2860-064	DISC-E-94130 LTR	
MS21052L06K	RMLHTA57-2860-62BC		
MS21052L08K	RMLHTA57-2860-82BC		
MS21052L3K	RMLHTA57-2860-02BC		
MS21052L4K	RMLHTA57-2860-048BC		
MS21052L5K	RMLHTA57-2860-054BC		
MS21052L06W	RMLHTA57-2860P-62		
MS21052L08W	RMLHTA57-2860P-82		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21052L3W	RMLHTA57-2860P-02
MS21052L4W	RMLHTA57-2860P-048
MS21052L5W	RMLHTA57-2860P-054
MS21052L6W	RMLHTA57-2860P-064
MS21052-06	LHTA57-2860-62
MS21052-08	LHTA57-2860-82
MS21052-3	LHTA57-2860-02
MS21052-4	LHTA57-2860-048
MS21052-5	LHTA57-2860-054
MS21052-6	LHTA57-2860-064
MS21052-06K	LHTA57-2860-62BC
MS21052-08K	LHTA57-2860-82BC
MS21052-3K	LHTA57-2860-02BC
MS21052-4K	LHTA57-2860-048BC
MS21052-5K	LHTA57-2860-054BC
MS21052-06W	LHTA57-2860P-62
MS21052-08H	LHTA57-2860P-82
MS21052-3W	LHTA57-2860P-02
MS21052-4W	LHTA57-2860P-048
MS21052-5W	LHTA57-2860P-0S4
MS21052-6W	LHTA57-2860P-064

MS21052-06	K2031-06	Report No.	Kaynar Technologies, Inc.
MS21052-08	K2031-08	NAEC-AML-2474	Kaynar Div.
MS21052-3	K2031-3	of 15 Jun 1966	P.0. Box 3001
MS21052-4	K2031-4		800 S. State College Blvd.
MS21052-5	K2031-5		Fullerton, CA 92634
MS21052-6	K2031-6		
MS21052-06K	K2031-06BC		Plant: Same address
MS21052-08K	K2031-08BC		
MS21052-3K	K2031-3BC		
MS21052-4K	K2031-4BC		
MS21052-5K	K2031-5BC		
MS21052-06W	K2031-06P		
MS21052-08W	K2031-08P		
MS21052-3W	K2031-3P		
MS21052-4W	K2031-4P		
MS21052-5W	K2031-5P		
MS21052-6W	K2031-6P		
MS21052L06	K2001-06		
MS21052L08	K2001-08		
MS21052L3	K2001-3		
MS21052L4	K2001-4		
MS21052L5	K2001-5		
MS21052L6	K2001-6		
MS21052L06K	K2001-06BC		
MS21052L08K	K2001-08BC		
MS21052L3K	K2001-3BC		
MS21052L4K	K2001-4BC		
MS21052L5K	K2001-5BC		
MS21052L06W	K2001-06P		
MS21052L08W	K2001-08P		
MS21052L3W	K2001-3P		
MS21052L4W	K2001-4P		
MS21052L5W	K2001-5P		
MS21052L6W	K2001-6P		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21052-08 MS21052L08 MS21052-08K MS21052L08K MS21052-08W MS21052L08W MS21052-3 MS21052L3 MS21052-3K MS21052L3K MS21052-3W MS21052L3M MS21052-4 MS21052L4 MS21052-4K MS21052L4K MS21052-4W MS21052L4W	R1000C08 R1000C08M R1000C08K R1000C08MK R1000C08W R1000C08MW R1000C3 R1000C3M R1000C3K R1000C3MK R1000C3W R1000C3MW R1000C4 R1000C4M R1000C4K R1000C4MK R1000C4W R1000C4MW	Report No. 305Q76023 of 14 May 1976	Republic Fasteners Mfg. Corp. 1300 Rancho Conejo Blvd. Newbury Park, CA 91320 Plant: Same address
MS21052-06 MS21052L06 MS21052-06K MS21052L06K MS21052-06W MS21052L06W	R1000C06 R1000C06M R1000C06K R1000C06MK R1000C06W R1000C06MW	Report No. 305Q83088 of 26 Jan 1983	
MS21052-08 MS21052-08K	AJ-508 AJ-508K	Report No. 305Q83112 of 28 Nov 1983	Simmonds Mecaero Fasteners, Inc. 1734 Sequoia Avenue Orange, CA 92668
MS21052-3 MS21052-3K	AJ-53 AJ-53K	Report No. 601Q8401 of 24 Feb 1984	Plant: Usine De Champaissant 72110 Saint-Cosme En Vairais France

Note: 1. Manufacturing process: Cold formed
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordanc FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals The contractor should include these provisions in every subcontract and purchase order.

MS21052-4 MS21052L4	AJ-54 AJ-54M	NADC Report 601Q8507 of 31 May 1985	

Note: 1. Manufacturing process: Cold stamping
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals) The contractor should include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21052-06	12710-62	Report No.	SPS Technologies
MS21052-08	12710-82	NAEC-AML-2369	2701 S. Harbor Blvd.
MS21052-3	12710-02	of 15 Mar 1966	Santa Ana, CA 92702
MS21052-4	12710-048		
MS21052-5	12710-054		Plant: Same address
MS21052-6	12710-064		
MS21052-06K	12710-62BC		
MS21052-08K	12710-82BC		
MS21052-3K	12710-02BC		
MS21052-4K	12710-048BC		
MS21052-5K	12710-054BC		
MS21052-06W	12710-62PW		
MS21052-08W	12710-82PH		
MS21052-3W	12710-02PW		
MS21052-4W	12710-048PW		
MS21052-5W	12710-054PW		
MS21052-6W	12710-064PW		
MS21052L06	12710E-62		
MS21052L08	12710E-82		
MS210S2L3	12710E-02		
MS21052L4	12710E-048		
MS21052L5	12710E-054		
MS21052L6	12710E-064		
MS21052L06K	12710E-628C		
MS21052L08K	12710E-82BC		
MS21052L3K	12710E-02BC		
MS21052L4K	12710E-048BC		
MS21052L5K	12710E-054BC		
MS21052L06W	12710E-62PW		
MS21052L08W	12710E-82PW		
MS21052L3H	12710E-02PW		
MS21052L4H	12710E-048PH		
MS21052L5H	12710E-054PW		
MS21052L6W	12710E-064PW		

MS21052-06	VN101-B1-62	Report No.	VOI-SHAN
MS21052-08	VN101-B1-82	NAEC-AML-2425	Fairchild Aerospace Fastener Div
MS21052-3	VN101-B1-02	of 15 Mar 1966	2950 W. Lomita Blvd.
MS21052-4	VN101-B1-048		Torrance, CA 90505-5103
MS21052-5	VN101-B1-054		
MS21052-6	VN101-B1-064		Plant: Same address
MS21052-06K	VN101-B2-62		
MS21052-08K	VN101-B2-82		
MS21052-3K	VN101-B2-02		
MS21052-4K	VN101-B2-048		
MS21052-5K	VN101-B2-054		
MS21052-06W	VN101-B3-62		
MS21052-08W	VN101-B3-82		
MS21052-3W	VN101-B3-02		
MS21052-4W	VN101-B3-048		
MS21052-5W	VN101-B3-054		
MS21052-6W	VN101-B3-064		
MS21052L06	VN101-D1-62		
MS21052L08	VN101-D1-82		
MS21052L3	VN101-D1-02		
MS21052L4	VN101-D1-048		
MS21052L5	VN101-D1-054		
MS21052L6	VN101-D1-064		
MS21052L06K	VN101-D2-62		
MS21052L08K	VN101-D2-82		
MS21052L3K	VN101-D2-02		
MS21052L4K	VN101-D2-048		
MS21052L5K	VN101-D2-054		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21052L06W	VN101-D3-62
MS21052L08W	VN101-D3-82
MS21052L3W	VN101-D3-02
MS21052L4W	VN101-D3-048
MS21052L5W	VN101-D3-054
MS21052L6W	VN101-D3-064

MS21053 NUT, SELF-LOCKING, PLATE, ONE LUG, 100° CSK, LOW HEIGHT, ALLOY STEEL, 125 KSI Ftu, 450 DEG F

MS21053-08	T12SH832CPC	NAWC Report	Boots Nut Division
MS21053-3	T12SH1032CPC	601Q9004 of	Republic Fasteners
MS21053-4	T12SH428CPC	22 Jan 90	1300 Rancho Conejo Blvd
MS21053L08	T12SH832		Newbury Park, CA 91320
MS21053L3	T12SH1032		
MS21053L4	T12SH428		Plant: Same address
MS21053-08K	T12SH832BCCPC		
MS21053-3K	T12SH1032BCCPC		
MS21053-4K	T12SH428BCCPC		
MS21053L08K	T12SH832BC		
MS21053L3K	T12SH1032BC		
MS21053L4K	T12SH428BC		

MS21053-08	T12SH832CPC	Report No.	Cherry/Textron
MS21053-3	T12SH1032CPC	NAEC-AML-2428	Cherry Div. of
MS21053-4	T12SH428CPC	of 15 Mar 1966	Textron Inc.
MS21053L08	T12SH832		P.0. Box 2157
MS21053L3	T12SH1032		1224 East Warner Ave.
MS21053L4	T12SH428		Santa Ana, CA 92702
MS21053-08K	T12SH832BCCPC		
MS21053-3K	T12SH1032BCCPC		Plant: Same address
MS21053-4K	T12SH428BCCPC		
MS21053L08K	T12SH832BC		
MS21053L3K	T12SH1032BC		
MS21053L4K	T12SH428BC		

MS21053-08	F52LHTA54-82	NAEC-AML-2429	ESNA
MS21053-3	F52LHTA54-02	of 15 Mar 1966 *	Division of Harvard Industries
MS21053-4	F52LHTA54-048		
MS21053-5	F52LHTA54-054	*MUST BE MANUFACTURED	
MS21053L08	RM52LHTA54-82	AFTER 10 MAY 1994	
MS21053L3	RM52LHTA54-02	DISC-E-94130 LTR	
MS21053L4	RM52LHTA54-048		
MS21053L5	RMS2LHTA54-054		
MS21053-08K	F52LHTA54-82BC		
MS21053-3K	F52LHTA54-02BC		
MS21053-4K	F52LHTA54-048BC		
MS21053-5K	F52LHTA54-054BC		
MS21053L08K	RM52LHTA54-82BC		
MS21053L3K	RM52LHTA54-02BC		
MS21053L4K	RM52LHTA54-048BC		
MS21053L5K	RM52LHTA54-054BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21053-08	K2100-08CW	Report No.	Kaynar Technologies, Inc.
MS21053-3	K2100-3CW	NAEC-AML-2474	Kaynar Div.
MS21053-4	K2100-4CW	of 15 Jun 1966	P.0. Box 3001
MS21053-08K	K2100-08BCCW		800 S. State College Blvd.
MS21053-3K	K2100-3BCCW		Fullerton, CA 92634
MS21053-4K	K2100-4BCCW		
MS21053L08	K2100-08		Plant: Same address
MS21053L3	K2100-3		
MS21053L4	K2100-4		
MS21053L08K	K2100-08BC		
MS21053L3K	K2100-3BC		
MS21053L4K	K2100-4BC		

MS21053-08	R1100X08	Report No.	Republic Fastener Mfg. Corp
MS21053L08	R1100A08	305Q83088 of	1300 Rancho Conejo Blvd
MS21053-08K	R1100X08K	26 Jan 1983	Newbury Park, CA 91320
MS21053L08K	R1100A08K		
MS21053-3	R1100X3		Plant: Same address
MS21053L3	R1100A3		
MS21053-3K	R1100X3K		
MS21053L3K	R1100A3K		
MS21053-4	R1100X4		
MS21053L4	R1100A4		
MS21053-4K	R1100X4K		
MS21053L4K	R1100A4K		

MS21053-08	15610NM-82	Report No.	SPS Technologies
MS21053-3	15610NM-02	NAEC-AML-2369	2701 S. Harbor Blvd.
MS21053-4	15610NM-048	of 15 Mar 1966	Santa Ana, CA 92702
MS21053-5	15610NM-054		
MS21053L08	15610-82		Plant: Same address
MS21053L3	15610-02		
MS21053L4	15610-048		
MS21053L5	15610-054		
MS21053-08K	15610NM-82BC		
MS21053-3K	15610NM-02BC		
MS21053-4K	15610NM-048BC		
MS21053-5K	15610NM-054BC		
MS21053L08K	15610-82BC		
MS21053L3K	15610-02BC		
MS21053L4K	15610-048BC		
MS21053L5K	15610-054BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21054 NUT, SELF-LOCKING, PLATE, ONE LUG, 100 DEG CSK, LOW HEIGHT, CRES, 125 KSI Ftu, 450 DEG & 800 DEG F

MS21054-08	T12CH832	NAWC Report	Boots Nut Division
MS21054-3	T12CH1032	601Q9004 of	Republic Fasteners
MS21054-4	T12CH428	22 Jan 90	1300 Rancho Conejo Blvd
MS21054-08K	T12CH832BC		Newbury Park, CA 91320
MS21054-3K	T12CH1032BC		
MS21054-4K	T12CH428BC		Plant: Same address
MS21054-08W	T12CH832PWB		
MS21054-3W	T12CH1032PWB		
MS21054-4W	T12CH428P		
MS21054L08	T12CH832M		
MS21054L3	T12CH1032M		
MS21054L4	T12CH428M		
MS21054L08K	T12CH832BCM		
MS21054L3K	T12CH1032BCM		
MS21054L4K	T12CH428BCM		
MS21054L08W	T12CH832PM		
MS21054L3W	T12CH1032PM		
MS21054L4W	T12CH428PM		

MS21054-08	T12CH832	Report No.	Cherry/Textron
MS21054-3	T12CH1032	NAEC-AML-2428	Cherry Div. of
MS21054-4	T12CH428	of 15 Mar 1966	Textron Inc.
MS21054-08K	T12CH832BC		P.0. Box 2157
MS21054-3K	T12CH1032BC		1224 East Warner Ave.
MS21054-4K	T12CH428BC		Santa Ana, CA 92707
MS21054-08N	T12CH832PWB		
MS21054-3W	T12CH1032PHB		Plant: Same address
MS21054-4W	T12CH428P		
MS21054L08	T12CH832M		
MS21054L3	T12CH1032M		
MS21054L4	T12CH428M		
MS21054L08K	T12CH832BCM		
MS21054L3K	T12CH1032BCM		
MS21054L4K	T12CH428BCM		
MS21054L08W	T12CH832PM		
MS21054L3W	T12CH1032PM		
MS21054L4W	T12CH42BPM		

MS21054L08	RMLHTA54-2860-82	NAEC-AML-2429	ESNA
MS21054L3	RMLHTA54-2860-02	of 15 Mar 1996*	Division of Harvard Industries
MS21054L4	RMLHTA54-2860-048		
MS21054L5	RMLHTA54-2860-054	*MUST BE MANUFACTURED	
MS21054L08K	RMLHTA54-2860-82BC	AFTER 10 MAY 1994	
MS21054L3K	RMLHTA54-2860-02BC	DISC-E-94130 LTR	
MS21054L4K	RMLHTAS4-2860-048BC		
MS21054L5K	RMLHTA54-2860-054BC		
MS21054L08W	RMLHTA54-2860P-82		
MS21054L3H	RMLHTA54-2860P-02		
MS21054L4W	RMLHTA54-2860P-048		
MS21054L5W	RMLHTA54-2860P-054		
MS21054-08	LHTA54-2860-82		
MS21054-3	LHTA54-2860-02		
MS21054-4	LHTA54-2860-048		
MS21054-5	LHTA54-2860-054		
MS21054-08K	LHTA54-2860-82BC		
MS21054-3K	LHTA54-2860-02BC		
MS21054-4K	LHTA54-2860-048BC		
MS21054-5K	LHTA54-2860-054BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21054-08W	LHTA54-2860P-82
MS21054-3W	LHTA54-2860P-02
MS21054-4H	LHTA54-2860P-048
MS21054-5W	LHTA54-2860P-054

MS21054-08	K2131-08	Report No.	Kaynar Technologies, Inc.
MS21054-3	K2131-3	NAEC-AML-2474	Kaynar Div.
MS21054-4	K2131-4	of 15 Jun 1966	P.0. Box 3001
MS21054-08K	K2131-08BC		800 S. State College Blvd.
MS21054-3K	K2131-3BC		Fullerton, CA 92634
MS21054-4K	K2131-4BC		
MS21054-08W	K2131-08P		Plant: Same address
MS21054-3W	K2131-3P		
MS21054-4W	K2131-4P		
MS21054L08	K2101-08		
MS21054L3	K2101-3		
MS21054L4	K2101-4		
MS21054L08K	K2101-08BC		
MS21054L3K	K2101-3BC		
MS21054L4K	K2101-4BC		
MS21054L08W	K2101-08P		
MS21054L3W	K2101-3P		
MS21054L4W	K2101-4P		

MS21054-08	R1100C08	Report No.	Republic Fastener Mfg. Corp
MS21054L08	R1100C08M	305Q83088 of	1300 Rancho Conejo Blvd
MS21054-08K	R1100C08K	26 Jan 1983	Newbury Park, CA 91320
MS21054L08K	R1100C08MK		
MS21054-08W	R1100C08W		Plant: Same address
MS21054L08W	R1100C08MW		
MS21054-3	R1100C3		
MS21054L3	R1100C3M		
MS21054-3K	R1100C3K		
MS21054L3K	R1100C3MK		
MS21054-3W	R1100C3W		
MS21054L3H	R1100C3MW		
MS21054-4	R1100C4		
MS21054L4	R1100C4M		
MS21054-4K	R1100C4K		
MS21054L4K	R1100C4MK		
MS21054-4W	R1100C4W		
MS21054L4W	R1100C4MW		

MS21054-08	15710-82	Report No.	SPS Technologies
MS21054-3	15710-02	NAEC-AML-2369	2701 S. Harbor Blvd.
MS21054-4	15710-048	of 15 Mar 1966	Santa Ana, CA 92702
MS21054-5	15710-054		
MS21054-08K	15710-82BC		Plant: Same address
MS21054-3K	15710-02BC		
MS21054-4K	15710-048BC		
MS21054-5K	15710-054BC		
MS21054-08W	15710-82PWB		
MS21054-3W	15710-02PWB		
MS21054-4W	15710-048PWB		
MS21054-5W	15710-054PWB		
MS21054L08	15710E-82		
MS21054L3	15710E-02		
MS21054L4	15710E-048		
MS21054L5	15710E-054		
MS21054L08K	15710E-82BC		
MS21054L3K	15710E-02BC		
MS21054L4K	15710E-048BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21054L5K	15710E-054BC
MS21054L08W	15710E-82PWB
MS21054L3W	15710E-02PWB
MS21054L4W	15710E-048PWB
MS21054L5W	15710E-054PWB

MS21055 NUT, SELF-LOCKING, PLATE, CORNER, LOW HEIGHT, ALLOY STEEL, 125 KSI Ftu, 450 DEG F

MS21055-06	T7S632CPC	NAWC Report	Boots Nut Division
MS21055-08	T7S832CPC	601Q9004 of	Republic Fasteners
MS21055-3	T7S1032CPC	22 Jan 90	1300 Rancho Conejo Blvd
MS21055-4	T7S428CPC		Newbury Park, CA 91320
MS21055L06	T7S632		
MS21055L08	T7S832		Plant: Same address
MS21055L3	T7S1032		
MS21055L4	T7S428		
MS21055-06K	T7S8CCPC		
MS21055-08K	T7S832BCCPC		
MS21055-3K	T7S1032BCCPC		
MS21055-4K	T7S428BCCPC		
MS21055L06K	T7S632BC		
MS21055L08K	T7S832BC		
MS21055L3K	T7S1032BC		
MS21055L4K	T7S428BC		

MS21055-06	T7S632CPC	Report No.	Cherry/Textron
MS21055-08	T7S832CPC	NAEC-AML-2428	Cherry Div. of
MS21055-3	T7S1032CPC	of 15 Mar 1966	Textron Inc.
MS21055-4	T7S428CPC		P.0. Box 2157
MS21055-5	T7S524CPC		1224 East Warner Ave.
MS21055-6	T7S624CPC		Santa Ana, CA 92707
MS21055L06	T7S632		
MS21055L08	T7S832		Plant: Same address
MS21055L3	T7S1032		
MS21055L4	T7S428		
MS21055L5	T7S524		
MS21055L6	T7S624		
MS21055-06K	T7S632BCCPC		
MS21055-08K	T7S832BCCPC		
MS21055-3K	T7S1032BCCPC		
MS21055-4K	T7S428BCCPC		
MS21055-5K	T7S524BCCPC		
MS21055L06K	T7S632BC		
MS21055L08K	T7S832BC		
MS21055L3K	T7S1032BC		
MS21055L4K	T7S428BC		
MS21055L5K	T7S524BC		

MS21055-06	F52LHTA55-62	NAEC-AML-2429	ESNA
MS21055-08	F52LHTA55-82	of 15 Mar 1966*	Division of Harvard Industries
MS21055-3	F52LHTA55-02		
MS21055-4	F52LHTA55-048		
MS21055-5	F52LHTA55_054		
MS21055-6	F52LHTA55-064		
MS21055L06	RM52LHTA55-62		
MS21055L08	RM52LHTA55-82		
MS21055L3	RM52LHTA55-02		
MS21055L4	RM52LHTA55-048		
MS21055L5	RM52LHTA55-054		
MS21055L6	RM52LHTA55-064		
MS21055-06K	F52LHTA55-62BC		
MS21055-08K	F52LHTA55-82BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21055-3K	F52LHTA55-02BC	
MS21055-4K	F52LHTA55-048BC	*MUST BE MANUFACTURED
MS21055-5K	F52LHTA55-054BC	AFTER 10 MAY 1994
MS21055L06K	RM52LHTA55-62BC	DISC-E-94130 LTR
MS21055L08K	RM52LHTA55-82BC	
MS21055L3K	RM52LHTA55-02BC	
MS21055L4K	RMS2LHTA55-048BC	
MS21055L5K	RM52LHTA55-054BC	

MS21055-06	K3000-06CW	Report No.	Kaynar Technologies, Inc.
MS21055-08	K3000-08CW	NAEC-AML-2474	Kaynar Div.
MS21055-3	K3000-3CW	of 15 June 1966	P.O. Box 3001
MS21055-4	K3000-4CW		800 S. State College Blvd.
MS21055-5	K3000-5CW		Fullerton, CA 92634
MS21055-6	K3000-6CCW		
MS21055-06K	K3000-06BCCW		Plant: Same address
MS21055-08K	K3000-08BCCW		
MS21055-3K	K3000-3BCCW		
MS21055-4K	K3000-4BCCW		
MS21055-5K	K3000-5BCCW		
MS21055L06	K3000-06		
MS21055L08	K3000-08		
MS21055L3	K3000-3		
MS21055L4	K3000-4		
MS21055L5	K3000-5		
MS21055L6	K3000-6		
MS21055L06K	K3000-06BC		
MS21055L08K	K3000-08BC		
MS21055L3K	K3000-3BC		
MS21055L4K	K3000-4BC		
MS21055L5K	K3000-5BC		

MS21055L7	K3000-7	Report No. 305Q83097 of 22 Mar 1983	

Note: Manufacturing process: Machined

MS21055-08	R3000X08	Report No.	Republic Fastener Mfg. Corp.
MS21055L08	R3000A08	305Q76023 of	1300 Rancho Conejo Blvd.
MS21055-08K	R3000X08K	14 May 1976	Newbury Park, CA 91320
MS21055L08K	R3000A08K		
MS21055-3	R3000X3		Plant: Same address
MS21055L3	R3000A3		
MS21055-3K	R3000X3K		
MS21055L3K	R3000A3K		
MS21055-4	R3000X4		
MS21055L4	R3000A4		
MS21055-4K	R3000X4K		
MS21055L4K	R3000A4K		

MS21055-06	R3000X06	Report No.
MS21055L06	R3000A06	305Q83088 of
MS21055-06K	R3000X06K	26 Jan 1983
MS21055L06K	R3000A06K	

MS21055-06	12620NM-62	Report No.	SPS Technologies
MS21055-08	12620NM-82	NAEC-AML-2369	2701 S. Harbor Blvd.
MS21055-3	12620NM-02	of 15 Mar 1966	Santa Ana, CA 92702
MS21055-4	12620NM-048		
MS21055-5	12620NM-054		Plant: Same address
MS21055-6	12620NM-064		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21055L06	12620-62
MS21055L08	12620-82
MS21055L3	12620-02
MS21055L4	12620-048
MS21055L5	12620-054
MS21055L6	12620-064
MS21055-06K	12620NM-62BC
MS21055-08K	12620NM-82BC
MS21055-3K	12620NM-02BC
MS21055-4K	12620NM-048BC
MS21055-5K	12620NM-054BC
MS21055L06K	12620-62BC
MS21055L08K	12620-82BC
MS21055L3K	12620-02BC
MS21055L4K	12620-048BC
MS21055L5K	12620-054BC

MS21055-06	VN103-C1-62	Report No.	VOI-SHAN
MS21055-08	VN103-C1-82	NAEC-AML-2425	Fairchild Aerospace Fastener Div
MS21055-3	VN103-C1-02	of 15 Mar 1966	2950 W. Lomita Blvd.
MS21055-4	VN103-C1-048		Torrance, CA 90505-5103
MS21055-5	VN103-C1-054		
MS21055-6	VN103-C1-064		Plant: Same address
MS21055L06	VN103-A1-62		
MS21055L08	VN103-A1-82		
MS21055L3	VN103-A1-02		
MS21055L4	VN103-A1-048		
MS21055LS	VN103-A1-054		
MS21055L6	VN103-A1-064		
MS21055-06K	VN103-C2-62		
MS21055-08K	VN103-C2-82		
MS21055-3K	VN103-C2-02		
MS21055-4K	VN103-C2-048		
MS21055-5K	VN103-C2-054		
MS21055L06K	VN103-A2-62		
MS21055L08K	VN103-A2-82		
MS21055L3K	VN103-A2-02		
MS21055L4K	VN103-A2-048		
MS21055L5K	VN103-A2-054		

MS21056 NUT, SELF-LOCKING, PLATE, CORNER, LOW HEIGHT, CRES, 125 KSI Ftu, 450 DEG & 800°F

MS21056-06	T7C632	NAWC Report	Boots Nut Division
MS21056-08	T7C832	601Q9004 of	Republic Fasteners
MS21056-3	T7C1032	22 Jan 90	1300 Rancho Conejo Blvd
MS21056-4	T7C428		Newbury Park, CA 91320
MS21056-06K	T7C632BC		
MS21056-08K	T7C832BC		Plant: Same address
MS21056-3K	T7C1032BC		
MS21056-4K	T7C428BC		
MS21056-06W	T7C632PWB		
MS21056-08W	T7C832PWB		
MS21056-3W	T7C1032PWB		
MS21056-4W	T7C428PWB		
MS21056L06	T7C632M		
MS21056L08	T7C832M		
MS21056L3	T7C1032M		
MS21056L4	T7C428M		
MS21056L06K	T7C632BCM		
MS21056L08K	T7C832BCM		
MS21056L3K	T7C1032BCM		
MS21056L4K	T7C428BCM		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21056L06W	T7C632PM
MS21056L08W	T7C832PM
MS21056L3W	T7C1032PM
MS21056L4W	T7C428PM

MS21056-06	T7C632	Report No.	Cherry/Textron
MS21056-08	T7C832	NAEC-AML-2428	Cherry Div. of
MS21056-3	T7C1032	of 15 Mar 1966	Textron Inc.
MS21056-4	T7C428		P.0. Box 2157
MS21056-5	T7C524		1224 East Warner Ave.
MS21056-6	T7C624		Santa Ana, CA 92707
MS21056-06K	T7C632BC		
MS21056-08K	T7C832BC		Plant: Same address
MS21056-3K	T7C1032BC		
MS21056-4K	T7C428BC		
MS21056-5K	T7C524BC		
MS21056-06W	T7C632PWB		
MS21056-08W	T7C832PWB		
MS21056-3W	T7C1032PWB		
MS21056-4N	T7C428PWB		
MS21056-5W	T7C524PWB		
MS21056-6W	T7C624PWB		
MS21056L06	T7C632M		
MS21056L08	T7C832M		
MS21056L3	T7C1032M		
MS21056L4	T7C428M		
MS21056L5	T7C524M		
MS21056L6	T7C624M		
MS21056L06K	T7C632BCM		
MS21056L08K	T7C832BCM		
MS21056L3K	T7C1032BCM		
MS21056L4K	T7C428BCM		
MS21056L5K	T7C524BCM		
MS21056L06W	T7C632PM		
MS21056L08W	T7C832PM		
MS21056L3W	T7C1032PM		
MS21056L4W	T7C428PM		
MS21056L5N	T7C524PM		
MS21056L6N	T7C624PM		

MS21056L06	RMLHTA55-2860-62	NAEC-AML-2429	ESNA
MS21056L08	RMLHTA55-2860-82	of 15 Mar 1966*	Division of Harvard Industries
MS21056L3	RMLHTA55-2860-02		
MS21056L4	RMLHTA55-2860-048	*MUST BE MANUFACTURED	
MS21056L5	RMLHTA55-2860-054	AFTER 10 MAY 1994	
MS21056L6	RMLHTA55-2860-064	DISC-E-94130 LTR	
MS21056L06K	RMLHTA55-2860-62BC		
MS21056L08K	RMLHTA55-2860-82BC		
MS21056L3K	RMLHTA55-2860-02BC		
MS21056L4K	RMLHTA55-2860-048BC		
MS21056L5K	RMLHTA55-2860-054BC		
MS21056L06W	RMLHTA55-2860P-62		
MS21056L08W	RMLHTA55-2860P-82		
MS21056L3W	RMLHTA55-2860P-02		
MS21056L4W	RMLHTA55-2860P-048		
MS21056L5H	RMLHTA55-2860P-054		
MS21056L6H	RMLHTA55-2860P-064		
MS21056-06	LHTA55-2860-62		
MS21056-08	LHTA55-2860-82		
MS21056-3	LHTA55-2860-02		
MS21056-4	LHTA55-2860-048		
MS21056-5	LHTA55-2860-054		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21056-6	LHTA55-2860-064
MS21056-06K	LHTA55-2860-62BC
MS21056-08K	LHTA55-2860-828C
MS21056-3K	LHTA55-2860-02BC
MS21056-4K	LHTA55-2860-048BC
MS21056-5K	LHTA55-2860-054BC
MS21056-06W	LHTA55-2860P-62
MS21056-08W	LHTA55-2860P-82
MS21056-3W	LHTA55-2860P-02
MS21056-4W	LHTA55-2860P-048
MS21056-5W	LHTAS5-2860P-054
MS21056-6W	LHTA55-2860P-064

MS21056-06	K3031-06	Report No.	Kaynar Technologies, Inc.
MS21056-08	K3031-08	NAEC-AML-2474	Kaynar Div.
MS21056-3	K3031-3	of 15 June 1966	P.0. Box 3001
MS21056-4	K3031-4		800 S. State College Blvd.
MS21056-5	K3031-5		Fullerton, CA 92634
MS21056-6	K3031-6		
MS21056-06K	K3031-06BC		Plant: Same address
MS21056-08K	K3031-08BC		
MS21056-3K	K3031-3BC		
MS21056-4K	K3031-4BC		
MS21056-5K	K3031-5BC		
MS21056-06W	K3031-06P		
MS21056-08W	K3031-08P		
MS21056-3W	K3031-3P		
MS21056-4W	K3031-4P		
MS21056-5W	K3031-5P		
MS21056-6W	K3031-6P		
MS21056L06	K3001-06		
MS21056L08	K3001-08		
MS21056L3	K3001-3		
MS21056L4	K3001-4		
MS21056L5	K3001-5		
MS21056L6	K3001-6		
MS21056L06K	K3001-06BC		
MS21056L08K	K3001-08BC		
MS21056L3K	K3001-3BC		
MS21056L4K	K3001-4BC		
MS21056L5K	K3001-5BC		
MS21056L06W	K3001-06P		
MS21056L08W	K3001-08P		
MS21056L3W	K3001-3P		
MS21056L4W	K3001-4P		
MS21056L5W	K3001-5P		
MS21056L6W	K3001-6P		

MS21056-08	R3000C08	Report No.	Republic Fastener Mfg. Corp.
MS21056L08	R3000C08M	305Q76023 of	1300 Rancho Conejo Blvd.
MS21056-08K	R3000C08K	14 May 1976	Newbury Park,CA 91320
MS21056L08K	R3000C08MK		
MS21056-08W	R3000C08W		Plant: Same address
MS21056L08W	R3000C08MW		
MS21056-3	R3000C3		
MS21056L3	R3000C3M		
MS21056-3K	R3000C3K		
MS21056L3K	R3000C3MK		
MS21056-3W	R3000C3W		
MS21056L3W	R3000C3MW		
MS21056-4	R3000C4		
MS21056L4	R3000C4M		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21056-4K	R3000C4K		
MS21056L4K	R3000C4MK		
MS21056-4W	R3000C4W		
MS21056L4W	R3000C4MW		

MS21056-06	R3000C06	Report No.	
MS21056L06	R3000C06M	305Q83088 of	
MS21056-06K	R3000C06K	26 Jan 1983	
MS21056L06K	R3000C06MK		
MS21056-06W	R3000C06W		
MS21056L06W	R3000C06MW		

MS21056-06	12720-62	Report No.	SPS Technologies
MS21056-08	12720-82	NAEC-AML-2369	2701 S. Harbor Blvd.
MS21056-3	12720-02	of 15 Mar 1966	Santa Ana, CA 92707
MS21056-4	12720-048		
MS21056-5	12720-054		Plant: Same address
MS21056-6	12720-064		
MS21056-06K	12720-62BC		
MS21056-08K	12720-82BC		
MS21056-3K	12720-02BC		
MS21056-4K	12720-048BC		
MS21056-5K	12720-054BC		
MS21056-06W	12720-62PW		
MS21056-08W	12720-82PW		
MS21056-3N	12720-02PW		
MS21056-4W	12720-048PW		
MS21056-5W	12720-054PW		
MS21056-6W	12720-064PH		
MS21056L06	12720E-62		
MS21056L08	12720E-82		
MS21056L3	12720E-02		
MS21056L4	12720E-048		
MS21056L5	12720E-054		
MS21056L6	12720E-064		
MS21056L06K	12720E-62BC		
MS21056L08K	12720E-82BC		
MS21056L3K	12720E-02BC		
MS21056L4K	12720E-048BC		
MS21056L5K	12720E-054BC		
MS21056L06W	12720E-62PN		
MS21056L08N	12720E-82PN		
MS21056L3W	12720E-02PN		
MS21056L4W	12720E-048PW		
MS21056L5W	12720E-054PW		
MS21056L6N	12720E-064PN		

MS21056-06	VN103-B1-62	Report No.	VOI-SHAN
MS21056-08	VN103-B1-82	NAEC-AML-2425	Fairchild Aerospace Fastener Div
MS21056-3	VN103-B1-02	of 15 Mar 1966	2950 W. Lomita Blvd.
MS21056-4	VN103-B1-048		Torrance, CA 90505-5103
MS21056-5	VN103-B1-054		
MS21056-6	VN103-B1-064		Plant: Same address
MS21056-06K	VN103-B2-62		
MS21056-08K	VN103-B2-82		
MS21056-3K	VN103-B2-02		
MS21056-4K	VN103-B2-048		
MS21056-5K	VN103-B2-054		
MS21056-06W	VN103-B3-62		
MS21056-08W	VN103-B3-82		
MS21056-4H	VN103-B3-048		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21056-5W	VN103-B3-054
MS21056-6W	VN103-B3-064
MS21056L06	VN103-D1-62
MS210S6L08	VN103-D1-82
MS21056L3	VN103-D1-02
MS21056L4	VN103-D1-048
MS21056L5	VN103-D1-054
MS21056L6	VN103-D1-064
MS21056L06K	VN103-D2-62
MS21056L08K	VN103-D2-82
MS21056L3K	VN103-D2-02
MS21056L4K	VN103-D2-048
MS21056L5K	VN103-D2-054
MS21056L06W	VN103-D3-62
MS21056L08W	VN103-D3-82
MS21056L3W	VN103-D3-02
MS21056L4W	VN103-D3-048
MS21056L5W	VN103-D3-054
MS21056L6W	VN103-D3-064

MS21057 NUT, SELF-LOCKING, PLATE, CORNER, 100° CSK, LOW HEIGHT, ALLOY STEEL, 125 KSI Ftu, 450 DEG F

MS21057-08	T7SH832CPC	NAWC Report	Boots Nut Division
MS21057-3	T7SH1032CPC	601Q9004 of	Republic Fasteners
MS21057-4	T7SH428CPC	22 Jan 90	1300 Rancho Conejo Blvd
MS21057-08K	T7SH832BCCPC		Newbury Park, CA 91320
MS21057-3K	T7SH1032BCCPC		
MS21057-4K	T7SH428BCCPC		Plant: Same address
MS21057L08	T7SH832		
MS21057L3	T7SH1032		
MS21057L4	T7SH428		
MS21057L08K	T7SH832BC		
MS21057L3K	T7SH1032BC		
MS210574K	T7SH428BC		

MS21057-08	T7SH832CPC	Report No.	Cherry/Textron
MS21057-3	T7SH1032CPC	NAEC-AML-2428	Cherry Div. of
MS21057-4	T7SH428CPC	of 15 Mar 1966	Textron Inc.
MS21057-5	T7SH524CPC		P.0. Box 2157
MS21057-08K	T7SH832BCCPC		1224 East Warner Ave.
MS21057-3K	T7SH1032BCCPC		Santa Ana, CA 92707
MS21057-4K	T7SH428BCCPC		
MS21057-5K	T7SH5248CCPC		Plant: Same address
MS21057L08	T7SH832		
MS21057L3	T7SH1032		
MS21057L4	T7SH428		
MS21057L5	T7SH524		
MS21057L08K	T7SH832BC		
MS21057L3K	T7SH1032BC		
MS21057L4K	T7SH428BC		
MS21057L5K	T7SH524BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21057-08	F52LHTA35-82	NAEC-AML-2429	ESNA
MS210S7-3	F52LHTA35-02	of 15 Mar 1966*	Division of Harvard Industries
MS21057-4	F52LHTA35-048		
MS21057-5	F52LHTA35-054	*MUST BE MANUFACTURED	
MS21057L08	RM52LHTA35-82	AFTER 10 MAY 1994	
MS21057L3	RM52LHTA35-02	DISC-E-94130 LTR	
MS21057L4	RM52LHTA35-048		
MS21057L5	RM52LHTA35-054		
MS21057-08K	F52LHTA35-82BC		
MS21057-3K	F52LHTA35-02BC		
MS21057-4K	F52LHTA35-048BC		
MS21057-5K	F52LHTA35-054BC		
MS21057L08K	RM52LHTA35-82BC		
MS21057L3K	RM52LHTA35-02BC		
MS21057L4K	RM52LHTA35-048BC		
MS210S7L5K	RM52LHTA35-054BC		

MS21057-08	K3100-08CW	Report No.	Kaynar Technologies, Inc.
MS21057-3	K3100-3CW	NAEC-AML-2474	Kaynar Div.
MS21057-4	K3100-4CW	of 15 June 1966	P.0. Box 3001
MS21057-5	K3100-5CW		800 S. State Co11ege Blvd.
MS21057-08K	K3100-08BCCW		Fullerton, CA 92634
MS21057-3K	K3100-3BCCW		
MS21057-4K	K3100-4BCCW		Plant: Same address
MS21057-5K	K3100-5BCCW		
MS21057L08	K3100-08		
MS21057L3	K3100-3		
MS21057L4	K3100-4		
MS21057L5	K3100-5		
MS21057L08K	K3100-08BC		
MS21057L3K	K3100-3BC		
MS21057L4K	K3100-4BC		
MS21057L5K	K3100-5BC		

MS21057-08	R3100X08	Report No.	Republic Fastener Mfg. Corp
MS21057L08	R3100A08	305Q83088 of	1300 Rancho Conejo Blvd
MS21057-08K	R3100X08K	26 Jan 1983	Newbury Park, CA 91320
MS21057L08K	R3100A08K		
MS21057-3	R3100X3		Plant: Same address
MS21057L3	R3100A3		
MS21057-3K	R3100X3K		
MS21057L3K	R3100A3K		
MS21057-4	R3100X4		
MS21057L4	R3100A4		
MS21057-4K	R3100X4K		
MS21057L4K	R3100A4K		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21057-08	15620NM-82	Report No.	SPS Technologies
MS21057-3	15620NM-02	NAEC-AML-2369	2701 S. Harbor Blvd.
MS21057-4	15620NM-048	of 15 Mar 1966	Santa Ana, CA 92702
MS21057-5	15620NM-054		
MS21057L08	15620-82		Plant: Same address
MS21057L3	15620-02		
MS21057L4	15620-048		
MS21057L5	15620-054		
MS21057-08K	15620NM-82BC		
MS21057-3K	15620NM-02BC		
MS21057-4K	15620NM-048BC		
MS21057-5K	15620NM-054BC		
MS21057L08K	15620-828C		
MS21057L3K	15620-02BC		
MS21057L4K	15620-048BC		
MS21057L5K	15620-054BC		

MS21058 NUT, SELF-LOCKING, PLATE, CORNER, 100 DEG CSK, LOW HEIGHT, CRES, 125 KSI Ftu, 450°F & 800°F

MS21058-08	T7CH832	NAWC Report	Boots Nut Division
MS21058-3	T7CH1032	601Q9004 of	Republic Fasteners
MS21058-4	T7CH428	22 Jan 90	1300 Rancho Conejo Blvd
MS21058-08K	T7CH832BC		Newbury Park, CA 91320
MS21058-3K	T7CH1032BC		
MS21058-4K	T7CH428BC		Plant: Same address
MS21058-08W	T7CH832P		
MS21058-3W	T7CH1032P		
MS21058-4W	T7CH428P		
MS21058L08	T7CH832M		
MS21058L3	T7CH1032M		
MS21058L4	T7CH428M		
MS21058L08K	T7CH832BCM		
MS21058L3K	T7CH1032BCM		
MS21058L4K	T7CH428BCM		
MS21058L08W	T7CH832PM		
MS21058L3W	T7CH1032PM		
MS21058L04K	T7CH428PM		

MS21058-08	T7CH832	Report No.	Cherry/Textron
MS21058-3	T7CH1032	NAEC-AML-2428	Cherry Div. of
MS21058-4	T7CH428	of 15 Mar 1966	Textron Inc.
MS21058-5	T7CH524		P.0. Box 2157
MS21058-08K	T7CH832BC		1224 East Warner Ave.
MS21058-3K	T7CH1032BC		Santa Ana, CA 92707
MS21058-4K	T7CH428BC		
MS21058-5K	T7CH524BC		Plant: Same address
MS21058-08W	T7CH832P		
MS21058-3W	T7CH1032P		
MS21058-4W	T7CH428P		
MS21058-5W	T7CH524P		
MS21058L08	T7CH832M		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21058L3	T7CH1032M
MS21058L4	T7CH428M
MS21058L5	T7CH524M
MS21058L08K	T7CH832BCM
MS21058L3K	T7CH1032BCM
MS21058L4K	T7CH428BCM
MS21058L5K	T7CH524BCM
MS21058L08W	T7CH832PM
MS21058L3W	T7CH1032PM
MS21058L4W	T7CH428PM
MS21058L5W	T7CH524PM

MS21058L08	RMLHTA35-2860-82	NAEC-AML-2429	ESNA
MS21058L3	RMLHTA35-2860-02	of 15 Mar 1966 *	Division of Harvard Industries
MS21058L4	RMLHTA35-2860-048		
MS21058L5	RMLHTA35-2860-054	*MUST BE MANUFACTURED	
MS21058L08K	RMLHTA35-2860-82BC	AFTER 10 MAY 1994	
MS21058L3K	RMLHTA35-2860-02BC	DISC-E-94130 LTR	
MS21058L4K	RMLHTA35-2860-048BC		
MS21058L5K	RMLHTA35-2860-054BC		
MS210S8L08W	RMLHTA35-2860P-82		
MS21058L3W	RMLHTA35-2B60P-02		
MS21058L4W	RMLHTA35-2860P-048		
MS21058L5W	RMLHTA35-2860P-054		
MS21058-08	LHTA35-2860-82		
MS21058-3	LHTA35-2860-02		
MS21058-4	LHTA35-2860-048		
MS21058-5	LHTA35-2860-054		
MS21058-08K	LHTA35-2860-82BC		
MS21058-3K	LHTA35-2860-02BC		
MS21058-4K	LHTA35-2860-0488C		
MS21058-5K	LHTA35-2860-054BC		
MS21058-08W	LHTA35-2860P-82		
MS21058-3W	LHTA35-2860P-02		
MS21058-5W	LHTA35-2860P-054		

MS21058-08	R3100C08	Report No.	Republic Fastener Mfg. Corp
MS21058L08	R3100C08M	305Q83088 of	1300 Rancho Conejo Blvd
MS21058-08K	R3100C08K	26 Jan 1983	Newbury Park, CA 91320
MS21058L08K	R3100C08MK		
MS21058-08W	R3100C08W		Plant: Same address
MS21058L08W	R3100C08MW		
MS21058-3	R3100C3		
MS21058L3	R3100C3M		
MS21058-3K	R3100C3K		
MS21058L3K	R3100C3MK		
MS21058-3W	R3100C3H		
MS21058L3W	R3100C3MH		
MS21058-4	R3100C4		
MS21058L4	R3100C4M		
MS21058-4K	R3100C4K		

MS21058L4K	R3100C4MK	Report No.	
MS21058-4W	R3100C4W	305Q83088 of	
MS21058L4W	R3100C4MW	26 Jan 1983	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21058-08	K3131-08	Report No.	Kaynar Technologies, Inc.
MS21058-3	K3131-3	NAEC-AML-2474	Kaynar Div.
MS21058-4	K3131-4	of 15 Jun 1966	P.0. Box 3001
MS21058-5	K3131-5		800 S. State College Blvd.
MS21058-08K	K3131-08BC		Fullerton, CA 92634
MS21058-3K	K3131-3BC		
MS21058-4K	K3131-4BC		Plant: Same address
MS21058-5K	K3131-5BC		
MS21058-08W	K3131-08P		
MS21058-3W	K3131-3P		
MS21058-4W	K3131-4P		
MS21058-5W	K3131-5P		
MS21058L08	K3101-08		
MS21058L3	K3101-3		
MS21058L4	K3101-4		
MS21058L5	K3101-5		
MS21058L08K	K3101-08BC		
MS21058L3K	K3101-3BC		
MS21058L4K	K3101-4BC		
MS21058L5K	K3101-5BC		
MS21058L08W	K3101-08P		
MS21058L3W	K3101-3P		
MS21058L4W	K3101-4P		
MS21058L5W	K3101-5P		

MS21058-08	15720-82	Report No.	SPS Technologies
MS21058-3	15720-02	NAEC-AML-2369	2701 S. Harbor Blvd.
MS21058-4	15720-048	of 15 Mar 1966	Santa Ana, CA 92702
MS210S8-5	15720-054		
MS21058-08K	15720-82BC		Plant: Same address
MS21058-3K	15720-02BC		
MS21058-4K	15720-048BC		
MS21058-5K	15720-054BC		
MS21058-08W	15720-B2PW		
MS21058-3W	15720-02PW		
MS21058-4W	5720-048PN		
MS21058-5W	15720-054PW		
MS21058L08	15720E-82		
MS21058L3	15720E-02		
MS21058L4	15720E-048		
MS21058L5	15720E-054		
MS21058L08K	15720E-82BC		
MS21058L3K	15720E-02BC		
MS21058L4K	15720E-048BC		
MS21058L5K	15720E-054BC		
MS21058L08H	15720E-82PH		
MS21058L3H	15720E-02PH		
MS21058L4W	15720E-048PW		
MS21058L5H	15720E-054PW		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21059 NUT, SELF-LOCKING, PLATE, TWO LUG, FLOATING, LOW HEIGHT, ALLOY STEEL, 125 KSI Ftu, 450°F

MS21059-04	T65S440SCPC	NAWC Report	Boots Nut Division
MS21059-06	T65S632SCPC	601Q9004 of	Republic Fasteners
MS21059-08	T65S832SCPC	22 Jan 90	1300 Rancho Conejo Blvd
MS21059-3	T65S1032SCPC		Newbury Park, CA 91320
MS21059-4	T65S428SCPC		
MS21059-5	T65S524SCPC		Plant: Same address
MS21059-6	T65S624SCPC		
MS21059L04	T65S440S		
MS21059L06	T65S632S		
MS21059L08	T65S832S		
MS21059L3	T65S1032S		
MS21059L4	T65S428S		
MS21059L5	T65S524S		
MS21059L6	T65S624S		
MS21059-04K	T65S440SBCCPC		
MS21059-06K	T65S632SBCCPC		
MS21059-08K	T65S832SBCCPC		
MS21059-3K	T65S1032SBCCPC		
MS21059-4K	T65S428SBCCPC		
MS21059-5K	T65S524SBCCPC		
MS21059L04K	T65S440SBC		
MS21059L06K	T65S632SBC		
MS21059L08K	T65S832SBC		
MS21059L3K	T65S1032SBC		
MS21059L4K	T65S428SBC		
MS21059L5K	T65S524SBC		

MS21059-04	T65S440SCPC	Report No.	Cherry/Textron
MS21059-06	T65S632SCPC	NAEC-AML-2428	Cherry Div. of
MS21059-08	T65S832SCPC	of 15 Mar 1966	Textron Inc.
MS21059-3	T65S1032SCPC		P.0. Box 2157
MS21059-4	T65S428SCPC		1224 East Warner Ave.
MS21059-5	T65S524SCPC		Santa Ana, CA 92707
MS21059-6	T65S624SCPC		
MS21059L04	T65S440S		Plant: Same address
MS21059L06	T65S632S		
MS21059L08	T65S832S		
MS21059L3	T65S1032S		
MS21059L4	T65S428S		
MS21059L5	T65S524S		
MS21059L6	T65S624S		
MS21059-04K	T65S440SBCCPC		
MS21059-06K	T65S632SBCCPC		
MS21059-08K	T65S832SBCCPC		
MS21059-3K	T65S1032SBCCPC		
MS21059-4K	T65S428SBCCPC		
MS21059-5K	T65S524SBCCPC		
MS21059L04K	T65S440SBC		
MS21059L06K	T65S632SBC		
MS21059L08K	T65S832SBC		
MS21059L3K	T65S1032SBC		
MS21059L4K	T65S428SBC		
MS21059L5K	T65S524SBC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21059-04	F52LHTA521-40	NAEC-AML-2429	ESNA
MS21059-06	F52LHTA521-62	of 15 Mar 1966	Division of Harvard Industries
MS21059-08	F52LHTA521-82		
MS21059-3	F52LHTA521-02	*MUST BE MANUFACTURED	
MS21059-4	F52LHTA521-048	AFTER 10 MAY 1994	
MS21059-5	F52LHTA521-054	DISC-E-94130 LTR	
MS21059-6	F52LHTA521-064		
MS21059L04	RM52LHTA521-40		
MS21059L06	RM52LHTA521-62		
MS21059L08	RM52LHTA521-82		
MS21059L3	RM52LHTA521-02		
MS21059L4	RM52LHTA521-048		
MS21059L5	RM52LHTA521-054		
MS21059L6	RM52LHTA521-064		
MS21059-04K	F52LHTA521-40BC		
MS21059-06K	F52LHTA521-62BC		
MS21059-08K	F52LHTA521-82BC		
MS21059-3K	F52LHTA521-02BC		
MS21059-4K	F52LHTA521-048BC		
MS21059-5K	F52LHTA521-054BC		
MS21059L04K	RM52LHTA521-40BC		
MS21059L06K	RM52LHTA521-62BC		
MS21059L08K	RM52LHTA521-82BC		
MS21059L3K	RM52LHTA521-02BC		
MS21059L4K	RM52LHTA521-048BC		
MS21059L5K	RM52LHTA521-054BC		

MS21059-04	F5000-04CW	Report No.	Kaynar Technologies, Inc.
MS21059-06	F5000-06CW	NAEC-AML-2474	Kaynar Div.
MS21059-08	F5000-08CW	of 15 June 1966	P.0. Box 3001
MS21059-3	F5000-3CW		800 S. State College Blvd.
MS21059-4	F5000-4CW		Fullerton, CA 92634
MS21059-5	F5000-5CW		
MS21059-6	F5000-6CW		Plant: Same address
MS21059-04K	F5000-04BCCW		
MS21059-06K	F5000-06BCCW		
MS21059-08K	F5000-08BCCW		
MS21059-3K	F5000-3BCCW		
MS21059-4K	F5000-4BCCW		
MS21059-5K	F5000-5BCCW		
MS21059L04	F5000-04		
MS21059L06	F5000-06		
MS21059L08	F5000-08		
MS21059L3	F5000-3		
MS21059L4	F5000-4		
MS21059L5	F5000-5		
MS21059L6	F5000-6		
MS21059L04K	F5000-04BC		
MS21059L06K	F5000-06BC		
MS21059L08K	F5000-08BC		
MS21059L3K	F5000-3BC		
MS21059L4K	F5000-4BC		
MS21059L5K	F5000-5BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21059-04	RF200X04	Report No.	Republic Fastener Mfg. Corp.
MS21059L04	RF200A04	305Q73001 of	1300 Rancho Conejo Blvd.
MS21059-04K	RF200X04K	6 Feb 1973	Newbury Park, CA 91320
MS21059L04K	RF200A04K		
MS21059-06	RF200X06		Plant: Same address
MS21059L06	RF200A06		
MS21059-06K	RF200X06K		
MS21059L06K	RF200A06K		
MS21059-08	RF200X08		
MS21059L08	RF200A08		
MS21059-08K	RF200X08K		
MS21059L08K	RF200A08K		
MS21059-3	RF200X3		
MS21059L3	RF200A3		
MS21059-3K	RF200X3K		
MS21059-L3K	RF200A3K		
MS21059-4	RF200X4		
MS21059L4	RF200A4		
MS21059-4K	RF200X4K		
MS21059L4K	RF200A4K		

Note: "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124 of 20 November 1970.

MS21059-5	RF200X5	Report No.
MS21059L5	RF200A5	305Q76023 of
MS21059-5K	RF200X5K	14 May 1976
MS21059L5K	RF200A5K	
MS21059-6	RF200X6	NADC Report No.
MS21059L6	RF200A6	305Q76024 of
		8 Oct 1976

MS21059-7	RF200X7	Report No.
MS21059L7	RF200A7	601Q9310 of
		21 Apr 93

Notes: 1. Manufacturing Process: Machined
2. Lubricant: (For Government Designation with "L")
Kal-Gard FA per MIL-L-46010, Type I

MS21059L3	LA-93M	Report No.	Simmonds Mecaero
		305Q83101 of	Fasteners, Inc.
		5 May 1 983	1734 Sequoia Avenue
			Orange, CA 92668

MS21059L3K	LA-93MK	Report No.	Plant:
		305Q83104 of	Simmonds
		12 Aug 1983	Usine De Champaissant
			72110 Saint-Cosme En Vairais
			France
MS21059L08	LA-908M	Report No.	
MS21059L08K	LA-908MK	305Q83112 of	
		28 Nov 1983	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21059-08	LA-908	Report No.
MS21059-3	LA-93	601Q8407 of
		20 Apr 1984

Note: 1. Manufacturing process: Cold formed
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21059-4	LA-94	NADC Report
MS21059-4K	LA-94K	601QB417 of
MS21059L4	LA-94M	25 Oct 1984
MS21059L4K	LA-94MK	

MS21059-06	LA-906	NADC Report
MS21059-06K	LA-906K	601QB510 of
MS21059L06	LA-906M	10 Jun 1985
MS21059L06K	LA-906MK	

Note: 1. Manufacturing process: Cold formed
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21059-04	13605NM-40	Report No.	SPS Technologies
MS21059-06	13605NM-62	NAEC-AML-2369	2701 S. Harbor Blvd.
MS21059-08	13605NM-82	of 15 Mar 1966	Santa Ana, CA 92702
MS21059-3	13605NM-02		
MS21059-4	13605NM-048		Plant: Same address
MS21059-5	13605NM-054		
MS21059-6	13605NM-064		
MS21059L04	13605-40		
MS21059L06	13605-62		
MS21059L08	13605-82		
MS21059L3	13605-02		
MS21059L4	13605-048		
MS21059L5	13605-054		
MS21059L6	13605-064		
MS21059-04K	13605NM-40BC		
MS21059-06K	13605NM-62BC		
MS21059-08K	13605NM-82BC		
MS21059-3K	13605NM-02BC		
MS21059-4K	13605NM-048BC		
MS21059-5K	13605NM-054BC		
MS21059L04K	13605NM-40BC		
MS21059L06K	13605-62BC		
MS21059L08K	13605-82BC		
MS21059L3K	13605-02BC		
MS21059L4K	13605-048BC		
MS21059L5K	13605-054BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21059-04	VN152-C1-40	Report No.	VOI-SHAN
MS21059-06	VN152-C1-62	NAEC-AML-2425	Fairchild Aerospace Fastener Div
MS21059-08	VN152-C1-82	of 15 Mar 1966	2950 W. Lomita Blvd.
MS21059-3	VN152-C1-02		Torrance, CA 90505-5103
MS21059-4	VN152-C1-048		
MS21059-5	VN152-C1-054		Plant: Same address
MS21059-6	VN152-C1-064		
MS21059L04	VN152-A1-40		
MS21059L06	VN152-A1-62		
MS21059L08	VN152-A1-82		
MS21059L3	VN152-A1-02		
MS21059L4	VN152-A1-048		
MS21059L5	VN152-A1-054		
MS21059L6	VN152-A1-064		
MS21059-04K	VN152-C2-40		
MS21059-06K	VN152-C2-62		
MS21059-08K	VN152-C2-82		
MS21059-3K	VN152-C2-02		
MS21059-4K	VN152-C2-048		
MS21059-5K	VN152-C2-054		
MS21059L04K	VN152-A2-40		
MS21059L06K	VN152-A2-62		
MS21059L08K	VN152-A2-82		
MS21059L3K	VN152-A2-02		
MS21059L4K	VN152-A2-048		
MS21059L5K	VN152-A2-054		

MS21060 NUT, SELF-LOCKING, PLATE, TW0 LUG, FLOATING, LOW HEIGHT, CRES, 125 KSI Ftu, 450°F & 800°F

MS21060-04	T65C440C	NAWC Report	Boots Nut Division
MS21060-06	T65C632C	601Q9004 of	Republic Fasteners
MS21060-08	T65C832C	22 Jan 90	1300 Rancho Conejo Blvd
MS21060-3	T65C103C		Newbury Park, CA 91320
MS21060-4	T65C428C		
MS21060-5	T65C524C		Plant: Same address
MS21060-6	T65C624C		
MS21060L04	T65C440S		
MS21060L06	T65C632S		
MS21060L08	T65C832S		
MS21060L3	T65C1032S		
MS21060L4	T65C428S		
MS21060L5	T65C524S		
MS21060L6	T65C624S		
MS21060-04K	T65C440SBCCPC		
MS21060-06K	T65C632SBCCPC		
MS21060-08K	T65C832SBCCPC		
MS21060-3K	T65C1032SBCCPC		
MS21060-4K	T65C428SBCCPC		
MS21060-5K	T65C524SBCCPC		
MS21060L04K	T65C440SBC		
MS21060L06K	T65C632SBC		
MS21060L08K	T65C832SBC		
MS21060L3K	T65C1032SBC		
MS21060L4K	T65C428SBC		
MS21060L5K	T65C524SBC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21060-04	T65C440C	Report No.	Cherry/Textron
MS21060-06	T65C632C	NAEC-AML-2428	Cherry Div. of
MS21060-08	T65C832C	of 15 Mar 1966	Textron Inc.
MS21060-3	T65C1032C		P.0. Box 2157
MS21060-4	T65C428C		1224 East Narner Ave.
MS21060-5	T65C524C		Santa Ana, CA 92707
MS21060-6	T65C624C		
MS21060-04K	T65C440CBC		Plant: Same address
MS21060-06K	T6SC632CBC		
MS21060-08K	T65C832CBC		
MS21060-3K	T65C1032CBC		
MS21060-4K	T65C428CBC		
MS21060-SK	T65C524CBC		
MS21060-04N	T65C440CPWB		
MS21060-06W	T65C632CPWB		
MS21060-08W	T65C832CPWB		
MS21060-3W	T65C1032CPWB		
MS21060-4W	T65C428CPWB		
MS21060-5W	T65C524CPWB		
MS21060-6H	T65C624CPHB		
MS21060L04	T65C440CM		
MS21060L06	T65C632CM		
MS21060L08	T65C832CM		
MS21060L3	T65C1032CM		
MS21060L4	T65C428CM		
MS21060L5	T65C524CM		
MS21060L6	T65C624CM		
MS21060L04K	T65C440CBCM		
MS21060L06K	T65C632CBCM		
MS21060L08K	T65C832CBCM		
MS21060L3K	T65C1032CBCM		
MS21060L4K	T65C428CBCM		
MS21060L5K	T65C524CBCM		
MS21060L04W	T65C440CPM		
MS21060L06W	T65C632CPM		
MS21060L08W	T65C832CPM		
MS21060L3W	T65C1032CPM		
MS21060L4W	T65C428CPM		
MS21060L5W	T65C524CPM		
MS21060L6W	T65C624CPM		

MS21060L04	RMLHTA521-2860-40	NAEC-AML-2429	ESNA
MS21060L06	RMLHTA521-2860-62	of 15 Mar 1966*	Division of Harvard Industries
MS21060L08	RMLHTA521-2860-82		
MS21060L3	RMLHTA521-2860-02		
MS21060L4	RMLHTA521-2860-048		
MS21060L5	RMLHTA521-2860-054		
MS21060L6	RMLHTA521-2860-064		
MS21060L04K	RMLHTA521-2860-40BC		
MS21060L06K	RMLHTAS21-2860-62BC		
MS21060L08K	RMLHTA521-2860-82BC		
MS21060L3K	RMLHTA521-2860-02BC		
MS21060L4K	RMLHTA521-2860-048BC		
MS21060L5K	RMLHTA521-2860-054BC		
MS21060L04N	RMLHTA521-2860P-40		
MS21060L06W	RMLHTA521-2860P-62		
MS21060L08W	RMLHTA521-2860P-82		
MS21060L3W	RMLHTA521-2860P-02		
MS21060L4W	RMLHTA521-2860P-048		
MS21060L5W	RMLHTA521-2860P-054	*MUST BE MANUFACTURED	
MS21060L6W	RMLHTA521-2860P-064	AFTER 10 MAY 1994	
MS21060-04	LHTA521-2860-40	DISC-E-94130 LTR	
MS21060-06	LHTA521-2860-62		
MS21060-08	LHTA521-2860-82		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21060-3	LHTA521-2860-02
MS21060-4	LHTA521-2860-048
MS21060-5	LHTA521-2860-054
MS21060-6	LHTA521-2860-064
MS21060-04K	LHTA521-2860-40BC
MS21060-06K	LHTA521-2860-62BC
MS21060-08K	LHTA521-2860-82BC
MS21060-3K	LHTA521-2860-02BC
MS21060-4K	LHTA521-2860-048BC
MS21060-5K	LHTA521-2860-054BC
MS21060-04N	LHTA521-2860P-40
MS21060-06W	LHTA521-2860P-62
MS21060-08W	LHTA521-2860P-82
MS21060-3W	LHTA521-2860P-02
MS21060-4H	LHTA521-2860P-048
MS21060-5W	LHTA521-2860P-054
MS21060-6W	LHTA521-2860P-064

MS21060-04	F5031-04	Report No.	Kaynar Technologies, Inc.
MS21060-06	F5031-06	NAEC-AML-2474	Kaynar Div.
MS21060-08	F5031-08	of 15 Jun 1966	P.0. Box 3001
MS21060-3	F5031-3		800 S. State College Blvd.
MS21060-4	F5031-4		Fullerton, CA 92634
MS21060-5	F5031-5		
MS21060-6	F5031-6		Plant: Same address
MS21060-04K	F5031-04BC		
MS21060-06K	F5031-06BC		
MS21060-08K	F5031-08BC		
MS21060-3K	F5031-3BC		
MS21060-4K	F5031-4BC		
MS21060-5K	F5031-5BC		
MS21060-04W	F5031-04P		
MS21060-06W	F5031-06P		
MS21060-08W	F5031-08P		
MS21060-3W	F5031-3P		
MS21060-4W	F5031-4P		
MS21060-5W	F5031-5P		
MS21060-6W	F5031-6P		
MS21060L04	F5001-04		
MS21060L06	F5001-06		
MS21060L08	F5001-08		
MS21060L3	F5001-3		
MS21060L4	F5001-4		
MS21060L5	F5001-5		
MS21060L6	F5001-6		
MS21060L04K	F5001-04BC		
MS21060L06K	F5001-06BC		
MS21060L08K	F5001-08BC		
MS21060L3K	F5001-3BC		
MS21060L4K	F5001-4BC		
MS21060L5K	F5001-5BC		
MS21060L04W	F5001-04P		
MS21060L06W	F5001-06P		
MS21060L08W	F5001-08P		
MS21060L3W	F5001-3P		
MS21060L4W	F5001-4P		
MS21060L5W	F5001-5P		
MS21060L6W	F5001-6P		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21060L04	RF200C04M	Report No.	Republic Fastener Mfg. Corp.
MS21060L04K	RF200C04MK	305Q73001 of	1300 Rancho Conejo Blvd.
MS21060L04W	RF200C04MW	6 Feb 1973	Newbury Park, CA 91320
MS21060-04	RF200C04		
MS21060-04K	RF200C04K		Plant: Same address
MS21060-04N	RF200C04W		
MS21060L06	RF200C06M		
MS21060L06K	RF200C06MK		
MS21060L06W	RF200C06MW		
MS21060-06	RF200C06		
MS21060-06K	RF200C06K		
MS21060-06W	RF200C06W		
MS21060L08	RF200C08M		
MS21060L08K	RF200C08MK		
MS21060L08W	RF200C08MW		
MS21060-08	RF200C08		
MS21060-08K	RF200C08K		
MS21060-08W	RF200C08W		
MS21060L3	RF200C3M		
MS21060L3K	RF200C3MK		
MS21060L3W	RF200C3MW		
MS21060-3	RF200C3		
MS21060-3K	RF200C3K		
MS21060-3H	RF200C3H		
MS21060L4	RF200C4M		
MS21060L4K	RF200C4MK		
MS21060L4W	RF200C4MW		
MS21060-4	RF200C4		
MS21060-4K	RF200C4K		
MS21060-4W	RF200C4W		

Note: "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124 of 20 November 1970.

MS21060-5	RF200C5	Report No.
MS21060L5	RF200C5M	305Q76023 of
MS21060-5K	RF200C5K	14 May 1976
MS21060L5K	RF200C5MK	
MS21060-5W	RF200C5W	
MS21060L5W	RF200C5MW	
MS21060L6	RF200C6M	
MS21060L6W	RF200C6MW	
MS21060-6	RF200C6	
MS21060-6W	RF200C6W	

MS21060-7	RF200C7	NAWC Report No.
MS21060L7	RF200C7M	601Q9310 of
		21 Apr 93

Notes: 1. Manufacturing Process: Machined
2. Lubricant: (For Government Designation with "L")
Kal-Gard FA per MIL-L-46010, Type I

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21060-08	LA-508	Report No.	Simmonds Mecaero
MS21060-08K	LA-508K	601Q8401 of	Fasteners, Inc.
MS21060-3	LA-53	24 Feb 1984	1734 Sequoia Avenue
MS21060-3K	LA-53K		Orange, CA 92668

Note: 1. Manufacturing process: Cold formed
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

Plant:
Simmonds
Usine De Champaissant
72110 Saint-Cosme En Vairais
France

MS21060-4	LA-54	NADC Report
MS21060-4K	LA-54K	601Q8401 of
		25 Oct 1984

MS21060-06	LA-506	NADC Report
MS21060-06K	LA-506K	601Q8510 of
		10 Jun 1985

MS21060L08	LA-508M	NADC Report
MS21060L3	LA-53M	601Q8517 of
		16 Dec 1985

MS21060-04	LA-504	NADC Report
MS21060L04	LA-504M	601Q8609 of
MS21060L06	LA-506M	8 Aug 1986
MS21060L4	LA-54M	

Note: 1. Manufacturing process: Cold stamping
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21060-04	13705-40	Report No.	SPS Technologies
MS21060-06	13705-62	NAEC-AML-2369	2701 S. Harbor Blvd.
MS21060-08	13705-82	of 15 Mar 1966	Santa Ana, CA 92702
MS21060-3	13705-02		
MS21060-4	13705-048		Plant: Same address
MS21060-5	13705-054		
MS21060-6	13705-064		
MS21060-04K	13705-40BC		
MS21060-06K	13705-62BC		
MS21060-08K	13705-82BC		
MS21060-3K	13705-02BC		
MS21060-4K	13705-048BC		
MS21060-5K	13705-054BC		
MS21060-04H	13705-40PH		
MS21060-06W	13705-62PN		
MS21060-08N	13705-82PW		
MS21060-3N	13705-02PN		
MS21060-4W	13705-048PW		
MS21060-5W	13705-054PH		
MS21060-6W	13705-064PW		
MS21060L04	13705E-40		
MS21060L06	13705E-62		
MS21060L08	13705E-82		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21060L3	13705E-02
MS21060L4	13705E-048
MS21060L5	13705E-054
MS21060L6	13705E-064
MS21060L04K	13705E-40BC
MS21060L06K	13705E-62BC
MS21060L08K	13705E-82BC
MS21060L3K	13705E-02BC
MS21060L4K	13705E-048BC
MS21060L5K	13705E-054BC
MS21060L04W	13705E-40PW
MS21060L06W	13705E-62PW
MS21060L08W	13705E-82PW
MS21060L3H	13705E-02P*
MS21060L4W	13705E-048PW
MS21060L5W	13705E-054PW
MS21060L6W	13705E-064PW

MS21060-04	VN152-B1-40	Report No.	VOI-SHAN
MS21060-06	VN152-B1-62	NAEC-AML-2425	Fairchild Aerospace Fastener Div
MS21060-08	VN152-B1-82	of 15 Mar 1966	2950 W. Lomita Blvd.
MS21060-3	VN152-B1-02		Torrance, CA 90505-5103
MS21060-4	VN152-B1-048		
MS21060-5	VN152-B1-054		Plant: Same address
M21060-6	VN152-B1-064		
MS21060-04K	VN152-B2-40		
MS21060-06K	VN152-B2-62		
MS21060-08K	VN152-B2-82		
MS21060-3K	VN152-B2-02		
MS21060-4K	VN152-B2-048		
MS21060-5K	VN152-B2-054		
MS21060-04N	VN152-B3-40		
MS21060-06W	VN152-B3-62		
MS21060-08N	VN152-B3-B2		
MS21060-3W	VN152-B3-02		
MS21060-4W	VN152-B3-048		
MS21060-5W	VN152-B3-054		
MS21060-6N	VN152-B3-064		
MS21060L04	VN152-D1-40		
MS21060L06	VN152-D1-62		
MS21060L08	VN152-D1-82		
MS21060L3	VN152-D1-02		
MS21060L4	VN152-D1-048		
MS21060L5	VN152-D1-054		
MS21060L6	VN152-D1-064		
MS21060L04K	VN152-D2-40		
MS21060L06K	VN152-D2-62		
MS21060L08K	VN152-D2-82		
MS21060L3K	VN152-D2-02		
MS21060L4K	VN152-D2-048		
MS21060L5K	VN152-D2-054		
MS21060L04W	VN152-D3-40		
MS21060L06W	VN152-D3-62		
MS21060L08H	VN152-D3-82		
MS21060L3W	VN152-D3-02		
MS21060L4W	VN152-D3-048		
MS21060L5W	VN152-D3-054		
MS21060L6W	VN152-D3-064		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21061 NUT, SELF-LOCKING, PLATE, ONE LUG, FLOATING, LOW HEIGHT, ALLOY STEEL, 125 KSI Ftu, 450°F

MS21061-04	T66S440SCPC	NAWC Report	Boots Nut Division
MS21061-06	T66S632SCPC	601Q9004 of	Republic Fasteners
MS21061-08	T66S832SCPC	22 Jan 90	1300 Rancho Conejo Blvd
MS21061-3	T66S1032SCPC		Newbury Park, CA 91320
MS21061-4	T66S428SCPC		
MS21061-5	T66S524SCPC		Plant: Same address
MS21061L04	T66S440S		
MS21061L06	T66S632S		
MS21061L08	T66S832S		
MS21061L3	T66S1032S		
MS21061L4	T66S428S		
MS21061L5	T66S524S		
MS21061-04K	T66S440SBCCPC		
MS21061-06K	T66S632SBCCPC		
MS21061-08K	T66S832SBCCPC		
MS21061-3K	T66S1032SBCCPC		
MS21061-4K	T66S428SBCCPC		
MS21061-5K	T66S524SBCCPC		
MS21061L04K	T66S440SBC		
MS21061L06K	T66S632SBC		
MS21061L08K	T66S832SBC		
MS21061L3K	T66S1032SBC		
MS21061L4K	T66S428SBC		
MS21061L5K	T66S524SBCS		

MS21061-04	T66S440SCPC	Report No.	Cherry/Textron
MS21061-06	T66S632SCPC	NAEC-AML-2428	Cherry Div. of
MS21061-08	T66S832SCPC	of 15 Mar 1966	Textron Inc.
MS21061-3	T66S1032SCPC		P.0. Box 2157
MS21061-4	T66S428SCPC		1224 East Warner Ave.
MS21061-5	T66S524SCPC		Santa Ana, CA 92707
MS21061L04	T66S440S		
MS21061L06	T66S632S		Plant: Same address
MS21061L08	T66S832S		
MS21061L3	T66S1032S		
MS21061L4	T66S428S		
MS21061L5	T66S524S		
MS21061-04K	T66S440SBCCPC		
MS21061-06K	T66S632SBCCPC		
MS21061-08K	T66S832SBCCPC		
MS21061-3K	T66S1032SBCCPC		
MS21061-4K	T66S428SBCCPC		
MS21061-5K	T66S524SBCCPC		
MS21061L04K	T66S440SBC		
MS21061L06K	T66S632SBC		
MS21061L08K	T66S832SBC		
MS21061L3K	T66S1032SBC		
MS21061L4K	T66S428SBC		
MS21061L5K	T66S524SBC		

MS21061-04	F52LHTA517-40	NAEC-AML-2429	ESNA
MS21061-06	F52LHTA517-62	of 15 Mar 1966 *	Division of Harvard Industries
MS21061-08	F52LHTA517-82		
MS21061-3	F52LHTA517-02	*MUST BE MANUFACTURED	
MS21061-4	F52LHTA517-048	AFTER 10 MAY 1994	
MS21061-5	F52LHTA517-054	DISC-E-94130 LTR	
MS21061L04	RM52LHTA517-40		
MS21061L06	RM52LHTA517-62		
MS21061L08	RM52LHTA517-82		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21061L3	RM52LHTA517-02
MS21061L4	RM52LHTA517-048
MS21061L5	RMS2LHTA517-054
MS21061-04K	F52LHTA517-40BC
MS21061-06K	F52LHTA517-62BC
MS21061-08K	F52LHTA517-82BC
MS21061-3K	F52LHTA517-02BC
MS21061-4K	F52LHTA517-0488C
MS21061-5K	F52LHTA517-054BC
MS21061L04K	RM52LHTA517-40BC
MS21061L06K	RM52LHTA517-62BC
MS21061L08K	RM52LHTA517-82BC
MS21061L3K	RM52LHTA517-02BC
MS21061L4K	RM52LHTA517-048BC
MS21061L5K	RM52LHTA517-0548C

MS21061-04	F2000-04CW	Report No.	Kaynar Technologies, Inc.
MS21061-06	F2000-06CW	NAEC-AML-2474	Kaynar Div.
MS21061-08	F2000-08CW	of 15 June 1966	P.0. Box 3001
MS21061-3	F2000-3CCW		800 S. State College Blvd.
MS21061-4	F2000-4CW		Fullerton, CA 92634
MS21061-5	F2000-5CW		
MS21061-04K	F2000-04BCCW		Plant: Same address
MS21061-06K	F2000-06BCCW		
MS21061-08K	F2000-08BCCW		
MS21061-3K	F2000-3BCCW		
MS21061-4K	F2000-4BCCW		
MS21061-5K	F2000-5BCCW		
MS21061L04	F2000-04		
MS21061L06	F2000-06		
MS21061L08	F2000-08		
MS21061L3	F2000-3		
MS21061L4	F2000-4		
MS21061L5	F2000-5		
MS21061L04K	F2000-04BC		
MS21061L06K	F2000-06BC		
MS21061L08K	F2000-08BC		
MS21061L3K	F2000-3BC		
MS21061L4K	F2000-4BC		
MS21061L5K	F2000-5BC		

MS21061-04	RF100X04	Report No.	Republic Fastener Mfg. Corp.
MS21061-04K	RF100X04K	305Q73001 of	1300 Rancho Conejo Blvd.
MS21061L04	RF100A04	6 Feb 1973	Newbury Park, CA 91320
MS21061L04K	RF100A04K		
MS21061-06	RF100X06		Plant: Same address
MS21061-06K	RF100X06K		
MS21061L06	RF100A06		
MS21061L06K	RF100A06K		
MS21061-08	RF100X08		
MS21061-08K	RF100X08K		
MS21061L08	RF100A08		
MS21061L08K	RF100A08K		
MS21061-3	RF100X3		
MS21061-3K	RF100X3K		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21061L3	RF100A3
MS21061L3K	RF100A3K
MS21061-4	RF100X4
MS21061-4K	RF100X4K
MS21061L4	RF100A4
MS21061L4K	RF100A4K

Note: "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124 of 20 November 1970.

MS21061-5	RF100X5	Report No.
MS21061L5	RF100A5	305Q83088 of
MS21061-5K	RF100X5K	26 Jan 1983
MS21061L5K	RF100A5K	

MS21061L08	AJF-908M	Report No.	Simmonds Mecaero
MS21061L08K	AJF-908MK	305Q83112 of	Fasteners, Inc.
MS21061L3	AJF-93M	28 Nov 1983	1734 Sequoia Avenue
MS21061L3K	AJF-93MK		Orange, CA 92668

			Plant:
MS21061-08	AJF-908	Report No.	Simmonds
MS21061-3	AJF-93	601Q8407 of	Usine De Champaissant
		20 Apr 1984	72110 Saint-Cosme En Vairais
			France

Note: 1. Manufacturing process: Cold formed
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21061-4	AJF-94	NADC Report
MS21061-4K	AJF-94K	601Q8502 of
MS21061L4	AJF-94M	11 Mar 1985
MS21061L4K	AJF-94MK	

MS21061-06	AJF-906	NADC Report
MS21061-06K	AJF-906K	601Q8510 of
MS21061L06	AJF-906M	10 Jun 1985
MS21061L06K	AJF-906MK	

MS21061-04	AJF-904	NADC Repot
MS21061L04	AJF-904M	601Q8609 of
		8 Aug 1986

Note: 1. Manufacturing process: Cold stamping
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21061-04	13615NM-40	Report No.	SPS Technologies
MS21061-06	13615NM-62	NAEC-AML-2369	2701 S. Harbor Blvd.
MS21061-08	13615NM-82	of 15 Mar 1966	Santa Ana, CA 92702
MS21061-3	13615NM-02		
MS21061-4	13615NM-048		Plant: Same address
MS21061-5	13615NM-054		
MS21061L04	13615-40		
MS21061L06	13615-62		
MS21061L08	13615-82		
MS21061L3	13615-02		
MS21061L4	13615-048		
MS21061L5	13615-054		
MS21061-04K	13615NM-40BC		
MS21061-06K	13615NM-62BC		
MS21061-08K	13615NM-82BC		
MS21061-3K	13615NM-02BC		
MS21061-4K	13615NM-04BC		
MS21061-5K	13615NM-054BC		
MS21061L04K	3615-40BC		
MS21061L06K	13615-62BC		
MS21061L08K	13615-82BC		
MS21061L3K	13615-02BC		
MS21061L4K	13615-048BC		
MS21061L5K	13615-054BC		

MS21061-04	VN151-C1-40	Report No.	VOI-SHAN
MS21061-06	VN151-C1-62	NAEC-AML-2425	Fairchild Aerospace Fastener Div
MS21061-08	VN151-C1-82	of 15 Mar 1966	2950 W. Lomita Blvd.
MS21061-3	VN151-C1-02		Torrance, CA 90505-5103
MS21061-4	VN151-C1-048		
MS21061-5	VN151-C1-054		Plant: Same address
MS21061L04	VN151-A1-40		
MS21061L06	VN151-A1-62		
MS21061L08	VN151-A1-82		
MS21061L3	VN151-A1-02		
MS21061L4	VN151-A1-048		
MS21061L5	VN151-A1-054		
MS21061-04K	VN151-C2-40		
MS21061-06K	VN151-C2-62		
MS21061-08K	VN151-C2-82		
MS21061-3K	VN151-C2-02		
MS21061-4K	VN151-C2-048		
MS21061-5K	VN151-C2-054		
MS21061L04K	VN151-A2-40		
MS21061L06K	VN151-A2-62		
MS21061L08K	VN151-A2-82		
MS21061L3K	VN151-A2-02		
MS21061L4K	VN151-A2-048		
MS21061L5K	VN151-A2-054		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21062 NUT, SELF-LOCKING, PLATE, ONE LUG, FLOATING, LOW HEIGHT, CRES, 125 KSI Ftu, 450° & 800°F

MS21062-04	T65C440C	NAWC Report	Boots Nut Division
MS21062-06	T65C632C	601Q9004 of	Republic Fasteners
MS21062-08	T65C832C	22 Jan 90	1300 Rancho Conejo Blvd
MS21062-3	T65C103C		Newbury Park, CA 91320
MS21062-4	T65C428C		
MS21062-5	T65C524C		Plant: Same address
MS21062-04K	T66C440CBC		
MS21062-06K	T66C632CBC		
MS21062-08K	T66C832CBC		
MS21062-3K	T66C1032CBC		
MS20162-4K	T66C428CBC		
MS21062-5K	T66C524CBC		
MS21062-04W	T66C440CPWB		
MS21062-06W	T66C632CPWB		
MS21062-08W	T66C832CPWB		
MS21062-3W	T66C1032CPWB		
MS21062-4W	T66C428CPWB		
MS21062-5W	T66C524CPWB		
MS21062L04	T66C440CM		
MS21062L06	T66C632CM		
MS21062L08	T66C832CM		
MS21062L3	T66C1032CM		
MS21062L4	T66C428CM		
MS21062L5	T66C524CM		
MS21062L04K	T66C440CBCM		
MS21062L06K	T66C632CBCM		
MS21062L08K	T66C832CBCM		
MS21062L3K	T66C103CBCM		
MS21062L4K	T66C428CBCM		
MS21062L5K	T66C524CBCM		
MS21062L04W	T66C440CPM		
MS21062L06W	T66C632CPM		
MS21062L08W	T66C832CPM		
MS21062L3W	T66C1032CPM		
MS21062L4W	T66C428CPM		
MS21062L5W	T66C524CPM		

MS21062-04	T66C440C	Report No.	Cherry/Textron
MS21062-06	T66C632C	NAEC-AML-2428	Cherry Div. of
MS21062-08	T66C832C	of 15 Mar 1966	Textron Inc.
MS21062-3	T66C1032C		P. 0. Box 2157
MS21062-4	T66C428C		1224 East Warner Ave.
MS21062-5	T66C524C		Santa Ana, CA 92702
MS21062-04K	T66C440CBC		
MS21062-06K	T66C632CBC		Plant: Same address
MS21062-08K	T66C832CBC		
MS21062-3K	T66C1032CBC		
MS21062-4K	T66C428CBC		
MS21062-5K	T66C524CBC		
MS21062-04W	T66C440CPWB		
MS21062-06N	T66C632CPWB		
MS21062-08W	T66C832CPWB		
MS21062-3W	T66C1032CPWB		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21062-4W	T66C428CPWB
MS21062-5H	T66C524CPWB
MS21062L04	T66C440CM
MS21062L06	T66C632CM
MS21062L08	T66C832CM
MS21062L3	T66C1032CM
MS21062L4	T66C428CM
MS21062L5	T66C524CM
MS21062L04K	T66C440CBCM
MS21062L06K	T66C632CBCM
MS21062L08K	T66C832CBCM
MS21062L3K	T66C1032CBCM
MS21062L4K	T66C428CBCM
MS21062L5K	T66C524CBCM
MS21062L04N	T66C440CPM
MS21062L06W	T66C632CPM
MS21062L08W	T66C832CPM
MS21062L3W	T66C1032CPM
MS21062L4W	T66C428CPM
MS21062L5W	T66C524CPM

MS21062L04	RMLHTA517-2860-40	NAEC-AML-2429	ESNA
MS21062L06	RMLHTA517-2B60-62	of 15 Mar 1966	Division of Harvard Industries
MS21062L08	RMLHTA517-2860-82		
MS21062L3	RMLHTA517-2860-02	*MUST BE MANUFACTURED	
MS21062L4	RMLHTA517-2860-048	AFTER 10 MAY 1994	
MS21062L5	RMLHTA517-2860-054	DISC-E-94130 LTR	
MS21062L04K	RMLHTA517-2860-40BC		
MS21062L06K	RMLHTA517-2860-62BC		
MS21062L08K	RMLHTA517-2860-82BC		
MS21062L3K	RMLHTA517-2860-02BC		
MS21062L4K	RMLHTA517-2860-048BC		
MS21062L5K	RMLHTA517-2860-054BC		
MS21062L04W	RMLHTA517-2860P-40		
MS21062L06W	RMLHTA517-2860P-62		
MS21062L08W	RMLHTA517-2860P-82		
MS21062L3W	RMLHTA517-2860P-02		
MS21062L4W	RMLHTA517-2860P-048		
MS21062L5N	RMLHTA517-2860P-054		
MS21062-04	LHTA517-2860-40		
MS21062-06	LHTA517-2860-62		
MS21062-08	LHTA517-2860-82		
MS21062-3	LHTA517-2860-02		
MS21062-4	LHTA517-2860-048		
MS21062-5	LHTA517-2860-054		
MS21062-04K	LHTA517-2860-40BC		
MS21062-06K	LHTA517-2860-62BC		
MS21062-08K	LHTA517-2860-82BC		
MS21062-3K	LHTA517-2860-02BC		
MS21062-4K	LHTA517-2860-048BC		
MS21062-5K	LHTA517-2860-054BC		
MS21062-04W	LHTA517-2860P-40		
MS21062-06N	LHTA517-2860P-62		
MS21062-08W	LHTA517-2860P-82		
MS21062-3W	LHTA517-2860P-02		
MS21062-4W	LHTA517-2860P-048		
MS21062-5W	LHTA517-2860P-054		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21062-04	F2031-04	Report No.	Kaynar Technologies, Inc.
MS21062-06	F2031-06	NAEC-AML-2474	Kaynar Div.
MS21062-08	F2031-08	of 15 Jun 1966	P.0. Box 3001
MS21062-3	F2031-3		800 S. State College Blvd.
MS21062-4	F2031-4		Fullerton, CA 92634
MS21062-5	F2031-5		
MS21062-04K	F2031-04BC		Plant: Same address
MS21062-06K	F2031-06BC		
MS21062-08K	F2031-08BC		
MS21062-3K	F2031-3BC		
MS21062-4K	F2031-4BC		
MS21062-5K	F2031-5BC		
MS21062-04W	F2031-04P		
MS21062-06W	F2031-06P		
MS21062-08W	F2031-08P		
MS21062-3W	F2031-3P		
MS21062-4W	F2031-4P		
MS21062-5W	F2031-5P		
MS21062L04	F2001-04		
MS21062L06	F2001-06		
MS21062L08	F2001-08		
MS21062L3	F2001-3		
MS21062L4	F2001-4		
MS21062L5	F2001-5		
MS21062L04K	F2001-04BC		
MS21062L06K	F2001-06BC		
MS21062L08K	F2001-08BC		
MS21062L3K	F2001-3BC		
MS21062L4K	F2001-4BC		
MS21062L5K	F2001-5BC		
MS21062L04W	F2001-04P		
MS21062L06W	F2001-06P		
MS21062L08W	F2001-08P		
MS21062L3W	F2001-3P		
MS21062L4W	F2001-4P		
MS21062L5W	F2001-5P		

MS21062L04	RF100C04M	Report No.	Republic Fastener Mfg. Corp.
MS21062L04K	RF100C04MK	305Q73001 of	1300 Rancho Conejo Blvd.
MS21062L04W	RF100C04MW	6 Feb 1973	Newbury Park, CA 91320
MS21062-04	RF100C04		
MS21062-04K	RF100C04K		Plant: Same address
MS21062-04W	RF100C04W		
MS21062L06	RF100C06M		
MS21062L06K	RF100C06MK		
MS21062L06W	RF100C06MW		
MS21062-06	RF100C06		
MS21062-06K	RF100C06K		
MS21062-06M	RF100C06W		
MS21062L08	RF100C08M		
MS21062L08K	RF100C08MK		
MS21062L08	RF100C08MW		
MS21062-08	RF100C08		
MS21062-08K	RF100C08K		
MS21062-08W	RF100C08W		
MS21062L3	RF100C3M		
MS21062L3K	RF100C3MK		
MS21062L3W	RF100C3MW		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21062-3	RF100C3
MS21062-3K	RF100C3K
MS21062-3W	RF100C3W
MS21062L4	RF100C4M
MS21062L4K	RF100C4MK
MS21062L4W	RF100C4MW
MS21062-4	RF100C4
MS21062-4K	RF100C4K
MS21062-4W	RF100C4W

Note: "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124 of 20 November 1970.

MS21062-5	RF100C5	Report No.
MS21062L5	RF100C5M	305Q83088 of
MS21062-5K	RF100C5K	26 Jan 1983
MS21062L5K	RF100C5MK	
MS21062-5W	RF100C5W	
MS21062L5W	RF100C5MW	

MS21062-4	AJF-54	NADC Report	Simmonds Mecaero
MS21062-4K	AJF-54K	601Q8417 of	Fasteners, Inc.
		25 Oct 1984	1734 Sequoia Avenue
			Orange, CA 92668
MS21062-08	AJF-508	NADC Report	
MS21062-08K	AJF-508K	601Q8502 of	Plant:
MS21062-3	AJF-53	11 Mar 1985	Simmonds
MS21062-3K	AJF-53K		Usine De Champaissant
			72110 Saint-Cosme En Vairais
			France
MS21062L08	AJF-508M	NADC Report	
MS21062L3	AJF-53M	601Q8604 of	
MS21062L4	AJF-54M	12 Mar 1986	

Note: 1. Manufacturing process: Cold stamping
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21062-06	AJF-506	NADC Report
MS21062L06	AJF-506M	601Q8518 of
		30 Dec 1985

Note: 1. Manufacturing process: Cold forging
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governin(1 Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21062-04	13715-40	Report No.	SPS Technologies
MS21062-06	13715-62	NAEC-AML-2369	2701 S. Harbor Blvd.
MS21062-08	13715-82	of 15 Mar 1966	Santa Ana, CA 92702
MS21062-3	13715-02		
MS21062-4	13715-048		Plant: Same address
MS21062-5	13715-054		
MS21062-04K	13715-40BC		
MS21062-06K	13715-62BC		
MS21062-08K	13715-82BC		
MS21062-3K	13715-02BC		
MS21062-4K	13715-048BC		
MS21062-5K	13715-054BC		
MS21062-04W	13715-40PW		
MS21062-06H	13715-62PH		
MS21062-08W	13715-82PW		
MS21062-3H	13715-02PH		
MS21062-4W	13715-048PW		
MS21062-5W	13715-054PH		
MS21062L04	13715E-40		
MS21062L06	13715E-62		
MS21062L08	13715E-82		
MS21062L3	13715E-02		
MS21062L4	13715E-048		
MS21062L5	13715E-054		
MS21062L04K	13715E-40BC		
MS21062L06K	13715E-62BC		
MS21062L08K	13715E-82BC		
MS21062L3K	13715E-02BC		
MS21062L4K	13715E-048BC		
MS21062L5K	13715E-054BC		
MS21062L04H	13715E-40PW		
MS21062L06W	13715E-62PW		
MS21062L08W	13715E-82PW		
MS21062L3W	13715E-02PW		
MS21062L4W	13715E-048PW		
MS21062L5W	13715E-054PN		

MS21062-04	VN151-B1-40	Report No.	VOI-SHAN
MS21062-06	VN151-B1-62	NAEC-AML-2425	Fairchild Aerospace Fastener Div
MS21062-08	VN151-B1-82	of 15 Mar 1966	2950 W. Lomita Blvd.
MS21062-3	VN151-B1-02		Torrance, CA 90505-5103
MS21062-4	VN151-B1-048		
MS21062-5	VN151-B1-054		Plant: Same address
MS21062-04K	VN151-B2-40		
MS21062-06K	VN151-B2-62		
MS21062-08K	VN151-B2-82		
MS21062-3K	VN151-B2-02		
MS21062-4K	VN151-B2-048		
MS21062-5K	VN151-B2-054		
MS21062-04W	VN151-B3-40		
MS21062-06N	VN151-B3-62		
MS21062-08H	VN151-B3-82		
MS21062-3W	VN151-B3-02		
MS21062-4W	VN151-B3-048		
MS21062-5W	VN151-B3-054		
MS21062L04	VN151-D1-40		
MS21062L06	VN151-D1-62		
MS21062L08	VN151-D1-82		
MS21062L3	VN151-D1-02		
MS21062L4	VN151-D1-048		
MS21062L5	VN151-D1-054		
MS21062L04K	VN151-D2-40		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21062L06K	VN151-D2-62
MS21062L08K	VN151-D2-82
MS21062L3K	VN151-D2-02
MS21062L4K	VN151-D2-048
MS21062L5K	VN151-D2-054
MS21062L04W	VN151-D3-40
MS21062L06N	VN151-D3-62
MS21062L08W	VN151-D3-82
MS21062L3W	VN151-D3-02
MS21062L4W	VN151-D3-048
MS21062L5W	VN151-D3-054

MS21063 NUT, SELF-LOCKING, CHANNEL, FLOATING, LOW HEIGHT, STEEL, 125 KSI Ftu, 250°

MS21063-08	BGC21063-08	NADC Report	Bristol Industries
MS21063-3	BGC21063-3	601Q8419 of	630 E. Lambert Rd.
MS21063-4	BGC21063-4	9 Nov 1984	P.0. Box 630
			Brea, CA 92621
MS21063L08	BGC21063L08	NADC Report	Plant: Same address
MS21063L3	BGC21063L3	601Q8703 of	
MS21063L4	BGC21063L4	3 Mar 1987	

MS21063-08-( )	T63S832-( )CPC	Report No.	Cherry/Textron
MS21063-3-( )	T63S1032-( )CPC	NAEC-AML-2428	Cherry Div. of
MS21063-4-( )	T63S428-( )CPC	of 15 Mar 1966	Textron Inc.
MS21063-5-( )	T63SS24-( )CPC		P.0. Box 2157
MS21063L08-( )	T63S832-( )		1224 East Warner Ave.
MS21063L3-( )	T63S1032-( )		Santa Ana, CA 92707
MS21063L4-( )	T63S428-( )		
MS21063L5-( )	T63S524-( )		Plant: Same address

MS21063-08-( )	F52LHTG51-82-( )	NAEC-AML-2429	ESNA
MS21063-3-( )	F52LHTG51-02-( )	of 15 Mar 1966 *	Division of Harvard Industries
MS21063-4-( )	F52LHTG51-048-( )		
MS21063-5-( )	F52LHTG51-054-( )	*MUST BE MANUFACTURED	
MS21063-6-( )	F52LHTG51-064-( )	AFTER 10 MAY 1994	
MS21063L08-( )	RM52LHTG51-82-( )	DISC-E-94130 LTR	
MS21063L3-( )	RM52LHTG51-02-( )		
MS21063L4-( )	RM52LHTG51-048-( )		
MS21063L5-( )	RMS2LHTG51-054-( )		
MS21063L6-( )	RM52LHTG51-064-( )		

MS21063-08-( )	G1000-08-( ) CW	Report No.	Kaynar Technologies, Inc.
MS21063-3-( )	G1000-3-( ) CW	NAEC-AML-2474	Kaynar Div.
MS21063-4-( )	G1000-4-( ) CW	of 15 Jun 1966	P.0. Box 3001
MS210B3-5-( )	G1000-5-( ) CW		800 S. State College Blvd.
MS21063-6-( )	G1000-6-( ) CW		Fullerton, CA 92634
MS21063L08-( )	G1000-08-( )		
MS21063L3-( )	G1000-3-( )		Plant: Same address
MS21063L4-( )	G1000-4-( )		
MS21063L5-( )	G1000-5-( )		
MS21063L6-( )	G1000-6-( )		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21063-08-( )	937RS908-( )	NADC Report	Simmonds Mecaero
MS21063-3-( )	937RS93-( )	601Q8418 of	Fasteners, Inc.
MS21063-4-( )	937RS94-( )	26 Oct 1984	1734 Sequoia Avenue
MS21063L08-( )	937RS908M-( )		Orange, CA 92668
MS21063L3-( )	937RS93M-( )		
MS21063L4-( )	937RS94M-( )		Plant: Same address and
			Simmonds S.A.
			Usine De Chapaissant
			72111 Saint-Cosme En Vairais
MS21063-4-( )	937 RS 94-( )	NAWC Report	France
MS21063L4-( )	937 RS 94M-( )	601Q9217 of	
		28 Dec 1992	

Note: 1. Manufacturing process: Cold stamping
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21063-08-( )	937RS908-( )	Report No.	Simmonds Mecaero Fasteners, Inc.
MS21063L08-( )	937RS908M-( )	435Q9512 of	1734 Sequoia Avenue
		26 May 1995	Orange, CA 92668

Note: 1. Manufacturing process: Cold stamping
2. Lubricant: (For Government Designation with "L") QPL-8937

Plant: Same address

MS21063-08-( )	C182-82-( )NM	Report No.	SPS Technologies
MS21063-3-( )	C182-3-( )NM	601Q8406 of	2701 South Harbor Blvd.
MS21063-4-( )	C182-4-( )NM	20 Mar 1984	Santa Ana, CA 92702
MS21063-5-( )	C182-5-( )NM		
MS21063-6-( )	C182-6-( )NM		Plant: Same address
MS21063L08-( )	C182-82-( )		
MS21063L3-( )	C182-3-( )		
MS21063L4-( )	C182-4-( )		
MS21063L5-( )	C182-5-( )		
MS21063L6-( )	C182-6-( )		

MS21064 NUT, SELF-LOCKING, CHANNEL, FLOATING, LOW HEIGHT, STEEL, 125 KSI Ftu, 450°F

MS21064-08	BGC21064-08	NADC Report	Bristol Industries
MS21064-3	BGC21064-3	601Q8419 of	630 E. Lambert Rd.
MS21064-4	BGC21064-4	9 Nov 1984	P.0. Box 630
			Bre
92621			
MS21064L08	BGC21064L08	NADC Report	Plant: Same address
MS21064L3	BGC21064L3	601Q8703 of	
MS21064L4	BGC21064L4	3 Mar 1987	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21064-08-( )	TC63S832-( )CPC	Report No.	Cherry/Textron
MS21064-3-( )	TC63S1032-( )CPC	NAEC-AML-2428	Cherry Div. of
MS21064-4-( )	TC63S428-( )CPC	of 15 Mar 1966	Textron Inc.
MS21064-5-( )	TC63S524-( )CPC		P.0. Box 2157
MS21064L08-( )	TC63S832-( )		1224 East Warner Ave.
MS21064L3-( )	TC63S1032-( )		Santa Ana, CA 92702
MS21064L4-( )	TC63S428-( )		
MS21064L5-( )	TC63S524-( )		Plant: Same address

MS21064-08-( )	F52LHTG51-82-( )	NAEC-AML-2429	ESNA
MS21064-3-( )	F52LHTG51-02-( )	of 15 Mar 1966*	Division of Harvard Industries
MS21064-4-( )	F52LHTG51-048-( )		
MS21064-5-( )	F52LHTG51-054-( )	*MUST BE MANUFACTURED	
MS21064L08-( )	RMS2LHTG51-82-( )	AFTER 10 MAY 1994	
MS21064L3-( )	RM52LHTG51-02-( )	DISC-E-94130 LTR	
MS21064L4-( )	RM52LHTG51-048-( )		
MS21064L5-( )	RM52LHTG51-054-( )		
MS21064L6-( )	RM52LHTG51-064-( )		

MS21064-08-( )	G1981-08-( ) CW	Report No.	Kaynar Technologies, Inc.
MS21064-3-( )	G1981-3-( ) CW	NAEC-AML-2474	Kaynar Div.
MS21064-4-( )	G1981-4-( ) CW	of 15 Jun 1966	P.0. Box 3001
MS21064-5-( )	G1981-5-( ) CM		800 S. State College Blvd.
MS21064L08-( )	G1981-08-( )		Fullerton, CA 92634
MS21064L3-( )	G1981-3-( )		
MS21064L4-( )	G1981-4-( )		Plant: Same address
MS21064L5-( )	G1981-5-( )		

MS21064-08-( )	95RS908-( )	NADC Report	Simmonds Mecaero
MS21064-3-( )	95RS93-( )	601Q8418 of	Fastener Inc.
MS21064-4-( )	95RS94-( )	26 Oct 1984	1734 Sequoia Avenue
			Orange, CA 92668
MS21064L08-( )	95RS908M-( )		
MS21064L3-( )	95RS93M-( )		Plant:
MS21064L4-( )	9SRS94M-( )		Simmonds
			Usine De Champaissant
			72110 Saint-Cosme En Vairais
			France

Note: 1. Manufacturing process: Cold stamping
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21064-4-( )	95 RS 94-( )	NADC Report	
MS21064L4-( )	95 RS 94M-( )	601Q9320 of	
		23 Dec 93	

Note: 1. Manufacturing Process: Cold Stamping
2. Nut Element Manufactured at France Plant Channel Manufactured at Orange, CA Plant
3. Lubricant: (For Government Designation with "L") Dow Corning 3400A per MIL-L-46010, Type II
4. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordanc
FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals).
The contractor should include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21064-08-( )	95RS9080( )	Report No.	Simmonds Mecaero Fasteners, Inc.
MS21064-3-( )	95RS93-( )	435Q9512 of	1734 Sequoia Avenue
MS21064L3-( )	95RS93M-( )	26 May 1995	Orange, CA 92663

Notes: 1. Manufacturing Process: Cold Stamping — Plant: Same address
2. Lubricant: (For Government Designation with "L")
QPL-46010

MS21064-08-( )	C184-82-( )NM	Report No.	SPS Technologies
MS21064-3-( )	C184-3-( )NM	601Q8406 of	2701 South Harbor Blvd.
MS21064-4-( )	C184-4-( )NM	20 Mar 1984	Santa Ana, CA 92702
MS21064-5-( )	C184-5-( )NM		
MS21064-6-( )	C184-6-( )NM		Plant: Same address
MS21064L08-( )	C184-82-( )		
MS21064L3-( )	C184-3-( )		
MS21064L4-( )	C184-4-( )		
MS21064L5-( )	C184-5-( )		
MS21064L6-( )	C184-6-( )		

MS21065 NUT, SELF-LOCKING, CHANNEL, FLOATING, LOW HEIGHT, CRES, 125 KSI Ftu, 450° & 800° F

MS21065-08	BGC21065-08	NADC Report	Bristol Industries
MS21065-3	BGC21065-3	601Q8419 of	630 E. Lambert Rd.
MS21065-4	BGC21065-4	9 Nov 1984	P.0. Box 630
			Brea, CA 92621
			Plant: Same address

MS21065L08-( )	TC63C832-( )M	Report No.	Cherry/Textron
MS21065L3-( )	TC63C1032-( )M	NAEC-AML-2428	Cherry Div. of
MS21065L4-( )	TC63C428-( )M	of 15 Mar 1966	Textron Inc.
MS21065L5-( )	TC63C524-( )M		P.0. Box 2157
MS21065-08-( )	TC63C832-( )		1224 East Warner Ave.
MS21065-3-( )	TC63C1032-( )		Santa Ana, CA 92707
MS21065-4-( )	TC63C428-( )		
MS21065-5-( )	TC63C524-( )		Plant: Same address

MS21065L08-( )	RMLHTG51-2B60-82-( )	NAEC-AML-2429	ESNA
MS21065L3-( )	RMLHTG51-2860-02-( )	of 15 Mar 1966*	Division of Harvard Industries
MS21065L4-( )	RMLHTG51-2860-048-( )		
MS21065L5-( )	RMLHTG51-2860-054-( )	*MUST BE MANUFACTURED	
MS21065L6-( )	RMLHTG51-2860-064-( )	AFTER 10 MAY 1994	
MS21065-08-( )	LHTG51-2860-82-( )	DISC-E-94130 LTR	
MS21065-3-( )	LHTG51-2860-02-( )		
MS21065-4-( )	LHTG51-2860-048-( )		
MS21065-5-( )	LHTG51-2860-054-( )		
MS21065-6-( )	LHTG51-2860-064-( )		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21065-08-( )	G1031-08-( )	Report No.	Kaynar Technologies, Inc.
MS21065-3-( )	G1031-3-( )	NAEC-AML-2474	Kaynar Div.
MS21065-4-( )	G1031-4-( )	of 15 Jun 1966	P.0. Box 3001
MS21065-5-( )	G1031-5-( )		800 S. State College Blvd.
MS21065L08-( )	G1001-08-( )		Fullerton, CA 92634
MS21065L3-( )	G1001-3-( )		
MS21065L4-( )	G1001-4-( )		Plant: Same address
MS21065L5-( )	G1001-5-( )		

MS21065-08-( )	55RS508-( )	NADC Report	Simmonds Mecaero
MS21065-3-( )	55RS53-( )	601Q8418 of	Fasteners, Inc.
MS21065-4-( )	55RS54-( )	26 Oct 1984	1734 Sequoia Avenue
			Orange, CA 92668
			Plant: Same address and
			Simmonds S.A.
			Usine De Chapaissant
			72111 Saint-Cosme En Vairais
			France

Note: 1. Manufacturing process: Cold stamping
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21065-4-( )	55 RS 54-( )	NADC Report
MS21065L4-( )	55 RS 54M-( )	601Q9320 of
		23 Dec 93

Note: 1. Manufacturing Process: Cold Stamping
2. Nut Element Manufactured at France Plant Channel Manufactured at Orange, CA Plant
3. Lubricant: (For Government Designation with "L") Dow Corning 3400A Per MIL-L-46010, Type II
4. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordar FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21065-08-( )	55RS508-( )	Report No.	Simmonds Mecaero Fasteners, Inc.
MS21065-3-( )	55RS53-( )	435Q9512 of	1734 Sequoia Avenue
MS21065L3-( )	55RS53M-( )	26 May 1995	Orange, CA 92668
			Plant: Same address

Notes: 1. Manufacturing Process: Cold Stamping
2. Lubricant: (For Government Designation with "L") QPL-46010

MS21065-08-( )	C185-82-( )	Report No.	SPS Technologies
MS21065-3-( )	C185-3-( )	601Q8406 of	2701 South Harbor Blvd.
MS21065-4-( )	C185-4-( )	20 Mar 1984	Santa Ana, CA 92702
MS21065-5-( )	C185-5-( )		
MS21065-6-( )	C185-6-( )		Plant: Same address
MS21065L08-( )	C185E82-( )		
MS21065L3-( )	C185E3-( )		
MS21065L4-( )	C185E4-( )		
MS21065L5-( )	C185E5-( )		
MS21065L6-( )	C185E6-( )		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21066 NUT, SELF-LOCKING, CHANNEL, 100° CSK, FLOATING, LOW HEIGHT, STEEL, 125 KSI Ftu, 250° F

MS21066L08-( )	T64SH832-( )	Report No.	Cherry/Textron
MS21066L3-( )	T64SH1032-( )	NAEC-AML-2428	Cherry Div. of
MS21066L4-( )	T64SH428-( )	of 15 Mar 1966	Textron Inc.
MS21066-08-( )	T64SH832-( )CPC		P.0. Box 2157
MS21066-3-( )	T64SH1032-( )CPC		1224 East warner Ave.
MS21066-4-( )	T64SH428-( )CPC		Santa Ana, CA 92707
			Plant: Same address

MS21066-08-( )	F52LHTG55-82-( )	NAEC-AML-2429	ESNA
MS21066-3-( )	F52LHTG55-02-( )	of 15 Mar 1966*	Division of Harvard Industries
MS21066-4-( )	F52LHTG55-048-( )		
MS21066L08-( )	RM52LHTG55-B2-( )	*MUST BE MANUFACTURED	
MS21066L3-( )	RM52LHTG5S-02-( )	AFTER 10 MAY 1994	
MS21066L4-( )	RM52LHTG55-048-( )	DISC-E-94130 LTR	

MS21066-08-( )	G1100-08-( )	Report No.	Kaynar Technologies, Inc.
MS21066-3-( )	G1100-3-( )	NAEC-AML-2474	Kaynar Div.
MS21066-4-( )	G1100-4-( )	of 15 Jun 1966	P.0. Box 3001
MS21066L08-( )	G1100-08-( )		800 S. State Co11ege Blvd.
MS21066L3-( )	G1100-3-( )	Fullerton, CA 92634	
MS21066L4-( )	G1100-4-( )		
			Plant: Same address

MS21067 NUT, SELF-LOCKING, CHANNEL, 100° CSK, FLOATING, LOW HEIGHT, STEEL, 125 KSI Ftu, 450°F

MS21067-08-( )	TC64SH832-( )	Report No.	Cherry/Textron
MS21067-3-( )	TC64SH1032-( )	NAEC-AML-2428	Cherry Div. of
MS21067-4-( )	TC64SH428-( )	of 15 Mar 1966	Textron Inc.
MS21067L08-( )	TC64SH832-( )		P.0. Box 2157
MS21067L3-( )	TC64SH1032-( )		1224 East 1'!arner Ave.
MS21067L4-( )	TC64SH428-( )		Santa Ana, CA 92707
			Plant: Same address

MS21067-08-( )	P52LHTG55-82-( )	NAEC-AML-2429 ESNA	
MS21067-3-( )	F52LHTG55-02-( )	of 15 Mar 1966*	Division of Harvard Industries
MS21067-4-( )	F52LHTG55-048-( )		
MS21067L08-( )	RM52LHTG5S-82-( )	*MUST BE MANUFACTURED	
MS21067L3-( )	RM52LHTG55-02-( )	AFTER 10 MAY 1994	
MS21067L4-( )	RM52LHTG55-048-( )	DISC-E-94130 LTR	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21067-08-( )	G1982-08-( ) CW	Report No.	Kaynar Technologies, Inc.
MS21067-3-( )	G1982-3-( ) CW	NAEC-AML-2474	Kaynar Div.
MS21067-4-( )	G1982-4-( ) CW	of 15 Jun 1966	P.O. Box 3001
MS21067L08-( )	G1982-08-( )		800 S. State College Blvd.
MS21067L3-( )	G1982-3-( )		Fullerton, CA 92634
MS21067L4-( )	G1982-4-( )		
			Plant: Same address

MS21067-08-( )	95RSF908-( )	NADC Report	Simmonds Mecaero
MS21067L08-( )	95RSF908M-( )	601Q8505 of	Fasteners, Inc.
		30 May 1985	1734 Sequoia Avenue
			Orange, CA 92668

Note: 1. Manufacturing process: Cold stamping Plant:
2. Lubricant: (For Government Designation with "L") QPL-8937 Simmonds
3. provisions Governing Procurement. Procurement of these self-locking Usine De Champaissant
nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and 72110 Saint-Cosme En Vaira
DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The France
contractor should include these provisions in every subcontract and purchase order.

MS21068 NUT, SELF-LOCKING, CHANNEL, 100° CSK, FLOATING, LOW HEIGHT, CRES, 125 KSI Ftu, 450° & 800°F

MS21068-08-( )	TC64CH832-( )	Report No.	Cherry/Textron
MS21068-3-( )	TC64CH1032-( )	NAEC-AML-2428	Cherry Div. of
MS21068-4-( )	TC64CH428-( )	of 15 Mar 1966	Textron Inc.
MS21068L08-( )	TC64CH832-( )M		P.O. Box 2157
MS21068L3-( )	TC64CH1032-( )M		1224 East Warner Ave.
MS21068L4-( )	TC64CH428-( )M		Santa Ana, CA 92707
			Plant: Same address
MS21068L08-( )	RMLHTG55-2860-82-( )	NAEC-AML-2429 ESNA	
MS21068L3-( )	RMLHTG55-2860-02-( )	of 15 May 1966*	Division of Harvard Industries
MS21068L4-( )	RMLHTG55-2860-048-( )		
MS21068-08-( )	LHTG55-2860-82-( )	*MUST BE MANUFACTURED	
MS21068-3-( )	LHTG55-2860-02-( )	AFTER 10 MAY 1994	
MS21068-4-( )	LHTG55-2860-048-( )	DISC-E-94130 LTR	

MS21068-08-( )	G1131-08-( )	Report No.	Kaynar Technologies, Inc.
MS21068-3-( )	G1131-3-( )	NAEC-AML-2427	Kaynar Div
MS21068-4-( )	G1131-4-( )	of 15 Jun 1966	P.O. Box 3001
MS21068L08-( )	G1101-08-( )		800 S. State College Blvd.
MS21068L3-( )	G1101-3-( )		Fullerton, CA 92634
MS21068L4-( )	G1101-4-( )		
			Plant: Same address

MS21069 NUT, SELF-LOCKING, PLATE, TWO LUG, REDUCED RIVET SPACING, LOW HEIGHT, STEEL,
125 KSI Ftu, 450° F

MS21069-04	MTL2S440CPC	NAWC Report	Boots Nut Division
MS21069-06	MTL2S632CPC	601Q9004 of	Republic Fasteners
MS21069-08	MT2S832CPC	22 Jan 90	1300 Rancho Conejo Blvd
MS21069-3	MT2S1032CPC		Newbury Park, CA 91320
MS21069-4	MT2S428CPC		
MS21069-5	MT2S524CPC		Plant: Same address
MT21069-6	MT2S632CPC		
MS21069L04	MTL2S440		
MS21069L06	MTL2S632		
MS21069L08	MT2S832		
MS21069L3	MT2S1032		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21069L4	MT2S428		
MS21069L5	MT2S524		
MS21069L6	MT2S624		
MS21069-04K	MTL2S440BCCPC		
MS21069-06K	MTL2S632BCCPC		
MS21069-08K	MT2S832BCCPC		
MS21069-3K	MT2S1032BCCPC		
MS21069-4K	MT2S428BCCPC		
MS21069-5K	MT2S524BCCPC		
MS21069L04K	MTL2S440BC		
MS21069L06K	MTL2S632BC		
MS21069L08K	MT2S832BC		
MS21069L3K	MT2S1032BC		
MS21069L4K	MT2S428BC		
MS21069L5K	MT2S524BC		

MS21069-04	MTL2S440CPC	Report No.	Cherry/Textron
MS21069-06	MTL2S632CPC	NAEC-AML-2428	Cherry Div. of
MS21069-08	MT2S832CPC	of 15 Mar 1966	Textron Inc.
MS21069-3	MT2S1032CPC		P.0. Box 2157
MS21069-4	MT2S428CPC		1224 East Warner Ave.
MS21069-5	MT2S524CPC		Santa Ana, CA 92707
MS21069-6	MT2S624CPC		
MS21069L04	MTL2S440		Plant: Same address
MS21069L06	MTL2S632	Report No.	Cherry/Textron
MS21069L08	MT2S832	NAEC-AML-2428	(Cont'd)
MS21069L3	MT2S1032	of 15 Mar 1966	
MS21069L4	MT2S428		
MS21069L5	MT2S524		
MS21069L6	MT2S624		
MS21069-04K	MTL2S440BCCPC		
MS21069-06K	MTL2S632BCCPC		
MS21069-08K	MT2S832BCCPC		
MS21069-3K	MT2S1032BCCPC		
MS21069-4K	MT2S428BCCPC		
MS21069-5K	MT2S524BCCPC		
MS21069L04K	MTL2S440BC		
MS21069L06K	MTL2S632BC		
MS21069L08K	MT2S832BC		
MS21069L3K	MT2S1032BC		
MS21069L4K	MT2S428BC		
MS21069L5K	MT2S524BC		

MS21069-04	F12LHTA1M-40	NAEC-AML-2429	ESNA
MS21069-06	F12LHTA1M-62	of 15 Mar 1966 *	A Division of Harvard Industries
MS21069-02	F52LHTA51M-26		
MS21069-08	F52LHTA51M-82	*MUST BE MANUFACTURED	
MS21069-3	F52LHTA51M-02	AFTER 10 MAY 1994	
MS21069-4	F52LHTA51M-048	DISC-E-94130 LTR	
MS21069-5	F52LHTA51M-054		
MS21069-6	F52LHTA51M-064		
MS21069L04	RM12LHTA1M-40		
MS21069L06	RM12LHTA1M-62		
MS21069L02	RM52LHTA51M-26		
MS21069L08	RM52LHTA51M-82		
MS21069L3	RM52LHTA51M-02		
MS21069L4	RM52LHTA51M-048		
MS21069L5	RM52LHTA51M-054		
MS21069L6	RM52LHTA51M-064		
MS21069-04K	F12LHTA1M-40BC		
MS21069-06K	F12LHTA1M-62BC		
MS21069-08K	F52LHTA51M-82BC		
MS21069-3K	F52LHTA51M-02BC		
MS21069-4K	F52LHTA51M-048BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21069-5K	F52LHTA51M-054BC
MS21069L04K	RM12LHTA1M-40BC
MS21069L06K	RM12LHTA1M-62BC
MS21069L08K	RM52LHIA51M-82BC
MS21069L3K	RM52LHTA51M-02BC
MS21069L4K	RM52LHTA51M-048BC
MS21069L5K	RM52LHTA51M-054BC

MS21069-02	MK1300-02CW	Report No.	Kaynar Technologies, Inc.
MS21069-04	MK1000-04CW	NAEC-AML-2474	Kaynar Div.
MS21069-06	MK1000-06CW	of 15 Jun 1966	P.0 Box 3001
MS21069-08	MK1000-08CW		800 S. State College Blvd.
MS21069-3	MK1000-3CW		Fullerton, CA 92634
MS21069-4	MK1000-4CW		
MS21069-5	MK1300-5CW		Plant: Same address
MS21069-6	MK1300-6CW	Report No.	Kaynar
MS21069-02K	MK1300-02BCCW	NAEC-AML-2474	(Cont'd)
MS21069-04K	MK1000-04BCCW	of 15 Jun 1966	
MS21069-06K	MK1000-06BCCW		
MS21069-08K	MK1000-08BCCW		
MS21069-3K	MK1000-3BCCW		
MS21069-4K	MK1000-4BCCW		
MS21069-5K	MK1300-5BCCW		
MS21069L02	MK1300-02		
MS21069L04	MK1000-04		
MS21069L06	MK1000-06		
MS21069L08	MK1000-08		
MS21069L3	MK1000-3		
MS21069L4	MK1000-4		
MS21069L5	MK1300-5		
MS21069L6	MK1300-6		
MS21069L02K	MK1300-02K		
MS21069L04K	MK1000-04BC		
MS21069L06K	MK1000-068C		
MS21069L08K	MK1000-08BC		
MS21069L3K	MK1000-3BC		
MS21069L4K	MK1000-4BC		
MS21069L5K	MK1300-5BC		

MS21069-04	RM200X04L	Report No.	Republic Fastener Mfg. Corp.
MS21069-04K	RM200X04LK	305Q73001 of	1300 Rancho Conejo Blvd.
MS21069L04	RM200A04L	6 Feb 1973	Newbury Park, CA 91320
MS21069L04K	RM200A04LK		
MS21069-06	RM200X06L		Plant: Same address
MS21069-06K	RM200X06LK		
MS21069L06	RM200A06L		
MS21069L06K	RM200A06LK		
MS21069-08	RM200X08		
MS21069-08K	RM200X08K		
MS21069L08	RM200A08		
MS21069L08K	RM200A08K		
MS21069-3	RM200X3		
MS21069-3K	RM200X3K		
MS21069L3	RM200A3		
MS21069L3K	RM200A3K		
MS21069-4	RM200X4		
MS21069-4K	RM200X4K		
MS21069L4	RM200A4		
MS21069L4K	RM200A4K		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21069-5	RM200X5	Report No.	
MS21069L5	RM200A5	305Q76023 of	
MS21069-5K	RM200X5K	14 May 1976	
MS21069L5K	RM200A5K		

Note: "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124 of 20 November 1970.

MS21069-6	RM200X6	Report No.	Republic Fastener
MS21069L6	RM200A6	305Q83088 of	(Cont'd)
		26 Jan 1983	

MS21069L3	GM-93M	Report No.	Simmonds Mecaero
		305Q83101 of	Fasteners, Inc.
		5 May 1983	1734 Sequoia Avenue
			Orange, CA 92668
MS21069L3K	GM-93MK	Report No.	Plant:
MS21069L4	GM-94M	305Q83104 of	Simmonds
MS21069L4K	GM-94MK	12 Aug 1983	Usine De Champaissant
			72110 Saint-Cosme En Vairais
			France
MS21069L04	GM-904M Report No.		
MS21069L04K	GM-904MK	305Q83112 of	
		28 Nov 1983	
MS21069L08	GM-908M	Report No.	
MS21069L08K	GM-908MK	601Q8401 of	
		24 Feb 1984	
MS21069-08	GM-908	Report No.	
MS21069-3	GM-93	601QB407 of	
MS21069-4	GM-94	20 Apr 1984	

Note: 1. Manufacturing process: Cold formed
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21069-04	GM-904	NAED Report	
MS21069-04K	GM-904K	601Q8502 of	
		11 Mar 1985	

Note: 1. Manufacturing process: Cold stamping
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21069-06	GSM-906	NADC Report	
MS21069L06	GSM-906M	601Q8518 of	
		30 Dec 1985	

Note: 1. Manufacturing process: Cold forging
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governin(1 Procurement. Procurement of these self-locking nuts shall be in accorda with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). Th contractor should include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21069-04	M12600NM-40	Report No.	SPS Technologies
MS21069-06	M12600NM-62	NAEC-AML-2369	2701 S. Harbor Blvd
MS21069-08	M12600NM-82	of 15 Mar 1966	Santa Ana, CA 92702
MS21069-3	M12600NM-02		
MS21069-4	M12600NM-048		Plant: Same address
MS21069-5	MA12600NM-054		
MS21069-6	MA12600NM-064		
MS21069L04	M12600-40		
MS21069L06	M12600-62		
MS21069L08	M12600-82		
MS21069L3	M12600-02		
MS21069L4	M12600-048		
MS21069L5	MA12600-054		
MS21069L6	MA12600-064		
MS21069-04K	M12600NM-40BC		
MS21069-06K	M12600NM-62BC		
MS21069-08K	M12600NM-82BC		
MS21069-3K	M12600NM-02BC		
MS21069-4K	M12600NM-048BC		
MS21069-5K	MA12600NM-054BC		
MS21069L04K	M12600-40BC		
MS21069L06K	M12600-62BC		
MS21069L08K	M12600-82BC		
MS21069L3K	M12600-02BC		
MS21069L4K	M12600-048BC		
MS21069L5K	MA12600-054BC		

MS21069-04	VN202-C1-40	Report No.	VOI-SHAN
MS21069-06	VN202-C1-62	NAEC-AML-2425	Fairchild Aerospace Fastener Div
MS21069-08	VN202-C1-82	of 15 Mar 1966	2950 W. Lomita Blvd.
MS21069-3	VN202-C1-02		Torrance, CA 90505-5103
MS21069-4	VN202-C1-048		
MS21069-5	VN202-C1-054		Plant: Same address
MS21069-6	VN202-C1-064		
MS21069L04	VN202-A1-40		
MS21069L06	VN202-A1-62		
MS21069L08	VN202-A1-82		
MS21069L3	VN202-A1-02		
MS21069L4	VN202-A1-048		
MS21069L5	VN202-A1-054		
MS21069L6	VN202-A1-064		
MS21069-04K	VN202-C2-40		
MS21069-06K	VN202-C2-62		
MS21069-08K	VN202-C2-82		
MS21069-3K	VN202-C2-02		
MS21069-4K	VN202-C2-048		
MS21069-5K	VN202-C2-054		
MS21069L04K	VN202-A2-40		
MS21069L06K	VN202-A2-62		
MS21069L08K	VN202-A2-82		
MS21069L3K	VN202-A2-02		
MS21069L4K	VN202-A2-048		
MS21069L5K	VN202-A2-054		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21070 NUT, SELF-LOCKING, PLATE, TW0 LUG, REDUCED RIVET SPACING, LOW HEIGHT, CRES, 125 KSI Ftu, 450° & 800°F

MS21070L04	MTL2C440M	NAWC Report 601Q9004 of 22 Jan 90	Boots Nut Division Republic Fasteners 1300 Rancho Conejo Blvd Newbury Park, CA 91320 Plant: Same address
MS21070L06	MTL2C632M		
MS21070L08	MT2SC832M		
MS21070L3	MT2C1032M		
MS21070L4	MT2C428M		
MS21070L5	MT2C524M		
MT21070L6	MT2S632M		
MS21070L04K	MTL2C440BCM		
MS21070L06K	MTL2C632BCM		
MS21070L08K	MT2C832BCM		
MS21070L3K	MT2C1032BCM		
MS21070L4K	MT2C428BCM		
MS21070L5K	MT2C524BCM		
MS21070-04	MTL2C440		
MS21070-06	MTL2C632		
MS21070-08	MT2C832		
MS21070-3	MT2C1032		
MS21070-4	MT2C428		
MS21070-5	MT2C524		
MS21070-6	MT2C624		
MS21070-04K	MTL2C440BC		
MS21070-06K	MTL2C632BC		
MS21070-08	MT2C832BC		
MS21070-3K	MT2C1032BC		
MS21070-4K	MT2C428BC		
MS21070-5K	MT2C524BC		
MS21070-3W	MT2C1032PWB		
MS21070-4W	MT2C428PWB		
MS21070-5W	MT2C524PWB		
MS21070-6W	MT2C624PWB		
MS21070L04W	MTL2C440PM		
MS21070L06W	MTL2C632PM		
MS21070L08W	MT2C832PM		
MS21070L3W	MT2C1032PM		
MS21070L4W	MT2C428PM		
MS21070L5W	MT2C524PM		
MS21070L6W	MT2C624PM		

MS21070L04	MTL2C440M	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry/Textron Cherry Div. of Textron, Inc. P.0. Box 2157 1224 East Warner Ave. Santa Ana, CA 92707 Plant: Same address
MS21070L06	MTL2C632M		
MS21070L08	MT2C832M		
MS21070L3	MT2C1032M		
MS21070L4	MT2C428M		
MS21070L5	MT2C524M		
MS21070L6	MT2C624M		
MS21070L04K	MTL2C440BCM		
MS21070L06K	MTL2C632BCM		
MS21070L08K	MT2C832BCM		
MS21070L3K	MT2C1032BCM		
MS21070L4K	MT2C428BCM		
MS21070L5K	MT2C524BCM		
MS21070-04	MTL2C440		
MS21070-06	MTL2C632	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry/Textron (Cont'd)
MS21070-08	MT2C832		
MS21070-3	MT2C1032		
MS21070-4	MT2C428		
MS21070-5	MT2C524		
MS21070-6	MT2C624		
MS21070-04K	MTL2C440BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21070-06K	MTL2C632BC
MS21070-08K	MT2C832BC
MS21070-3K	MT2C1032BC
MS21070-4K	MT2C428BC
MS21070-5K	MT2C524BC
MS21070-04W	MTL2C440PWB
MS21070-06W	MTL2C632PWB
MS21070-08W	MT2C832PWB
MS21070-3W	MT2C1032PWB
MS21070-4W	MT2C428PWB
MS21070-5W	MT2C524PWB
MS21070-6W	MT2C624PWB
MS2170L04W	MTL2C440PM
MS21070L06W	MTL2C632PM
MS21070L08W	MT2C832PM
MS21070L3N	MT2C1032PM
MS21070L4W	MT2C428PM
MS21070L5W	MT2C524PM
MS21070L6W	MT2C624PM

MS21070L04	RMLHTA1M2860-40	NAEC-AML-2429	ESNA
MS21070L06	RMLHTA1M2860-62	of 15 Mar 1966 *	Division of Harvard Industries
MS21070L02	RMLHTA51M2860-26		
MS21070L08	RMLHTA51M2860-82		
MS21070L3	RMLHTA51M2860-02		
MS21070L4	RMLHTA51M2860-048		
MS21070L5	RMLHTA51M2860-054		
MS21070L6	RMLHTA51M2860-064		
MS21070L04K	RMLHTA1M2860-408C		
MS21070L06K	RMLHTA1M2860-62BC		
MS21070L08K	RMLHTA51M2860-82BC		
MS21070L3K	RMLHTA51M2860-02BC		
MS21070L5K	RMLHTA51M2860-054BC		
MS21070L04W	RNLHTA1M2860P-40		
MS21070L06W	RMLHTA1M2860P-62		
MS21070L02W	RMLHTA51M2860P-26		
MS21070L08W	RMLHTA51M2860P-82		
MS21070L3W	RMLHTA51M2860P-02		
MS21070L4W	RMLHTA51M2860P-048		
MS21070L5W	RMLHTA51M2860P-054		
MS21070L6W	RMLHTA51M2860P-064		
MS21070-04	LHTA1M2860-40		
MS21070-06	LHTA1M2860-62		
MS21070-02	LHTA51M2860-26		
MS21070-08	LHTA51M2860-82		
MS21070-3	LHTA51M2860-02		
MS21070-4	LHTA51M2860-048		
MS21070-5	LHTA51M2860-054		
MS21070-6	LHTA51M2860-064		
MS21070-04K	LHTA1M2860-40BC	NAEC-AML-2429	ESNA - Harvard Industries
MS21070-06K	LHTA1M2860-62BC	of 15 Mar 1966 *	(Cont'd)
MS21070-08K	LHTA51M2860-82BC		
MS21070-3K	LHTA51M2860-02BC	*MUST BE MANUFACTURED	
MS21070-4K	LHTA51M2860-048BC	AFTER 10 MAY 1994	
MS21070-5K	LHTA51M2860-054BC	DISC-E-94130 LTR	
MS21070-04W	LHTA1M2860P-40		
MS21070-06W	LHTA1M2860P-62		
MS210V0-02W	LHTA51M2860P-26		
MS21070-08H	LHTA51M2860P-82		
MS21070-3W	LHTA51M2860P-02		
MS21070-4W	LHTA51M2860P-048		
MS21070-5W	LHTA51M2860P-054		
MS21070-6W	LHTA51M2860P-064		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21070-02	MK1331-02	Report No.	Kaynar Technologies, Inc.
MS21070-04	MK1031-04	NAEC-AML-2474	Kaynar Div.
MS21070-06	MK1031-06	of 15 Jun 1966	P.0. Box 3001
MS21070-08	MK1031-08		800 S. State College Blvd.
MS21070-3	MK1031-3		Fullerton, CA 92634
MS21070-4	MK1031-4		
MS21070-5	MK1331-5		Plant: Same address
MS21070-6	MK1331-6		
MS21070-04K	MK1031-04BC		
MS21070-06K	MK1031-06BC		
MS21070-08K	MK1031-08BC		
MS21070-3K	MK1031-3BC		
MS21070-4K	MK1031-4BC		
MS21070-5K	MK1331-5BC		
MS21070-02W	MK1331-02P		
MS21070-04W	MK1031-04P		
MS21070-06W	MK1031-06P		
MS21070-08W	MK1031-08P		
MS21070-3W	MK1031-3P		
MS21070-4W	MK1031-4P		
MS21070-5W	MK1331-5P		
MS21070-6W	MK1331-6P		
MS21070L02	MK1301-02		
MS21070L04	MK1001-04		
MS21070L06	MK1001-06		
MS21070L08	MK1001-08		
MS21070L3	MK1001-3		
MS21070L4	MK1001-4		
MS21070L5	MK1301-5		
MS21070L6	MK1301-6		
MS21070L04K	MK1001-04BC		
MS21070L06K	MK1001-06BC		
MS21070L08K	MK1001-08BC		
MS21070L3K	MK1001-3BC		
MS21070L4K	MK1001-4BC		
MS21070L5K	MK1301-5BC		
MS21070L02W	MK1301-02P		
MS21070L04W	MK1001-04P		
MS21070L06W	MK1001-06P		
MS21070L08W	MK1001-08P	Report No.	Kaynar Technologies
MS21070L3W	MK1001-3P	NAEC-AML-2474	(Cont'd)
MS21070L4W	MK1001-4P	of 15 Jun 1966	
MS21070L5W	MK1301-5P		
MS21070L6W	MK1301-6P		

MS21070-04	RM200C04L	Report No.	Republic Fastener Mfg. Corp.
MS21070-04K	RM200C04LK	305Q73001 of	1300 Rancho Conejo Blvd.
MS21070-04W	RM200C04LW	6 Feb 1973	Newbury Park, CA 91320
MS21070L04	RM200C04LM		
MS21070L04K	RM200C04LMK		Plant: Same address
MS21070L04W	RM200C04LMW		
MS21070-06	RM200C06L		
MS21070-06K	RM200C06LK		
MS21070-06W	RM200C06LW		
MS21070L06	RM200C06LM		
MS21070L06K	RM200C06LMK		
MS21070L06W	RM200C06LMN		
MS21070-08	RM200C08		
MS21070-08K	RM200C08K		
MS21070-08W	RM200C08W		
MS21070L08	RM200C08M		
MS21070L08K	RM200C08MK		
MS21070L08W	RM200C08MW		
MS21070-3	RM200C3		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21070-3K	RM200C3K		
MS21070-3W	RM200C3W		
MS21070L3	RM200C3M		
MS21070L3K	RM200C3MK		
MS21070L3W	RM200C3MW		
MS21070-4	RMM200C4		
MS21070-4K	RM200C4K		
MS21070-4W	RM200C4W		
MS21070L4	RM200C4M		
MS21070L4K	RM200C4MK		
MS21070L4W	RM200C4MW		

MS21070-5	RM200C5	Report No.	
MS21070-5K	RM200C5K	305Q76023 of	
MS21070-5W	RM200C5H	14 May 1976	
MS21070L5	RM200C5M		
MS21070L5K	RM200C5MK		
MS21070L5W	RM200C5MW		

MS21070-6	RM200C6	Report No.	
MS21070-6W	RM200C6W	305Q83088 of	
MS21070L6	RM200C6M	26 Jan 1983	
MS21070L6W	RM200C6MW		

MS21070-3	GM-53	Report No.	Simmonds Mecaero
MS21070-3K	GM-53K	305Q83104 of	Fasteners, Inc.
		12 Aug 1983	1734 Sequoia Avenue
			Orange, CA 92668

MS21070-08	GM-508	Report No.	Plant:
MS21070-08K	GM-508K	305Q83111 of	Simmonds
MS21070-4	GM-54	19 Oct 1983	Usine De Champaissant
MS21070-4K	GM-54K		72110 Saint-Cosme En Vairais

France

Note: Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in eve subcontract and purchase order.

MS21070L08	GM-508M	NADC Report
MS21070L3	GM-53M	601Q8417 of
		16 Dec 1985

Note: 1. Manufacturing process: Cold stamping
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21070-06	GSM-506	NADC Report
MS21070L06	GSM-506M	601Q8518 of
		30 Dec 1985

Note: 1. Manufacturing process: Cold forging
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governin(1 Procurement. Procurement of these self-locking nuts shall be in accordar with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). Th contractor should include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21070-04	M12700-40	Report No.	SPS Technologies
MS21070-06	M12700-62	NAEC-AML-2369	2701 S. Harbor Blvd.
MS21070-08	M12700-82	of 15 Mar 1966	Santa Ana, CA 92702
MS21070-3	M12700-02		
MS21070-4	M12700-048		Plant: Same address
MS21070-5	M12700-054		
MS21070-6	M12700-064		
MS21070-04K	M12700-40BC		
MS21070-06K	M12700-62BC		
MS21070-08K	M12700-82BC		
MS21070-3K	M12700-02BC		
MS21070-4K	M12700-048BC		
MS21070-5K	MA12700-054BC		
MS21070-04W	M12700-40PW		
MS21070-06W	M12700-62PW		
MS21070-08W	M12700-82PW		
MS21070-3W	M12700-02PW		
MS21070-4W	M12700-048PW		
MS21070-5W	MA12700-054PW		
MS21070-6W	MA12700-064PW		
MS21070L04	M12700E-40	Report No.	SPS Technologies -
MS21070L06	M12700E-62	NAEC-AML-2369	Santa Ana, CA
MS21070L08	M12700E-82	of 15 Mar 1966	(Cont'd)
MS21070L3	M12700E-02		
MS21070L4	M12700E-048		
MS21070L5	MA12700E-054		
MS21070L6	MA12700E-064		
MS21070L04K	MA12700E-408C		
MS21070L06K	MA12700E-628C		
MS21070L08K	MA12700E-82BC		
MS21070L3K	MA12700E-028C		
MS21070L4K	MA12700E-048BC		
MS21070L5K	MA12700E-0548C		
MS21070L04W	M12700E-40PW		
MS21070L06W	M12700E-62PW		
MS21070L08W	M12700E-82PW		
MS21070L3W	M12700E-02PW		
MS21070L4W	M12700E-048PW		
MS21070L5W	MA12700E-054PW		
MS21070L6W	MA12700E-064PW		

MS21070-04	VN202-B1-40	Report No.	VOI-SHAN
MS21070-06	VN202-B1-62	NAEC-AML-2425	Fairchild Aerospace Fastener Div
MS21070-08	VN202-B1-82	of 15 Mar 1966	2950 W. Lomita Blvd.
MS21070-3	VN202-B1-02		Torrance, CA 90505-5103
MS21070-4	VN202-B1-048		
MS21070-5	VN202-B1-054		Plant: Same address
MS21070-6	VN202-B1-064		
MS21070-04K	VN202-B2-40		
MS21070-06K	VN202-B2-62		
MS21070-08K	VN202-B2-82		
MS21070-3K	VN202-B2-02		
MS21070-4K	VN202-B2-048		
MS21070-5K	VN202-B2-054		
MS21070-04W	VN202-B3-40		
MS21070-06W	VN202-B3-62		
MS21070-08W	VN202-B3-82		
MS21070-3W	VN202-B3-02		
MS21070-4W	VN202-B3-048		
MS21070-5W	VN202-B3-054		
MS21070-6W	VN202-B3-064		
MS21070L04	VN202-D1-40		
MS21070L06	VN202-D1-62		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21070L08	VN202-D1-82		
MS21070L3	VN202-D1-02		
MS21070L4	VN202-D1-048		
MS21070L5	VN202-D1-054		
MS21070L6	VN202-D1-064		
MS21070L04K	VN202-D2-40		
MS21070L06K	VN202-D2-62		
MS21070L08K	VN202-D2-82		
MS21070L3K	VN202-D2-02		
MS21070L4K	VN202-D2-048		
MS21070L5K	VN202-D2-054		
MS21070L04W	VN202-D3-40	Report No.	VOI-SHAN
MS21070L06W	VN202-D3-62	NAEC-AML-2425	(Cont'd)
MS21070L08W	VN202-D3-82	of 15 Mar 1966	
MS21070L3W	VN202-D3-02		
MS21070L4W	VN202-D3-048		
MS21070L5W	VN202-D3-054		
MS21070L6W	VN202-D3-064		

MS21071 NUT, SELF-LOCKING, PLATE, ONE LUG, REDUCED RIVET SPACING, LOW HEIGHT, STEEL, 12S KSI Ftu, 450°F

MS21071-04	MTL12S440CPC	NAWC Report	Boots Nut Division
MS21071-06	MTL12S632CPC	601Q9004 of	Republic Fasteners
MS21071-08	MT12S832CPC	22 Jan 90	1300 Rancho Conejo Blvd
MS21071-3	MT12S1032CPC		Newbury Park, CA 91320
MS21071-4	MT12S428CPC		
MS21071-5	MT12S524CPC		Plant: Same address
MT21071-6	MT12S624CPC		
MS21071L04	MTL12S440		
MS21071L06	MTL12S632		
MS21071L08	MT12S832		
MS21071L3	MT12S1032		
MS21071L4	MT12S428		
MS21071L5	MT12S524		
MS21071L6	MT12S624		
MS21071-04K	MTL12S440BCCPC		
MS21071-06K	MTL12S632BCCPC		
MS21071-08K	MT12S832BCCPC		
MS21071-3K	MT12S1032BCCPC		
MS21071-4K	MT12S428BCCPC		
MS21071-5K	MT12S524BCCPC		
MS21071L04K	MTL12S440BC		
MS21071L06K	MTL12S632BC		
MS21071L08K	MT12S832BC		
MS21071L3K	MT12S1032BC		
MS21071L4K	MT12S428BC		
MS21071L5K	MT12S524BC		

MS21071-04	MTL12S440CPC	Report No.	Cherry/Textron
MS21071-06	MTL12S632CPC	NAEC-AML-2428	Cherry Div. of
MS21071-08	MT12S832CPC	of 15 Mar 1966	Textron Inc.
MS21071-3	MT12S1032CPC		P.0. Box 2157
MS21071-4	MT12S428CPC		1224 East Warner Ave.
MS21071-5	MT12S524CPC		Santa Ana, CA 92707
MS21071-6	MT12S624CPC		
MS21071L04	MTL12S440		Plant: Same address
MS21071L06	MTL12S632		
MS21071L08	MT12S832		
MS21071L3	MT12S1032		
MS21071L4	MT12S428		
MS21071L5	MT12S524		
MS21071L6	MT12S624		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21071-04K	MTL12S440BCCPC		
MS21071-06K	MTL12S632BCCPC		
MS21071-08K	MT12S832BCCPC	Report No.	Cherry/Textron
MS21071-3K	MT12S1032BCCPC	NAEC-AML-2428	(Cont'd)
MS21071-4K	MT12S428BCCPC	of 15 Mar 1966	
MS21071-5K	MT12S524BCCPC		
MS21071L04K	MTL12S440BC		
MS21071L06K	MTL12S632BC		
MS21071L08K	MT12S8328C		
MS21071L3K	MT12S1032BC		
MS21071L4K	MT12S428BC		
MS21071L5K	MT12S524BC		

MS21071-04	F12LHTA17M-40	NAEC-AML-2429	ESNA
MS21071-06	F12LHTA17M-62	of 15 Mar 1966*	Division of Harvard Industries
MS21071-02	F52LHTA57M-26		
MS21071-08	F52LHTA57M-82	*MUST BE MANUFACTURED	
MS21071-3	F52LHTA57M-02	AFTER 10 MAY 1994	
MS21071-4	F52LHTA57M-048	DISC-E-94130 LTR	
MS21071-5	F52LHTA57M-054		
MS21071-6	F52LHTA57M-064		
MS21071L04	RM12LHTA17M-40		
MS21071L06	RM12LHTA17M-62		
MS21071L02	RM52LHTA57M-26		
MS21071L08	RM52LHTA57M-82		
MS21071L3	RM52LHTA57M-02		
MS21071L4	RM52LHTA57M-048		
MS21071L5	RM52LHTA57M-054		
MS21071L6	RM52LHTA57M-064		
MS21071-04K	F12LHTA17M-40BC		
MS21071-06K	F12LHTA17M-62BC		
MS21071-08K	F52LHTA57M-82BC		
MS21071-3K	F52LHTA57M-02BC		
MS21071-4K	F52LHTA57M-048BC		
MS21071-5K	F52LHTA57M-054BC		
MS21071L04K	RM12LHTA17M-40BC		
MS21071L06K	RM12LHTA17M-62BC		
MS21071L08K	RM52LHTA57M-82BC		
MS21071L3K	RM52LHTA57M-02BC		
MS21071L4K	RM52LHTA57M-048BC		
MS21071L5K	RM52LHTA57M-054BC		

MS21071-04	MK2000-04CW	Report No.	Kaynar Technologies, Inc.
MS21071-06	MK2000-06CW	NAEC-AML-2474	Kaynar Div.
MS21071-08	MK2000-08CW	of 15 Jun 1966	P.0. Box 3001
MS21071-3	MK2000-3CW		800 S. State College Blvd.
MS21071-4	MK2000-4CW		Fullerton, CA 92634
MS21071-04K	MK2000-04BCCW		
MS21071-06K	MK2000-06BCCW		Plant: Same address
MS21071-08K	MK2000-08BCCW		
MS21071-3K	MK2000-3BCCW		
MS21071-4K	MK2000-4BCCW		
MS21071L04	MK2000-04		
MS21071L06	MK2000-06		
MS21071L08	MK2000-08		
MS21071L3	MK2000-3		
MS21071L4	MK2000-4		
MS21071L04K	MK2000-04BC	Report No.	Kaynar Technologies
MS21071L06K	MK2000-06BC	NAEC-AML-2474	(Cont'd)
MS21071L08K	MK2000-08BC	of 15 Jun 1966	
MS21071L3K	MK2000-3BC		
MS21071L4K	MK2000-4BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21071-08	RM100X08	Report No.	Republic Fastener Mfg. Co.
MS21071L08	RM100A08	305Q76023 of	1300 Rancho Conejo Blvd.
MS21071-08K	RM100X08K	14 May 1976	Newbury Park, CA 91320
MS21071L08K	RM100A08K		
MS21071-3	RM100X3		Plant: Same address
MS21071L3	RM100A3		
MS21071-3K	RM100X3K		
MS21071L3K	RM100A3K		
MS21071-4	RM100X4		
MS21071L4	RM100A4		
MS21071-4K	RM100X4K		
MS21071L4K	RM100A4K		
MS21071-04	RM100X04L		
MS21071L04	RM100A04L		
MS21071-04K	RM100X04LK		
MS21071L04K	RM100A04LK		
MS21071-06	RM100X06L		
MS21071L06	RM100A06L		
MS21071-06K	RM100X06LK		
MS21071L06K	RM100A06LK		
MS21071-5	RM100X5		
MS21071L5	RM100A5		
MS21071-5K	RM100X5K		
MS21071L5K	RM100A5K		

MS21071-6	RM100X6	Report No.	
MS21071L6	RM100A6	305Q83088 of	
		26 Jan 1983	

Note: "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124 of 20 November1970.

MS21071L3	AJM-93M	Report No.	Simmonds Mecaero
MS21071L3K	AJM-93MK	305Q83104 of	Fasteners, Inc.
MS21071L4	AJM-94M	12 Aug 1983	1734 Sequoia Avenue
MS21071L4K	AJM-94MK		Orange, CA 92668

	Plant:		
MS21071L08	AJM-908M	601Q8401 of	Simmonds
MS21071L08K	AJM-908MK	24 Feb 1984	Usine De Champaissant
MS21071-3	AJM-93	601Q8407 of	72110 Saint-Cosme En Vairais
		20 Apr 1984	France

Note: 1. Manufacturing process: Cold formed
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordar
FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals).
The contractor should include these provisions in every subcontract and purchase order.

MS21071-08	AJM-908	NADC Report	Simmonds Mecaero
MS21071-08K	AJM-908K	601Q8417 of	(Cont'd)
		25 Oct 1984	

MS21071-4	AJM-94	NADC Report	
		601Q8517 of	
		16 Dec 1985	

Note: 1. Manufacturing process: Cold stamping
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordar
FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals).
The contractor should include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21071-06	AJSM-906	NADC Report
MS21071L06	AJSM-906M	601Q8518 of
		30 Dec 1985

Note: 1. Manufacturing process: Cold forging
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governin(1 Procurement. Procurement of these self-locking nuts shall be in accordar with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). Th contractor should include these provisions in every subcontract and purchase order.

MS21071-04	M12610NM-40	Report No.	SPS Technologies
MS21071-06	M12610NM-62	NAEC-ANL-2369	2701 S. Harbor Blvd.
MS21071-08	M12610NM-82	of 15 Mar 1966	Santa Ana. CA 92702
MS21071-3	M12610NM-02		
MS21071-4	M12610NM-048		Plant: Same address
MS21071-5	MA12610NM-054		
MS21071-6	MA12610NM-064		
MS21071L04	M12610-40		
MS21071L06	M12610-62		
MS21071L08	M12610-82		
MS21071L3	M12610-02		
MS21071L4	M12610-048		
MS21071L5	MA12610-054		
MS21071L6	MA12610-064		
MS21071-04K	M12610NM-40BC		
MS21071-06K	M12610NM-62BC		
MS21071-08K	M12610NM-82BC		
MS21071-3K	M12610NM-02BC		
MS21071-4K	M12610NM-048BC		
MS21071-5K	MA12610NM-054BC		
MS21071L04K	M12610-40BC		
MS21071L06K	M12610-62BC		
MS21071L08K	M12610-82BC		
MS21071L3K	M12610-02BC		
MS21071L4K	M12610-048BC		
MS21071L5K	MA12610-054BC		

MS21071-04	VN201-C1-40	Report No.	VOI-SHAN
MS21071-06	VN201-C1-62	NAEC-AML-2425	Fairchild Aerospace Fastener Div
MS21071-08	VN201-C1-82	of 15 Mar 1966	2950 W. Lomita Blvd.
MS21071-3	VN201-C1-02		Torrance, CA 90505-5103
MS21071-4	VN201-C1-048		
MS21071-5	VN201-C1-054		Plant: Same address
MS21071-6	VN201-C1-064		
MS21071L04	VN201-A1-40		
MS21071L06	VN201-A1-62		
MS21071L08	VN201-A1-82		
MS21071L3	VN201-A1-02		
MS21071L4	VN201-A1-048		
MS21071L5	VN201-A1-054		
MS21071L6	VN201-A1-064		
MS21071-04K	VN201-C2-40		
MS21071-06K	VN201-C2-62		
MS21071-08K	VN201-C2-82		
MS21071-3K	VN201-C2-02		
MS21071-4K	VN201-C2-048		
MS21071-5K	VN201-C2-054		
MS21071L04K	VN201-A2-40		
MS21071L06K	VN201-A2-62		
MS21071L08K	VN201-A2-82		
MS21071L3K	VN201-A2-02		
MS21071L4K	VN201-A2-048		
MS21071L5K	VN201-A2-054		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21072 NUT, SELF-LOCKING, PLATE, ONE LUG, REDUCED RIVET SPACING, LOW HEIGHT, CRES, 125 KSI Ftu, 450° & 800° F

MS21072-04	MTL12C440	NAWC Report	Boots Nut Division
MS21072-06	MTL12C632	601Q9004 of	Republic Fasteners
MS21072-08	MTL12C832	22 Jan 90	1300 Rancho Conejo Blvd
MS21072-3	MT12C1032		Newbury Park, CA 91320
MS21072-4	MT12C428		
MS21072-5	MT12C524		Plant: Same address
MS21072-6	MT12C624		
MS21072-04K	MTL12C440BC		
MS21072-06K	MTL12C632BC		
MS21072-08K	MT12C832BC		
MS21072-3K	MT12C1032BC		
MS20172-4K	MT12C428BC		
MS21072-5K	MT12C524BC		
MS21072-04W	MTL12C440CP		
MS21072-06W	MTL12C632CP		
MS21072-08W	MT12C832CP		
MS21072-3W	MT12C1032P		
MS21072-4W	MT12C428P		
MS21072-5W	MT12C524P		
MS21072-6W	MT12C624P		
MS21072L04	MTL12C440M		
MS21072L06	MTL12C632M		
MS21072L08	MT12C832M		
MS21072L3	MT12C1032M		
MS21072L4	MT12C428M		
MS21072L5	MT12C524M	NAWC Report	Boots Nut
MS21072L6	MT12C624M	601Q9004 of	(Cont'd)
MS21072L04K	MTL12C440BCM	22 Jan 90	
MS21072L06	MTL12C632BCM		
MS21072L08	MT12C832BCM		
MS21072L3K	MT12C1032BCM		
MS21072L4K	MT12C428BCM		
MS21072L5K	MT12C524BCM		
MS21072L04W	MTL12C440PM		
MS21072L06W	MTL12C632PM		
MS21072L08W	MT12C832PM		
MS21072L3W	MT12C1032PM		
MS21072L4W	MT12C428PM		
MS21072L5W	MT12C524PM		
MS21072L6W	MT12C624PM		

MS21072-04	MTL12C440	Report No.	Cherry/Textron
MS21072-06	MTL12C632	NAEC-AML-2428	Cherry Div. of
MS21072-08	MT12C832	of 15 Mar 1966	Textron Inc.
MS21072-3	MT12C1032		P.0. Box 2157
MS21072-4	MT12C428		1224 East Warner Ave.
MS21072-5	MT12C524		Santa Ana, CA 92707
MS21072-6	MT12C624		
MS21072-04K	MTL12C440BC		Plant: Same address
MS21072-06K	MTL12C632BC		
MS21072-08K	MT12C832BC		
MS21072-3K	MT12C1032BC		
MS21072-4K	MT12C428BC		
MS21072-5K	MT12C524BC		
MS21072-04W	MTL12C440P		
MS21072-06W	MTL12C632P		
MS21072-08W	MT12C832P		
MS21072-3W	MT12C1032P		
MS21072-4W	MT12C428P		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21072-5W	MT12C524P
MS21072-6W	MT12C624P
MS21072L04	MTL12C440M
MS21072L06	MTL12C632M
MS21072L08	MT12C832M
MS21072L3	MT12C1032M
MS21072L4	MT12C428M
MS21072L5	MT12C524M
MS21072L6	MT12C624M
MS21072L04K	MTL12C440BCM
MS21072L06K	MTL12C632BCM
MS21072L08K	MT12C832BCM
MS21072L3K	MT12C1032BCM
MS21072L4K	MT12C428BCM
MS21072L5K	MT12C524BCM
MS21072L04W	MTL12C440PM
MS21072L06W	MTL12C632PM
MS21072L08W	ML12C832PM
MS21072L3N	ML12C1032PM
MS21072L4W	ML12C428PM
MS21072L5N	ML12C524PM
MS21072L6N	ML12C624PM

MS21072L04	RMLHTA17M2860-40	NAEC-AML-2429	ESNA
MS21072L06	RMLHTA17M2860-62	of 15 Mar 1966	Division of Harvard Industrie
MS21072L02	RMLHTA57M2860-26		
MS21072L08	RMLHTA57M2860-82	*MUST BE MANUFACTURED	
MS21072L3	RMLHTA57M2860-02	AFTER 10 MAY 1994	
MS21072L4	RMLHTA57M2860-048	DISC-E-94130 LTR	
MS21072L5	RMLHTA57M2860-054		
MS21072L6	RMLHTA57M2860-064		
MS21072L04K	RMLHTA17M2860-40BC		
MS21072L06K	RMLHTA17M2860-62BC		
MS21072L08K	RMLHTA57M2860-82BC		
MS21072L3K	RMLHTA57M2860-02BC		
MS21072L4K	RMLHTA57M2860-048BC		
MS21072L5K	RMLHTA57M2860-054BC		
MS21072L04N	RMLHTA17M2860P-40		
MS21072L06W	RMLHTA17M2860P-62		
MS21072L02W	RMLHTA57M2860P-26		
MS21072L08W	RMLHTA57M2860P-82		
MS21072L3W	RMLHTA57M2860P-02		
MS21072L4W	RMLHTA57M2860P-048		
MS21072L5W	RMLHTA57M2860P-054		
MS21072L6W	RMLHTA57M2860P-064		
MS21072-04	LHTA17M2860-40		
MS21072-06	LHTA17M2860-62		
MS21072-02	LHTA57M2860-26		
MS21072-08	LHTA57M2860-82		
MS21072-3	LHTA57M2860-02		
MS21072-4	LHTA57M2860-048		
MS21072-5	LHTA57M2860-054		
MS21072-6	LHTA57M2860-064		
MS21072-04K	LHTA17M2860-40BC		
MS21072-06K	LHTA17M2860-62BC		
MS21072-08K	LHTA57M2860-82BC		
MS21072-3K	LHTA57M2860-02BC		
MS21072-4K	LHTA57M2860-048BC		
MS21072-5K	LHTA57M2860-054BC		
MS21072-04W	LHTA17M2860P-40		
MS21072-06W	LHTA17M2860P-62		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21072-02W	LHTA57M2860P-26		
MS21072-08W	LHTA57M2860P-82		
MS21072-3W	LHTA57M2860P-02		
MS21072-4W	LHTA57M2860P-048		
MS21072-5W	LHTA57M2860P-054		
MS21072-6W	LHTA57M2860P-064		

MS21072-04	MK2031-04	Report No.	Kaynar Technologies, Inc.
MS21072-06	MK2031-06	NAEC-AML-2474	Kaynar Div.
MS21072-08	MK2031-08	of 15 Jun 1966	P.0. Box 3001
MS21072-3	MK2031-3		800 S. State College Blvd.
MS21072-4	MK2031-4		Fullerton, CA 92634
MS21072-04K	MK2031-04BC		
MS21072-06K	MK2031-06BC		Plant: Same address
MS21072-08K	MK2031-08BC		
MS21072-3K	MK2031-3BC		
MS21072-4K	MK2031-4BC		
MS21072-04W	MK2031-04P	Report No.	Kaynar Technologies
MS21072-06W	MK2031-06P	NAEC-AML-2474	(Cont'd)
MS21072-08W	MK2031-08P	of 15 Jun 1966	
MS21072-3W	MK2031-3P		
MS21072-4W	MK2031-4P		
MS21072L04	MK2001-04		
MS21072L06	MK2001-06		
MS21072L08	MK2001-08		
MS21072L3	MK2001-3		
MS21072L4	MK2001-4		
MS21072L04K	MK2001-04BC		
MS21072L06K	MK2001-06BC		
MS21072L08K	MK2001-08BC		
MS21072L3K	MK2001-3BC		
MS21072L4K	MK2001-4BC		
MS21072L04W	MK2001-04P		
MS21072L06W	MK2001-06P		
MS21072L08W	MK2001-08P		
MS21072L3W	MK2001-3P		
MS21072L4W	MK2001-4P		

MS21072-04	RM100C04L	NADC Report No.	Republic Fastener Mfg. Corp.
MS21072-04K	RM100C04LK	305Q76023 of	1300 Rancho Conejo Blvd.
MS21072-04W	RM100C04LW	14 May 1976	Newbury Park, CA 91320
MS21072L04	RM100C04LM		
MS21072L04K	RM100C04LMK		Plant: Same address
MS21072L04W	RM100C04LMW		
MS21072-06	RM100C06L		
MS21072-06K	RM100C06LK		
MS21072-06W	RM100C06LW		
MS21072L06	RM100C06LM		
MS21072L06K	RM100C06LMK		
MS21072L06H	RM100C06LMW		
MS21072-08	RM100C08		
MS21072-08K	RM100C08K		
MS21072-08W	RM100C08W		
MS21072L08	RM100C08M		
MS21072L08K	RM100C08MK		
MS21072L08W	RM100C08MW		
MS21072-3	RM100C3		
MS21072-3K	RM100C3K		
MS21072-3W	RM100C3W		
MS21072L3	RM100C3M		
MS21072L3K	RM100C3MK		
MS21072L3W	RM100C3MW		
MS21072-4	RM100C4		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21072-4K	RM100C4K		
MS21072-4W	RM100C4W		
MS21072L4	RM100C4M		
MS21072L4K	RM100C4MK		
MS21072L4W	RM100C4MW		
MS21072-5	RM100C5		
MS21072-5K	RM100C5K		
MS21072-5W	RM100C5W		
MS21072L5	RM100C5M		
MS21072L5K	RM100C5MK	Report No. 305Q76023 of 14 May 1976	Republic Fastener (Cont'd)
MS21072L5W	RM100C5MW		

Note: "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124 of 20 November 1970.

MS21072-6	RM100C6	Report No. 305Q83088 of 26 Jan 1983	
MS21072L6	RM100C6M		
MS21072-6W	RM100C6W		
MS21072L6W	RM100C6MW		

MS21072-3	AJM-53	Report No. 305Q83104 of 12 Aug 1983	Simmonds Mecaero Fasteners, Inc. 1734 Sequoia Avenue Orange, CA 92668
MS21072-3K	AJM-53K		
MS21072-4	AJM-54	Report No. 305Q83112 of 28 Nov 1983	Plant: Simmonds Usine De Champaissant 72110 Saint-Cosme En Vairais France
MS21072-4K	AJM-54K		
MS21072-08	AJM-508	Report No. 601Q8401 of 24 Feb 1984	
MS21072-08K	AJM-508K		

Note: 1. Manufacturing process: Cold formed
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordar FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21072-06	AJSM-506	NADC Report 601Q8518 of 30 Dec 1985	
MS21072L06	AJSM-506M		

Note: 1. Manufacturing process: Cold forging
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governin(1 Procurement. Procurement of these self-locking nuts shall be in accordar with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). Th contractor should include these provisions in every subcontract and purchase order.

MS21072L08	AJM-508M	NAEC Report 601Q8609 of 8 Aug 1986	
MS21072L3	AJM-53M		

Note: 1. Manufacturing process: Cold stamping
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordar FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21072-04	M12710-40	Report No.	SPS Technologies
MS21072-06	M12710-62	NAEC-AML-2369	2701 South Harbor Blvd.
MS21072-08	M12710-82	of 15 Mar 1966	Santa Ana, CA 92702
MS21072-3	M12710-02		
MS21072-4	M12710-048		Plant: Same address
MS21072-5	MA12710-054		
MS21072-6	MA12710-064		
MS21072-04K	M12710-40BC		
MS21072-06K	M12710-62BC		
MS21072-08K	M12710-82BC		
MS21072-3K	M12710-02BC		
MS21072-4K	M12710-048BC		
MS21072-5K	MA12710-054BC		
MS21072-04W	M12710-40PW		
MS21072-06W	M12710-62PW		
MS21072-08W	M12710-82PW		
MS21072-4W	M12710-048PW		
MS21072-5W	MA12710-054PW		
MS21072-6W	MA12710-064PW		
MS21072L04	M12710E-40		
MS21072L06	M12710E-62		
MS21072L08	M12710E-82		
MS21072L3	M12710E-02		
MS21072L4	M12710E-048		
MS21072L5	MA12710E-054		
MS21072L6	MA12710E-064		
MS21072L04K	M12710E-40BC		
MS21072L06x	M12710E-62BC		
MS21072L08K	M12710E-82BC		
MS21072L3K	M12710E-028C		
MS21072L4K	M12710E-048BC		
MS21072L5K	MA12710E-054BC		
MS21072L04W	M12710E-40PN		
MS21072L06W	M12710E-62PW		
MS21072L08W	M12710E-82PW		
MS21072L3W	M12710E-02PN		
MS21072L4W	M12710E-048PW		
MS21072L5W	MA12710E-054PW		
MS21072L6W	MA12710E-064PW		

MS21072-04	VN201-B1-40	Report No.	VOI-SHAN
MS21072-06	VN201-B1-62	NAEC-AML-2425	Fairchild Aerospace Fastener Div
MS21072-08	VN201-B1-82	of 15 Mar 1966	2950 W. Lomita Blvd.
MS21072-3	VN201-B1-02		Torrance, CA 90505-5103
MS21072-4	VN201-B1-048		
MS21072-5	VN201-B1-054		Plant: Same address
MS21072-6	VN201-B1-064		
MS21072-04K	VN201-B2-40		
MS21072-06K	VN201-B2-62		
MS21072-08K	VN201-B2-82		
MS21072-3K	VN201-B2-02		
MS21072-4K	VN201-B2-048		
MS21072-5K	VN201-B2-054		
MS21072-04W	VN201-B3-40		
MS21072-06W	VN201-B3-62		
MS21072-08W	VN201-B3-82	Report No.	VOI-SHAN
MS21072-3W	VN201-B3-02	NAEC-AML-2425	(Cont'd)
MS21072-4W	VN201-B3-048	of 15 Mar 1966	
MS21072-5W	VN201-B3-054		
MS21072-6W	VN201-B3-064		
MS21072L04	VN201-D1-40		
MS21072L06	VN201-D1-62		
MS21072L08	VN201-D1-82		
MS21072L3	VN201-D1-02		
MS21072L4	VN201-D1-048		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21072L5	VN201-D1-054
MS21072L6	VN201-D1-064
MS21072L04K	VN201-D2-40
MS21072L06K	VN201-D2-62
MS21072L08K	VN201-D2-82
MS21072L3K	VN201-D2-02
MS21072L4K	VN201-D2-048
MS21072L5K	VN201-D2-054
MS21072L04W	VN201-D3-40
MS21072L06W	VN201-D3-62
MS21072L08W	VN201-D3-82
MS21072L3W	VN201-D3-02
MS21072L4W	VN201-D3-048
MS21072L5H	VN201-D3-054
MS21072L6W	VN201-D3-064

MS21073 NUT, SELF-LOCKING, PLATE, CORNER, REDUCED RIVET SPACING, LOW HEIGHT, STEEL, 125 KSI Ftu, 450°F

MS21073-04	MTL7S440CPC	NAWC Report	Boots Nut Division
MS21073-06	MTL7S632CPC	601Q9004 of	Republic Fasteners
MS21073-08	MT7S832CPC	22 Jan 90	1300 Rancho Conejo Blvd
MS21073-3	MT7S1032SCPC		Newbury Park, CA 91320
MS21073-4	MT7S428SCPC		
MS21073-5	MT7S524SCPC		Plant: Same address
MT21073-6	MT7S624CPC		
MS21073L04	MTL7S440		
MS21073L06	MTL7S632		
MS21073L08	MT7S832		
MS21073L3	MT7S1032		
MS21073L4	MT7S428		
MS21073L5	MT7S524		
MS21073L6	MT7S624		
MS21073-04K	MTL7S440BCCPC		
MS21073-06K	MTL7S632BCCPC		
MS21073-08K	MT7S832BCCPC		
MS21073-3K	MT7S1032BCCPC		
MS21073-4K	MT7S428BCCPC		
MS21073-5K	MT7S524BCCPC		
MS21073L04K	MTL7S440BC		
MS21073L06K	MTL7S632BC		
MS21073L08K	MT7S832BC		
MS21073L3K	MT7S1032BC		
MS21073L4K	MT7S428BC		
MS21073L5K	MT7S524BC		
MS21073-04	MTL7S440CPC	Report No.	Cherry/Textron
MS21073-06	MTL7S632CPC	NAEC-AML-2428	Cherry Div. of
MS21073-08	MT7S832CPC	of 15 Mar 1966	Textron Inc.
MS21073-3	MT7S1032CPC		P.0. Box 2157
MS21073-4	MT7S428CPC		1224 East Warner Ave.
MS21073-5	MT7S524CPC		Santa Ana, CA 92707
MS21073-6	MT7S624CPC		
MS21073L04	MTL7S440		Plant: Same address
MS21073L06	MTL7S632		
MS21073L08	MT7S832		
MS21073L3	MT7S1032		
MS21073L4	MT7S428		
MS21073L5	MT7S524		
MS21073L6	MT7S624		
MS21073-04K	MTL7S440BCCPC		
MS21073-06K	MTL7S632BCCPC		
MS21073-08K	MT7S832BCCPC		
MS21073-3K	MT7S1032BCCPC		
MS21073-4K	MT7S428BCCPC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21073-SK	MT7S524BCCPC
MS21073L04K	MTL7S440BC
MS21073L06K	MTL7S632BC
MS21073L08K	MT7S832BC
MS21073L3K	MT7S1032BC
MS21073L4K	MT7S428BC
MS21073L5K	MT7S524BC

MS21073-04	F12LHTA5M-40	NAEC-AML-2429	ESNA
MS21073-06	F12LHTA5M-62	of 15 Mar 1966	Division of Harvard Industries
MS21073-02	F52LHTA55M-26		
MS21073-08	F52LHTA55M-82	*MUST BE MANUFACTURED	
MS21073-3	F52LHTA55M-02	AFTER 10 MAY 1994	
MS21073-4	F52LHTA55M-048	DISC-E-94130 LTR	
MS21073-5	F52LHTA55M-054		
MS21073-6	F52LHTA55M-064		
MS21073L04	RM12LHTA5M-40		
MS21073L06	RM12LHTA5M-62		
MS21073L02	RM52LHTA55M-26		
MS21073L08	RM52LHTA55M-82		
MS21073L3	RM52LHTA55M-02		
MS21073L4	RM52LHTA55M-048		
MS21073L5	RM52LHTA55M-054		
MS21073L6	RM52LHTA55M-064		
MS21073-04K	F12LHTA5M-40BC		
MS21073-06K	F12LHTA5M-62BC		
MS21073-08K	F52LHTA55M-82BC		
MS21073-3K	F52LHTA55M-02BC		
MS21073-4K	F52LHTA55M-048BC		
MS21073-5K	F52LHTAS5M-054BC		
MS21073L04K	RM12LHTA5M-40BC		
MS21073L06K	RM12LHTA5M-62BC		
MS21073L08K	RM52LHTA55M-82BC		
MS21073L3K	RM52LHTA55M-02BC		
MS21073L4K	RM52LHTA55M-048BC		
MS2107315K	RM52LHTA55M-054BC		
MS21073-04	MK300C-04CW	Report No.	Kaynar Technologies, Inc.
MS21073-06	MK3000-06CW	NAEC-AML-2474	Kaynar Div.
MS21073-08	MK3000-08CW	of 15 Jun 1966	P.0. Box 3001
MS21073-3	MK3000-3CW		800 S. State College Blvd.
MS21073-4	MK3000-4CW		Fullerton, CA 92634
MS21073-5	MK3300-5CW		
MS21073-04K	MK3000-04BCCW		Plant: Same address
MS21073-06K	MK3000-06BCCW		
MS21073-08K	MK3000-08BCCW		
MS21073-3K	MK3000-3BCCW		
MS21073-4K	MK3000-4BCCW		
MS21073-5K	MK3300-5BCCW		
MS21073L04	MK3000-04		
MS21073L06	MK3000-06		
MS21073L08	MK3000-08		
MS21073L3	MK3000-3		
MS21073L4	MK3000-4		
MS21073L5	MK3300-5		
MS21073L04K	MK3000-04BC		
MS21073L06K	MK3000-06BC		
MS21073L08K	MK3000-08BC		
MS21073L3K	MK3000-3BC		
MS21073L4K	MK3000-4BC		
MS21073L5K	MK3300-5BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21073-08	RM300X08	Report No.	Republic Fastener Mfg. Corp.
MS21073L08	RM300A08	305Q76023 of	1300 Rancho Conejo Blvd.
MS21073-08K	RM300X08K	14 May 1976	Newbury Park, CA 91320
MS21073L08K	RM300A08K		
MS21073-3	RM300X3		Plant: Same address
MS21073L3	RM300A3		
MS21073-3K	RM300X3K		
MS21073L3K	RM300A3K		
MS21073-04	RM300X04L		
MS21073L04	RM300A04L		
MS21073-04K	RM300X04LK		
MS21073L04K	RM300A04LK		
MS21073-06	RM300X06L		
MS21073L06	RM300A06L		
MS21073-06K	RM300X06LK		
MS21073L06K	RM300A06LK		
MS21073-4	M300X4		
MS21073L4	RM300A4		
MS21073-4K	RM300X4K		
MS21073L4K	RM300A4K		
MS21073-5	RM300X5		
MS21073L5	RM300A5		
MS21073-5K	RM300X5K		
MS21073L5K	RM300A5K		

MS21073-6	RM300X6	Report No.	
MS21073L6	RM300A6	305Q83088 of	
		26 Jan 1983	

MS21073-04	M12620NM-40	Report No.	SPS Technologies
MS21073-06	M12620NM-62	NAEC-AML-2369	2701 South Harbor Blvd.
MS21073-08	M12620NM-82	of 15 Mar 1966	Santa Ana, CA 92702
MS21073-3	M12620NM-02		
MS21073-4	M12620NM-048		Plant: Same address
MS21073-5	MA12620NM-054		
MS21073-6	MA12620NM-064		
MS21073L04	M12620-40		
MS21073L06	M12620-62		
MS21073L08	M12620-82		
MS21073L3	M12620-02		
MS21073L4	M12620-048		
MS21073L5	MA12620-054		
MS21073L6	MA12620-064		
MS21073-04K	M12620NM-40BC		
MS21073-06K	M12620NM-62BC		
MS21073-08K	M12620NM-82BC		
MS21073-3K	M12620NM-02BC		
MS21073-4K	M12620NM-048BC		
MS21073-5K	MA12620NM-054BC		
MS21073L04K	M12620-40BC		
MS21073L06K	M1262n-62BC		
MS21073L08K	M12620-82BC		
MS21073L3K	M12620-02BC		
MS21073L4K	M12620-048BC		
MS21073L5K	MA12620-054BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21073-04	VN203-C1-40	Report No.	VOI-SHAN
MS21073-06	VN203-C1-62	NAEC-AML-2425	Fairchild Aerospace Fastener Div
MS21073-08	VN203-C1-82	of 15 Mar 1966	2950 W. Lomita Blvd.
MS21073-3	VN203-C1-02		Torrance, CA 90505-5103
MS21073-4	VN203-C1-048		
MS21073-5	VN203-C1-054		Plant: Same address
MS21073-6	VN203-C1-064		
MS21073L04	VN203-A1-40		
MS21073L06	VN203-A1-62		
MS21073L08	VN203-A1-82		
MS21073L3	VN203-A1-02		
MS21073L4	VN203-A1-048		
MS21073L5	VN203-A1-054		
MS21073L6	VN203-A1-064		
MS21073-04K	VN203-C2-40		
MS21073-06K	VN203-C2-62		
MS21073-08K	VN203-C2-82		
MS21073-3K	VN203-C2-02		
MS21073-4K	VN203-C2-048		
MS21073-5K	VN203-C2-054		
MS21073L04K	VN203-A2-40		
MS21073L06K	VN203-A2-62		
MS21073L08K	VN203-A2-82		
MS21073L3K	VN203-A2-02		
MS21073L4K	VN203-A2-048		
MS21073L5K	VN203-A2-054		

MS21074 NUT, SELF-LOCKING. PLATE, CORNER, REDUCED RIVET SPACING, LOW HEIGHT, CRES, 125 KSI Ftu, 450° & 800°F

MS21074-04	MTL7C440	NAWC Report	Boots Nut Division
MS21074-06	MTL7C632	601Q9004 of	Republic Fasteners
MS21074-08	MTL7C832	22 Jan 90	1300 Rancho Conejo Blvd
MS21074-3	MT7C1032		Newbury Park, CA 91320
MS21074-4	MT7C428		
MS21074-5	MT7C524		Plant: Same address
MS21074-6	MT7C624		
MS21074-04K	MTL7C440BC		
MS21074-06K	MTL7C632BC		
MS21074-08K	MT7C832BC		
MS21074-3K	MT7C1032BC		
MS20174-4K	MT7C428BC		
MS21074-5K	MT7C524BC		
MS21074-04W	MTL7C440PWB		
MS21074-06W	MTL7C632PWB		
MS21074-08W	MT7C832PWB		
MS21074-3W	MT7C1032PWB		
MS21074-4W	MT7C428PWB		
MS21074-5W	MT7C524PWB		
MS21074-6W	MT7C624PWB		
MS21074L04	MTL7C440M		
MS21074L06	MTL7C632M		
MS21074L08	MT7C832M		
MS21074L3	MT7C1032M		
MS21074L4	MT7C428M		
MS21074L5	MT7C524M		
MS21074L6	MT7C624M		
MS21074L04K	MTL7C440BCM		
MS21074L06K	MTL7C632BCM		
MS21074L08K	MT7C832BCM		
MS21074L3K	MT7C1032BCM		
MS21074L4K	MT7C428BCM		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21074L5K	MT7C524BCM
MS21074L04W	MTL7C440PM
MS21074L06W	MTL7C632PM
MS21074L08W	MT7C832PM
MS21074L3W	MT7C1032PM
MS21074L4W	MT7C428PM
MS21074L5W	MT7C524PM
MS21074L6W	MT7C624PM

MS21074-04	MTL7C440	Report No.	Cherry/Textron
MS21074-06	MTL7C632	NAEC-AML-2428	Cherry Div. of
MS21074-08	MT7C832	of 15 Mar 1966	Textron Inc.
MS21074-3	MT7C1032		P.0. Box 2157
MS21074-4	MT7C428		1224 East Warner Ave.
MS21074-5	MT7C524		Santa Ana, CA 92707
MS21074-6	MT7C624		
MS21074-04K	MTL7C440BC		Plant: Same address
MS21074-06K	MTL7C632BC		
MS21074-08K	MT7C832BC		
MS21074-3K	MT7C1032BC		
MS21074-4K	MT7C428BC		
MS21074-5K	MT7C524BC		
MS21074-04W	MTL7C440PWB		
MS21074-06W	MTL7C632PWB		
MS21074-08W	MT7C832PWB		
MS21074-3W	MT7C1032PWB		
MS21074-4W	MT7C428PWB		
MS21074-5W	MT7C524PWB		
MS21074-6W	MT7C624PWB		
MS21074L04	MTL7C440M		
MS21074L06	MTL7C632M		
MS21074L08	MT7C832M		
MS21074L3	MT7C1032M		
MS21074L4	MT7C428M		
MS21074L5	MT7C524M		
MS21074L6	MT7C624M		
MS21074L04K	MTL7C440BCM		
MS21074L06K	MTL7C6328CM		
MS21074L08K	MT7C832BCM		
MS21074L3K	MT7C1032BCM		
MS21074L4K	MT7C428BCN		
MS21074L5K	MT7C524BCM		
MS21074L04W	MTL7C440PM		
MS21074L06W	MTL7C632PM		
MS21074L08W	MT7C832PM		
MS21074L3W	MT7C1032PM		
MS21074L4W	MT7C428PM		
MS21074L5W	MT7C524PM		
MS21074L6W	MT7C624PM		

MS21074L04	RMLHTA5M2860-40	NAEC-AML-2429	ESNA
MS21074L06	RMLHTA5M2860-62	of 15 Mar 1966 *	Division of Harvard Industries
MS21074L02	RMLHTA55M2860-26		
MS21074L08	RMLHTA55M2860-82		
MS21074L3	RMLHTA55M2860-02		
MS21074L4	RMLHTA55M2860-048		
MS21074L5	RMLHTA55M2860-054		
MS21074L6	RMLHTA55M2860-064		
MS21074L04K	RMLHTA5M2860-40BC		
MS21074L06K	RMLHTA5M2860-62BC		
MS21074L08K	RMLHTA55M2860-82BC		
MS21074L3K	RMLHTA55M2860-02BC		
MS21074L4K	RMLHTA55M2860-048BC		
MS21074L5K	RMLHTA55M2860-054BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21074L04W	RMLHTA5M2860P-40	
MS21074L06W	RMLHTA5M2860P-62	
MS21074L02W	RMLHTA55M2860P-26	
MS21074L08N	RMLHTA5SM2860P-82	
MS21074L3W	RMLHTA55M2860P-02	
MS21074L4W	RMLHTA55M2860P-048	
MS21074L5N	RMLHTA55M2860P-054	
MS21074L6W	RMLHTA55M2860P-064	
MS21074-04	LHTA5M2860-40	
MS21074-06	LHTA5M2860-62	
MS21074-02	LHTA55M2860-26	
MS21074-08	LHTA55M2860-82	
MS21074-3	LHTA55M2860-02	
MS21074-4	LHTA55M2860-048	
MS21074-5	LHTA55M2860-054	
MS21074-6	LHTA55M2860-064	*MUST BE MANUFACTURED
MS21074-04K	LHTA5M2860-40BC	AFTER 10 MAY 1994
MS21074-06K	LHTA5M2860-62BC	DISC-E-94130 LTR
MS21074-08K	LHTA55M2860-828C	
MS21074-3K	LHTA55M2860-02BC	
MS21074-4K	LHTA55M2860-048BC	
MS21074-5K	LHTA55M2860-054BC	
MS21074-04W	LHTA5M2860P-40	
MS21074-06H	LHTA5M2860P-62	
MS21074-02N	LHTA55M2860P-26	
MS21074-08W	LHTA55N2860P-82	
MS21074-3W	LHTA55M2860P-02	
MS21074-4W	LHTA55M2860P-048	
MS21074-SW	LHTA55M2860P-054	
MS21074-6W	LHTA55M2860P-064	

MS21074-04	MK3031-04	Report No.	Kaynar Technologies, Inc.
MS21074-06	MK3031-06	NAEC-AML-2474	Kaynar Div.
MS21074-08	MK3031-08	of 15 Jun 1966	P.0. Box 3001
MS21074-3	MK3031-3		800 S. State College Blvd.
MS21074-4	MK3031-4		Fullerton, CA 92634
MS21074-5	MK3331-5		
MS21074-04K	MK3031-04BC		Plant: Same address
MS21074-06K	MK3031-06BC		
MS21074-08K	MK3031-08BC		
MS21074-3K	MK3031-3BC		
MS21074-4K	MK3031-4BC		
MS21074-5K	MK3331-5BC		
MS21074-04W	MK3031-04P		
MS21074-06W	MK3031-06P		
MS21074-08W	MK3031-08P		
MS21074-3W	MK3031-3P		
MS21074-4W	MK3031-4P		
MS21074-5W	MK3331-5P		
MS21074L04	MK3001-04		
MS21074L06	MK3001-06		
MS21074L08	MK3001-08		
MS21074L3	MK3001-3		
MS21074L4	MK3001-4		
MS21074L5	MK3301-5		
MS21074L04K	MK3001-04BC		
MS21074L06K	MK3001-06BC		
MS21074L08K	MK3001-08BC		
MS21074L3K	MK3001-3BC		
MS21074L4K	MK3001-4BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21074L5K	MK3301-5BC
MS21074L04W	MK3001-04P
MS21074L06W	MK3001-06P
MS21074L08W	MK3001-08P
MS21074L3W	MK3001-3P
MS21074L4W	MK3001-4P
MS21074L5W	MK3301-5P

MS21074-04	RM300C04L	NADC Report No.	Republic Fastener Mfg. Corp.
MS21074L04	RM300C04LM	305Q76023 of	1300 Rancho Conejo Blvd.
MS21074-04K	RM300C04LK	14 May 1976	Newbury Park, CA 91320
MS21074L04K	RM300C04LMK		
MS21074-04W	RM300C04LW		Plant: Same address
MS21074L04W	RM300C04LMW		
MS21074L3	RM300C3M		
MS21074L3K	RM300C3MK		
MS21074L3W	RM300C3MW		
MS21074-3	RM300C3		
MS21074-3K	RM300C3K		
MS21074-3W	RM300C3W		
MS21074L08	RM300C08M		
MS21074L08K	RM300C08MK		
MS21074L08W	RM300C08MW		
MS21074-08	RM300C08		
MS21074-08K	RM300C08K		
MS21074-08W	RM300C08W		

Note: "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124 of 20 November 1970.

MS21074-06	RM300C06L	Report No.
MS21074-06K	RM300C06LK	305Q76023 of
MS21074L06K	RM300C06LMK	14 May 1976
MS21074L06	RM300C06LM	
MS21074-06W	RM300C06LW	
MS21074L06W	RM300C06LMW	
MS21074-4	RM300C4	
MS21074L4	RM300C4M	
MS21074-4K	RM300C4K	
MS21074L4K	RM300C4MK	
MS21074-4w	RM300C4W	
MS21074L4W	RM300C4MW	
MS21074-5	RM300C5	
MS21074L5	RM300C5M	
MS21074-5K	RM300C5K	
MS21074L5K	RM300C5MK	
MS21074-5W	RM300C5W	
MS21074L5W	RM300C5MN	

MS21074-6	RM300C6	Report No.
MS21074L6	RM300C6M	305Q83088 of
MS21074-6N	RM300C6W	26 Jan 1983
MS21074L6W	RM300C6MW	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21074-04	M12720-40	Report No.	SPS Technologies
MS21074-06	M12720-62	NAEC-AML-2369	2701 S. Harbor Blvd.
MS21074-08	M12720-82	of 15 Mar 1966	Santa Ana, CA 92702
MS21074-3	M12720-02		
MS21074-4	M12720-048		Plant: Same address
MS21074-5	MA12720-054		
MS21074-6	MA12720-064		
MS21074-04K	M12720-40BC		
MS21074-06K	M12720-62BC		
MS21074-08K	M12720-82BC		
MS21074-3K	M12720-02BC		
MS21074-4K	M12720-048BC		
MS21074-5K	MA12720-054BC		
MS21074-04W	M12720-40PW		
MS21074-06W	M12720-62PW		
MS21074-08W	M12720-82PW		
MS21074-3W	M12720-02PW		
MS21074-4W	M12720-048PW		
MS21074-5W	MA12720-054PW		
MS21074-6W	MA12720-064PW		
MS21074L04	M12720E-40		
MS21074L06	M12720E-62		
MS21074L08	M12720E-82		
MS21074L3	M12720E-02		
MS21074L4	M12720E-048		
MS21074L5	MA12720E-054		
MS21074L6	MA12720E-064		
MS21074L04K	M12720E-40BC		
MS21074L06K	M12720E-62BC		
MS21074L08K	M12720E-82BC		
MS21074L3K	M12720E-02BC		
MS21074L4K	M12720E-048BC		
MS21074L5K	MA12720E-054BC		
MS21074L04W	M12720*-40PH		
MS21074L06W	M12720E-62PW		
MS21074L08W	M12720E-82PW		
MS21074L3W	M12720E-02PW		
MS21074L4W	M12720E-048PW		
MS21074L5W	MA12720E-054PW		
MS21074L6W	MA12720E-064PW		

MS21074-04	VN203-B1-40	Report No.	VOI-SHAN
MS21074-06	VN203-B1-62	NAEC-AML-2425	Fairchild Aerospace Fastener Div
MS21074-08	VN203-B1-82	of 15 Mar 1966	2950 W. Lomita Blvd.
MS21074-3	VN203-B1-02		Torrance, CA 90505-5103
MS21074-4	VN203-B1-048		
MS21074-5	VN203-B1-054		Plant: Same address
MS21074-6	VN203-B1-064		
MS21074-04K	VN203-B2-40		
MS21074-06K	VN203-B2-62		
MS21074-08K	VN203-B2-82		
MS21074-3K	VN203-B2-02		
MS21074-4K	VN203-B2-048		
MS21074-5K	VN203-B2-054		
MS21074-04W	VN203-B3-40		
MS21074-06W	VN203-B3-62		
MS21074-08W	VN203-B3-82		
MS21074-3W	VN203-B3-02		
MS21074-4W	VN203-B3-048		
MS21074-5W	VN203-B3-054		
MS21074-6W	VN203-B3-064		
MS21074L04	VN203-D1-40		
MS21074L06	VN203-D1-62		
MS21074L08	VN203-D1 -82		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21074L3	VN203-D1-02
MS21074L4	VN203-D1-048
MS21074L5	VN203-D1-054
MS21074L6	VN203-D1-064
MS21074L04K	VN203-D2-40
MS21074L06K	VN203-D2-62
MS21074L08K	VN203-D2-82
MS21074L3K	VN203-D2-02
MS21074L4K	VN203-D2-048
MS21074L5K	VN203-D2-054
MS21074L04W	VN203-D3-40
MS21074L06W	VN203-D3-82
MS21074L08W	VN203-D3-82
MS21074L3W	VN203-D3-02
MS21074L4W	VN203-D3-048
MS21074L51	VN203-D3-054
MS21074L6W	VN203-D3-064

MS21075 NUT, SELF-LOCKING, PLATE, TWO LUG, FLOATING, REDUCED RIVET SPACING, LOW HEIGHT, STEEL, 125 KSI Ftu, 450°F

MS21075-04	MTL65S440SCPC	NAWC Report	Boots Nut Division of
MS21075-06	MTL65S632SCPC	601Q9004 of	Republic Fasteners Mfg. Corp.
MS21075-08	MT65S832SCPC	22 Jan 90	1300 Rancho Conejo Blvd.
MS21075-3	MT65S1032SCPC		Newbury Park, CA 91320
MS21075-4	MT65S428SCPC		
MS21075L04	MTPHL65S440S		Plant: Same address
MS21075L06	MTL65S632S		
MS21075L08	MT65S832S		
MS21075L3	MT65S1032S		
MS21075L4	MT65S428S		

MS21075-04	MTL65S440SCPC	Report No. NAEC-	Cherry/Textron
MS21075-06	MTL65S632SCPC	AML-2428 of	Cherry Div. of
MS21075-08	MT65S832SCPC	15 Mar 1966	Textron Inc.
MS21075-3	MT65S1032SCPC		P.0. Box 2157
MS21075-4	MT65S428SCPC		1224 East Warner Ave.
MS21075L04	MTL65S440S		Santa Ana, CA 92707
MS21075L06	MTL65S632S		
MS21075L08	MT65S832S		Plant: Same address
MS21075L3	MT65S1032S		
MS21075L4	MT65S428S		

MS21075-04	F52LHTA531M-40	NAEC-AML-2429	ESNA
MS21075-06	F52LHTA531M-62	of 15 Mar 1966*	Division of Harvard Industries
MS21075-08	F52LHTA521M-82		
MS21075-3	F52LHTA521N-02	*MUST BE MANUFACTURED	
MS21075-4	F52LHTA521M-048	AFTER 10 MAY 1994	
MS21075-5	F52LHTAS21M-054	DISC-E-94130 LTR	
MS21075L04	RM52LHTA531M-40		
MS21075L06	RM52LHTA531M-62		
MS21075L08	RM52LHTA521M-82		
MS21075L3	RM52LHTA521M-02		
MS21075L4	RM52LHTA521M-048		
MS21075L5	RM52LHTA521M-054		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21075-04	MF1000-04CW	Report No.	Kaynar Technologies, Inc.
MS21075-06	MF1000-06CW	NAEC-AML-2474	Kaynar Div.
MS21075-08	MF1000-08CW	of 15 Jun 1966	P.O. Box 3001
MS21075-3	MF1000-3CW		800 S. State College Blvd.
MS21075-4	MF1000-4CW		Fullerton, CA 92634
MS21075-5	MF1300-5CW		
MS21075L04	MF1000-04		Plant: Same address
MS21075L06	MF1000-06		
MS21075L08	MF1000-08		
MS21075L3	MF1000-3		
MS21075L4	MF1000-4		
MS21075L5	MF1300-5		

MS21075-3	MF5000-3CH	Report No.
MS21075L3	MF5000-3	305Q74016 of
		22 Nov 1974

Note: "CW" indicates cadmium plated with Kaywax added.

MS21075-08	MF5000-08CW	Report No.
MS21075L08	MF5000-08	305Q75013 of
		23 Jun 1975

Notes: 1. "CW" cadmium plated with KayWax added.
2. "L" Kaylube, molybdenum disulfide, dry lubricant coated.

MS21075-04	MF5000-04CW	NADC Report No.
MS21075L04	MF5000-04	305Q77037 of
MS21075-06	MF5000-06CW	12 Jul 1977
MS21075L06	MF5000-06	
MS21075-4	MF5000-4CW	
MS21075L4	MF5000-4	

Note: 1. "CW" cadmium plated with Kaywax added.
2. MF5000 cadmium plated, Kaylube M0S2 (dry film lubricant).
3. "L" designates dry film.

MS21075-5	MF5000-5CW	NADC Report No.
MS21075L5	MF5000-5	305Q7905 of
		5 Jun 1979

Note: "CW" cadmium plated With Kaywax added.

MS21075-04	RFM20X04L	Report No.	Republic Fastener Mfg. Corp
MS21075L04	RFM20A04L	305Q73001 of	1300 Rancho Conejo Blvd.
MS21075-06	RFM20X06L	6 Feb 1973	Newbury Park, CA 91320
MS21075L06	RFM20A06L		
MS21075-08	RFM20X08		Plant: Same address
MS21075L08	RFM20A08		
MS21075-3	RFM20X3		
MS21075L3	RFM20A3		
MS21075-4	RFM20X4		
MS21075L4	RFM20A4		

Note: "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21075-3E	RFM20X3E	Report No. 601Q9305 of 26 Feb 93	
MS21075L3E	RFM20A3E		

Notes: 1. Manufacturing Process: Stamping
2. Lubricant: (For Government Designation with "L") Kal-Gard FA per MIL-L-46010, Type I

MS21075-5	RFM20X5	Report No. 305Q83088 of 26 Jan 1983	
MS21075L5	RFM20A5		

MS21075L3	LAM-93M	Report No. 305Q83111 of 19 Oct 1983	Simmonds Mecaero Fasteners, Inc. 1734 Sequoia Avenue Orange, CA 92668
MS21075-08	LAM-908	Report No. 601Q8401 of 24 Feb 1984	. Plant: Simmonds Usine De Champaissant 72110 Saint-Cosme En Vairais France
MS21075L08	LAM-908M		

Note: 1. Manufacturing process: Cold formed
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21075-3	LAM-93	NADC Report 601Q8417 of 25 Oct 1984	
MS21075-4	LAM-94	NADC Report 601Q8505 of 30 May 1985	
MS21075L4	LAM-94M		
MS21075-04	LASMR-904	NADC Report 601Q8510 of 10 Jun 1985	
MS21075L04	LASMR-904M		
MS21075-06	LASMR-906		
MS21075L06	LASMR-906M		

Note: 1. Manufacturing process: Cold stamping
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21075-04	MA13600NM-40	Report No. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies 2701 South Harbor Blvd. Santa Ana, CA 92702
MS21075-06	MA13600NM-62		
MS21075-08	MA13600NM-82		
MS21075-3	MA13600NM-02		
MS21075-4	MA13600NM-048		Plant: Same address
MS21075-5	MA13600NM-054		
MS21075L04	MA13600-40		
MS21075L06	MA13600-62		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21075L08	MA13600-82	Report No. NAEC-	
MS21075L3	MA13600-02	AML-2369 of	
MS21075L4	MA13600-048	15 Mar 1966	
MS21075L5	MA13600-054		

MS21075-04	VN252-C1-40	Report No.	VOI-SHAN
MS21075-06	VN252-C1-62	NAEC-AML-2425	Fairchild Aerospace Fastener Div
MS21075-08	VN252-C1-82	of 15 Mar 1966	2950 W. Lomita Blvd.
MS21075-3	VN252-C1-02		Torrance, CA 90505-5103
MS21075-4	VN252-C1-048		
MS21075-5	VN252-C1-054		Plant: Same address
MS21075L04	VN252-A1-40		
MS21075W06	VN252-A1-62		
MS21075L08	VN252-A1-82		
MS21075L3	VN252-A1-02		
MS21075L4	VN252-A1-048		
MS21075L5	VN252-A1-054		

MS21076 NUT, SELF-LOCKING, PLATE, TW0 LUG, FLOATING, REDUCED RIVET SPACING, LOW HEIGHT, CRES, 125 KSI Ftu, 450 DEG & 800 DEG F

MS21076-04	MTL65C440C	NAWC Report	Boots Nut Division of
MS21076-06	MTL65C632C	601Q9004 of	Republic Fasteners Mfg. Corp.
MS21076-08	MT65C832C	22 Jan 90	1300 Rancho Conejo Blvd.
MS21076-3	MT65C1032C		Newbury Park, CA 91320
MS21076-4	MT65C428C		
MS21076L04	MTL65C440CM		Plant: Same address
MS21076L06	MTL65C632CM		
MS21076L08	MT65C832CM		
MS21076L3	MT65S1032CM		
MS21076L4	MT65C428CM		

MS21076-04	MTL65C440C	Report No.	Cherry/Textron
MS21076-06	MTL6SC632C	NAEC-AML-2428	Cherry Div. of
MS21076-08	MT65C832C	of 15 Mar 1966	Textron Inc.
MS21076-3	MT65C1032C		P.0. Box 2157
MS21076-4	MT65C428C		1224 East Warner Ave.
MS21076L04	MTL65C440CM		Santa Ana, CA 92707
MS21076L06	MTL65C632CM		
MS21076L08	MT65C832CM		Plant: Same address
MS21076L3	MT65C1032CM		
MS21076L4	MT65C428CM		

MS21076L04	RMLHTA3452-40	NAEC-AML-2429	ESNA
MS21076L06	RMLHTA3452-62	of 15 Mar 1966*	Division of Harvard Industries
MS21076L08	RMLHTA3300-82		
MS21076L3	RMLHTA3300-02	*MUST BE MANUFACTURED	
MS21076L4	RMLHTA3300-048	AFTER 10 MAY 1994	
MS21076L5	RMLHTA3300-054	DISC-E-94130 LTR	
MS21076-04	LHTA3452-40		
MS21076-06	LHTA3452-62		
MS21076-08	LHTA3300-82		
MS21076-3	LHTA3300-02		
MS21076-4	LHTA3300-048		
MS21076-5	LHTA3300-054		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21076-04	MF1031-04	Report No.	Kaynar Technologies, Inc.
MS21076-06	MF1031-06	NAEC-AML-2474	Kaynar Div.
MS21076-08	MF1031-08	of 15 Jun 1966	P.0. Box 3001
MS21076-3	MF1031-3		800 S. State College Blvd.
MS21076-4	MF1031-4		Fullerton, CA 92634
MS21076-5	MF1331-5		
MS21076L04	MF1001-04		Plant: Same address
MS21076L06	MF1001-06		
MS21076L08	MF1001-08		
MS21076L3	MF1001-3		
MS21076L4	MF1001-4		
MS21076L5	MF1301-5		

MS21076-3	MF5031-3	Report No.
MS21076L3	MF5001-3	305Q74016 of
MS21076-08	MF5031-08	22 Nov 1974
MS21076L08	MF5001-08	

MS21076-04	MF5031-04	NADC Report No.
MS21076L04	MF5001-04	305Q77037 of
MS21076-06	MF5031-06	12 Jul 1977
MS21076L06	MF5001-06	

MS21076-4	MF5031-4	NADC Report No.
MS21076L4	MF5001-4	305Q77037 of
		12 Jul 1977

Note: 1. "L" designates dry film.

MS21076-5	MF5031-5	NADC Report No.
MS21076L5	MF5001-5	305Q79050 of
		5 Jun 1979

MS21076-04	RFM20C04L	Report No.	Republic Fastener Mfg. Corp.
MS21076L04	RFM20C04LM	305Q73001 of	1300 Rancho Conejo Blvd.
MS21076-06	RFM20C06L	6 Feb 1973	Newbury Park, CA 91320
MS21076L06	RFM20C06LM		
MS21076-08	RFM20C08		Plant: Same address
MS21076L08	RFM20C08M		
MS21076-3	RFM20C3		
MS21076L3	RFM20C3M		
MS21076-4	RFM20C4		
MS21076L4	RFM20C4M		

Note: "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124 of 20 November 1970.

MS21076-5	RFM20C5	Report No.
MS21076L5	RFM20C5M	305Q83088 of
		26 Jan 1983

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21076-3E	RFM20C3E	Report No.	
MS21076L3E	RFM20C3ME	601Q9305	
		of 26 Feb 93	

Notes: 1. Manufacturing Process: Stamping
2. Lubricant: (For Government Designation with "L") Kal-Gard FA per MIL-L-46010, Type I

MS21076-08	LAM-508	Report No.	Simmonds Mecaero
MS21076-3	LAM-53	601Q8401 of	Fasteners, Inc.
		24 Feb 1984	1734 Sequoia Avenue
			Orange, CA 92668
MS21076L06	LASMR-506M	Report No.	Plant:
		601Q8407 of	Simmonds
		20 Apr 1984	Usine De Champaissant
			72110 Saint-Cosme En Vairais
			France

Note: 1 Manufacturing process: Cold formed
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21076L3	LAM-53M	NADC Report
MS21076-4	LAM-54	601Q8507 of
MS21076L4	LAM-54M	31 May 1985

MS21076L08	LAM-508M	NADC Report
		601Q8517 of
		16 Dec 1985
MS21076-06	LASMR-506	NADC Report
		601Q8604 of
		12 Mar 1986

Note: 1. Manufacturing process: Cold stamping
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21076-04	MA13700-40	Report No.	SPS Technologies
MS21076-06	MA13700-62	NAEC-AML-2369	2701 South Harbor Blvd.
MS21076-08	MA13700-82	of 15 Mar 1966	Santa Ana, CA 92702
MS21076-3	MA13700-02		
MS21076-4	MA13700-048		Plant: Same address
MS21076-5	MA13700-054		
MS21076L04	MA13700E-40		
MS21076L06	MA13700E-62		
MS21076L08	MA13700E-82		
MS21076L3	MA13700F-02		
MS21076L4	MA13700E-048		
MS21076L5	MA13700E-054		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21076-04	VN252-B1-40	Report No.	VOI-SHAN
MS21076-06	VN252-B1-62	NAEC-AML-2425	Fairchild Aerospace Fastener Div
MS21076-08	VN252-B1-82	of 15 Mar 1966	2950 W. Lomita Blvd.
MS21076-3	VN252-B1-02		Torrance, CA 90505-5103
MS21076-4	VN252-B1-048		
MS21076-5	VN252-B1-054		Plant: Same address
MS21076L04	VN252-D1-40		
MS21076L06	VN252-D1-62		
MS21076L08	VN252-D1-82		
MS21076L3	VN252-D1-02		
MS21076L4	VN252-D1-048		
MS21076L5	VN252-D1-054		

MS21077 NUT. SELF-LOCKING, PLATE, TWO LUG, FLOATING, NONMETALLIC INSERT, STEEL, 125 KSI Ftu, 250°F

MS21077-06	FNA401-62	NAEC-AML-2429	ESNA
MS21077-08	FNA401-82	of 15 Mar 1966 *	Division of Harvard Industries
MS21077-3	FNA401-02		
MS21077-4	FNA401-048	*MUST BE MANUFACTURED	
MS21077-5	FNA401-054	AFTER 10 MAY 1994	
MS21077-6	FNA401-064	DISC-E-94130 LTR	
MS21077-06K	FNA401-62BC		
MS21077-08K	FNA401-82BC		
MS21077-3K	FNA401-02BC		
MS21077-4K	FNA401-048BC		
MS21077-5K	FNA401-054BC		
MS21077-6K	FNA401-064BC		

MS21077-06	SNLA-069-06	NADC Report	Simmonds Mecaero
MS21077-08	SNLA-069-08	601QB511 of	Fasteners, Inc.
MS21077-3	SNLA-069-3	21 Jun 1985	1734 Sequoia Avenue
MS21077-4	SNLA-069-4		Orange, CA 92668
		NADC Ltr 02872 5 Apr 1988	

Note: 1. Manufacturing process: Machined

2. Locking element material is nylon (blue or gold until 31 December 1990, gold thereafter)

3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

Plant:

Simmonds
Usine De Champaissant
72110 Saint-Cosme En Vairais
France

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21077-5	SNLA-069-5	NADC Report 601Q8604 of 12 Mar 1986 NADC Ltr 20872 5 Apr 1988	
MS21077-6	SNLA-069-6		

Note: 1. Manufacturing process: Cold stamping
2. Insert: Blue or gold nylon until 31 December 1990, gold thereafter
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21078 NUT, SELF-LOCKING, PLATE, TW0 LUG, NONMETALLIC INSERT, STEEL, 125 KSI Ftu, 250° F

MS21078-04	F22NA1-40	NAEC-AML-2429 of 15 Mar 1966 *MUST BE MANUFACTURED AFTER 10 MAY 1994 DISC-E-94130 LTR	ESNA Division of Harvard Industries
MS21078-06	F22NA1-62		
MS21078-08	F22NA1-82		
MS21078-3	F22NA1-02		
MS21078-4	F22NA1-048		
MS21078-5	F22NA1-054		
MS21078-6	F42NA1-064		
MS21078-7	F52NA1Q-070		
MS21078-8	F52NA1Q-080		
MS21078-9	F52NA1Q-098		
MS21078-10	F52NA1Q-108		
MS21078-04K	F22NA1-40BC		
MS21078-06K	F22NA1-62BC		
MS21078-08K	F22NA1-82BC		
MS21078-3K	F22NA1-02BC		
MS21078-4K	F22NA1-048BC		
MS21078-5K	F22NA1-054BC		
MS21078-6K	F42NA1-064BC		

MS21078-6	F42NA1-624	AMD Report No. MA769418 of 6 Oct 1969	Greer Stop Nut, Inc. 481 McNally Drive Nashville, TN 37211 Plant: Same address
MS21078-8	F52NA1-820		

MS21078-3	GAL-63	NADC Report 601Q8604 of 12 Mar 1986 NADC Ltr 02872 5 Apr 1988	Simmonds Mecaero Fasteners, Inc. 1734 Sequoia Avenue Orange, CA 92668

Note: 1. Manufacturing process: Cold stamping
2. Locking insert: Blue or gold nylon until 31 December 1990, gold thereafter
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

Plant:
Simmonds
Usine De Champaissant
72110 Saint-Cosme En Vairais
France

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21078-3	SN-102NA1-24	NAWCADWAR Report No. 435Q9623 of 15 Jul 1996	Abbott Interfast Corp 190 Abbott Drive Wheeling, IL 60090

MS21079 NUT, SELF-LOCKING, GANG CHANNEL, NONMETALLIC INSERT, 125 KSI Ftu, 250°F

MS21079-08-X	F22NG41-82-JX	NAEC-AML-2429	ESNA
MS21079-3-X	F22NG41-02-JX	of 15 Mar 1966	Division of Harvard Industries
MS21079-4-X	F22NG41-048-JX		
MS21079-5-X	F22NG41-054-JX	*MUST BE MANUFACTURED	
MS21079-6-X	F22NG41-064-JX	AFTER 10 MAY 1994	
		DISC-E-94130 LTR	

MS21080 NUT, SELF-LOCKING, PLATE, ONE LUG, NONMETALLIC INSERT, STEEL, 125 KSI Ftu, 250° F

MS21080-06	F22NA17A-62	NAEC-AML-2429	ESNA
MS21080-08	F22NA17A-82	of 15 Mar 1966 *	Division of Harvard Industries
MS21080-3	F22NA17A-02		
MS21080-4	F22NA17A-048	*MUST BE MANUFACTURED	
MS21080-5	F22NA17A-054	AFTER 10 MAY 1994	
MS21080-6	F42NA17A-064	DISC-E-94130 LTR	
MS21080-06K	F22NA17A-62BC		
MS21080-08K	F22NA17A-82BC		
MS21080-3K	F22NA17A-02BC		
MS21080-4K	F22NA17A-048BC		
MS21080-5K	F22NA17A-054BC		
MS21080-6K	F42NA17A-064BC		

MS21080-3	AJAL-63	NADC Report 601Q8604 of 12 Mar 1986 NADC Ltr 02872 5 Apr 1988	Simmonds Mecaero Fasteners, Inc. 1734 Sequoia Avenue Orange, CA 92668

Note: 1. Manufacturing process: Cold stamping
2. Locking insert: Blue or gold nylon until 31 December 1990, gold thereafter
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.22S-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

Plant:
Simmonds
Usine De Champaissant
72110 Saint-Cosme En Vairais
France

MS21081 NUT, SELF-LOCKING, PLATE, CORNER, NONMETALLIC INSERT, STEEL, 125 KSI Ftu, 250° F

MS21081-06	F22NA5-62	NAEC-AML-2429	ESNA
MS21081-08	F22NA5-82	of 15 Mar 1966*	Division of Harvard Industries
MS21081-3	F22NA5-02		
MS21081-4	F22NA5-048	*MUST BE MANUFACTURED	
MS21081-5	F22NA5-054	AFTER 10 MAY 1994	
MS21081-6	F42NA5-064	DISC-E-94130 LTR	
MS21081-7	F52NA5Q-070		
MS21081-8	F52NA5Q-080		
MS21081-10	F52NA5Q-108		
MS21081-06K	F22NA5-62BC		
MS21081-08K	F22NA5-82BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21081-3K	F22NA5-02BC		
MS21081-4K	F22NA5-048BC		
MS21081-5K	F22NA5-054BC		
MS21081-6K	F42NA5-064BC		

MS21082 NUT, SELF-LOCKING, PLATE, ONE LUG, FLOATING, NONMETALLIC INSERT, STEEL, 125 KSI Ftu, 250 DEG F

MS21082-08	FNA417-82	NAEC-AML-2429	ESNA
MS21082-3	FNA417-02	of 15 Mar 1966*	Division of Harvard Industries
MS21082-4	FNA417-048		
MS21082-5	FNA417-054	*MUST BE MANUFACTURED	
MS21082-08K	FNA417-82BC	AFTER 10 MAY 1994	
MS21082-3K	FNA417-02BC	DISC-E-94130 LTR	
MS21082-4K	FNA417-048BC		
MS21082-5K	FNA417-054BC		

MS21083 NUT, SELF-LOCKING, HEXAGON, NONMETALLIC INSERT, LOW HEIGHT, 250° F

MS21083N04	MS21083N04	Report No.	Abbott Interfast Corporation
MS21083N06	MS21083N06	601Q9114 of	190 Abbott Drive
MS21083N08	MS21083N08	8 Feb 1992	Wheeling, IL 60090
MS21083N3	MS21083N3		
MS21083N4	MS21083N4		Plant: Same Address

Note: Manufacturing Process: Forged

MS21083B04	Y92NTM-440	Report No.	Greer Stop Nut, Inc.
MS21083B08	Y92NTM-832	NAEC-AML-2242	481 McNally Drive
MS21083B3	Y92NTM-1032	of 6 Jul 1965	Nashville, TN 37211

Plant: Same Address

MS21083N4	F52NTE-428	Report No.
MS21083N5	F52NTE-524	NAEC-AML-2331
MS21083N6	F52NTE-624	of 1 Dec 1965
MS21083N7	F52NTE-720U	
MS21083N8	F52NTE-820	
MS21083N9	F52NTE-918	
MS21083N10	F52NTE-1018	
MS21083N12	F52NTE-1216	
MS21083C4	L79NTE-428	
MS21083D5	68NTE-524	
MS21083D6	68NTE-624	
MS21083D8	68NTE-820	
MS21083B8	Y92NTE-820	

Note: 1. Manufacturing process: Machined
2. A1uminum alloy and cres parts lubricated With Carbo Wax.

MS21083N04	F22NTM-440	Report No.
MS21083C04	L79NTM-440	NAEC-AML-2146 of
MS21083B06	Y92NTM-632	9 Mar 1965 and
		NAEC-AML-ltr
		M-62-BRS 10410 (7701)
		of 13 Apr 1966

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21083D08	NTMJ-832	Report No. NAEC-AML-2457 of 10 May 1966

MS21083D04	NTMJ-440	Report No. NAEC-AML-2133 of 24 May 1966
MS21083D06	NTMJ-632	
MS21083D3	NTMJ-1032	
MS21083N06	F22NTM-632	
MS21083N08	F22NTM-832	
MS21083N3	F22NTM-1032	
MS21083C06	L79NTM-632	
MS21083C08	L79NTM-832	
MS21083C3	L79NTM-1032	

Note: 1. Manufacturing process: Machined

MS21083B5	Y92NTE-524	AML Report No. 78601-67 of 24 May 1967

Note: Manufacturing process: Machined

MS21083B3	Y92NTM-1032	NADC Report No. 305Q79055 of 24 Aug 1979
MS21083C5	L79NTE-524	
MS21083C6	L79NTE-624	
MS21083C8	L79NTE-820	
MS21083C16	L79NTE-1612	
MS21083N16	F52NTE-1612	
MS21083N20	F52NTE-2012	

Note: 1. Material: Green nylon.
2. "L" manufacturing part number designates Carbo-Wax.
3. Manufacturing process: Machined

MS21083B5	Y79NTE-524	AML Report No. 78601-67 of 24 May 1967

MS21083D10	68NTE-1018	Report No. 601Q8715 of 31 Aug 87
MS21083D12	68NTE-1216	

MS21083C10	L79NTE-1018	Report No. 601Q8803 of 9 May 88
MS21083C12	L79NTE-1216	
MS21083C14	L79NTE-1414	
MS21083C14	F52NTE-1414	

MS21083N04	F22NTM-40	NAWCADWAR	MacLean-ESNA
MS21083N06	F22NTM-62	Report No.	A MacLean-Fogg Co.
MS21083N08	F22NTM-82	435Q9519 of	611 Country Club Road
MS21083N3	F22NTM-02	20 Oct 1995	P. O. Box 988
MS21083N4	F52NTE-048		Pocahontas, AR 72455
MS21083N5	F52NTE-054		
MS21083N6	F52NTE-064		Plant: Same address
MS21083N7	F52NTE-070U		
MS21083N8	F52NTE-080		
MS21083N9	F52NTE-098		
MS21083N10	F52NTE-108		
MS21083N12	F52NTE-126		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21083N14	F52NTE-144
MS21083N16	F52NTE-162
MS21083N18	F52NTE-182
MS21083N20	F52NTE-202
MS21083N22	F52NTE-222
MS21083N24	F52NTE-242
MS21083C04	L79NTM-40
MS21083C06	L79NTM-62
MS21083C08	L79NTM-82
MS21083C3	L79NTM-02
MS21083C4	L79NTE-048
MS21083C5	L79NTE-054
MS21083C6	L79NTE-064
MS21083C7	L79NTE-070U
MS21083C8	L79NTE-080
MS21083D04	NTMJ-40
MS21083D06	NTMJ-62
MS21083D08	NTMJ-82
MS21083D3	NTMJ-02
MS21083D5	68NTE-054
MS21083D6	68NTE-064
MS21083D7	68NTE-070U
MS21083D8	68NTE-080
MS21083D9	68NTE-098
MS21083D10	68NTE-108
MS21083D12	68NTE-126
MS21083B04	Y92NTM-40
MS21083B06	Y92NTM-62
MS21083B08	Y92NTM-82
MS21083B3	Y92NTM-02
MS21083B4	Y92NTE-048
MS21083B5	Y92NTE-054
MS21083B6	Y92NTE-064
MS21083B7	Y92NTE-070U
MS21083B8	Y92NTE-080
MS21083B9	Y92NTE-098
MS21083B10	Y92NTE-108
MS21083B12	Y92NTE-126
MS21083B14	Y92NTE-144
MS21083B16	Y92NTE-162
MS21083B18	Y92NTE-182
MS21083B20	Y92NTE-202

Note: 1. Manufacturing process: Machined or Forged
2. Stainless parts lubricated with Carbo Nax.

MS21083D4	8NTE-048
MS21083D14	68NTE-144
MS21083D16	68NTE-162
MS21083D18	68NTE-1B2
MS21083D20	68NTE-202
MS21083N08	F22NTM-82
MS21083N3	F22NTM-02
MS21083N4	F22NTE-048
MS21083N5	F55NTE-054
MS21083N6	F22NTE-064
MS21083C04	79NTM-40
MS21083C06	79NTM-62
MS21083C08	79NTM-82
MS21083C3	79NTM-02
MS21083C4	79NTE-048

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21083C5	79NTE-054
MS21083C6	79NTE-064
MS21083C7	79NTE-070U
MS21083C8	79NTE-080

Note: Manufacturing process: Machined or forged

MS21083C9	79NTE-098
MS21083C10	79NTE-108
MS21083C20	79NTE-202

Note: 1. Manufacturing process: Machined or forged
2. All stainless steel parts are passivated plus Carbo Wax.

MS21086 NUT, SELF-LOCKING, PLATE, SIDE BY SIDE, REDUCED RIVET SPACING, LOW-HEIGHT, STEEL, 125 KSI Ftu, 450 DEG F

MS21086-08	MT13S832CP	Report No.	Cherry/Textron
MS21086-3	MT13S1032CP	NAEC-AML-2428 of	Cherry Div. of
MS21086-4	MT13S428CP	15 Mar 1966	Textron Inc.
MS21086-S	MT13S524CP		P.0. Box 2157
MS21086-6	MT13S624CP		1224 East Warner Ave.
MS21086L08	MT13S832		Santa Ana, CA 92707
MS21086L3	MT13S1032		
MS21086L4	MT13S428		Plant: Same address
MS21086L5	MT13S524		
MS21086L6	MT13S624		
MS21086-08K	MT13S832BCCP		
MS21086-3K	MT13S1032BCCP		
MS21086-4K	MT13S428BCCP		
MS21086-5K	MT13S524BCCP		
MS21086L08K	MT13S832BC		
MS21086L3K	MT13S1032BC		
MS21086L4K	MT13S428BC		
MS21086L5K	MT13S524BC		

MS21086-08	F52LHTA575M-82	NAEC-AML-2429	ESNA
MS21086-3	F52LHTA575M-02	of 15 Mar 1966*	Division of Harvard Industries
MS21086-4	F52LHTA575M-048		
MS21086-5	F52LHTA575M-054		
MS21086-6	F52LHTA575M-064		
MS21086L08	RM52LHTA575M-82		
MS21086L3	RM52LHTA575M-02		
MS21086L4	RM52LHTA575M-048		
MS21086L5	RM52LHTA575M-054		
MS21086L6	RM52LHTA575M-064		
MS21086-08K	F52LHTA575M-82BC		
MS21086-3K	F52LHTA575M-02BC	*MUST BE MANUFACTURED	
MS21086-4K	F52LHTA575M-048BC	AFTER 10 MAY 1994	
MS21086-5K	F52LHTA575M-054BC	DISC-E-94130 LTR	
MS21086L08K	RM52LHTA575M-82BC		
MS21086L3K	RM52LHTA575M-02BC		
MS21086L4K	RM52LHTA575M-048BC		
MS21086L5K	RM52LHTA575M-054BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21086-08	MK4000-08CW	Report No.	Kaynar Technologies, Inc.
MS21086-3	MK4000-3CW	NAEC-AML-2474 of	Kaynar Div.
MS21086-4	MK4000-4CW	5 Jun 1966	P.0. Box 3001
MS21086-5	MK4300-5CW		800 S. State College Blvd.
MS21086-08K	MK4000-08BCCW		Fullerton, CA 92634
MS21086-3K	MK4000-3BCCW		
MS21086-4K	MK4000-4BCCW		Plant: Same address
MS21086-5K	MK4300-5BCCW		
MS21086L08	MK4000-08		
MS21086L3	MK4000-3		
MS21086L4	MK4000-4		
MS21086L5	MK4300-5		
MS21086L08K	MK4000-08BC		
MS21086L3K	MK4000-3BC		
MS21086L4K	MK4000-4BC		
MS21086L5K	MK4300-5BC		

MS21086-08	R300X08	Report No.	Republic Fastener Mfg. Corp.
MS21086L08	R300A08	305Q5095 of	1300 Rancho Conejo Blvd.
MS21086-08K	R300X08K	17 Jun 1976	Newbury Park, CA 91320
MS21086L08K	R300A08K		
MS21086-3	R300X3		Plant: Same address
MS21086L3	R300A3		
MS21086-3K	R300X3K		
MS21086L3K	R300A3K		
MS21086-4	R300X4		
MS21086L4	R300A4		
MS21086-4K	R300X4K		
MS21086L4K	R300A4K		

MS21086-08	M12640NM-82	AMD Report No.	SPS Technologies
MS21086-3	M12640NM-02	MA769328 of	2701 S. Harbor Blvd.
MS21086-4	M12640NM-048	22 Jan 1969	Santa Ana, CA 92702
MS21086-5	MA12640NM-054		
MS21086L08	MA12640NM-82		Plant: Same address
MS2i086L3	MA12640NM-02		
MS21086L4	MA12640NM-048		
MS21086L5	MA12640NM-054		
MS21086-08K	M12640NM-82BC		
MS21086-3K	MA12640NM-02BC		
MS21086-4K	MA12640NM-048BC		
MS21086-5K	MA12640NM-054BC		
MS21086L08K	M12640-82BC		
MS21086L3K	M12640-02BC		
MS21086L4K	M12640-048BC		
MS21086L5K	MA12640-054BC		

Note: 1. Manufacturing process: Stamped or forged
2. Molybdenum disulfide dry film lubricant as approved by NAMATCEN ltr XM-621-FTR:mlp J9 (1434).

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21087 NUT, SELF-LOCKING, PLATE, SIDE BY SIDE, REDUCED RIVET SPACING, LOW HEIGHT, CRES, 125 KSI Ftu, 450 DEG & 800 DEG F

MS21087L08	MT13C832M	NAWC Report	Boots Nut Division of
MS21087L3	MT13C1032M	601Q9004 of	Republic Fasteners Mfg Corp
MS21087L4	MT13C428M	22 Jan 1990	1300 Rancho Conejo Blvd.
MS21087L08K	MT13C832BCM		Newbury Park, CA 91320
MS21087L3K	MT13C1032BCM		
MS21087L4K	MT13C428BCM		Plant: Same address
MS21087L08W	MT13C832PM		
MS21087L3W	MT13C1032PM		
MS21087L4W	MT13C428PM		
MS21087-08	MT13C832		
MS21087-3	MT13C1032		
MS21087-4	MT13C428		
MS21087-08K	MT13C832BC		
MS21087-3K	MT13C1032BC		
MS21087-4K	MT13C428BC		
MS21087-08W	MT13C832P		
MS21087-3W	MT13C1032P		
MS21087-4W	MT13C428P		

Notes: 1. Manufacturing Process: Stamped
2. Lubricant: Ferrocote 348

MS21087L08	MT13C832M	Report No.	Cherry/Textron
MS21087L3	MT13C1032M	NAEC-AML-2428 of	Cherry Div. of
MS21087L4	MT13C428M	15 Mar 1966	Textron Inc.
MS21087L5	MT13C524M		P.0. Box 2157
MS21087L6	MT13C624M		1224 East Harner Ave.
MS21087L08K	MT13C832BCM		Santa Ana, CA 92707
MS21087L3K	MT13C1032BCM		
MS21087L4K	MT13C428BCM		Plant: Same address
MS21087L5K	MT13C524BCM		
MS21087L08W	MT13C832PM		
MS21087L3W	MT13C1032PM		
MS21087L4W	MT13C42BPM		
MS21087L5W	MT13C524PM		
MS21087L6W	MT13C624PM		
MS21087-08	MT13C832		
MS21087-3	MT13C1032		
MS21087-4	MT13C428		
MS21087-5	MT13C524		
MS21087-6	MT13C624		
MS21087-08K	MT13C832BC		
MS21087-3K	MT13C1032BC		
MS21087-4K	MT13C428BC		
MS21087-5K	MT13C524BC		
MS21087-08W	MT13C832P		
MS21087-3W	MT13C1032P		
MS21087-4N	MT13C428P		
MS21087-5H	MT13C524P		
MS21087-6W	MT13C624P		

Note: 1. Manufacturing process: Machined
2. Lubrication: Ferrocote #348

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21087L08	RMLHTA575M2860-82	NAEC-AML-2429	ESNA
MS21087L3	RMLHTA575M2860-02	of 15 Mar 1966*	Divison of Harvard Industries
MS21087L4	RMLHTA575M2860-048		
MS21087L5	RMLHTA575M2860-054	*MUST BE MANUFACTURED	
MS21087L6	RMLHTA575M2860-064	AFTER 10 MAY 1994	
MS21087L08K	RMLHTA575M2860-82BC	DISC-E-94130 LTR	
MS21087L3K	RMLHTA575M2860-02BC		
MS21087L4K	RMLHTA575M2860-048BC		
MS21087L5K	RMLHTA575M2860-054BC		
MS21087L08W	RMLHTA575M2860P-82		
MS21087L3W	RMLHTA575M2860P-02		
MS21087L4W	RMLHTA575M2860P-048		
MS21087L5W	RMLHTA575M2860P-054		
MS21087L6W	RMLHTA575M2860P-064		
MS21087-08	LHTA575M2860-82		
MS21087-3	LHTA575M2860-02		
MS21087-4	LHTA575M2860-048		
MS21087-5	LHTA575M2860-054		
MS21087-6	LHTA575M2860-064		
MS21087-08K	LHTA575M2860-82BC		
MS21087-3K	LHTA575M2860-02BC		
MS21087-4K	LHTA575M2860-048BC		
MS21087-5K	LHTA575M2860-054BC		
MS21087-08W	LHTA575M2860P-82		
MS21087-3W	LHTA575M2860P-02		
MS21087-4W	LHTA575M2860P-048		
MS21087-5W	LHTA575M2860P-054		
MS21087-6W	LHTA575M2860P-064		

MS21087-08	MK4031-08	Report No.	Kaynar Technologies, Inc.
MS21087-3	MK4031-3	NAEC-AML-2474	Kaynar Div.
MS21087-4	MK4031-4	of 15 Jun 1966	P.0. Box 3001
MS21087-5	MK4331-5		800 S. State College Blvd.
MS21087-08K	MK4031-08BC		Fullerton, CA 92634
MS21087-3K	MK4031-3BC		
MS21087-4K	MK4031-4BC		Plant: Same address
MS21087-5K	MK4331-5BC		
MS21087-08W	MK4031-08P		
MS21087-3W	MK4031-3P		
MS21087-4W	MK4031-4P		
MS21087-5W	MK4331-5P		
MS21087L08	MK4001-08		
MS21087L3	MK4001-3		
MS21087L4	MK4001-4		
MS21087L5	MK4301-5		
MS21087L08K	MK4001-08BC		
MS21087L3K	MK4001-3BC		
MS21087L4K	MK4001-4BC		
MS21087L5K	MK4301-5BC		
MS21087L08W	MK4001-08P		
MS21087L3W	MK4001-3P		
MS21087L4W	MK4001-4P		
MS21087L5W	MK4301-5P		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21087-08	R300C08	NADC ltr	Republic Fastener Mfg. Corp.
MS21087L08	R300C08M	305Q5095 of	1300 Rancho Conejo Blvd.
MS21087-08K	R300C08K	17 Jun 1976	Newbury Park, CA 91320
MS21087L08K	R300C08MK		
MS21087-08W	R300C08W		Plant: Same address
MS21087L08W	R300C08MW		
MS21087-3	R300C3		
MS21087L3	R300C3M		
MS21087-3K	R300C3K		
MS21087L3K	R300C3MK		
MS21087-3W	R300C3W		
MS21087L3W	R300C3MW		
MS21087-4	R300C4		
MS21087L4	R300C4M		
MS21087-4K	R300C4K		
MS21087L4K	R300C4MK		
MS21087-4W	R300C4W		
MS21087L4W	R300C4MW		

MS21087-08	M12740-82	AMD Report No.	SPS Technologies
MS21087-3	M12740-02	MA769328 of	2701 S. Harbor Blvd.
MS21087-4	M12740-048	22 Jan 1969	Santa Ana, CA 92702
MS21087-5	MA12740-054		
MS21087L08	M12740E-82		Plant: Same address
MS21087L3	M12740E-02		
MS21087L4	M12740E-048		
MS21087L5	M12740E-054		
MS21087-08K	M12740-82BC		
MS21087-3K	M12740-02BC		
MS21087-4K	M12740-048BC		
MS21087-5K	MA12740-054BC		
MS21087L08K	M12740E-82BC		
MS21087L3K	M12740E-02BC		
MS21087L4K	M12740E-048BC		
MS21087L5K	M12740E-054BC		

Note: 1. Manufacturing process: Stamped or forged
2. Molybdenum disulfide dry film lubricant as approved by NAMATCEN ltr XM-621-FTR:mlp J9 (1434)

MS21088 NUT, SELF-LOCKING, CHANNEL, FLOATING, LOW HEIGHT, CRES, 125 KSI Ftu, 250°F

Note: 1. MS21088 Canceled.
2. Use MS21065 for interchangeability.

MS21089 NUT, SELF-LOCKING, CHANNEL, 100 DEG CSK, FLOATING, LOW HEIGHT, CRES, 125 KSI Ftu, 250° F

Note: 1. MS21089 Canceled.
2. Use MS21068 for interchangeability.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21224 NUT, SELF-LOCKING, CASTELLATED, HEXAGON, COUNTERBORED, ASSEMBLED WASHER, 250° F, NONMETALLIC INSERT (FOR SELF-RETAINING BOLTS)

MS21224-3	NE8235-3	AMD Report No.	ESNA
MS21224-4	NE8235-4	MA669012 of	Division of Harvard Industries
MS21224-5	NE8235-5	5 Nov 1968 *	
MS21224-6	NE8235-6		
MS21224-7	NE8235-7		
MS21224-8	NE8235-8		
MS21224-9	NE8235-9	AMD Report No. MA772017 of 15 May 1972 *	
MS21224-10	NE8235-10	NADC Report No. 305Q81062 of 15 May 1981*	
MS21224-12	NE8235-12		
MS21224-16	NE8235-16		

Note: Manufacturing process: Machined

*MUST BE MANUFACTURED AFTER 10 MAY 1994 DISC-E-94130 LTR

MS21224-3	F12N7699-1032	AMD Report No.	Greer Stop Nut, Inc.
MS21224-4	F12N7699-428	MA669029 of	481 McNally Drive
MS21224-5	F12N7699-524	30 Apr 1969	Nashville, TN 37211
MS21224-6	F12N7699-624		
MS21224-7	F12N7699-720		Plant: Same address
MS21224-8	F12N7699-820		
MS21224-12	N7699-1216	NAWCAD Report No. 435Q8917 of 20 AUG 1997	Greer Stop Nut, Inc. 481 McNally Drive Nashville, TN 37211 Plant: Same address

MS21224-3	CR-5937	NADC Report	Simmonds Mecaero
MS21224-4	CR-5937	601Q8516 of	Fasteners, Inc.
MS21224-5	CR-5937	12 Nov 1985	1734 Sequoia Avenue
MS21224-6	CR-5937		Orange, CA 92668

Note: 1. Manufacturing process: Machined
2. Lubricant: (For Government Designation with "L") QPL-8937
3. Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

Plant:
Simmonds
Usine De Champaissant
72110 Saint-Cosme En Vairais
France

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21224-3	NE8235-3	DISC-E MEMORANDUM	SPS Technologies
MS21224-4	NE8235-4	JANUARY 4, 1996	Highland Avenue
MS21224-5	NE8235-5		Jenkintown, PA 19046
MS21224-6	NE8235-6		
MS21224-7	NE8235-7		Plant: Same address
MS21224-8	NE8235-8		
MS21224-9	NE8235-9		
MS21224-12	NE8235-12		
MS21224-16	NE8235-16		

Note: Manufacturing process: Machined

MS21224-10	NE8235-10	NAWCADWAR Report No. 435Q9604 of 12 Feb 1996	

Note: Manufacturing Process: for nut element, machined

MS21225 NUT, SELF-LOCKING, CASTELLATED, HEXAGON, 800 DEG F

MS21225-5	Z7764-5	NADC Report No. 305Q87077 of 21 Jun 1982*	ESNA Division of Harvard Indstries

---

MS21225-4	Z7764-4	NADC Report No. 601Q8408 of 26 Apr 1984*	

MS21225-6	Z7764-6	NAWC Report No. 601Q9214 of 28 Oct 92*	

Note: Manufacturing process: Machined

*MUST BE MANUFACTURED
AFTER 10 MAY 1994
DISC-E-94130 LTR

MS21225-4	75147-428	Report No.	SPS Technologies
MS21225-5	75147-524	305Q83106 of 12 Aug 1983	Highland Avenue Jenkintown, PA 19046
			Plant: Same address
MS21225-7	75147-720	NADC Report No. 601Q9312 of 7 June 1993	

Note: Manufactured process: Machined

MS21225-4	Z7764-4	Report No.	
MS21225-5	Z7764-5	435Q9505 of 31 Mar 1995	

MS21225-6	75147-624 Z7764-6	NAWCADWAR Report No. 435Q9611 of 18 Mar 1996	

Note: Manufactured process: Machined

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS21225-3	75147-1032 Z7764-3	NAWCADWAR Report No. 435Q9624 of 25 Jul 1996	

MS21245 NUT, SELF-LOCKING, HEXAGON THIN, 450 DEG F, 80 KSI Ftu

---

MS21245L10	MS21245L10	Report No. 601Q9212 of 31 Aug 92	Automatic Screw Machine Products Company P.O. Box 1608 Decatur, AL 35602 Plant: Same Address

Note: 1. Manufacturing Process: Forged
2. Lubricant: Everlube 620C per MIL-L-46010 Type I

MS21245-7 MS21245L7 MS21245-9 MS21245-10 MS21245L10	47FT-720UN 48FT-720UN 47FT-918 47FT-1018 48FT-1018	Report No. 305Q83107 of 1 Sep 1983	SPS Technologies Highland Avenue Jenkintown, PA 19046 Plant: Same address

Note: Manufacturing process: Machined

MS21245L8 MS21245L9 MS2124SL12 MS21245L14	48FT-820 48FT-918 48FT-1216 48FT-1414	Report No. 305Q81063 of 27 May 1981

MS21245-8 MS21245L20	47FT-820 48FT-2102	Report No. 305Q82073 of 18 Feb 1982

Note: Manufacturing process: Machined

MS21245L08 MS21245L9	28FH-832 38FH-918	Report No. 601Q9210 of 2 Sep 1992

Note: 1. Manufacturing process: Machined
2. Lubricant: Everlube 620C per MIL-L-46010 Type I

MS21245-12	47FT-1216	NAWCADWAR Report No. 435Q9619 of 17 Apr 1996

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

MS90415 NUT, SELF-LOCKING, STEEL, 160 KSI, 450 DEG F, 12 POINT, CAPTIVE WASHER

MS90415-3	LH8099-02	NAEC-AML-2459	ESNA
MS90415-4	LH8099-048	of 25 May 1966*	Division of Harvard Industries
MS90415-5	LH8099-054		
MS90415-6	LH8099-064	*MUST BE MANUFACTURED AFTER 10 MAY 1994 DISC-E-94130 LTR	

MS90415-6	68118-624 LH8099-064 435Q9610 of	NAWCADWAR Report No. Jenkintown, PA 19046 1 Mar 1996	SPS Technologies Highland Avenue Plant: Same address
MS90415-3	68118-1032 LH8099-02	NAWCADWAR Report No. 435Q9617 of 12 Apr 1996	
MS90415-5	68118-524 LH8099-054		

Notes: 1. Manufacturing Process: Forged for nut element
2. Lubricant: Everlube 620C per MIL-L-46010, Type I

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.