MIL-F-60320 (MU)
Amendment I
3 June 1968

MILITARY SPECIFICATION
FUZE, POINT DETONATING, M527B1
LOADING, ASSEMBLING AND PACKING

This amendment forms a part of Military Specification, MIL-F-60320(MU), dated 22 March 1965.

1. Para. 2.1, Standards sub. paragraph: delete "MIL-STD-350- Jolt Test for Use in Production of Fuzes".

2. Para 2.1, Standards sub. paragraph: delete "MIL-STD-351- Jumble Test for Use in Production of Fuzes".

3. Para 2.1, Standards sub. paragraph: include "MIL-STD-331 - Fuze and Fuze Components, Environmental and Performance Tests for".

4. Para. 3.3: delete para. 3.3 in its entirety and sub. "3.3 Jolt and Jumble.-The fuze assembly shall comply with the requirements specified in MIL-STD-331. The test shall be performed as specified in para. 4.3.2."

5. Para. 3.5: delete para. 3.5 in its entirety.

6. Para. 3.6: delete "3.6" and sub "3.5".

7. Include "3.6 Transportation-vibration.-The fuze assembly shall comply with the requirements specified in MIL-STD-331. The test shall be performed as specified in para. 4.3.5."

8. Para. 4.2.2.1, Major category: include "107 Guide pin bent or broken.....Visual 01007".

9. Para. 4.2.2.1, Minor 201: delete minor 201 in its entirety.

10. Para. 4.2.2.1, Minor category: delete "202, 203 and 204" and sub. "201, 202 and 203" respectively.

11. Para. 4.2.2.1, Minor 203: delete "3.6" and sub. "3.5".

12. Para. 4.2.2.2, Critical 1: delete Critical 1 in its entirety.

FSC 1390

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:28Z
Check the source to verify that this is the current version before use.

13. Para. 4.2.2.3, Major category: delete "AQL 0.40 percent" and sub. "AQL 0.65 percent".

14. Para. 4.2.2.3, Major category: include "103 Torque failure (head must withstand an assembly torque of 30-50 inch lbs.).....test 03015".

15. Para 4.2.2.3, Minor 205: delete "3.6" and sub. "3.5".

16. Para. 4.2.3.1.1, end of paragraph: include "Defects affecting only the operability of the fuze shall not be considered grounds for rejection of the lot."

17. Para. 4.2.3.1.2, end of paragraph: include "Defects affecting only the operability of the fuze shall not be considered grounds for rejection of the lot."

18. Para. 4.2.3.2.1.2: delete para. 4.2.3.2.1.2 in its entirety and sub. "4.2.3.2.1.2 After three consecutive lots have complied with the criteria of 4.2.3.2.1.1, a sample of 54 fuzes shall be selected from each lot for this test. If three or more fuzes fail to comply with the applicable functioning requirement or if a premature burst occurs, the lot shall be rejected. This test shall be performed as specified in 4.3.3."

19. Para. 4.2.3.5: delete para. 4.2.3.5 in its entirety.

20. Include "4.2.3.5 Positioning of firing pin (see dwg. 8800461) - Critical defect - Code No. 02004.-This test shall be performed 100%. Assemblies failing to comply with the requirement shall be classed defective and removed from the lot. The test shall be performed as specified in 4.3.1."

21. Include "4.2.3.6 Transportation-vibration - Safety deficiency - Critical defect - Code No. 03014 - Operability deficiency - Major defect - Code No. 03016.-This test shall be performed as specified in 4.3.5."

22. Include "4.2.3.6.1 Beginning with the first lot produced and continuing until three consecutive lots have complied with the requirements of para. 3.6, thirty fuze assemblies shall be selected from each lot for this test. If one or more assemblies fail to comply with the operability and/or safety requirement, the lot shall be rejected.

23. Include "4.2.3.6.2 After three consecutive lots have complied with the criteria of para. 4.2.3.6.1, ten fuze assemblies shall be selected from each lot for this test. If one or more assemblies fail to comply with the operability and/or safety requirements, the lot shall be rejected."

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:28Z
Check the source to verify that this is the current version before use.

24. Para. 4.3.1: delete para. 4.3.1 in its entirety and sub. "4.3.1 Positioning of firing pin.-After mounting the assembly in a suitable fixture, a power operated ram shall exert the specified load (50 + 5.0 lbs.) to the striker to seat the firing pin against the slider in the required position. The rate at which the load is applied shall not exceed 0.25 inch per second."

25. Para. 4.3.2: delete para. 4.3.2 in its entirety and sub. "4.3.2. Jolt and jumble.-The loaded fuze assembly shall be subjected to the jolt test in accordance with MIL-STD-331. After completion of the jolt test, the assembly shall not be disassembled but shall be subjected to the jumble test in accordance with MIL-STD-331. The fuze assembly shall be jumble tested in a jumble fixture in accordance with para. 4.2.4. Disassembly and examination to determine compliance with the requirements of para. 3.3 shall be accomplished after both the jolt and jumble tests have been accomplished. Examination for safety deficiencies shall include but not be limited to determining that the safety pin is not completely or partially ejected, that the set-back pin is not disengaged by the safety wire, the head assembly is not partially or completely disassembled from the body assembly, that the firing pin is not broken, that the head assembly is not armed, that the head assembly does not arm instantaneously and that the slider cavity and/or exterior surface of the fuze is free of explosive material (see 6.6).

26. Para. 4.3.3.2: delete "200" and sub. "150".

27. Para. 4.3.5: delete para. 4.3.5 in its entirety.

28. Include "4.3.5 Transportation-vibration.-The loaded fuze assembly shall be subjected to the transportation-vibration test in accordance with MIL-STD-331. Upon completion of the test, the fuze assembly shall be examined to determine compliance with the requirements of para. 3.6. Examination for safety deficiencies shall include but not be limited to determining compliance with the criteria specified in para. 4.3.2 and examination for operability deficiencies shall include but not be limited to determining that the head assembly striker is not immovable, that the firing pin is not bent, that the safety pin ejects freely and that the slider moves freely into the armed position (see 6.6)."

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:28Z
Check the source to verify that this is the current version before use.

29 Include "6.6 Categorizing of defects.-Since the contained list of defects is not comprehensive and is intended to be a guide, it is not to be construed that examination is to be limited to the aforementioned list."

Custodian:
Army-MU

Preparing activity:
Army-MU

Project Number: 1390-A-644

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:28Z
Check the source to verify that this is the current version before use.