INCH-POUND

MIL-P-70819 (AR)
AMENDMENT 1
12 June 1995

MILITARY SPECIFICATION

PRIMER, ELECTRIC, M128
LOADING, ASSEMBLING AND PACKING

This amendment forms a part of Military Specification MIL-P-70819 (AR), dated 28 February 1991, and is approved for use by the U.S. Army Armament Research, Development and Engineering Center and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

2.1.1 SPECIFICATIONS MILITARY, add:

"MIL-A-70625 - Automated Acceptance Inspection Equipment Design, Testing and Approval, of."

PAGE 3

3.6: Delete in its entirety and substitute:

"3.6 Torque.

3.6.1 Head loading assembly. The Retainer and Closing Plug Loading Assembly shall comply with drawing torque requirements. (See 4.8.4.1).

3.6.2 Primer loading assembly. The Primer Head/Body threaded joint shall comply with drawing torque requirements. (See 4.8.4.2.)"

PAGE 13

4.6.2.5: Delete in its entirety and substitute new paragraph 4.6.2.5.



DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T04:03Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF CHARACTERISTICS



| PARAGRAPH | TITLE | SHEET | DRAWING NUMBER |
|---|---|---|---|
| 4.6.2.5 | Head Loading Assembly | 1 OF 1 | 9327345 |
| | | | NEXT HIGHER ASSEMBLY: 12910250 |

| CLASSIFICATION | EXAMINATION OR TEST | CONFORMANCE CRITERIA | REQUIREMENT PARAGRAPH | INSPECTION METHOD REFERENCE |
|---|---|---|---|---|
| Critical | | | | |
| 1 | Non-functioning test | 4.7.4 | 3.8.2 | 4.8.6 |
| Major | | | | |
| 101 | Closing disk missing or damaged exposing explosive | Table II | 3.2 | Visual or gage |
| 102 | Retainer torque failure | Table II | 3.6.1 | 4.8.4.1 |
| 103 | Retainer lacquer or stake missing 1/ | Table II | 3.2 | Visual |
| 104 | Functioning test | 4.7.3 | 3.8.1 | 4.8.5 |
| 105 | Electrical resistance test | 100% | 3.7 | 4.8.3 |
| 106 | Depth to electrode | Table II | 3.2 | Gage |
| 107 | Flash hole obstructed | Table II | 3.2 | Gage or Visual |
| 108 | Closing plug torque failure 1/ | Table II | 3.6.1 | 4.8.4.1 |
| 109 | Lacquer missing from closing plug threads | Table II | 3.2 | Visual |
| Minor | | | | |
| 201 | Workmanship | Table II | 3.12 | Visual |

NOTES: Inspections requiring access to inner components and inspections conducted by automatic assembly machine may be performed before completion of entire Head Loading Assembly.

1/ For automatic machine assembly, disassemble 1 unit/hr. and visually inspect. Absence of lacquer/stake or inadequate lacquer application will cause rejection of all production since last acceptable sample was inspected.



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T04:03Z
Check the source to verify that this is the current version before use.

PAGE 16

4.6.2.8, Category 107: Delete "4.8.4" and substitute "4.8.4.2".

PAGE 25

4.8.4: Delete in its entirety and substitute:

"4.8.4 Torque testing.

4.8.4.1 Head loading assembly. Torque shall be verified by either performing torque inspections of assembled components or by periodic verification of the torque machine. When torque is verified by inspection of assembled components, torque tests shall be performed by reapplication of torque, while the lacquer is still wet (within 5 minutes of application), and with the part suitably marked and held for detection of movement between adjacent parts. Any discernible movement between adjacent parts is a torque test failure. When torque application is confirmed by monitoring the torque machine, a periodic verification of machine output values is required. Detailed requirements of the verification technique shall be in accordance with MIL-A-70625A and 6.4. Failure to meet the requirement will cause rejection of all production since the last successful verification.

4.8.4.2 Primer loading assembly. After a 2 hour minimum curing of sealant, the torque shall be applied in the loosening direction, while holding the head. The joint under test shall be marked to provide a means of detecting any movement between adjacent parts. Any discernible movement between adjacent parts shall be regarded as a torque test failure."

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1315-0086)



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T04:03Z
Check the source to verify that this is the current version before use.