MILITARY SPECIFICATION

PONTON FLOAT: PNEUMATIC, THREE-TUBE HALF FLOAT,

12-TON CAPACITY

This interim amendment is approved for use within the US Army Belvoir Research, Development, and Engineering Center, Department of the Army, with MIL-P-11386G, dated 12 Februrary 1985.

PAGE 6

3.10, delete in its entirety and substitute the following:

"3.10 Repairs. The first article ponton half float shall not contain any repair patches. No individual tube component of any production ponton half float may contain more than five patches. Patched tubes shall not exceed 7 percent of the total number of tubes submitted for acceptance at any one time. No patch shall be less than six inches in diameter nor more than 64 square inches in area. The edges of any repair patch shall extend not less than three inches beyond the extremity of the defect. Patching of seams is not allowed. Patching of bulkheads is not allowed. Likewise, no patch shall extend over a seamed area nor cover another patch, nor shall any two patches overlap or intersect. Patches shall be prepared from coated cloth conforming to MIL-C-14505, class 7, applied with adhesive specified in 3.3.6 and vulcanized with the local application of heat and pressure. Gum strips specified in 3.3.4 shall be used on the periphery of all repair patches. Any applied patches shall not adversely affect the strength of serviceability of the ponton half float. Injury or damage that exposes the base fabric (nylon) of the ponton half float's air chamber cloth shall be repaired with patch materials as specified and limited herein. Exposed base fabric of non-air-retaining, ponton-coated fabric shall be repaired with gum sheeting, cemented and cured by applying local heat and pressure. Nonadhering surfaces of cemented material shall be repaired by recementing and curing by applying local heat and pressure, except that in cases of minor edge looseness (maximum distance of 1/4 inch from edge) on non-air-retention material (i.e., gumstrips, tape splices), repairs may be made by recementing with appropriate air-curing cement, or by removing loose edge section with a razor and recementing (with appropriate air-curing cement) a gum strip over the removed section (the gum strip shall be applied in line with the original gum strip). Gum strip over gum strip repair shall be limited to no more than five such repairs per tube with each repair being limited to no more than four inches in length excluding overlap. A minimum of one-inch overlap is required on each of gum strip repair."

AMSC N/A FSC 5420

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T15:59Z
Check the source to verify that this is the current version before use.

3.11, delete in its entirety and substitute the following:

"3.11 Workmanship. Workmanship shall be the highest quality and the fabricated and assembled ponton half float, complete with all specified bonded and attached components, shall be free from defects (as defined in MIL-C-14505) adversely affecting the strength or serviceability of the finished ponton half float. Surfaces to be cemented shall be wiped clean with a cleaning solvent before applying cement; the surfaces shall be free from grease, grit, dirt, oil, excess material used in fabrication, and any other foreign materials that could harmfully affect the application of the cement and the bonding of cemented surfaces. The halter assembly shall be free of defects that could impair servicability. Such workmanship shall be indicative of the provisions of 3.4, 3.5, 3.6, and 3.7. Servicability is defined as the ability of the ponton to carry out its operational role. The pontons mission, is to be joined together (stern-to-stern) to form a complete float 9 feet wide, 44 feet long, and 3 feet high capable of supporting hollow aluminum sections to make up the M4T6 floating bridge, raft, or ferry. The ponton must retain air and have the necessary attachment laces and points for multiple unit assembly to be considered serviceable."

PAGE 9

4.5.1, delete defect 122 and add the following:

"122. Repair patches not as specified.
123. More than five patches on any production tube unit.
124. Patched tube units comprise more than 20 percent of total tubes (as three tube ponton half floats) scheduled for delivery.
125. Workmanship not as specified."

PAGE 10

4.5.2.3.1, line 4, after "2.5 psi.", add, "After an additional hour, readjust the pressure (if needed) to 2.5 psi".

Custodians:
Army - ME
Navy - MC

Preparing activity:
Army - ME

Project 5420-A364

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T15:59Z
Check the source to verify that this is the current version before use.