MIL-R-55504(EL)
Amendment 2
12 February 1970
Superseding
Amendment 1
19 September 1967

MILITARY SPECIFICATION

RECEIVER, RADIO R-1041B/ARN

This Amendment forms a part of MIL-R-55504(EL), 25 January 1967.

1. Add the following to paragraph 2, Applicable Documents; Under STANDARDS, MILITARY: "MIL-STD-461A, Electromagnetic Interference Characteristics Requirements for Equipment" and "MIL-STD-781B, Reliability Test Exponential Distribution."

2. Paragraph 3.2 change "SC-DL-425200-E" to "SC-DL-425200-G."

3. Between paragraph 4, Quality Assurance Provisions and paragraph 4.1, Responsibility for Inspection, insert the following:

"Note:

"(1) Combined Burn-In/Reliability of each equipment on order shall be tested in accordance with drawing SC-A-678006."

4. Paragraphs 3.9.1.2 Sensitivity: 4.6.14, Sensitivity Range Tests: 4.7.1, Temperature: reference to low and high sensitivity controls are sufficient for adjusting the tolerances without referring to the resistor numbers "R"$_{21}$ and "R"$_{59}$.

5. Paragraph 3.9.4 Automatic Gain Control: In first sentence, change "100,000 microvolts" to read "from 1,000 to 100,000 microvolts."

6. Paragraph 3.9.6 Differential: In last sentence, change "the lamp flickers at light-on-point, as RF increase of 3 db" to read "the lamp flickers at light-on-point, an RF voltage increase of 3 db."

7. Paragraph 3.9.7 Power Source and Power Consumption: In the last sentence, change "the received" to read "the receiver."

8. Paragraph 3.9.8 Power Source Voltage Variation: Change "42 to 32 volts" to read "24 volts to 32 volts."

9. Paragraph 3.9.12 Sensitivity: In the second sentence, change "sensitivity of 300 microvolts ± 1 db" to read "sensitivity of 3,000 microvolts ± 1 db."

10. Paragraph 3.9.16 Volume Attenuation: Change "0 db to 21 ± 30 db" to read "0 db to 21 ± 3.0 db."

11. Table II Group A Inspection: For paragraph 3.9.8 and 4.6.10, change "sourve" to read "source."

FSC 5326

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T23:26Z
Check the source to verify that this is the current version before use.

12. Add the following paragraph "3.12 Specified MTBF: The Specified MTBF (Mean Time Between Failure) shall be 200 hours."

13. Paragraph 3.9.15 Spurious response, on the eighth line down, after last sentence add: "In performing spurious tests lowpass filter units shall be used between the RF Signal Generator Output and the R-1041B/ARN input in conformance with MIL-STD-461A, 31 July 1967 which reiterates paragraph 4.3.4.5 of Specification MIL-D-6181D. These filters shall at least attenuate the 75 MHz HP 608D Signal Generator signal beyond the 40 db capacity of the generator with cutoff at 49 MHz (See Figure 2)."

14. Paragraph 4.6.10 Power Source Variation Test: Change last sentence "The requirements of 3.9.5 shall be met" to read "The requirements of 3.9.8 shall be met."

15. Use the Block Diagram, Figure 2, attached . instead of Figure 2 of MIL-R-55504(EL).

CUSTODIAN:


Army - EL

PREPARING ACTIVITY

Army - EL

Project No.5826-A071

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T23:26Z
Check the source to verify that this is the current version before use.



BLOCK DIAGRAM
TEST SET-UP FOR R-1041B /ARN

FIGURE 2

Source: https://assist.dla.mil -- Downloaded: 202610-22T23:26Z
Check the source to verify that this is the current version before use.