MILITARY SPECIFICATION

FUZE, ROCKET: M439
PARTS AND ASSEMBLY WITH DETONATOR

This Amendment forms a part of Military Specification MIL-F-48877 (AR), dated 17 September 1982, and is approved for use by the U.S. Army Armament, Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 5

* 3.14.4.3, Delete "+160° ± 5°F" and substitute "+150° ± 5°F".

3.15.1: Delete in its entirety.

PAGE 6

3.17: Delete in its entirety.

3.18: Delete the first sentence and substitute "The safe position of S&A's shall be verified just prior to issuance for fuze final assembly; limited to a maximum of half-a-day's production."

PAGE 7

3.22: Delete "- Non-Arm and Arming Times only".

* 3.23.3, Delete "+160° ± 5°F" and substitute "+150° ± 5°F"

3.26: Add immediately after "Ballistic firing.": "The fuze shall perform properly following temperature conditioning for a minimum of 8 hours after stabilization at: -50° ± 5°F, 70° ± 15°F (ambient) and +150° ± 5°F."

PAGE 8

3.28.1: Add "All required markings shall be neat and legible."

FSC 1340

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:43Z
Check the source to verify that this is the current version before use.

PAGE 10

4.3.1: Under "Quantity" delete "810" and substitute "486".

PAGE 12

TABLE II: For "Rotor Housing" delete "4.4.2.16" and substitute "4.4.2.6".

PAGE 18

TABLE II: Delete "Module Turn on Time" in its entirety, 2 places.

Under "No. of Sample Units" delete "810" and substitute "486".

PAGE 19

TABLE II, Electronics Housing Assembly: Delete "Corrosion Resistance of Protective Coating 25 3.4" and "Umbilical Assembly Pull Test 25 3.4".

PAGE 27

4.4.2.6, Category 103: Delete "positin" and substitute "position".

PAGE 30

4.4.2.9, Delete "Angle of bend (83° + 2°)" and substitute "Angle of bend (83° - 87°)".

Delete "Angle of bend (65° + 2°)" and substitute "Angle of bend (62° - 67°)".

PAGE 31

4.4.2.10, Category 102: Delete "90°" and substitute "89° + 3°".

PAGE 33

4.4.2.12, Category 102: Delete "positin" and substitute "position".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:43Z
Check the source to verify that this is the current version before use.

PAGE 34

4.4.2.13, Category 104: Delete "90°" and substitute "89° + 3°".

PAGE 35

4.4.2.14, Category 109: Delete in its entirety.
Category 201: Delete "places".

PAGE 36

4.4.2.15, Category 105: Delete "eyelet holes, 5 places" and substitute "dimples, 6 places".

PAGE 43

4.4.2.22, Category 102: Delete in its entirety.

PAGE 45

4.4.2.24, Categories 105 and 106: Delete "(a)" and substitute "a,b".

Add Note (b):

"(b) Special Inspection Level S-4 of MIL-STD-105D".

PAGE 50

4.4.2.27, Category 109: Add "or less than two speed clip retaining detonator".

PAGE 51

4.4.2.25: Delete "4.4.2.25" and substitute, "4.4.2.27".

Add Major Category 116:

"116. Eyelets too close to surface of bottom plate assembly, 2 places 0.40% 3.4 Gage".

PAGE 52

4.4.2.28, Category 201: Delete "3.28" and substitute "3.28/3.4".

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:43Z
Check the source to verify that this is the current version before use.

PAGE 55

4.4.2.31, Categories 105, 108, 112, and 113: Delete in their entirety.

Category 110: Delete "8 seconds" and substitute "10 seconds".

Category 111: Delete "12 seconds" and substitute "24 seconds".

PAGE 56

4.4.2.31, Delete Category 204 in its entirety and substitute: "Excessive molding defects or a component or substrate is exposed to 0.65% 3.4 visual standards".

PAGE 57

4.4.2.32, Category 103: Delete "Termination radius of switch assy, connector pin" and "visual" and substitute "Interface tip flat over max." and "gage", respectively.

PAGE 58

4.4.2.33, Category 103: Delete "Radius termination of interface" and substitute "Interface tip flat over max".

Category 104: Delete "4.5.2" and substitute "gage".

PAGE 59

4.4.2.34, Categories 102, 103, 106, and 107: Add "(a)" to "EXAMINATION".

Add Major Categories 108, 109, and 110:

"108	True position of blind hole	0.40%	3.4	Gage"
"109	Diameter of blind hole	0.40%	3.4	Gage"
"110	Depth of blind hole, min	0.40%	3.4	Gage"

Minor 201: Delete "3.28" and substitute "3.28/3.4".

Add Note (a):

"(a) If pins are molded into housing, categories 106 and 107 do not apply; categories 102 and 103 refer to pins instead of pin holes."

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:43Z
Check the source to verify that this is the current version before use.

PAGE 60

4.4.2.35, Categories 102 and 103: Delete in their entirety.

PAGE 61

4.4.2.36, Critical 1: Delete "3.17" and substitute "3.18".

PAGE 63

4.4.4.1.2b: Delete "4.5.17".

PAGE 64

4.4.4.2: Delete "Paragraph 4.5.17 - Module Turn On Time".

PAGE 66

4.5.6.1: Delete "Apply an" and substitute "Apply the required".

PAGE 67

4.5.6.2, 4.5.6.3, 4.5.6.4, and 4.5.6.5: Delete "Apply an" and substitute "Apply the required".

4.5.6.6: Add "and removed from the Lot."

4.5.6.7: Delete "outside face of the annular gear" and substitute "end of the stud".

PAGE 70

4.5.1.5: Delete "4.5.1.5" and substitute "4.5.15".

* 4.5.14, Delete "+160° ± 5°F" and substitute "+150° ± 5°F".

4.5.17: Delete in its entirety.

4.5.18: Delete "four seconds" and substitute "seven seconds".

PAGE 72

4.5.23: Delete "the nominal 24 second time before" and substitute "20.275 seconds prior to".

Source: https://assist.dla.mil -- Downloaded: 202640-22T19:43Z
Check the source to verify that this is the current version before use.

PAGE 74

4.5.29: Delete paragraph under Table IV in its entirety.

PAGE 75

4.5.33: Delete in its entirety and substitute:

"4.5.33 Test equipment failure. If the test equipment fails to produce an arming readout (i.e., recording paper skewes, audio pick-up, or amplifier inoperative) during the arming time test as verified by the Government, the Safety and Arming Device shall be visually inspected for arming; if found to be armed or partially armed, score as a "no test" and replace with a spare fuze. The timing record produced by the fuze on the approved fuze timing equipment shall be considered the timing record of the fuze under the applicable defect classification."

PAGE 79

6.3.1: Delete "ARRADCOM, ATTN: DRDAR-QAF-T" and substitute "Armament Research and Development Center, US Army Armament, Munitions and Chemical Command, ATTN: AMSMC-QAF-T(D)".

6.5: Delete "ARRADCOM, ATTN: DRDAR-QAF-I" and substitute "Armament Research and Development Center, US Army Armament, Munitions and Chemical Command, ATTN: AMSMC-QAF-I(D)".

PAGE 81

* TABLE V: Delete in its entirety and substitute new Page 81 (attached).

PAGE 82

* TABLE VI: Delete in its entirety and substitute new Page 82 (attached).


PAGE 83

TABLE VI, Paragraph 3: Delete in its entirety.

PAGE 84

* TABLE VII: Delete in its entirety and substitute new Page 84 (attached).

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:43Z
Check the source to verify that this is the current version before use.



*8 from T&H, 16 from HV, 8 from NE.

**4 from T&H, 16 from Hel-Vibr, 20 from Non-Envir.

*** Includes 16 spares from Hel-Vibr to replace launches scored as "No Tests".

NOTE: A setter that represents the helicopter setter system shall be used for delay time acceptance tests in all cases.

TABLE V First article test

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:43Z
Check the source to verify that this is the current version before use.


1. All modules shall be serialized.

2. A setter that represents the helicopter setter system shall be used for acceptance of all modules.

Nominal time settings	Environment	Module quantity	Acceptance limits (Sec)
2 Sec.	-50°F +70°F +150°F Thermal Shock	50 50 50 12	1.96 to 2.04
10 Sec.	-50°F +70°F +150°F Thermal Shock	50 50 50 12	9.80 to 10.20
THIS	SPACE	INTENTIONALLY	LEFT BLANK
THIS	SPACE	INTENTIONALLY	LEFT BLANK
24 Sec.	-50°F +70°F +150°F Thermal Shock	50 50 50 12	23.52 to 24.48

TABLE VI. Module time delay test.

Source: https://assist.dla.mil -- Downloaded: 20261O-22T19:43Z
Check the source to verify that this is the current version before use.



*20 from HV, 12 from NE
**12 from Hel-Vibr, 8 from Non-Envir.
***16 from Hel-Vibr, 8 from Non-Envir.
****Includes 5 spares from Hel-Vibr to replace launches scored as "No Tests"
NOTE: A setter that represents the helicopter setter system shall be used for delay time acceptance in all cases.

TABLE VII Fuze lot acceptance test

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:43Z
Check the source to verify that this is the current version before use.

*The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1340-A693)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:43Z
Check the source to verify that this is the current version before use.