INCH-POUND

MIL-C-70544A (AR)
AMENDMENT 4
24 February 1993
SUPERSEDING
AMENDMENT 3
15 March 1991

MILITARY SPECIFICATION

CARTRIDGE, 81MM, ILLUMINATING, M853A1,
LOADING, ASSEMBLING AND PACKING

This amendment forms a part of MIL-P-70544A (AR), dated 28 January 1988, and is approved for use by the U.S. Army Armament, Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 2

* 2.2, Change this paragraph to "2.1.2".

Under Inspection Equipment Drawings, add the following:

"6518071 - Alignment Gage
6518072 - Alignment Check Gage

PAGE 3

3.4, Change "60" to "65" and change "550,000" to "525,000".

3.4.1, Delete in its entirety and substitute the following:

"3.4.1 Pull test for oval sleeve crimp to suspension wire. The oval sleeve crimp to the suspension wire shall withstand a pull force of 1800 pounds minimum."

PAGE 7

4.4.1.d, Delete in its entirety and substitute the following:

"4.4.1.d Propelling charges, of one lot interfix number, from one manufacturer."

AMSC N/A

FSC 1315

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:39Z
Check the source to verify that this is the current version before use.

PAGE 11

4.4.2.4, Under Major 105, delete in its entirety and substitute the following:

"Taped shroud loops not attached to suspension wire loop ...0.40% ...3.2 ...Visual."

Under Major category, add the new following:

"106 Tape missing from the sleeve and cable ...0.40% ...3.2 ...Visual."

PAGE 12

* 4.4.2.5, Change Major 107,

From: "Obturator ring not flush or below, Note 1 ...100% ...3.2 ...Visual"

To: "Entire obturator including tack weld not flush or below bourrelet diameter, Note 1 and 3 ...100% ...3.2 ...Gage"

* Add new Major 112 as follows:

"112 Tail cone improperly assembled to the body tube assembly ... Note 4 ...3.2 ...4.4.5.11/Visual"

* Add Note 3 and 4 as follows:

"Note 3. The inspection shall be performed at two places for each obturator, one at the tackweld and the other at 180 degrees from the tackweld.

* Note 4. If a total of two or more defective units are found, the lot shall be rejected."

PAGE 16

4.4.2.8, Under Major category add the following:

"104 Increment tape missing ...0.40% ...3.2 ...Visual
105 Propelling charge support missing or damaged ...0.40% ...3.2 ...Visual.
106 Tab at the end of increment tape inadequate ...0.40% ...3.2 ...Visual.
107 Tab at the end of increment tape covered by propellant charge support label ...0.40% ...3.2 ...Visual."

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:39Z
Check the source to verify that this is the current version before use.

PAGE 18

4.4.2.10, Change existing "Minor 202" to "Minor 204".

Add new following Minor 202, 203, 205 and 206 as follows:

"202 Plastic sheet not present in every sixth box ...0.65% ...3.2 ...Visual
203 Box containing plastic sheet not appropriately marked ...0.65% ...3.2 ...Visual
205 Circular firing scale not present in every third box ...0.65% ...3.2 ...Visual
206 Box containing circular firing scale not appropriately marked ...0.65% ...3.2 ...Visual"

PAGE 20

4.4.3.2, Change "60" to "65" and change "550,000" to "525,000".

PAGE 22

* 4.4.3.3, Change "Major: Illuminant fails to ignite or provide effective illumination for less than 50 seconds (see Note 2)." to "Major: Illuminant fails to ignite or provide effective illumination for less than 50 seconds in the air (See Note 2 & 3)"

* Note 2, Delete in its entirety and substitute the following:

"If the height above ground level at which the tail cone separated from the tube body was less than 300 meters, the performance of the cartridge will not be considered in evaluating the acceptability of the lot for illumination time defects."

* Add Note 3, as follows:

"Note 3: The following are considered some causes of this defect:

a. Streaming chute/ripped chute.
b. Partial or fully tangled chute.
c. Chute fails to deploy.
d. Illuminant detached from canister (illuminant dropout).
e. Parachute detached from canister.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:39Z
Check the source to verify that this is the current version before use.

PAGE 23

4.4.3.5, Change "8865018" to "9209555-8".

Delete "4.4.3.5.1 and 4.4.3.5.2" and substitute "4.4.5.10"

4.4.3.5.1, Change "1050" to "1800".

At the last sentence, delete "until it is requalified in accordance with paragraph 4.4.3.5.2."

4.4.3.5.2, Delete in its entirety.

PAGE 26

4.4.5.6, Delete the word "primers" from the fifth line. Add "and chamber pressure" after muzzle velocity in the last sentence before Table III.

PAGE 27

* 4.4.5.11, Add new paragraph as follows:

"4.4.5.11 Tail cone and body tube inspection. At the end of each assembly lot produced, fifty random samples shall be selected for this inspection. The projectile loading assemblies shall be subjected to a pull load sufficient to shear the pins; slowly remove the body tube assembly from the tail cone and once the canister is visible, hold the canister down to prevent movement from the tail cone while removing the body tube. Inspect the pull cord for the following: Pull cord should be coiled about one half of the length and inserted into a 3/4" loop attaching the pull cord to the parachute bag and the other one half should be between the parachute disc and the droque plate. If the pull cord does not meet the above or is tangled or pinched, the sample shall be classed as defective. In addition, if the cable is frayed, kinked or deformed, the sample shall be classed as defective.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:39Z
Check the source to verify that this is the current version before use.

NOTE: The margins of this amendment are marked with an asterisk or vertical line to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1315-AE75)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:39Z
Check the source to verify that this is the current version before use.