INCH-POUND

MIL-P-50578D (AR)
AMENDMENT 4
24 February 1993
SUPERSEDING
AMENDMENT 3
3 October 1986

MILITARY SPECIFICATION

PROJECTILE, 155MM, HE, RA, M549 AND M549A1
(WITH WARHEAD AND MOTOR BODY)
LOADING, ASSEMBLING AND PACKING

This amendment forms a part of Military Specification MIL-P-50578D (AR), dated 1 May 1985, and is approved for use by the US Army Armament, Munitions, and Chemical Command, and is available for use by all Department and Agencies of the Department of Defense.

PAGE 5

3.6.1.1 Add the following:

"The rocket motor shall ignite not earlier than four seconds after firing. Lots with early motor ignitions, which pass all other proving ground test requirements, shall be referred to the technical agency for disposition."

PAGE 6

3.6.1.2.2 Add the following: "unless the rocket motor fails to ignite".

3.6.2 Delete in its entirety and substitute the following:

"3.6.2 Safety. There shall be no premature burst or indication of metal parts separation in the gun bore, or in flight, when fired at any of the conditions specified in 4.5.3. In addition, no projectile fired in the safety phase shall have a horizontal range less than 97.5 percent of the mean unless the rocket motor fails to ignite."

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:29Z
Check the source to verify that this is the current version before use.

PAGE 12

* 4.4.2.2, Minor 203:

Delete: "Anti-seize compound not 360 degrees around liner"

Substitute: "Silicone compound not 360 degrees around liner"

PAGE 25

4.4.2.13: Delete Major Defect 204.

PAGE 29

4.4.3.4 Delete in its entirety and substitute the following:

"4.4.3.4 Proving ground. These tests shall be performed as specified in 4.5.3. Defects shall be classified as follows:

Critical	
1	Premature burst or metal parts separation
Special	
a	Range less than 97.5 percent of mean horizontal range unless rocket motor fails to ignite (see 6.16)
Major	
101	Range probable error exceeds allowable limit (see 3.6.1.2.1)
102	Rocket motor fails to ignite
Minor	None defined"

PAGE 30

4.4.3.4.2.2 Change "15" in the first sentence to "14".

PAGE 35

4.5.3.2 Delete in its entirety and substitute the following:

Source: https://assist.dla.mil -- Downloaded: 202610-22T20:29Z
Check the source to verify that this is the current version before use.

"4.5.3.2 Safety. The projectiles for this test shall be divided into three groups. Group 1, consisting of five projectiles, shall be conditioned and fired at -65 degrees F with Charge 8, M203 series propelling charges conditioned at -65 degrees F. Group 2, consisting of four projectiles, shall be conditioned and fired at 145 degrees F. Group 3, consisting of five projectiles, shall be conditioned at 145 degrees F and fired with PXR-6297 proof propelling charges conditioned at 145 degrees F. The cold phase (Group 1) shall be fired at a quadrant elevation of 51 degrees, and the hot phases (Groups 2 and 3) may be fired at a quadrant elevation of 53 degrees."

PAGE 36

* 6.3 Line 4.

Delete: "ATTN: AMSMC-QAR-I(D), Dover New Jersey 07801-5001".

Substitute: "ATTN: SMCAR-QAR-I, Picatinny Arsenal, New Jersey 07806-5000".

PAGE 37

6.7 Under safety phase, change "15" to "14".

* 6.8 Line 5 and 6:

Delete: "Dover, New Jersey 07801-5001, ATTN: AMSMC-QAR-Q(D) and SMCAR-LCU-SA(D)."

Substitute: Picatinny Arsenal New Jersey 07806-5000, ATTN: SMCAR-QAR-Q and SMCAR-FSA-MS."

PAGE 38

Add the following paragraph:

"6.16 Short range. Projectiles failing to achieve required range with proper motor function shall be considered critical defects. Projectiles failing to achieve required range due to improper motor ignition delay or motor burn shall be considered as major defects."

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:29Z
Check the source to verify that this is the current version before use.

The margin of this amendment are marked with an asterisk to indicate where changes (additions, modifications, corrections, or deletions) from the previous amendment were made. This was done as a convenience only, and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army - AR

Preparing activity:
Army - AR

(Project 1320-AC05)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:29Z
Check the source to verify that this is the current version before use.