MIL-C-25601C(USAF)
AMENDMENT 2
26 January 1971

Superseding
Amendment 1
9 January 1970

MILITARY SPECIFICATION

COUPLER, ANTENNA
CU-308D/U

This amendment forms a part of Military Specification
MIL-C-25601C(USAF), dated 16 October 1970

Page 1, paragraph 2.1 Military Specifications: Delete "MIL-C-3608".

Page 2, paragraph 2.1, under Military Standards: Add "MIL-STD-704 Electric Power, Aircraft, Characteristics and Utilization of".

Page 3, paragraph 3.3.1.1a: Add "ohm" after 100K.

Page 3, paragraph 3.3.5, line 3: Delete "or MIL-C-3608".

Page 5, paragraph 3.5.2: Delete "cycle" after 1000 and substitute "hertz".

Page 5, paragraph 3.5.5: Add "ohm" after 120K.

Page 6, paragraph 3.5.9.1: Delete "MV" after 50 and substitute "mv".

Page 6, paragraph 3.5.9.2: Delete "MV" after 100 and substitute "mv". Delete "UV" after ten and substitute "microvolts".

Page 6, paragraph 3.5.9.3: Delete "MV" after 200 and substitute "mv".

Page 6, paragraph 3.5.10.1: Delete "UV" after two and substitute "microvolts". Delete "V" after one and substitute "Volt". Delete "cycle" after 1000 and substitute "hertz".

Page 6, paragraph 3.5.10.2: Delete "cycle" after 1000 and substitute "hertz".

Page 8, paragraph 4.3e: Add "volts" after 27.5.

FSC 5826

Source: https://assist.dla.mil -- Downloaded: 2026-10-20T06:47Z
Check the source to verify that this is the current version before use.

Page 12, add following paragraph after paragraph 4.6.2.2:

"4.6.2.3 Power Source Transient Response.- The coupler shall be tested in accordance with MIL-STD-704 and in addition must accept spikes of plus 120 VDC for 0.001 second duration as shown in figure 9 and minus 400 VDC for 0.001 second duration as shown in figure 10. Each of the five transients in the figures shall be repeated at least three times. The intervals between transients shall not be less than 30 seconds. Tolerances shall be ±2% on voltages and ±10% in time intervals".

Page 13, paragraph 6.1: Delete "simplify" and substitute "amplify".

Page 21, figure 7, front view: Delete "6.00 inches" as coupler face width and substitute "5.25 inches".


Add figures 8, 9 and 10 between pages 21 and 22.

FSC to basic document dated 10 April 1962 should be changed to FSC 5826.

Custodian:
Air Force 84

Preparing Activity:
Air Force 84

Source: https://assist.dla.mil -- Downloaded: 2026-10-20T06:47Z
Check the source to verify that this is the current version before use.



NOTES:
DIMENSIONS IN INCHES. UNLESS OTHERWISE SPECIFIED TOLERANCES ARE ±.031

FIGURE 8 Antenna coupler CU-308 D/U

Source: https://assist.dla.mil -- Downloaded: 2026-10-20T06:47Z
Check the source to verify that this is the current version before use.




FIGURE 9 Overvoltage transient tests




FIGURE 10 Undervoltage transient tests

Source: https://assist.dla.mil -- Downloaded: 2026-10-20T06:47Z
Check the source to verify that this is the current version before use.