MIL-P-48762 (PA)
AMENDMENT 1
7 February 1977

MILITARY SPECIFICATION

PROJECTILE, 155MM, HE, ROCKET ASSISTED, M549, INERT, SIMULATED PARTS AND LOADING

This amendment forms a part of Military Specification MIL-P-48762, dated 25 April 1975, and is approved for use by all Departments and Agencies of the Department of Defense.

Change the title by adding the following:

"FOR METAL PARTS AND PROPELLANT ACCEPTANCE TESTING ONLY"

Paragraph 1.1, Delete this paragraph in its entirety and substitute the following:

"1.1 This specification covers the fabrication of the inert parts and the complete inert round loading and assembly of Projectile, M549 for Metal Parts and Propellant Acceptance Testing Only".

Paragraph 2.1, Delete the following under Army, Drawings:

"9298010 Grain, Forward, Inert
9298011 Grain, Aft, Inert"

Paragraph 3.4.1, Delete this paragraph in its entirety.

Paragraph 4.3.1, Delete the following items from the table:

"Inert grain forward	9298010	15
Inert grain aft	9299011	15"

Paragraph 4.4.2.1, Delete this paragraph in its entirety.

Paragraph 4.4.2.2, Delete this paragraph in its entirety.

Paragraph 4.4.2.7, Change the title to read as follows:

"Motor Body Assembly Prior to Inert Loading"

FSC: 1320

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:39Z
Check the source to verify that this is the current version before use.

Paragraph 4.4.2.7, Add the following Major defect:

"134. Grain support bonding assembly missing or improperly bonded....0.40%....3.2....Visual/Manual".

Paragraph 4.4.2.7.1, Delete this paragraph in its entirety.

Paragraph 4.4.2.8, Delete Major defects 133 and 134 and add the following defects:

"133. Warhead and motor body knurl and threads not free from grease, inert fill or foreign matter prior to application of adhesive.....100%....3.2...Visual
134. Grain cushion missing or lubricant improper.....0.40%...3.2...Visual.
136. Height of Motor body inert fill.....0.40%...3.2...Gage
137. Relief in inert fill missing or improper.....0.40%...3.2...Gage

Paragraph 4.4.2.9, Add to Major defect 101: "(.002 feeler)".

Paragraph 4.4.2.9, Add the following Major A defect:

"103. Excessive gap between the warhead and Motor Body (.005 feeler)....100%....3.2....Gage".

Paragraph 4.4.2.9, Delete Major defect 132 and add the following:

"132. Lifting plug not fully seated...0.40%...3.2...Visual
133. Lifting plug gasket missing.....0.40%...3.2...Visual".

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:39Z
Check the source to verify that this is the current version before use.

Paragraph 4.4.3.3, Delete this paragraph in its entirety and substitute the following:

"4.4.3.3 X-ray examination for missing or improperly assembled components. Major "A" Defect.-Each motor body assembly shall be subjected to a single x-ray examination in a plane that will clearly define the ring seal between the motor body and delay. The shear ring seal shall be fully expanded in the delay and motor body grooves. Any assembly which shows evidence of missing or improperly assembled components, as listed below, shall be classed as defective and removed from the lot.

a. Delay housing not properly seated in motor body.

b. Shear ring seal not fully expanded in delay and motor body grooves.

c. Gap between the grain support bonding assembly and motor body step exceeding 0.50 inches maximum as compared to the x-ray Std (the standard for HE M549 shell should be used).

Paragraph 4.5.1, Change the title to read as follows:

"4.5.1 Determination of missing or improperly assembled components".

Custodian:
Army - PA

Preparing Activity:
Army - PA

Project Number: 1320-A363

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:39Z
Check the source to verify that this is the current version before use.