MILITARY SPECIFICATION

REPAIR KIT, CBR AGENT SAMPLING

AND ANALYZING KIT, M32

1. SCOPE

1.1 This specification covers a repair kit containing miscellaneous replacement components of the Sampling and Analyzing Kit, CBR Agents, M19.

2. APPLICABLE DOCUMENTS

2.1 Government documents. The following documents of the issue in effect on date of invitation for bids or request for proposal form a part of this specification to the extent specified herein:

SPECIFICATIONS

FEDERAL

UU-P-258	-	Paper; Index.
ZZ-T-831	-	Tubing; Rubber.
GGG-S-121	-	Screwdrivers and Screw Starter, Hand.
PPP-B-566	-	Boxes, Folding, Paperboard.
PPP-B-576	-	Box, Wood, Cleated, Veneer, Paper Overlaid.
PPP-B-585	-	Boxes, Wood, Wirebound.
PPP-B-591	-	Boxes, Fiberboard, Wood-Cleated.
PPP-B-601	-	Boxes, Wood, Cleated-Plywood.
PPP-B-621	-	Boxes, Wood, Nailed and Lock-Corner.
PPP-B-636	-	Box, Fiberboard.

Source: https://assist.dla.mil -- Downloaded: 202610-22T20:53Z
Check the source to verify that this is the current version before use.

MILITARY

MIL-P-116 - Preservation, Methods of.
MIL-A-5092 - Adhesive, Rubber (Synthetic and Reclaimed Rubber Base.)

STANDARDS

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes.
MIL-STD-129 - Marking for Shipment and Storage.

DRAWINGS

EDGEWOOD ARSENAL

A5-77-378 - Clamp, Lower.
A5-77-379 - Clamp, Upper.
A5-77-437 - Gasket.
A5-77-440 - Cap, Rear.
B5-77-383 - Holder, Tube.
B5-77-384 - Plate, Backing.
B5-77-439 - Cap, Front.
C5-77-438 - Head, Sample, Assembly.
C5-77-792 - Bulb, Aspirator, Assembly.

(Copies of specifications, standards, drawings, and publications required by suppliers in connection with specific procurement functions should be obtained from the procuring activity or as directed by the contracting officer.)

2.2 Other publications. The following document forms a part of this specification to the extent specified herein. Unless otherwise indicated, the issue in effect on date of invitation for bids or request for proposal shall apply.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:53Z
Check the source to verify that this is the current version before use.

UNIFORM CLASSIFICATION COMMITTEE

Uniform Freight Classification Ratings, Rules and Regulations.

(Application for copies of these freight classification rules should be addressed to the Uniform Classification Committee, 202 Union Station, Chicago 6, Illinois.)

3. REQUIREMENTS

3.1 Materials and components. All materials and components used in the assembly of the repair kit shall conform to the specifications and drawings forming a part of this specification.

3.2 Contents. The repair kit shall be composed of items listed in table I in the quantities specified.

3.2.1 Instruction card.

3.2.1.1 Material. The instruction card shall be made of white paper, approximately 3 inches by 4 inches by 0.0105 inch, conforming to grade C of UU-P-258.

3.2.1.2 Printing. The following instructions shall be printed in sans-serif type on the instruction card with black printer's ink:

INSTRUCTIONS

FOR

USE OF THE M32 REPAIR KIT

1. Remove and discard expended items from the M19 CBR Agent Sampling and Analyzing Kit.
2. Repair items in the M19 Kit, using items in the M32 Kit.

3.3 Workmanship. The repair kit will be free from damage (breakage, tears, or cracks) and foreign matter (grease, oil, or viscous material) that could affect serviceability of the components.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:53Z
Check the source to verify that this is the current version before use.

Table I. Contents of the repair kit

Item	Quantity	Applicable document or MSA part number
Tube holder assembly consisting of the following components cemented together as noted on Dwg C5-77-438:	2	
2 Gaskets		A5-77-437
1 Tube holder		B5-77-383
1 Backing plate		B5-77-384
Upper and lower clamps	1 each	A5-77-378 & A5-77-379
Screwdriver, 3 inches long	1	GGG-S-121 (type I, class 1, design A, style 2)
Rubber tubing, heavy wall, 1/4 inch ID	4-1/2 feet	ZZ-T-831 (grade L, type I)
Aspirator bulb assembly	1	C5-77-792
Rubber adhesive	1 tube	MIL-A-5092
Front and rear caps	1 each	B5-77-439 & A5-77-440
Repair parts kit (for MSA pump No. 83241) consisting of:		84419
8 Copper burrs (#14)		57671
8 Fiber washers		14298
8 Rubber washers		14600
4 Cylinder cap gaskets		14559
8 Brass screws, 2-5/16 by 3/16 in.		50854
1/4 oz. Castor oil in oval polyethylene bottle		21344
		59898

Source: https://assist.dla.mil -- Downloaded: 202610-22T20:53Z
Check the source to verify that this is the current version before use.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection. Unless otherwise specified in the contract or purchase order, the supplier is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified, the supplier may utilize his own facilities or any commercial laboratory acceptable to the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements.

4.2 Special provisions.

4.2.1 Alternative inspection. The supplier may utilize any alternative inspection procedure which will provide equal or better assurance of quality by submitting a written proposal with justification and obtaining written approval from the Government prior to instituting the procedure. In case of dispute, the procedures of this specification will govern.

4.2.2 Objective evidence. The supplier shall provide objective evidence acceptable to the contracting officer that the requirements of 3.1, 3.2 and section 5 for which specific inspection has not been provided in this specification have been satisfied.

4.2.3 Inspection substation. If the supplier elects to establish inspection substations for the purpose of conducting inspection for certain listed defects, the Acceptable Quality Levels (AQL's) for each inspection substation shall be equal to the AQL which is the next numerically lower value than the AQL specified for the total listed defects. The requirements of MIL-STD-105 are applicable to each substation and to the end item.

4.3 Lotting. A lot shall consist of the repair kit assembled by one manufacturer, at one plant, from the same materials, under essentially the same manufacturing conditions.

4.4 Sampling for examination. Sampling shall be conducted in accordance with MIL-STD-105

Source: https://assist.dla.mil -- Downloaded: 202610-22T20:53Z
Check the source to verify that this is the current version before use.

4.5 Inspection provisions.

4.5.1 For examination. Sample repair kits shall be examined in accordance with the classification of defects and MIL-STD-105.

4.5.2 Classification of defects.

4.5.2.1 Repair Kit, CBR Agent Sampling and Analyzing Kit, M32.

Categories	Defects
Critical:	None defined
Major:	AQL 1.0 percent defective
101	Component missing
102	Component incorrectly assembled
103	Marking missing
104	Marking illegible or incorrect
105	Workmanship

5. PREPARATION FOR DELIVERY

5.1 Packaging. Level shall be as specified (see 6.2).

5.1.1 Level A.

5.1.1.1 Unit packaging. Items in the quantities specified in table I shall be unit packaged as specified in table II.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:53Z
Check the source to verify that this is the current version before use.

Table II. Unit packaging

Item	MIL-P-116 Method
Tube holder assembly	IC-2*
Upper and lower clamps	IC-1 or IC-3
Screwdriver	IC-1 or IC-3
Rubber tubing	III
Aspirator bulb assembly	III
Rubber adhesive	III
Front and rear caps	III
Repair parts kit**	IC-2*

** Unit box in accordance with PPP-B-566, type or class optional.
** Like components of the repair kit shall be packaged together in accordance with IC-1 or IC-3 and then packaged with the bottle of castor oil as specified.

5.1.1.2 Intermediate packaging. Items unit packaged as specified in table II shall be packaged together in a W5c (style optional) fiberboard box conforming to PPP-B-636. In addition to specified box closure requirements, all seams, corners, and manufacturer's joint shall be taped.

5.1.2 Level C. The components of the repair kit shall be packaged together to afford adequate protection from the supply source to the first receiving activity for immediate use.

5.2 Packing. Level shall be as specified (see 6.2).

5.2.1 Level A. Repair kits packaged as specified in 5.1 shall be packed not to exceed a gross weight of 200 pounds in an overseas type or class container conforming to PPP-B-576, PPP-B-585, PPP-B-591, PPP-B-601 or PPP-B-621; or repair kits shall be packed not to exceed the box weight limitations in a V3c, style optional, fiberboard box conforming to PPP-B-636. The containers shall be closed and strapped in accordance with applicable container specification and the appendix thereto, using galvanized strapping.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:53Z
Check the source to verify that this is the current version before use.

In addition to specified closure requirements, all corners, seams, and manufacturer's joints of the fiberboard boxes shall be taped. Tape banding may be used in lieu of metal banding on fiberboard containers as the box reinforcement.

5.2.2 Level C. Repair kits packaged as specified in 5.1 shall be packed to insure carrier acceptance and safe delivery to the first domestic destination. Containers shall comply with Uniform Freight Classification rules or regulations of other carriers applicable to the mode of transportation.

5.3 Marking. In addition to any special marking required by the contract or order, unit and intermediate packages and shipping containers shall be marked in accordance with MIL-STD-129.

6. NOTES

6.1 Intended use. The repair kit covered by this specification is intended to replace nonanalytical components of the Sampling and Analyzing Kit, CBR Agents, M19.

6.2 Ordering data. Procurement documents should specify the following:

(a) The title, number, and date of this specification.
(b) The level of packaging and packing required.

6.3 Supersession data. This specification supersedes in part Chemical Corps Purchase Description 197-54-724, dated 14 April 1959.

Custodian:

Army - MU

Preparing activity:

Army - MU

Project No. 6665-A118

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:53Z
Check the source to verify that this is the current version before use.