HH-G-450D
AMENDMENT-1
November 25, 1974

FEDERAL SPECIFICATION

GLOVES, CLOTH (ASBESTOS)

This amendment, which forms part of Federal Specification HH-G-450D, dated February 11, 1972, was approved by the Commissioner, Federal Supply Service, General Services Administration, for the use of all Federal agencies.

PAGE 1

2.1, under "Federal Specifications". Add "SS-C-1783 - Cloth, Asbestos".

PAGE 2

2.1, under "Military Specifications". Delete "MIL-C-10316 - Cloth Asbestos".

Preceding paragraph 2.2. Add the following:

"LAWS AND REGULATIONS

US Postal Service Manual.

(Copies of the Manual may be obtained from the Superintendent of Documents, US Government Printing Office, Washington, DC 20402.)".

PAGE 3

2.2, line 8. Delete "Room 202, Union Station, 516 W. Jackson Blvd.," and substitute "Room 1106, 222 South Riverside Plaza".

3.2.1, line 2. Delete "MIL-C-10316" and substitute "SS-C-1783".

At end of paragraph. Add: "Use of an additive finish as may be customary to reduce lint and dust during manufacturing operations is not precluded. The additive shall have a minimum effect on the flexibility of the fabric and shall not decrease the asbestos fiber content below the minimum requirements."

PAGE 4

3.2.5 Delete heading and substitute "Combination identification and caution label."

Delete first sentence and substitute: "The labels shall conform to type I, class 5 of DDD-L-20".

FSC 8415

Source: https://assist.dla.mil -- Downloaded: 202610-26T11:55Z
Check the source to verify that this is the current version before use.

Line 3, delete information in parentheses and substitute: "(type I, classes 1 or 2, or type II, as applicable.)"

At end of second sentence. Add: "The glove size shall be included on the labels for the type I, class 2 gloves. The letters for type, class, and size, shall be 1/8-inch high capitals.

At end of paragraph. Add: "In addition to the information required by DDD-L-20, the following information will be included on the label in the same format shown below. The word "CAUTION" shall be in capital letters and have a minimum height of 1/4-inch. All remaining letters shall be capital and shall have a minimum height of 1/8-inch.

CAUTION

CONTAINS ASBESTOS FIBERS

AVOID CREATING DUST

BREATHING ASBESTOS FIBERS MAY CAUSE SERIOUS

BODILY HARM

3.5, after third sentence. Delete remainder of paragraph.

Add the following new paragraphs:

"3.5.1 Type 301 stitching. Ends of all stitching shall be backstitched or overstitched 3/8 inch minimum except where ends are turned under in a hem or held down by other stitching. Thread tension shall be maintained so there will be no loose stitching resulting in loose bobbin or top thread, or excessively tight stitching resulting in puckering of the material sewn. The lock shall be imbedded in the materials sewn.

3.5.1.1 Repairs of type 301 stitching. Repairs of type 301 stitching shall be as follows:

a. When thread breaks or bobbin run-outs occur during sewing, the stitching shall be repaired by restarting the stitching a minimum of 3/8 inch back of the end of stitching.

b. Thread breaks, or two or more consecutive skipped stitches or run-offs noted during inspection of the item (in-process or end item) shall be repaired by overstitching. The stitching shall start a minimum of 3/8 inch back of the defective area, continue over the defective area and continue a minimum of 3/8 inch



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T11:55Z
Check the source to verify that this is the current version before use.

PAGE 4 (cont'd)

beyond the defective area onto the existing stitching. Loose or tight stitching shall be repaired by removing the defective stitching without damaging the material and restitching in the required manner. 1/

1/ When making the above repairs, the ends of stitching are not required to be backstitched.

3.5.1.2 Type 401 stitching. Thread tension shall be maintained so that there will be no loose stitching. Where stitch type 401 is used, the looper thread shall be on the inside of the gloves. Both ends of all seams or stitching produced with 401 stitch type, when not caught in other seams or stitching shall have a 1/2 to 3/4 inch chain extending beyond each end. All repairs shall be in accordance with 3.5.1.1 a and 3.5.1.1 b."

PAGE 6

After 3.9. Add the following new paragraph:

"3.10 Replacement of defective components. During the manufacturing process, components having material defects or damages that are classified as defects in 4.2.2.1, and 4.2.2.2 shall be removed from production and replaced with non-defective and properly matched components."

PAGE 8

In defect column, line 7. Delete "or approved" and substitute "or not approved".

Line 16. Delete "deficiencies" and substitute "deficiency".

Line 21, after "defect". Add "seriously".

PAGE 9

4.2.2.1, in defect column at end of "NOTE". Add "When the repair of an open seam is not as specified it shall be classified as a minor defect."

PAGE 10

In defect column, line 15, after "1/2 inch". Add "or more than 3/4 inch".



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T11:55Z
Check the source to verify that this is the current version before use.

PAGE 11

At top of page. Delete "Label (marking)" and all reference thereto in defect and classification columns and substitute the following in the columns indicated:

| Examine | Defect | Classification Major | Classification Minor |
|---|---|---|---|
| "Identification and caution label (marking) | Missing, incomplete, incorrect, illegible | X | |
| | Not specified type, not in proper location or not accomplished as specified | | X" |

4.2.3, in "Examine" column. Delete "and interior".

PAGE 13

5.1.3 Delete and substitute the following:

5.1.3 Level C (commercial packing). Gloves shall be packed in a manner to insure carrier acceptance and safe deliveries at destination at the lowest transportation rate for such supplies. The quantity per shipping container shall be the same as that normally used by the supplier for retail distribution. Containers shall comply with the U.S. Postal Service Manual, Uniform Freight Classification Rules or National Motor Freight Classification Rules, as applicable.

Custodians:

Army - GL
Navy - SA
Air Force - 82

Review activities:

Army - MD
Navy - SH

User activities:

Navy - YD, MC

Preparing activity:

Army - GL

Civil Agencies Coordinating Activities:

AEC - AEC
GSA - FSS
JUSTICE - FPJ
TREASURY - IRS

Project No. 8415-0814



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T11:55Z
Check the source to verify that this is the current version before use.