INCH-POUND

MIL-C-70549 (AR)
AMENDMENT 3
12 May 1993
SUPERSEDING
AMENDMENT 2
10 August 1988

MILITARY SPECIFICATION

CARTRIDGE, 81MM, SMOKE, RED PHOSPHORUS
M819, WITH FUZE, MTSQ, M772
LOADING, ASSEMBLING AND PACKING

This amendment forms a part of MIL-C-70549 (AR), dated 5 September 1986, and is approved for use by the U.S. Army Armament, Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 4

* 3.4.6, Delete in its entirety and substitute new paragraph as follows:

"3.4.6 Fuze function: The fuze shall air burst when set in accordance with paragraph 4.5.5, Table III."

PAGE 5

4.3.1, Change "9362899" to "9362799"

* Add the following under "Projectile loading assembly ...9327838 ...5"

"Projectile loading assembly (when LAP is split between two facilities) ...9327838 ...50*"

* In last line under "Quantity" delete "5" and substitute "50*"

* After list add "*Same group of samples when LAP is split"

AMSC N/A FSC 1315

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.
Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:40Z
Check the source to verify that this is the current version before use.

PAGE 6

* TABLE I: Add "4.4.2.21" before "4.4.2.5" in "Paragraph Reference" column

* In "Projectile Loading Assembly ..." add "1/" next to "5" in "NO. OF SAMPLE UNITS" column

* Under "Projectile Loading Assembly ...Examination for defects...": add: "Ballistic test ...502/ ...100% ...3.2 ...4.5.5"

* In "Cartridge, 81MM Smoke ...Examination for defects ...": Change "5" to "50" in "NO. OF SAMPLE UNITS" column

* In "Ballistic test ..." add "3/" next to "50" in "NO. OF SAMPLE UNITS" column

* Add Notes" "1/ Sample shall be 50 when LAP is split
2/ Required only when LAP is split
3/ Same units as in Note 2/ when LAP is split"

Change "9354333" to "9362799" where it appears

Change "9362899" to "9362799" and change ballistic test sample quantity from "5" to "50"

PAGE 9

4.4.2.2., Major 105: Change to read, "Piston plate assembly missing or foil punctured"

* Add Major 110, 111, 112 and 113 as follows:

"110 ...Presence of foreign matter between foil disc and piston plate or presence of contaminant on piston plate ...0.40% ...3.2 ...Visual/Manual"

111 ...Foil punctured, wrinkled or not adhering fully to piston plate ...0.40% ...3.2 ...Visual

112 ...Concentricity of foil disc with piston plate outside diameter (OD) ...0.40% ...3.2 ...Gage

113 ...Presence of foreign matter in tail con groove ...0.40% ...3.2 ...Visual"

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:40Z
Check the source to verify that this is the current version before use.

PAGE 10

* 4.4.2.3, Major 105: delete "5" in "NO. OF SAMPLE UNITS" column and delete "100%" in "AQL or 100%" column

* Delete Note "1/..." in its entirety and substitute "1/ ...See 4.4.3.1"

PAGE 12

* 4.4.2.5, Major 109: Change "0.40%" to "100%" and change "Visual" to "Gage"

PAGE 13

* 4.4.2.5, Delete "Major 112" in its entirety

* Add new "Major 112 ...Assembly fails to freely traverse alignment gage ...1/ ...3.2 ...Gage"

* Add Note "1/. Applies to split LAP only. At startup, 30 consecutive assemblies must successfully pass. Thereafter, one out of each 20 assemblies shall be checked. If any failures occur, the preceding 50 assemblies shall be checked. If any more failures occur, continue to screen groups of 50 until all pass."

PAGE 15

In Next Higher Assembly block change "9362899" to "9362799"

* 4.4.2.7, Major 106: Delete in its entirety and substitute:

"106 Inadequate torque applied to fin boom or fuze ...1/ ...-...3.2 ...Torque test/4.5.2"

* Note 1/: add "and 5 assemblies per hour thereafter. Any failures shall cause rejection back to the last successful inspection."

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:40Z
Check the source to verify that this is the current version before use.

PAGE 16

* Delete "4.4.2.8" in "PARAGRAPH" block and substitute "4.4.2.7"

In Next Higher Assembly block change "9362899" to "9362799"

* Major 109, delete "100%" in "AQL" column.

* Note 1/, delete second sentence in its entirety and substitute "Repaint and recheck if the ring inspection exposes bare metal."

* Major 110, delete in its entirety.

* Major 111, delete "Foil tape not centered on back of fuze" and substitute "Foil tape touches any part of fuze threads".

PAGE 17

* In drawing number block, delete "9354333" and substitute "9362799".

* In NEXT HIGHER ASSEMBLY block, delete "9362799".

* Under major category, add the following:

"104 Propelling charge support missing or damaged ...0.40% ...3.2 ...Visual

105 Increment tape missing ...0.40% ...3.2 ...Visual

106 Tab at the end of increment tape inadequate ...0.40% ...3.2 ... Visual

107 Tab at the end of increment tape covered by propellant charge support label ...0.40% ...3.2 ...Visual"

PAGE 18

In Drawing Number block, change "9362899" to "9362799".

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:40Z
Check the source to verify that this is the current version before use.

PAGE 19

Change Title block to, "Box, Packing for Container, Ammunition Fiber for Cartridges, 81MM, M819/M853"

* 4.4.2.11, Major 102: delete in its entirety.

Add Minor 203 and 204 as follows:

"Minor 203 Plastic sheet not present in every sixth box ...(-) ...0.65% ...3.2 ...Visual.

Minor 204 Box containing plastic sheet not appropriately marked ...(-) ...0.65% ...3.2 ...Visual"

* Add new minor defects 205 and 206 as follows:

"205 Graphical firing scale not present in every third box ...(-) ...0.65% ...3.2 ...Visual

206 Box containing graphical firing scale not appropriately marked ...(-) ...0.65% ...3.2 ...Visual"

PAGE 20

In Title block, change "Wirebound" to "Wooden" where it appears.

PAGE 21

* Under "PRECAUTION..." add new paragraph:

"4.4.3.1 Tack weld pull test. Ten consecutive assemblies shall pass this test whenever equipment is started. Five (5) shall be tested each hour thereafter and ten (10) whenever tooling is changed or equipment is adjusted. Failure of any sample shall cause rejection of all obturators welded since the last successful test. See 4.5.4."

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:40Z
Check the source to verify that this is the current version before use.

PAGE 21 (Cont'd)

4.4.5, Table II: Delete "Fuze non-function ...2" and substitute:

* "Fuze non-functions, functions upon ground impact or fails to separate tail cone from body tube assembly ...1 ...2 (See Note 1)".

* Delete: "Major ...Fuze functioning time (See Note 1) ...2 ...3"

* Delete "Note 1: ..." in its entirety and substitute:

* "Note 1: If two (2) failures occur, another sample of 50 shall be fired. If two (2) or more additional failures occur the lot shall be rejected. If three (3) or more failures occur during the first 50 fired, the lot shall be rejected."

PAGE 22

4.5.2, Change "4.2.3.4" to "4.4.2.7"

* Add to the end of the last sentence:

"and shall cause rejection of all cartridges produced since the last successful test."

* 4.5.5, Delete full sentences 5, 6 and 7 ("However ..." "...meters") in their entirety and substitute:

"Observation shall be made for compliance with the requirements specified for security of parts, air burst, horizontal range and smoke production. Horizontal range shall be reported to the point on the ground under the position of fuze functioning and shall be measured to the nearest five (5) meters.

* Delete "The cartridges shall be conditioned at 70 plus or minus 2.5 degrees Fahrenheit for a minimum of 4 hours prior to testing and fired at this temperature." and substitute:

"The cartridges shall be conditioned at 70 plus or minus 2.5 degrees Fahrenheit for a minimum of 24 hours prior to testing and shall be fired at this temperature."

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:40Z
Check the source to verify that this is the current version before use.

PAGE 22 (Cont'd)

* Delete "TABLE III..." in its entirety and substitute:

"TABLE III

* Fuze Setting (sec.)	Charge Zone	Elevation (mils)"
24.5	1	1459
46.0	4	1489

PAGE 25

On Form 1426, change "M19" to "M819" where it appears.

The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1315-AE86)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:40Z
Check the source to verify that this is the current version before use.