INCH-POUND

MIL-C-83503A
AMENDMENT 2
3 March 1995
SUPERSEDING
AMENDMENT 1
13December1985

MILITARY SPECIFICATION

CONNECTORS, ELECTRICAL, FLAT CABLE, AND/OR
PRINTED WIRING BOARD, NONENVIRONMENTAL
GENERAL SPECIFICATION FOR

This amendment forms a part of MIL-C-83503A, dated 1 July 1983, and is approved for use by all Departments and Agencies of the Department of Defense.

PAGE 2

2.1, add
"MIL-STD-202 - Test Methods for Electronic and Electrical Component Parts "

PAGE 3

Add the following new paragraph:

"3.3.2.1.2 3.4 Insulation displacing connectors. Unless otherwise specified, insulation displacing connectors shall be assembled with M22520/32 tool utilizing the appropriate termination die and connector holder."

PAGE 5

Add the following new paragraph:

"3.5.19 Solderability. Solder tail terminations shall withstand the test specified in 4.7.19."

PAGE 6

4 5.1, delete "Eight" and substitute "Ten".

PAGE 7

TABLE I, add:

"Group VI (2 sample units) 2/		
Solderability	3.5.19	4.7.19"

Add the following footnote:

"2/ These samples shall not be subjected to any test in any other group "

PAGE 8

4 6.1.3 1, delete "Four" and substitute "Six".

DISTRIBUTION STATEMENT A Approved for public release, distribution is unlimited

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T08:20Z
Check the source to verify that this is the current version before use.

Table II Revise Table II and associated notes, adding Note 3/ as shown below

TABLE II Group A inspection

Inspection	Requirements paragraph	Method paragraph	AQL (percent defective)	
			Major 1/	Minor 2/
Visual and mechanical 3/ examination	3 1, 3.3, 3 4, 3 6, and 3 7	4.7.1	1 0	4 0
Insulation resistance	3.5 2	4 7.3	4 0	
Dielectric withstanding voltage (sea level)	3.5 3	4.7 4.1	4 0	

1/ Major defects.
Malfunction of contacts
Inability to mate with counterpart
Part missing
Incorrect marking
Inability to seal properly (when applicable)
Mounting hole dimensions in error
Incorrect materials
Poor contact finish

2/ Minor defects:
Poor exterior finishes
Incorrect exterior or outline dimensions not preventing engagement or mounting
Minor workmanship flaws

3/ Mechanical inspection measurements on two samples only. If one or more of the two samples fail, the lot sample will then be inspected for physical dimensions in accordance with the AQL specified in table II

PAGE 9

TABLE III, add

"Subgroup III (2 samples)

Solderability 3.5 19 4.7.19"

PAGE 14

Add the following new paragraph:

"4 7.19 Soderability (see 3.5.19). The solder tail terminals shall be subjected to the testing as specified in method 208 of MIL-STD-202."

CONCLUDING MATERIAL

Custodians
Air Force - 85

Review Activities
Air Force - 11, 99, 17

Preparing activity
DLA - ES

(Project 5935-F526)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T08:20Z
Check the source to verify that this is the current version before use.