MIL-C-46614 (CmlC)
22 December 1961
(See section 6)

# MILITARY SPECIFICATION

## CLUSTER, INCENDIARY BOMB, PTV, 750-POUND, M35

## (W/O FUZE, FIN, AND WIRE)

1. SCOPE

1.1 This specification covers a side opening cluster for incendiary bombs.

2. APPLICABLE DOCUMENTS

2.1 Government documents. The following documents of the issue in effect on the date of invitation for bids form a part of this specification to the extent specified herein:

SPECIFICATIONS

MILITARY

MIL-F-26862 - Fiberboard, Solid, Dunnage, Multipurpose Cushioning and Blocking Applications.

STANDARDS

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes.
MIL-STD-129 - Marking for Shipment and Storage.

DRAWINGS

CHEMICAL CORPS

D14-23-1537 - Cluster, Incendiary Bomb, 750-lb., PT1, M35 (W/O Fuze, Fin, and Wire) - Bill of Material.

FSC 1325

Source: https://assist.dla.mil -- Downloaded: 202610-22T06:27Z
Check the source to verify that this is the current version before use.

(Copies of specifications, standards, drawings, and publications required by suppliers in connection with specific procurement functions should be obtained from the procuring activity or as directed by the contracting officer.)

## 3. REQUIREMENTS

### 3.1 Materials and components.

3.1.1 Materials. All materials cited on Drawing D14-23-1537 and on the subsidiary drawings shall conform to the specifications listed thereon, or to the specific characteristics set forth in the drawings.

3.1.2 Components. All components of the item shall conform to the specifications and drawings listed on Drawing D14-23-1537 and subsidiary drawings. Bombs shall contain PTV.

3.2 Assembly. The cluster shall be assembled as specified on Drawing E14-23-3266 and subsidiaries, which are listed on Drawing D14-23-1537. Each bomb shall have its retaining wire removed prior to clustering. The removal of the retaining wire shall be accomplished in such a manner that the bomb cannot become armed as long as the cluster remains intact (see 6.2).

3.3 Leakage. The cluster shall not leak when tested as specified in 4.7.1.

3.4 Air drop. The cluster (for preproduction lot only) shall perform so that 95 percent of the bombs function properly when tested and computed as specified in 4.7.2.

3.5 Cushions. The end cushions (Dwg C14-23-1558 and C14-23-1559) shall be manufactured from material conforming to Specification MIL-F-26862.

3.6 Preproduction sample. Prior to the start of regular production, a preproduction sample of 25 clusters shall be produced using the same methods, materials, and equipment as will be used during regular production.

3.7 Workmanship. The cluster shall be free from damage that would affect normal assembly and functioning; also free from contamination, such as oil, grease, and cutting lubricants.

## 4. QUALITY ASSURANCE PROVISIONS

4.1 The supplier is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified, the supplier may utilize his own or any other inspection facilities and services acceptable to the Government. Inspection records of the examination and tests shall be kept complete and available to the Government as specified in the contract or order. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements.



Source: https://assist.dla.mil -- Downloaded: 202610-22T06:27Z
Check the source to verify that this is the current version before use.

4.2 Special provisions.

4.2.1 Alternative inspection (including testing) procedures. The supplier may utilize any alternative inspection procedure which will insure equal or better quality by submitting a written proposal with justification and obtaining written approval from the Government prior to instituting the procedure. In case of dispute, the procedures of this specification will govern.

4.2.2 Supplemental evidence. The supplier shall provide evidence acceptable to the contracting officer that the requirements of 3.1 and section 5 have been satisfied.

4.3 Preproduction sample inspection.

4.3.1 Examination. The preproduction sample shall be inspected for all the requirements of the applicable drawings and this specification.

4.3.2 Tests. Sixteen clusters shall be tested in accordance with 4.7.2.

4.3.3 Acceptance/rejection criteria. The clusters shall meet the examinations and tests specified in 4.3.1 and 4.3.2 for preproduction sample acceptance. The supplier shall obtain written approval from the contracting officer before proceeding with regular production.

4.4 Lotting. A regular production lot shall consist of the clusters produced by one manufacturer, at one plant, from the same materials, under the same manufacturing conditions and offered for delivery at one time. However, not more than one lot of bombs and one lot of adapters shall be represented in any one lot of clusters.

4.5 Sampling. Sampling shall be conducted in accordance with Standard MIL-STD-105.

4.6 Examination. Sample clusters and level A preparation for delivery requirements shall be examined in accordance with the classification of defects and with Standard MIL-STD-105.



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:27Z
Check the source to verify that this is the current version before use.

4.6.1 Classification of defects.

4.6.1.1 Cluster, incendiary bomb, 750-lb., PTV, M35 (W/O fuze, fin, and wire) - assembly (Dwg E14-23-3266).

| Categories | Defects | Acceptance standards |
|---|---|---|
| Critical: | | |
| *1 | Bomb fuze armed | |
| Major: | AQL 0.65 percent defective | |
| 101 | Component missing, incorrect, or incorrectly assembled | |
| 102 | Bombs loose | |
| 103 | Bombs oriented incorrectly | |
| 104 | Retaining wires not removed | |
| 105 | Detonating cord ends not sealed | |
| 106 | Damage | |
| Minor: | AQL 1.5 percent defective | |
| 201 | Length of detonating cord incorrect | |
| 202 | Interior contamination | |
| Major A: | AQL 0.25 percent defective | |
| 301 | Leakage | 4.7.1 |
| Incidental: | AQL 10.0 percent defective | |
| 401 | Exterior contamination | |

*Each item in each lot shall be inspected for this defect.



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:27Z
Check the source to verify that this is the current version before use.

4.6.1.2 Filler, plain; or filler, slotted (Dwg C14-23-1562 or C14-23-3215).

| Categories | Defects |
|---|---|
| Critical: | None defined |
| Major: | AQL 1.0 percent defective |
| 101 | Profile incorrect |
| 102 | Slot dimensions or location incorrect |
| Minor: | AQL 2.5 percent defective |
| 201 | Length incorrect |
| 202 | Contamination |

4.6.1.3 Spacer (Dwg C14-23-1543).

| Categories | Defects |
|---|---|
| Critical: | None defined |
| Major: | AQL 1.0 percent defective |
| 101 | Width across flats (13-5/8) incorrect |
| 102 | Damage |
| 103 | Thickness incorrect |
| Minor: | AQL 10.0 percent defective |
| 201 | Contamination |

4.6.1.4 Spacer, side (Dwg D14-23-3310).

| Categories | Defects |
|---|---|
| Critical: | None defined |
| Major: | AQL 1.0 percent defective |
| 101 | Side profile incorrect |
| 102 | Length (59-5/8) incorrect |
| 103 | Damage |
| Minor: | AQL 2.5 percent defective |
| 201 | Width (7.0) incorrect |
| 202 | Edges not broken |
| 203 | Coating missing or inadequate |
| 204 | Contamination |



Source: https://assist.dla.mil -- Downloaded: 202610-22T06:27Z
Check the source to verify that this is the currentversion before use.

4.6.1.5 Bag, desiccant (Dwg D14-23-3391).

| Categories | Defects |
|---|---|
| Critical: | None defined |
| Major: | AQL 1.0 percent defective |
| 101 | Contents missing or inadequate |
| 102 | Thickness (1 max) incorrect |
| 103 | Damage |
| Minor: | AQL 2.5 percent defective |
| 201 | Overall length (13.0) incorrect |
| 202 | Stitching incorrect or incorrectly located (when applicable) |
| 203 | Heat sealing inadequate (when applicable) |
| 204 | Width (7.0) incorrect |
| 205 | Length (5-3/4) incorrect |
| 206 | Contamination |

4.6.1.6 Spacer, rear end - assembly; or spacer, front end - assembly (Dwg C14-23-1544 or C14-23-1546).

| Categories | Defects |
|---|---|
| Critical: | None defined |
| Major: | AQL 1.0 percent defective |
| 101 | Component missing, incorrectly assembled, or incorrect |
| 102 | Facings' profile incorrect |
| 103 | Cushion width across flats incorrect |
| *104 | Cable box cutout dimensions or location incorrect |
| 105 | Cushion dimensions incorrect |
| 106 | Reinforcement overall length incorrect |
| 107 | Width across flats incorrect |
| Minor: | AQL 2.5 percent defective |
| 201 | Facings not beveled |
| 202 | Reinforcement coating missing or inadequate |
| 203 | Reinforcement height or width incorrect |
| *204 | Facing not flush or below cushion |
| 205 | Cement missing or inadequate |
| 206 | Damage |
| 207 | Contamination |

*Applicable only to Drawing C14-23-1544.



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:27Z
Check the source to verify that this is the current version before use.

4.6.1.7 Packing - assembly (Dwg E14-23-3318).

| Categories | Defects |
|---|---|
| Critical: | None defined |
| Major: | AQL 2.5 percent defective |
| 101 | Shipping guard missing |
| 102 | Damaged shipping guard |
| 103 | Strapping loose or missing |
| 104 | Marking incorrect, missing, or illegible |
| 105 | Cluster loose |
| 106 | Strapping sent improperly crimped |
| Minor: | AQL 4.0 percent defective |
| 201 | Marking located incorrectly or obscured |

4.7 Tests.

4.7.1 Cluster leakage. Dry air shall be introduced into the cluster using the air inlet fitting provided in the center lug well and a minimum internal air pressure of 12 ± 2 pounds per square inch gage (psig) maintained. The cluster shall be completely submerged in a water-filled tank properly illuminated to permit rapid detection of air bubbles. The tank shall contain a wetting agent in sufficient concentration to prevent air bubbles from clinging to the surface. The temperature of the water shall be 90° ± 10°F. Tilting the cluster may be permitted to assist in freeing the entrapped air. After allowing a reasonable period for releasing the entrapped air, the cluster shall be observed for a minimum period of 1 minute.

4.7.2 Air drop.

4.7.2.1 Procedure. The 16 clusters of the preproduction lot with tail fuzes set to function at 5,000 feet above the ground, shall be dropped from an airplane traveling at a true air speed of 250 ± 50 knots per hour at 10,000 ± 500 feet above the ground. Should one cluster fail to function properly due to improper fuzing or improper aircraft installation or operation, that cluster shall be disregarded and the results shall be computed on the basis of the remaining 15 clusters. Should more than one cluster fail to function for the same reason, additional clusters shall be dropped until a total of 16 clusters have been properly fuzed, installed, and dropped.



Source: https://assist.dla.mil -- Downloaded: 202610-22T06:27Z
Check the source to verify that this is the currentversion before use.

4.7.2.2 Functioning. Not less than 90 percent of the bombs from the satisfactorily dropped clusters shall be recovered. If 90 percent of the bombs are not recovered, additional clusters shall be dropped until 90 percent of the total number of bombs dropped has been recovered. The percent bomb functioning shall be determined in accordance with the following equation:

Percent bomb functioning = 100 percent - (percent airbursts / percent duds)

where:

$$\text{percent airbursts} = \frac{\text{number of airbursts} \times 100}{57 \times \text{number of clusters satisfactorily dropped}} \quad \text{and}$$

$$\text{percent duds} = \frac{\text{number of duds} \times 100}{\text{number of bombs recovered}}.$$

All duds shall be analyzed for cause of failure to function (see 6.5).

5. PREPARATION FOR DELIVERY

5.1 Packing, level A. The cluster shall be packed for shipment as specified on Drawing E14-23-3318, which is listed on Drawing D14-23-1537.

5.2 Marking. In addition to any special markings required by drawings, contract, or order, the shipping guard shall be marked in accordance with Standard MIL-STD-129 and Drawing E14-23-3318.

6. NOTES

6.1 Ordering data. Procurement documents should specify the title, number, and date of this specification.

6.2 Caution. Adequate precaution should be taken to prevent fires while clustering in accordance with this specification.

6.3 Components. The components necessary to assemble the complete cluster covered by this specification are listed on Drawing D14-23-3324.

6.4 Safety classification. This item carries the following safety classification: explosive hazard class 2, chemical group D (Chemical Corps Safety Directive 385-10).

6.5 Classification of bombs. When bombs from clusters which have been dropped are recovered, the following information should be obtained as an aid in determining the cause for failure of each bomb and corrective



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:27Z
Check the source to verify that this is the current version before use.

action (if any) to be taken:

Bomb improperly functioned
Bomb not ejected from cluster adapter
Bomb landed safe (safety wire not removed or release bar still on bomb)
Primer not struck
Primer struck but not initiated
Primer blow-back
First fire failed to ignite
Delay failed to ignite

6.6 Supersession data. This specification supersedes Chemical Corps Purchase Description 196-131-633B, dated 20 December 1955.

Notice. When Government drawings, specifications, or other data are used for any purpose other than in connection with a definitely related Government procurement operation, the United States Government thereby incurs no responsibility nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use, or sell any patented invention that may in any way be related thereto.

Custodian:

Army - CmlC

Preparing activity:

Army - CmlC



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:27Z
Check the source to verify that this is the current version before use.