MILITARY SPECIFICATION

PROJECTILE METAL PARTS: LESS BALL ASSEMBLY: WITH FUZE, PD, M536

This amendment forms a part of Military Specification MIL-P-50203 (MU), dated 12 November 1968 and is approved for use by the US Army Armament Research and Development Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

Add the following preamble underneath the title:

"This specification is approved for use by the US Army Armament Research and Development Command and is available for use by all Departments and Agencies of the Department of Defense."

PAGE 8

Add new paragraph 4.2.2.1.23 as follows:

"4.2.2.1.23 Qualitative spot test for cadmiun (when applicable). Five (5) rotor springs and ten (10) lock springs shall be subjected to this test."

PAGE 9

4.2.4.5: Before "NOTE" add "ADVISORY."

PAGE 13

4.3.2.3, Major defect 101: Delete in its entirety and substitute the following:

"101. Diameter of hole Gage 03003."

FSC: 1310

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:16Z
Check the source to verify that this is the current version before use.

PAGE 19

4.3.2.21: Add new Major defect 112 as follows:

"112. Inverted pusher plate Visual 21013."

PAGE 20

4.3.2.23, Minor Category:

AQL: Delete "1.50 percent" and substitute "2.50 percent."

Add new Minor defect 205 as follows:

"205. Foil missing Visual 23012."

PAGE 21

4.3.2.26, line 1: After "fiber" add "inner."

4.3.2.27:

Line 1: After "box" add "inner."

Major defect 102: Delete in its entirety and substitute the following:

"103. Corners not blunted Visual 27004."

AQL: Delete "0.65 percent" and substitute "1.00 percent."

Add new Minor defect 202 as follows:

"202. Label missing Visual 27005."

4.3.2.28, line 1: After "fiber" add "inner."

PAGE 22

4.3.2.29, line 1: After "box" add "inner."

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:16Z
Check the source to verify that this is the current version before use.

Add new paragraphs 4.3.2.36 and 4.3.2.37 as follows:

"4.3.2.36 Unsealed outer fiber box for Fuze, Primary, PD, M536 (see dwg. 9232348).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major	AQL 0.65 Percent		
101.	Large fold of bags facing wrong way	Visual	70001
102.	Bag torn or perforated	Visual	70002
103.	BAg improperly sealed	Visual	70003
104.	Fillers missing	Visual	70004
Minor	AQL 0.65 Percent		
201.	Marking of bag misleading or unidentifiable	Visual	70005

4.3.2.37 Sealed outer fiber box for Fuze, Primary, PD, M536 (see dwg. 9232348).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major	AQL 0.65 Percent		
101.	Box damaged	Visual	71001
102.	Top improperly assembled	Visual	71002
103.	Strapping missing or improperly assembled	Visual	71003
104.	Dot (ICC) nomenclature missing or unidentifiable	Visual	71004
Minor	AQL 0.65 Percent		
201.	Marking misleading or unidentifiable."	Visual	71005

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:16Z
Check the source to verify that this is the current version before use.

4.3.3.18: Delete in its entirety and substitute the following:

"4.3.3.18 Push test of simulated setback pin into retainer setback pin (see dwg. 8876212), Major defect, Code No. (51001). One hundred and twenty-five (125) setback pin retainers shall be selected from each heat treat batch and subjected to this test. If two (2) or more of each 125 fail to comply with the requirement specified on the applicable drawing, the batch represented by the sample shall be rejected. The test shall be performed as specified in 4.4.15 using equipment in accordance with 4.3.4."

PAGE 31

4.3.3.35: Before "NOTE" and "ADVISORY."

Add new paragraph 4.3.3.36 and 4.3.3.37 as follows:

"4.3.3.36 Qualitative spot test for cadmiun (see dwg. 8864648 and 8864653), Major defect, Code No. (69001) (when applicable). Five (5) rotor springs and ten (10) lock springs shall be selected from each lot and subjected to this test. If any part fails to comply with applicable requirements, the lot shall be rejected. NOTE: For the purpose of this test, one lot of springs shall consist of parts manufactured from not more than one roll of spring wire. This test shall be performed as specified in 4.4.3.2, using equipment in accordance with 4.3.4.

4.3.3.37 Verification of hat treat of setback pin retainer (see dwg. 8876212), Major defect, Code No. (72001). After completion of test specified in 4.3.3.18, the three (3) setback pin retainers exhibiting the lowest push test force shall be subjected to this test. If any retainer fails to comply with the requirement specified on the applicable drawing, the heat treat batch represented by the sample shall be rejected. The test shall be performed as specified in 4.4.33 using equipment in accordance with 4.3.4."

PAGE 36

Add new paragraphs 4.4.32 and 4.4.33 as follows:

"4.4.32 Qualitative spot test for cadmium. The rotor springs and lock springs shall be tested in accordance with the following procedure:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:16Z
Check the source to verify that this is the current version before use.

a. Clean the parts in acetone and place on (1) rotor spring or two (2) lock springs in a clean test tube. Add 10 ml. concentrated hydrochloric acid and allow cadmium to dissolve.

b. Decant fluid into a beaker and dilute with distilled water to total 10 ml.

c. Add 50 ml. of saturated hydrogen sulfide.

d. The development of a yellow precipitant indicates the presence of cadmium. This test is a destructive test. Parts so tested shall not be returned to the lot.

4.4.33 Verification of heat treat of setback pin retainer. The setback pin retainer shall be subjected to the Kroop Hardness Test in accordance with ASTM Test Method D1474-68. This test is a destructive test. Parts so tested shall not be returned to the lot."

Custodian:
Army-AR

Preparing Activity:
Army-AR

Project No: 1310-A271

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:16Z
Check the source to verify that this is the current version before use.