INCH-POUND

MIL-C-48697 (AR)
AMENDMENT 4
03 April 1995
SUPERSEDING
AMENDMENT 3
8 December 1992

MILITARY SPECIFICATION

CARTRIDGE, 60MM, TP, M50A3
LOADING, ASSEMBLING AND PACKING

This amendment forms a part of MIL-C-48697 (AR), dated 11 August 1987, and is approved for use by the U.S. Army Armament Research, Development and Engineering Center, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 6

* 4.4.2, Delete in its entirety and substitute:

"4.4.2 Examination. See MIL-A-48078.

a. Sampling plans. Unless otherwise specified in the Classification of Defects and Test Tables, sampling plans for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

b. Tool control dimensions. Dimensions marked tool control shall be inspected as follows: select and gage one cartridge from each press in operation every two hours or fraction thereof and whenever tooling is changed. Prior to any tooling change, the last fin assembly canted by the old tooling shall be gaged for the requirements of the applicable drawing. All cartridges produced prior to periodic inspection shall be rejected and screened whenever a defective tool control dimension is found and corrective action must be taken."

AMSC N/A FSC 1310
DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:37Z
Check the source to verify that this is the current version before use.

PAGE 10

4.4.2.4, Critical Defect 2, Delete in its entirety.

Major 101, Delete in its entirety.

Major 103, Delete: "(except as described by Critical 2 above)".

Major 105 and 106, Add as follows:

"105 Sealing compound bead improperly located, missing or not full 360 degrees in base of cartridge housing cavity (prior to insertion of ignition cartridge) . . . Visual

106 Sealing compound bead improperly located, missing or not full 360 degrees on red end of ignition cartridge (prior to seating of primer into fin cavity) . . . Visual".

Major 107 and 108, Add as follows:

"107 Fuze not fully seated . . . 0.40% . . . 3.2 . . . Visual

108 Fin and fin extension not fully seated . . . 0.40% . . . 3.2 . . . Visual".

Major 109 and 110, Add as follows:

"109 Fin blade(s) canted in improper direction . . . 0.40% . . . 3.2 . . . Visual".

110 Height of fin blade cant . . . 0.40% . . . 3.2 . . . Visual".

Minor 203, Delete in its entirety.

PAGE 11

4.4.2.5, Major Defect 101, Delete and substitute:

101 Propellant sheets damaged. . . 0.40% . . . 3.2 . . . Visual".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:37Z
Check the source to verify that this is the current version before use.

The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (modifications, additions, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in this notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1310-0562)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:37Z
Check the source to verify that this is the current version before use.