INCH-POUND

MIL-S-63348A(AR)
AMENDMENT 4
29 October 1992
SUPERSEDING
AMENDMENT 3
3 August 1983

MILITARY SPECIFICATION

SUBMACHINE GUN, 5.56MM, PORT FIRING, M231

This Amendment forms a part of Military Specification MIL-S-63348A(AR), dated 20 Auqust 1981, and is approved for use by the U.S. Army Armament; Munitions and Chemical Command, and is available for use by all Department and Agencies of the Department of Defense.

PAGE 4

3.3.2.7, Delete paragraph 3.3.2.7 in its entirety.

PAGE 5

* 3.3.3.5 Change “Flash Suppressor” to "Compensator" in two Placeso

PAGE 7

3.4.4, lines 3 & 4: Delete “at least 1225” and substitute “within 1225 and 1300”.

* 3.4.6, lines 2: Delete “10,200” and substitute “10,000”.

3.4.6, line 9: Delete “minute” and substitute “minute for 2 consecutive 600 round cycles”.

PAGE 8

3.4.8 line 4: Delete “1500” and substitute “500”.

* 3.4.8, lines 5 & 6: “A weapon that continueS to fire after the trigger is release shall be considered to have failed the test”.

* 3.6, Add:

“The bare code label shall be firmly affixed to the lower receiver in the position specified on the applicable drawing, the bar coding shall be clearly defined and the number on the label shall agree with the serial number stamped on the receiver.”

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026l0-23T02:42Z
Check the source to verify that this is the currentversion before use.

PAGE 9

Delete “TABLE I“ and substitute the following:

“TABLES I - Malfunctions and Unserviceable Parts Permitted in 10,200 Rounds

Malfunctions	Single Sub MG[6]	Two Sub MG[6]	Four Sub MG[6]	Five Sub MG[6]
Failure of bolt to lock	1	2	3	4
Failure to Fire	2	3	4	5
Failure to Feed (from Magazine)	3	4	7	9
Failure to Eject	2	3	4	5
Failure to Chamber	3	4	6	7
Failure to Extract	1	2	2	3
Bolt Fails/Hold Rear	6	8	12	14
All other malfunctions	0	0	0	0
Total - above malfunctions combined	9	13	20	25

Unserviceable Parts[1]	Minimum life[4] Rounds	Two Sub MG	Four Sub MG[5] Combined	Five Sub MG[6]
Bolt	5,000	2	4	5
Bolt Rings (3 in a unit)	4,000	1	2	3
Cam Pin	4,000	4	8	10
Extractor	4,000	4	8	10
Ejector Spring	4,000	1	2	3
Extractor Spring Assembly	4,000	2	4	5
other Parts (See note 2)	3,000	1	1	1
Total Unserviceable parts above combined”		8	18	23

PAGE 10

TABLE I, Note 6, line 11: Delet “two” and substitute “two and the five”.

PAGE 11

4.4.1, line 5, under Quantity: Delete “10” and substitute “15”.

Line 6: Delete “ten” and substitute “fifteen”.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:42Z
Check the source to verify that this is the current version before use.

4.4.2: Delete in its entirety and substitute the following:

"4.4.2 Inspection to be performed. The submachine guns shall be subjected to the following tests, in the quantities as specified.

Test	Number To Test	Require-ment	Test Method
a. Headspace	15	3.4.1	4.7.1
b. Trigger Pull	15	3.4.2	4.7.3
c. Firing Pin Protrusion	15	3.3.4.2	4.7.2
d. High pressure Resistance	15	3.4.3	4.7.4
e. Function/Cyclic Rate of fire	15	3.4.4	4.7.5 - 4.7.5.3.5
f. Targeting and Accuracy	15	3.4.5	4.7.6 - 4.7.6.2.1
g. Interchangeability	10	3.5	4.7.7.1
h. Endurance	5	3.4.6	4.7.8 - 4.7.8.4.5
i. High Temperature	5	3.4.7	4.80
j. Low Temperature	5	3.4.8	4.81"

4.4.3.1.1, line 3: Delete "18" and substitute "48"

line 3: Delete "three" and substitute 'five".

4.4.3.1.2, line 3: Delete "6" and substitute "30".

line 3: Delete "three" and substitute "five".

PAGE 18

4.5.2.2.3, lines 21 thru 26: Delete Defect No. 19 in its entirety. Delete Defect No. 20 in its entirety.

PAGE 22

* 4.5.2.2.3, Defect No. 49, change "Flash Suppressor" to "Compensator"

* Defect No. 50, Change "Flash Suppressor" to "Compensator"

PAGE 23

* 4.5.2.2.3, Defect NO. 54, line 5 change "Flash Suppressor" to "Compensator".

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:42Z
Check the source to verify that this is the current version before use.

PAGE 25

* 4.5.2.2.3, Defect No. 71, change to read:

"Lower Receiver. Incorrect, dislocated, damaged, illegible or missing markings (serial number, bar code label, manufacturer's identification, selector markings, etc.)"

PAGE 28

4.5.3.1, Table III, line 7: Delete "100%[3]" and substitute "100%".

PAGE 29

4.5.3.1, Table III, lines 1 thru 17: Delete Note 3 in its entirety.

PAGE 37

4.7.7.1.1, GROUP V, line 10: Delete "Buttstock (9327049)".
GROUP IV, line 4: Delete "Latch, Buttstock (9327050)".

PAGE 38

4.7.7.1.1, GROUP VII, line 1: change "Flash Suppressor (8448576)" to "Compensator (9349051)".
GROUP VII, line 4: Delete "Brackett, Buttstock (9327048)".

GROUP VIII, line 4: Change "Flash Suppressor, Lock Washer (8448577)" to "Spacer, Compensator (9349052)"

PAGE 39

4.7.7.1.1, GROUP X, line 1: Delete "Spring Pin (Buttstock Retaining Pin MS-16562-117)".

GROUP X, line 8 & 9: Delete "Springs (3 total) Buttstock Latch, Safety Detent, and Ejector" and substitute "Springs, (2 total) Safety Detent and Ejector (8448516)".

PAGE 41

* 4.7.8.2, line 1: Delete "Ten" and substitute "Thirty-four[W]".

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:42Z
Check the source to verify that this is the current version before use.

PAGE 42

* Delete “Table V” and substitute the following:

“TABLE V

Number 30 Round Magazines	Number of Rounds Fired	Remarks
5	150	cool
5	150	cool
5	150	cool
5	150	Cool, Clean Inspect & Lubricate
TOTAL: 20	600	

NOTES:

1. Firing - Fire 4 bursts of approximately 7 to 10 rounds from each magazine.

2. Magazines - Each magazine shall be fully loaded (30 rounds).
No magazine shall be used more than 10 times.”

P A G E 4 5

* 4.8.0, line 4: Delete “prior to firing.” and substitute “prior to firing. Each weapon shall be conditioned with bolt closed and locked on empty chamber.”

* line 9: Delete “fired per weapon.” and substitute “fired per weapon. Immediately prior to the firing of each 100 round group, each weapon shall be dry cycled twice (i.e. charging and firing the weapon without ammunition)."

* 4.8.1, line 5: Delete “prior to firing.” and substitute “prior to firing. Each weapon shall be conditioned with bolt closed and locked on empty chamber.”

* lines 5 & 6: Delete “The weapon shall be conditioned in the open bolt condition.”

PAGE 46

* 4.8.1, lines 4 & 5: Delete “weapon without ammunition.” and substitute “weapon without ammunition. Perorm functional check on cartridge magazine to ensure cartridges and internal parts of cartridge magazine to ensure cartridges and internal parts of the magazine are free to move and not frozen in the magazine.”

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:42Z
Check the source to verify that this is the current version before use.

* 6.1, Add: “O. Bar code marking requirements”

The margins of this amendment are marked with an asterisk to indicate where changes from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(project 1005-A645)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:42Z
Check the source to verify that this is the current version before use.