DEPARTMENT OF THE AIR FORCE
Headquarters US Air Force
Washington, DC 20330-1030

Change 1
CFETP 2A6X5
4 September 2023

ACCESSIBILTY: Publications and Forms are available on the E-Publishing website at: www.e-publishing.af.mil for downloading or ordering.

RELEASIBILITY: There are no releasability restrictions on this publication.

AFSC 2A6X5

AIRCRAFT HYDRAULIC SYSTEMS

This change is effective immediately and updates the 2A6X5 CFETP dated 31 January 2023. Implement immediately.

1. C-17, Attachment A8

Task	Attachment	Action
A8.13.52	8	Change action to "Repair cargo winch" Keep as 5-lvl core task
A8.13.53	8	Insert a new row, add "Overhaul cargo winch" Will not be 5-Lvl core task
Bench check actuator stabilizer strut assembly	8	Change task number to A8.13.54
Repair/overhaul actuator stabilizer strut assembly	8	Change task number to A8.13.55
Bench check drogue chute deploy cylinder	8	Change task number to A8.13.56
Repair/overhaul drogue chute deploy cylinder	8	Change task number to A8.13.57
Bench check cargo door down lock cylinder	8	Change task number to A8.13.58
Repair/overhaul cargo door down lock cylinder	8	Change task number to A8.13.59
Bench check cargo door up lock cylinder	8	Change task number to A8.13.60
Repair/overhaul cargo door up lock cylinder	8	Change task number to A8.13.61

Bench check cargo door down latch assembly	8	Change task number to A8.13.62
Repair/overhaul cargo door down latch assembly	8	Change task number to A8.13.63
Bench check cargo door up lock assembly	8	Change task number to A8.13.64
Repair/overhaul cargo door up lock assembly	8	Change task number to A8.13.65
Bench check ramp toe cylinder	8	Change task number to A8.13.66
Repair/overhaul ramp toe cylinder	8	Change task number to A8.13.67
Bench check ramp latch linear cylinder	8	Change task number to A8.13.68
Repair/overhaul ramp latch linear cylinder	8	Change task number to A8.13.69
Bench check NLG steering cylinder	8	Change task number to A8.13.70
Repair/overhaul NLG steering cylinder	8	Change task number to A8.13.71
Bench check MLG integral jack hose assembly	8	Change task number to A8.13.72
Repair MLG integral jack hose assembly	8	Change task number to A8.13.73
Bench check fan thrust reverse duct actuator hand pump	8	Change task number to A8.13.74
Repair/overhaul fan thrust reverse duct actuator hand pump	8	Change task number to A8.13.75

2. After making the required changes, file this change in the back of the CFETP.

BY ORDER OF THE SECRETARY OF THE AIR FORCE

OFFICIAL

TOM D. MILLER
Lieutenant General, USAF
DCS/Logistics, Engineering, & Force Protection