




(a) P1 Factory logistics




(b) P2 Sharp-turn transition




(c) P3 Long up/down slope



(d) P4 Mild slope-turn coupling



(e) P5 Flat factory logistics



(f) P6 Downhill recovery

