MARKET VALUATION REPORT

Prepared for GEICO PROTECTION INSURANCE COMPANY

REPORT SUMMARY

CLAIM INFORMATION

Owner	Wang, Alfred 900 W Las Palmas Dr Fullerton, CA 92835-1442
Loss Vehicle	2020 BMW X7 xDrive40i Sports Activity Vehicle
Loss Incident Date	08/01/2026
Claim Reported	09/23/2026

INSURANCE INFORMATION

Report Reference Number	133368197
Claim Reference	0346064580101041-01
Adjuster	Mckinney, Kyrstien
Odometer	67,821
Last Updated	09/23/2026 06:27 PM

VALUATION SUMMARY

Base Vehicle Value	**$ 31,897.00**
OWNER RETENTION*	- $ 22,944.85
Adjusted Vehicle Value	**$ 8,952.15**
Vehicular Tax (7.75%)	+ $ 693.79
Tax reflects applicable state, county and municipal taxes.	
PREVIOUS REPAIR PAYMENTS*	- $ 14,642.61
DMV FEE*	+ $ 563.41
Value before Deductible	**$ 0.00**
Deductible*	- $ 1,000.00
Total	**$ 0.00**

Adjustments indicated with an Asterisk (*) have been determined by GEICO PROTECTION INSURANCE COMPANY and have been added here for convenience.

The total may not represent the total of the settlement as other factors (i.e. other applicable fees) may need to be taken into account.

The CCC ONE® Market Valuation Report reflects CCC Intelligent Solutions Inc.'s opinion as to the value of the loss vehicle, based on information provided to CCC by GEICO PROTECTION INSURANCE COMPANY.

Loss vehicle has 12% fewer than average mileage of 77,200.

BASE VEHICLE VALUE

This is derived per our Valuation methodology described on the next page.

ADJUSTED VEHICLE VALUE

This is determined by adjusting the Base Vehicle Value to account for the actual condition of the loss vehicle and certain other reported attributes, if any, such as refurbishments and after factory equipment.

Any applicable title, registration and other fees owed to the claimant are calculated separately by GEICO PROTECTION INSURANCE COMPANY and may not be reflected here.

Inside the Report

Valuation Methodology.....3
Vehicle Information.....4
Vehicle Condition.....8
Taxes and Fees.....10

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.

REPORT SUMMARY

Comparable Vehicles..... 11
Valuation Notes..... 15
Supplemental Information.....16

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.

VALUATION METHODOLOGY

How was the valuation determined?



CLAIM INSPECTION

GEICO PROTECTION INSURANCE COMPANY has provided CCC with the zip code where the loss vehicle is garaged, loss vehicle VIN, mileage, equipment, as well as loss vehicle condition, which is used to assist in determining the value of the loss vehicle.



DATABASE REVIEW

CCC maintains an extensive database of vehicles that currently are or recently were available for sale in the U.S. This database includes vehicles advertised for sale by dealerships or private parties. CCC also obtains vehicle sales prices from a database of California Department of Motor Vehicles vehicle registration sold transactions. All of these sources are updated regularly.



SEARCH FOR COMPARABLES

When a valuation is created the database is searched and comparable vehicles in the area are selected. The zip code where the loss vehicle is garaged determines the starting point for the search. Comparable vehicles are similar to the loss vehicle based on relevant factors.



CALCULATE BASE VEHICLE VALUE

Adjustments to the price of the selected comparable vehicles are made to reflect differences in vehicle attributes, including mileage and options. Dollar adjustments are based upon market research.

Finally, the Base Vehicle Value is the straight average of the adjusted values of the comparable vehicles.

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.

VEHICLE INFORMATION

VEHICLE DETAILS

Location	FULLERTON, CA 92835-1442
VIN	5UXCW2C08L9C13105
Year	2020
Make	BMW
Model	X7
Trim	xDrive40i
Body Style	Sports Activity Vehicle
Body Type	Sports Utility
Engine -	
Cylinders	6
Displacement	3.0L
Induction	Turbocharged
Fuel Type	Gasoline
Carburation	Gasoline Direct Injection
Transmission	Automatic Transmission 4 Wheel Drive
Curb Weight	5370 lbs

Vehicles sold in the United States are required to have a manufacturer assigned Vehicle Identification Number(VIN). This number provides certain specifications of the vehicle.

Please review the information in the Vehicle Information Section to confirm the reported mileage and to verify that the information accurately reflects the options, additional equipment or other aspects of the loss vehicle that may impact the value.

VEHICLE ALLOWANCES

Odometer	67,821	+ 1,287
Options		
Luggage/Roof Rack	Reported	+ 50
Surround View Camera	Reported	+ 200

Reported* Option(s) added after initial valuation

Allowances are factors influencing the value of the loss vehicle when compared to a typical vehicle. The typical vehicle is a vehicle of the same year, make, and model as the loss vehicle, including average mileage, and all standard equipment. These allowances are displayed for illustrative purposes only.

The Base Vehicle Value is calculated from the comparable vehicles with adjustments to reflect the loss vehicle configuration

VEHICLE HISTORY SUMMARY

Experian AutoCheck	No Title Problem Found
National Highway Traffic Safety Administration	12 Recalls

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.

VEHICLE INFORMATION

VEHICLE EQUIPMENT

Package 1:	Parking Assistance	
Odometer	67,821	
Transmission	Automatic Transmission	✓
	4 Wheel Drive	✓
Driver Convenience	Keyless Entry	✓
	Remote Starter	✓
	Message Center	✓
	Memory Package	✓
	Power Driver Seat	✓
	Power Windows	✓
	Power Locks	✓
	Power Mirrors	✓
	Heated Mirrors	✓
	Power Trunk/Liftgate	✓
	Cruise Control	✓
	Intermittent Wipers	✓
	Tilt Wheel	✓
	Telescopic Wheel	✓
	Steering Wheel Touch Controls	✓
	Console/Storage	✓
	Home Link	✓
Instrument Panel	Traction Control	✓
	Stability Control	✓
	Blind Spot Detection	✓
	Lane Departure Warning	✓
	Alarm	✓
	Air Conditioning	✓
	Climate Control	✓
	Rear Defogger	✓
	Hands Free	✓
	Communications System	✓

To the left is the equipment of the loss vehicle that GEICO PROTECTION INSURANCE COMPANY provided to CCC.

✓ **Standard** This equipment is included in the base configuration of the vehicle at time of purchase.

Additional Equipment that is not Standard but was noted to be on the loss vehicle.

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.

VEHICLE INFORMATION

VEHICLE EQUIPMENT

	Wood Interior Trim	✓
	Navigation System	✓
Radio	AM Radio	✓
	FM Radio	✓
	Stereo	✓
	Search/Seek	✓
	Auxiliary Audio Connection	✓
	Satellite Radio	✓
Roof	Electric Glass Roof	✓
	Skyview Roof	✓
Safety	Air Bag (Driver Only)	✓
	Passenger Air Bag	✓
	Front Side Impact Air Bags	✓
	Head/Curtain Air Bags	✓
Paint	Clearcoat Paint	✓
	Metallic Paint	📋
Front End	Fog Lamps	✓
	Xenon Or L.E.D. Headlamps	✓
	Power Steering	✓
	Power Brakes	✓
	Anti-lock Brakes (4)	✓
Glass And Mirrors	Dual Mirrors	✓
	Signal Integrated Mirrors	✓
	Privacy Glass	✓
Seats	Leather Seats	✓
	Bucket Seats	✓
	Power Passenger Seat	✓
	Heated Seats	✓
	Power Third Seat	✓
Rear Convenience	Dual Air Conditioning	✓
Decor	Luggage/Roof Rack	📋
Rear End	Parking Sensors	✓

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.

VEHICLE INFORMATION

VEHICLE EQUIPMENT

	Backup Camera	✓
	Surround View Camera	📋
	Rear Window Wiper	✓
	Rear Spoiler	✓
Wheels	4-wheel Disc Brakes	✓
	20" Or Larger Wheels	✓

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.

VEHICLE CONDITION

COMPONENT CONDITION

	Condition	Inspection Notes/Typical Vehicle Description	Value Impact
Mechanical	AVERAGE	**Notes:** minimal dirt **Typical Vehicle Desc:** **Engine:** Minor to no seepage. Belts and hoses firm, show minimal wear. Minimal dirt and grease in engine compartment. **Transmission:** Fluid slightly discolored. None to a few areas of seepage.	$ 0
Tires	AVERAGE	**Notes:** average tread **Typical Vehicle Desc:** **Front Tires:** 41% to 90% of new. Example: Typical new car tires are 11/32, loss measures at 5/32 = 46% (5/11) **Rear Tires:** 41% to 90% of new. Example: Typical new car tires are 11/32, loss measures at 5/32 = 46% (5/11)	$ 0
Paint	AVERAGE	**Notes:** minor swirl marks **Typical Vehicle Desc:** A few small to minimal deep surface chips and/or scratches. No significant peeling and/or flaking. Minor swirl marks. Slight to no Fading.	$ 0
Body	AVERAGE	**Notes:** no surface rest **Typical Vehicle Desc:** **Sheet Metal:** Few to no dents. Few to numerous dings. No significant to no surface rust. **Trim:** Minimal damage to components. No missing components. A few to zero dents. Numerous to a few dings.	$ 0
Glass	AVERAGE	**Notes:** surface scratches **Typical Vehicle Desc:** Light surface scratches and/or pitting. Few to no chips.	$ 0
Seats	AVERAGE	**Notes:** clean **Typical Vehicle Desc:** Lightly soiled or clean, faded and/or discolored. None to no significant tears, holes and/or burn marks. None or no significant bare spots.	$ 0

GEICO PROTECTION INSURANCE COMPANY uses condition inspection guidelines to rate the condition of key components of the loss vehicle on a three-point scale. A rating of average condition results in a valuation of that component that is consistent with typical vehicles for that year, make and model of vehicle. If a component is rated in exceptional condition, then a positive monetary adjustment is made to reflect the impact of that condition level on the value of the loss vehicle. Similarly, if a component is rated in below average condition, then a negative monetary adjustment is made to reflect the impact of that condition level on the value of the loss vehicle. Inspection Notes, if any, reflect additional observations from the appraiser regarding the loss vehicle's condition. Monetary adjustments are based upon market research consisting of data gathered from dealerships in California.

CCC makes dollar adjustments that reflect the impact the reported condition has on the value of the loss vehicle as compared to Average condition. These dollar adjustments are based upon interviews with dealerships across the United States.

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.

VEHICLE CONDITION

COMPONENT CONDITION

	Condition	Inspection Notes/Typical Vehicle Description	Value Impact
Carpets	AVERAGE	**Notes:** clean **Typical Vehicle Desc:** Lightly soiled to clean and/or stained. None to a few small tears, holes and /or burn marks. None or no significant bare spots.	$ 0
Dashboard	AVERAGE	**Notes:** light wear **Typical Vehicle Desc:** A few small to no scratches and/or gouges. Minimal damage to firmly intact components. Light to no significant wear.	$ 0
Headliner	AVERAGE	**Notes:** no holes **Typical Vehicle Desc:** A few small to no holes and/or burn marks. No significant scuffing to lightly scuffed.	$ 0
Total Condition Adjustments			**$ 0**

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.

TITLE, REGISTRATION AND OTHER FEES

VEHICLE FEES

Any applicable title, registration and other fees owed to the claimant are calculated separately by GEICO PROTECTION INSURANCE COMPANY and are not reflected here.

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.

COMPARABLE VEHICLES

Options	Loss Vehicle	Comp 1	Comp 2	Comp 3
Parking Assistance	✓	✓	✓	✓
Harman Kardon	✗	✓	✓	✓
Executive	✗	✓	✗	✗
Premium	✗	✗	✓	✓
M Sport	✗	✗	✗	✓
Odometer	67,821	70,281	62,131	63,854
Automatic Transmission	✓	✓	✓	✓
4 Wheel Drive	✓	✓	✓	✓
Keyless Entry	✓	✓	✓	✓
Remote Starter	✓	✓	✓	✓
Message Center	✓	✓	✓	✓
Memory Package	✓	✓	✓	✓
Power Driver Seat	✓	✓	✓	✓
Power Windows	✓	✓	✓	✓
Power Locks	✓	✓	✓	✓
Power Mirrors	✓	✓	✓	✓
Heated Mirrors	✓	✓	✓	✓
Power Trunk/Liftgate	✓	✓	✓	✓
Cruise Control	✓	✓	✓	✓
Intermittent Wipers	✓	✓	✓	✓
Tilt Wheel	✓	✓	✓	✓
Telescopic Wheel	✓	✓	✓	✓
Heated Steering Wheel	✗	✗	✗	✓
Steering Wheel Touch Controls	✓	✓	✓	✓
Console/Storage	✓	✓	✓	✓
Home Link	✓	✓	✓	✓
Traction Control	✓	✓	✓	✓
Stability Control	✓	✓	✓	✓
Blind Spot Detection	✓	✓	✓	✓
Lane Departure Warning	✓	✓	✓	✓
Heads Up Display	✗	✓	✓	✓
Alarm	✓	✓	✓	✓
Air Conditioning	✓	✓	✓	✓
Climate Control	✓	✓	✓	✓
Rear Defogger	✓	✓	✓	✓
Hands Free	✓	✓	✓	✓
Communications System	✓	✓	✓	✓
Wood Interior Trim	✓	✓	✓	✓
Navigation System	✓	✓	✓	✓
AM Radio	✓	✓	✓	✓

Comp 1 Updated Date: 08/29/2026
2020 Bmw X7 Xdrive40i Sports Activity Vehicle 6 3.0l Gasoline Turbocharged Gasoline Direct Injection
VIN 5UXCW2C08L9B19354
Dealership Carz 88 Auto
Telephone (747) 327-7777
Source Dealer Ad
Stock # B19354
Distance from Fullerton, CA
5 Miles - Rowland Heights, CA

Comp 2 Updated Date: 09/20/2026
2020 Bmw X7 Xdrive40i Sports Activity Vehicle 6 3.0l Gasoline Turbocharged Gasoline Direct Injection
VIN 5UXCW2C05L9B15746
Dealership Pnw Luxury Oc
Telephone (714) 844-4441
Source Autotrader
Stock # 2308
Distance from Fullerton, CA
9 Miles - Garden Grove, CA

Comp 3 Updated Date: 09/20/2026
2020 Bmw X7 Xdrive40i Sports Activity Vehicle 6 3.0l Gasoline Turbocharged Gasoline Direct Injection
VIN 5UXCW2C04L9C95575
Dealership Jaguar Land Rover Newport Beach
Telephone (949) 432-4085
Source Autotrader
Stock # TL9C95575
Distance from Fullerton, CA
18 Miles - Newport Beach, CA

Comparable vehicles used in the determination of the Base Vehicle Value are not intended to be replacement vehicles but are reflective of the market value, and may no longer be available for sale.

List Price is the sticker price of an inspected dealer vehicle and the advertised price for the advertised vehicle.

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.

COMPARABLE VEHICLES

Options	Loss Vehicle	Comp 1	Comp 2	Comp 3
FM Radio	✓	✓	✓	✓
Stereo	✓	✓	✓	✓
Search/Seek	✓	✓	✓	✓
CD Changer/Stacker	✗	✗	✓	✗
Auxiliary Audio Connection	✓	✓	✓	✓
Premium Radio	✗	✓	✓	✓
Satellite Radio	✓	✓	✓	✓
Electric Glass Roof	✓	✓	✓	✓
Skyview Roof	✓	✓	✓	✓
Drivers Side Air Bag	✓	✓	✓	✓
Passenger Air Bag	✓	✓	✓	✓
Front Side Impact Air Bags	✓	✓	✓	✓
Head/Curtain Air Bags	✓	✓	✓	✓
Clearcoat Paint	✓	✓	✓	✓
Metallic Paint	✓	✓	✗	✓
Fog Lamps	✓	✓	✓	✓
Xenon Or L.E.D. Headlamps	✓	✓	✓	✓
Power Steering	✓	✓	✓	✓
Power Brakes	✓	✓	✓	✓
Anti-lock Brakes (4)	✓	✓	✓	✓
Dual Mirrors	✓	✓	✓	✓
Signal Integrated Mirrors	✓	✓	✓	✓
Privacy Glass	✓	✓	✓	✓
Leather Seats	✓	✓	✓	✓
Bucket Seats	✓	✓	✓	✓
Power Passenger Seat	✓	✓	✓	✓
Ventilated Seats	✗	✗	✓	✗
Heated Seats	✓	✓	✓	✓
Rear Heated Seats	✗	✗	✗	✓
Power Third Seat	✓	✓	✓	✓
Dual Air Conditioning	✓	✓	✓	✓
Luggage/Roof Rack	✓	✗	✓	✓
Running Boards/Side Steps	✗	✗	✓	✗
Parking Sensors	✓	✓	✓	✓
Backup Camera	✓	✓	✓	✓
Surround View Camera	✓	✓	✓	✓
Rear Window Wiper	✓	✓	✓	✓
Rear Spoiler	✓	✓	✓	✓
4-wheel Disc Brakes	✓	✓	✓	✓
Aluminum/Alloy Wheels	✗	✓	✗	✓

Distance is based upon a straight line between loss and comparable vehicle locations.

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.

COMPARABLE VEHICLES

Options	Loss Vehicle	Comp 1	Comp 2	Comp 3
20" Or Larger Wheels	✓	✗	✓	✗
List Price		$ 31,999	$ 33,084	$ 33,988
Adjustments:				
Package		- $ 326	- $ 245	- $ 1,223
Options			- $ 750	- $ 250
Mileage		+ $ 270	- $ 495	- $ 360
Adjusted Comparable Value		**$ 31,943**	**$ 31,594**	**$ 32,155**

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.

COMPARABLE VEHICLES

COMPARABLE VEHICLE SUMMARY

	Source	Comparable Vehicle	Price	Adjusted Comp Value
1	Verified	**2020 Bmw X7 Xdrive40i Sports Activity Vehicle 6 3.0l Gasoline Turbocharged Gasoline Direct Injection**	$ 31,999 (List)	$ 31,943
2	Verified	**2020 Bmw X7 Xdrive40i Sports Activity Vehicle 6 3.0l Gasoline Turbocharged Gasoline Direct Injection**	$ 33,084 (List)	$ 31,594
3	Verified	**2020 Bmw X7 Xdrive40i Sports Activity Vehicle 6 3.0l Gasoline Turbocharged Gasoline Direct Injection**	$ 33,988 (List)	$ 32,155
	Base Vehicle Value		**$ 31,897.00**	

The following comparable vehicle(s) were used to determine this Base Vehicle Value by computing the arithmetic average of the adjusted values of the comparable vehicles. Details on these comparable vehicles are in the Comparable Vehicles section.

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.

VALUATION NOTES

09/23/2026 18:27 - POADJ CHANGE REQUESTED BY: MCKINNEY,KYRSTIEN

09/23/2026 18:27 - Pre/Post Tax data modified after Valuation

09/23/2026 18:27 - Packages removed : M SPORT

09/23/2026 18:27 - Post Valuation Adjustment entered for:

This Market Valuation Report has been prepared exclusively for use by GEICO PROTECTION INSURANCE COMPANY, and no other person or entity is entitled to or should rely upon this Market Valuation Report and/or any of its contents. CCC is one source of vehicle valuations, and there are other valuation sources available.

Regulations concerning vehicle value include California Code of Regulations 10 CA ADC 2695.

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.

SUPPLEMENTAL INFORMATION

CARRIER INFORMATION

Prepared for: GEICO PROTECTION INSURANCE COMPANY

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.

SUPPLEMENTAL INFORMATION

EXPERIAN® AUTOCHECK® VEHICLE HISTORY REPORT

TITLE CHECK	RESULTS FOUND
Abandoned	✔ No Abandoned Record Found
Damaged	✔ No Damaged Record Found
Fire Damage	✔ No Fire Damage Record Found
Grey Market	✔ No Grey Market Record Found
Hail Damage	✔ No Hail Damage Record Found
Insurance Loss	✔ No Insurance Loss Record Found
Junk	✔ No Junk Record Found
Rebuilt	✔ No Rebuilt Record Found
Salvage	✔ No Salvage Record Found

EVENT CHECK	RESULTS FOUND
NHTSA Crash Test Vehicle	✔ No NHTSA Crash Test Vehicle Record Found
Frame Damage	✔ No Frame Damage Record Found
Major Damage Incident	✔ No Major Damage Incident Record Found
Manufacturer Buyback/Lemon	✔ No Manufacturer Buyback/Lemon Record Found
Odometer Problem	✔ No Odometer Problem Record Found
Recycled	✔ No Recycled Record Found
Water Damage	✔ No Water Damage Record Found
Salvage Auction	✔ No Salvage Auction Record Found

VEHICLE INFORMATION	RESULTS FOUND
Accident	Accident Record Found
Corrected Title	✔ No Corrected Title Record Found
Driver Education	✔ No Driver Education Record Found
Fire Damage Incident	✔ No Fire Damage Incident Record Found
Lease	✔ No Lease Record Found
Lien	✔ No Lien Record Found
Livery Use	✔ No Livery Use Record Found
Government Use	✔ No Government Use Record Found
Police Use	✔ No Police Use Record Found
Fleet	✔ No Fleet Record Found
Rental	✔ No Rental Record Found
Fleet and/or Rental	✔ No Fleet and/or Rental Record Found
Repossessed	✔ No Repossessed Record Found
Taxi use	✔ No Taxi use Record Found
Theft	✔ No Theft Record Found
Fleet and/or Lease	✔ No Fleet and/or Lease Record Found
Emissions Safety Inspection	✔ No Emissions Safety Inspection Record Found
Duplicate Title	✔ No Duplicate Title Record Found

CCC provides GEICO PROTECTION INSURANCE COMPANY information reported by Experian regarding the **2020 BMW X7 (5UXCW2C08L9C13105)**. This data is provided for informational purposes. Unless otherwise noted in this Valuation Detail, CCC does not adjust the value of the loss vehicle based upon this information.

LEGEND :

✔ No Event Found

⛔ Event Found

Information Needed

TITLE CHECK

THIS VEHICLE CHECKS OUT

AutoCheck's result for this loss vehicle show no significant title events. When found, events often indicate automotive damage or warnings associated with the vehicle.

EVENT CHECK

THIS VEHICLE CHECKS OUT

AutoCheck's result for this loss vehicle show no historical events that indicate a significant automotive problem. These problems can indicate past previous car damage, theft, or other significant problems.

VEHICLE INFORMATION

INFORMATION FOUND

AutoCheck found additional information on this vehicle. These records will provide more history for this loss vehicle

ODOMETER CHECK

THIS VEHICLE CHECKS OUT

AutoCheck's result for this loss vehicle show no indication of odometer rollback or tampering was found. AutoCheck determines odometer rollbacks by searching for records that indicate odometer readings less than a previously reported value. Other odometer events can report events of tampering, or possible odometer breakage.

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.

SUPPLEMENTAL INFORMATION

FULL HISTORY REPORT RUN DATE: 09/23/2026

Below are the historical events for this vehicle listed in chronological order.

EVENT DATE	RESULTS FOUND	ODOMETER READING	DATA SOURCE	EVENT DETAIL
02/07/2020	CA	4	Independent Repair Center	Vehicle Serviced or Inspected
07/18/2020	CA	127	Motor Vehicle Dept.	Odometer Reading from DMV
07/29/2020	CA		Motor Vehicle Dept.	Title (Lien Reported) (Lease Reported)
07/29/2020	FULLERTON, CA		Motor Vehicle Dept.	Registration Event/ Renewal (Lease Reported)
01/24/2023	CA		Motor Vehicle Dept.	Title (Lien Reported) (Lease Reported)
02/01/2023	FULLERTON, CA		Motor Vehicle Dept.	Registration Event/ Renewal (Lease Reported)
07/25/2023	CA	35137	Motor Vehicle Dept.	Odometer Reading from DMV
08/22/2023	FULLERTON, CA		Motor Vehicle Dept.	Title (Lease Reported)
08/22/2023	FULLERTON, CA		Motor Vehicle Dept.	Registration Event/ Renewal (Lease Reported)
01/09/2026	CA	61782	Service Record	Vehicle Inspected
01/09/2026	CA		Service Record	Battery Serviced or Replaced
01/09/2026	BUENA PARK, CA		Service Record	Vehicle Recall Service Performed
01/09/2026	BUENA PARK, CA		Service Record	Starter System Serviced
01/09/2026	CA		Service Record	Brakes Serviced
01/09/2026	CA		Service Record	Electrical System Serviced
01/09/2026	CA		Service Record	Tires or Wheels Service Performed
01/09/2026	CA		Service Record	Lube, Oil And/Or Filter Changed
08/01/2026	PISMO BEACH, CA		Police Report	Accident Reported
08/25/2026			Damage Report	Very severe accident or vehicle damage reported
08/25/2026	BUENA PARK, CA	67821	Damage Report	Accident or Damage Reported
08/25/2026			Damage Report	Left side damage or repair reported
08/25/2026			Damage Report	Front Damage or Repair Reported
08/25/2026			Damage Report	Rear Damage or Repair Reported

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.

SUPPLEMENTAL INFORMATION

EVENT DATE	RESULTS FOUND	ODOMETER READING	DATA SOURCE	EVENT DETAIL
08/25/2026			Damage Report	Damage or Repair to Bumper Reported
08/25/2026			Damage Report	Damage or Repair to Wheels Reported
08/25/2026			Damage Report	Damage or Repair to Fender Reported
08/25/2026			Damage Report	Damage or Repair to Exterior Lights Reported
08/25/2026			Damage Report	Damage or Repair to Quarter Panel Reported

AUTOCHECK TERMS AND CONDITIONS:

Experian's Reports are compiled from multiple sources. It is not always possible for Experian to obtain complete discrepancy information on all vehicles; therefore, there may be other title brands, odometer readings or discrepancies that apply to a vehicle that are not reflected on that vehicle's Report. Experian searches data from additional sources where possible, but all discrepancies may not be reflected on the Report.

These Reports are based on information supplied to Experian by external sources believed to be reliable, BUT NO RESPONSIBILITY IS ASSUMED BY EXPERIAN OR ITS AGENTS FOR ERRORS, INACCURACIES OR OMISSIONS. THE REPORTS ARE PROVIDED STRICTLY ON AN "AS IS WHERE IS" BASIS, AND EXPERIAN FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE REGARDING THIS REPORT.

YOU AGREE TO INDEMNIFY EXPERIAN FOR ANY CLAIMS OR LOSSES, INCLUDING COSTS, EXPENSES AND ATTORNEYS FEES, INCURRED BY EXPERIAN ARISING DIRECTLY OR INDIRECTLY FROM YOUR IMPROPER OR UNAUTHORIZED USE OF AUTOCHECK VEHICLE HISTORY REPORTS.

Experian shall not be liable for any delay or failure to provide an accurate report if and to the extent which such delay or failure is caused by events beyond the reasonable control of Experian, including, without limitation, "acts of God", terrorism, or public enemies, labor disputes, equipment malfunctions, material or component shortages, supplier failures, embargoes, rationing, acts of local, state or national governments, or public agencies, utility or communication failures or delays, fire, earthquakes, flood, epidemics, riots and strikes.

These terms and the relationship between you and Experian shall be governed by the laws of the State of Illinois (USA) without regard to its conflict of law provisions. You and Experian agree to submit to the personal and exclusive jurisdiction of the courts located within the county of Cook, Illinois.

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.

SUPPLEMENTAL INFORMATION

NHTSA VEHICLE RECALL

The National Highway Traffic Safety Administration has issued 12 safety related recall notices that may apply to the above valued vehicle.

NHTSA Campaign ID : 19V631000

Mfg's Report Date : AUG 27, 2019

Component : STEERING:RACK AND PINION:RACK

Potential Number Of Units Affected : 12

Summary : BMW of North America, LLC (BMW) is recalling certain 2020 X5 sDrive40i, X5 xDrive40i, X5 M50i, X7 xDrive40i and X7 M50i vehicles. The steering rack pinion teeth may break under load, resulting in a loss of steering control.

Consequence : A loss of steering control increases risk of a crash.

Remedy : BMW will notify owners, and dealers will replace the steering rack, free of charge. The recall began August 21, 2019. Owners may contact BMW customer service at 1-800-525-7417.

Dates Of Manufacture : AUG 08, 2019 to AUG 15, 2019

NHTSA Campaign ID : 20V052000

Mfg's Report Date : JAN 29, 2020

Component : EXTERIOR LIGHTING

Potential Number Of Units Affected : 683

Summary : BMW of North America, LLC (BMW) is recalling certain 2020 X7 xDrive40i and X7 xDrive50i vehicles. The rear reflex reflectors may not reflect an adequate amount of light. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment."

Consequence : An inadequate amount of reflected light will decrease the vehicle's visibility to other drivers, increasing the risk of a crash.

Remedy : BMW will notify owners, and dealers will replace both rear reflex reflectors, free of charge. The recall began March 30, 2020. Owners may contact BMW customer service at 1-800-525-7417.

NHTSA Campaign ID : 20V465000

Mfg's Report Date : AUG 06, 2020

Component : POWER TRAIN:AUTOMATIC TRANSMISSION

Potential Number Of Units Affected : 21

Summary : BMW of North America, LLC (BMW) is recalling certain 2020 X5 sDrive 40i, X5 xDrive 40i and one X7 xDrive 40i vehicle. The starter motor may have an extra bolt that could potentially fall into the transmission housing and cause an engine stall.

Consequence : An engine stall increases the risk of a crash.

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.

SUPPLEMENTAL INFORMATION

Remedy : BMW will notify owners, and dealers will inspect the starter motor for the extra bolt, removing it if necessary. Dealers will also inspect the starter for damage, and check if the bolt has fallen into the transmission housing, replacing any damaged parts as necessary. All repairs will be performed free of charge. The recall began on October 2, 2020. Owners may contact BMW customer service at 1-800-525-7417.

NHTSA Campaign ID : 20V528000

Mfg's Report Date : AUG 31, 2020

Component : EXTERIOR LIGHTING:HEADLIGHTS

Potential Number Of Units Affected : 307

Summary : BMW of North America, LLC (BMW) is recalling certain 2020-2021 X5 sDrive40i, xDrive40i, xDrive50i, X5 M50i, X5M, X6 sDrive40i, xDrive40i, X6 M50i, X6M, X7 M50i and 2021 X5 xDrive45e vehicles. The headlamps may allow a blue light to illuminate. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 108, "Lamps, Reflective Devices, and Associated Equipment."

Consequence : Oncoming drivers may be confused by the blue light of approaching vehicles, which could potentially increase the risk of a crash.

Remedy : BMW will notify owners, and dealers will inspect the headlamps and, if necessary, replace them, free of charge. The recall began October 30, 2020. Owners may contact BMW customer service at 1-800-525-7417.

Dates Of Manufacture : JUL 27, 2020 to AUG 02, 2020

NHTSA Campaign ID : 20V678000

Mfg's Report Date : NOV 03, 2020

Component : SUSPENSION:FRONT:CONTROL ARM

Potential Number Of Units Affected : 83

Summary : BMW of North America, LLC (BMW) is recalling certain 2020 X5 sDrive40i, xDrive40i, X5 M50i, X5M, X7 xDrive40i, X7 M50i, X6 xDrive40i, X6 M50i and X6M vehicles and 2021 X5 xDrive45e vehicles. The weld between the front axle support and the right front control arm bearing bracket may separate.

Consequence : If the weld between the front axle support and the right front control arm bearing bracket separates, vehicle handling and control may be affected, increasing the risk of a crash.

Remedy : BMW will notify owners, and dealers will replace the front axle support, free of charge. The recall began December 18, 2020. Owners may contact BMW customer service at 1-800-525-7417.

NHTSA Campaign ID : 21V062000

Mfg's Report Date : FEB 09, 2021

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.

SUPPLEMENTAL INFORMATION

Component : SERVICE BRAKES, HYDRAULIC:POWER ASSIST:HYDRAULIC

Potential Number Of Units Affected : 893

Summary : BMW of North America, LLC (BMW) is recalling certain 2020-2021 8 Series Coupe, Grand Coupe and convertible 840i, 840i xDrive, M850i xDrive, M8 and 740 Li, 740 Li xDrive, 750 Li xDrive, M760 Li xDrive, X6 sDrive40i, X6 xDrive40i, X6 xdrive50i, X6 M50i, X6M, and 2019-2021 X5 sDrive40i, X5 xDrive40i, X5 xDrive50i, X5 M50i, X5M, X7 xDrive40i, X7 xDrive50i, X7 M50i, and 2021 M3, M3 Competition, M4 Coupe, M4 Competition Coupe, X5 xDrive45e, 745 Le xDrive. The rotor and shaft within the integrated brake system may not have been welded properly and could separate during a hard braking event, possibly resulting in a loss of the Antilock Brake System (ABS) and braking assistance.

Consequence : A loss of ABS and a reduction in braking assistance can increase the risk of a crash.

Remedy : BMW will notify owners, and dealers will replace the integrated brake system, free of charge. Owner notification letters were mailed on May 25, 2021. Owners may contact BMW customer service at 1-800-525-7417.

NHTSA Campaign ID : 21V096000

Mfg's Report Date : FEB 18, 2021

Component : BACK OVER PREVENTION: SENSING SYSTEM: CAMERA

Potential Number Of Units Affected : 13858

Summary : BMW of North America, LLC (BMW) is recalling certain 2019-2021 X3 sDrive30i, X3 xDrive30i, X3 M40i, X3M, X4 xDrive30i, X4 M40i, M550i, X4M, X5 sDrive40i, X5 xDrive40i, X5 xDrive50i, X5M, X5 M50i, X7 xDrive40i, X7 xDrive50i, X7 M50i, Alpina XB7, 330i, 330i xDrive, M340i, M340i xDrive, and 8 Series Coupe, Convertible and Grand Coupe, 840i, 840i xDrive, M850i xDrive, M8, 2020-2021 530e, 530e xDrive, 330e, 330e xDrive, 745Le, 745Le xDrive, X5 xDrive45e, X3 xDrive30e, X6 sDrive40i, X6 xDrive40i, X6 xDrive50i, X6 M50i, X6M, 530i, 530i xDrive, 540i, 540i xDrive, M550i xDrive, M5, 740i, 740Li, 740Li xDrive, M760i Drive, M760Li xDrive, 750Li xDrive Alpina, Alpina B7 xDrive, and 2021 4 Series Coupe 430i, 430i xDrive, M440i xDrive vehicles. When shifting into Reverse, a small portion of the rearview image may be obscured, or the screen may not illuminate. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 111, "Rear Visibility."

Consequence : If the driver relies on only the rearview camera image, the missing or reduced rearview image view can increase the risk of a crash or injury.

Remedy : BMW will notify owners, and dealers will inspect the rearview camera software and update it if necessary, free of charge. The recall began April 16, 2021. Owners may contact BMW customer service at 1-800-525-7417.

NHTSA Campaign ID : 19V684000

Mfg's Report Date : SEP 26, 2019

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.

SUPPLEMENTAL INFORMATION

Potential Number Of Units Affected : 257473

Summary : BMW of North America, LLC (BMW) is recalling certain 2018 540d, 2018-2020 530i, 530i xDrive, 540i, 540i xDrive, M550i xDrive, M5, 530e, 530e xDrive, X3 sDrive, X3 xDrive, X3 M40i, X3 M, and 2019-2020 X4 xDrive, X4 M40i, X4 M, X7 xDrive, X7 M50i, 740Li, 740Li xDrive, 750Li, 750Li xDrive, 8 Series Convertible and Coupe 840i, 840i xDrive, M850i xDrive, X5 sDrive, X5 xDrive, X5 M50i, X6 xDrive, X6 M50i, 330i, 330i xDrive, M340i, M340i xDrive, Z4 sDrive, Z4 M40i, 740Le xDrive and 745Le xDrive, 2018-2019 640i xDrive Gran Turismo and Rolls-Royce Phantom, 2019 M850i xDrive Gran Coupe and Rolls-Royce Cullinan and 2020 Toyota Supra vehicles. The back-up camera and display settings can be adjusted such that the rear view image is no longer visible and the system will retain that setting the next time the vehicle is placed in reverse. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 111, "Rearview Mirrors."

Consequence : The lack of an image in the back-up camera display increases the risk of a crash.

Remedy : BMW will notify owners, and dealers will update the back-up camera software, free of charge. The recall began November 8, 2019. Owners may contact BMW customer service at 1-800-525-7417 or Rolls-Royce at 1-877-877-3735. Toyota owners may contact Toyota customer service at 1-888-270-9371.

Dates Of Manufacture : JUL 09, 2018 to AUG 12, 2019

NHTSA Campaign ID : 22V267000

Mfg's Report Date : APR 19, 2022

Component : VISIBILITY:SUN/MOON ROOF ASSEMBLY

Potential Number Of Units Affected : 61221

Summary : BMW of North America, LLC (BMW) is recalling certain 2022 4 Series Gran Coupe (430i, 430i xDrive, M440i xDrive); 2019-2022 X5 sDrive40i, X5 xDrive40i, X5 xDrive50i, X5 M50i, X5M; 2021-2022 X5 xdrive45e; 2020-2022 X6 sDrive40i, X6 xDrive40i, X6 xDrive50i, X6M and 2019-2023 X7 xDrive40i, X7 xDrive50i, X7 M50i, X7 xDrive60i, X7 M60i, X7M, Alpina XB7 vehicles. The roof function control unit may be programmed incorrectly, allowing the sunroof to close without the key fob present inside the vehicle. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 118, "Power-Operated Window Systems."

Consequence : A sunroof that closes without the key fob present inside the vehicle can increase the risk of injury.

Remedy : Dealers will reprogram the roof function control unit, free of charge. Owner notification letters were mailed June 20, 2022. Owners may contact BMW customer service at 1-800-525-7417.

NHTSA Campaign ID : 22V670000

Mfg's Report Date : SEP 06, 2022

Component : SEATS

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.

SUPPLEMENTAL INFORMATION

Potential Number Of Units Affected : 246

Summary : BMW of North America, LLC (BMW) is recalling certain 2019-2022 BMW X7 xDrive40i, X7 Drive50i, X7 M50i vehicles with third-row seats. One or more of the compression springs that lock the backrest may not have been installed properly, and could dislodge or detach.

Consequence : In a crash, the seat backrest may not fully lock, increasing the risk of injury.

Remedy : Dealers will inspect the third-row seat and, if necessary, remove and reinstall improperly installed compression springs, and reinstall any missing springs, free of charge. Owner notification letters were mailed November 4, 2022. Owners may contact BMW customer service at 1-800-525-7417.

NHTSA Campaign ID : 24V576000

Mfg's Report Date : JUL 31, 2024

Component : ELECTRICAL SYSTEM:STARTER ASSEMBLY

Potential Number Of Units Affected : 105588

Summary : BMW of North America, LLC is recalling certain 2019-2020 X5, X7, 2020 3 Series Sedan, X6, 2020-2021 7 Series Sedan, 2020 8 Series Convertible, 8 Series Coupe, and 2020 8 Series Gran Coupe vehicles. Please see the recall report for the complete list of models. In the event the starter motor fails, repeated attempts to start the vehicle can cause the starter motor to overheat from an electrical overload.

Consequence : A starter motor that overheats can ignite nearby combustible material in the engine compartment, increasing the risk of a fire.

Remedy : Dealers will update the vehicle software, free of charge. Owner notification letters were mailed September 27, 2024. Owners may contact BMW customer service at 1-800-525-7417.

NHTSA Campaign ID : 25V644000

Mfg's Report Date : SEP 24, 2025

Potential Number Of Units Affected : 145102

Summary : BMW of North America, LLC (BMW) is recalling certain 2020 340I, X6, 2020-2025 840I, 2020-2022 740LI, 2019-2020 X7, and X5 vehicles. After repeated attempts, the starter motor may overheat from an electrical overload.

Consequence : An overheated starter motor can ignite nearby combustible material in the engine compartment, increasing the risk of a fire.

Remedy : Dealers will replace the engine starter, free of charge. This recall includes vehicles repaired under recall 24V576 and those owners will need to have their vehicle repaired again. Owner notification letters were mailed February 9, 2026. Owners may contact BMW customer service at 1-800-525-7417. Vehicle Identification Numbers (VINs) involved in this recall became searchable on NHTSA.gov November 17, 2025.

Dates Of Manufacture : JUL 28, 2020

© Copyright 2025 CCC Intelligent Solutions Inc. All Rights Reserved.