

Vehicle Diagnostic Report

The Report is created by **LAUNCH** X-431

Vehicle Information

Year:2008
Make:GM
Model:Yukon XL
VIN:1GKFK16368J144884
Vehicle Software Version:V50.35
Diagnostic Application Version:V8.00.037
Diagnostic path:Automatically Search > Engine Control Module (ECM)



Repair Shop

Shop Name:BC
Address:
Zip Code:
Telephone:
Email:
SN:989347712041
Test Time:2026-03-14 08:00:18



DTC 【Pre-Repair】

DTC	Description	State
P0121-00	Throttle Position (TP) Sensor 1 Performance	Last Test:Not Run This Ignition:Not Run Since Clear:Passed & Failed
P0300-00	Engine Misfire Detected	Last Test:Passed This Ignition:Not Run Since Clear:Passed & Failed
P0513-00	Theft Deterrent Key Incorrect	Last Test:Passed This Ignition:Passed Since Clear:Passed & Failed
P0633-00	Theft Deterrent Key Not Programmed	Last Test:Passed This Ignition:Passed Since Clear:Passed & Failed

P1380-00	Misfire Detected - Rough Road Data Not Available	Last Test:Failed/Current This Ignition:Not Run Since Clear:Passed & Failed
P1631-00	Theft Deterrent Fuel Enable Signal Not Correct	Last Test:Passed This Ignition:Passed Since Clear:Passed & Failed

.....

Disclaimer

This test report is for reference only for vehicle test and maintenance. The vehicle operating data provided in this report are all static data. The detailed dynamic diagnostic data can be read by professional maintenance device, and LAUNCH will not be liable for any accidents and failures arising therefrom!