



4611 Kelly Place  
Delta BC  
V4K 1G8  
Tel: 604-317-3786  
Email: ted@phoenixroofofconsultants.ca

## Installation Monitoring Report

**Date:** October 9, 2025

<b>Project</b>	NW 2050 Cypress Point	<b>Job Number</b>	24064	<b>RGC Number</b>	53216		
<b>Address</b>	7511, 7531, 7651 Minoru Boulevard	<b>Inspector</b>	Matthew	<b>Report Number</b>	50		
	Richmond, B.C.	<b>Weather</b>	Cloud / 19°C	<b>Time</b>	11:45am		
<b>Contractor</b>	Flynn Canada Ltd.	<b>Crew Size</b>	0	<b>Red Seal</b>	0	<b>Apprentices</b>	0

**Distribution List:** keith.lodge@flynncompanies.com, ken.brown@flynncompanies.com, nw2050@telus.net. matt@phoenixroofofconsultants.ca



**50.1 Building A, unit 307**

Pavers still remain to be leveled around drain location.




**50.2 Building A, unit 307**

Flashing corner has been corrected.



**50.3 Building A, unit 307**

Spacers under the mounting bracket to be trimmed back flush to the bracket edges.



**50.4 Building A, unit 307**

Missing fasteners to be installed.



**50.5 Building A, unit 307**

Asphalt and adhesive marks on walls and doors to be cleaned off. Also, the caulking on the trim did not cure enough prior to being painted, this will need to be corrected.



**50.6 Building A**

As previously stated, the pavers on the edge are to be no smaller than half a piece at the perimeter of the decks.


Correction remains.



## **Outstanding Items:**

- Items #34.6 – 34.7, #39.7, #40.5, #46.1, #49.1, #49.3, #49.4.

Reported by:



Matthew Blackstock, RRO  
Phoenix Roof Consultants

Phoenix Roof Consultants field reviews are for general conformance to specifications and roofing compliance only. Our reviews are not to take the place of the contractor's own quality control which shall remain the responsibility of the contractor. Phoenix Roof Consultants will not be responsible for acts or omissions of the contractor or for the contractor's failure to fulfill the intent of the specifications, contract, or quote.