


A Mechanism Ladder Must Add Degrees of Freedom Without Redefining Transfer



Observables Stay Fixed: Reference Point, Frame, Force, Couple, Velocity, Angular Velocity, and Power