


## **DFM** analysis report\_JLCDFM


 $WorkFlow X\_Final.zip$ File name:

Report generated at: 2025-10-21 09:58:35

PCB layers: PCB size: 10.5x11cm

✓ PCB DFM SMT DFM Analyze project:





Analyze project	Analysis results	B DFM>Routing layer analy	Layer distribution	Statistics
	Analysis results	r ob scieensnot	Layer distribution	
Sharp trace corner (Check for sharp corners in traces)	No	No	No	Danger: 0 Warning: 0 Good: 0
BGA pad Check BGA pads on the board)	No	No	No	Danger: 0 Warning: 0 Good: 0
Via placed within a pad (Check if there is a via placed within a pad)	No	No	No	Danger: 0 Warning: 0 Good: 0
Trace to board edge (Detect traces too close to the board edge)	No	No	No	Danger: 0 Warning: 0 Good: 0
Trace spacing (Measure spacing between adjacent parallel traces)	0.15mm <mark>Warning</mark>		Gerber_BottomLayer.GBL Gerber_TopLayer.GTL	Danger: 0 Warning: 7 Good: 2
Unconnected trace end (Free-standing trace ends not connected to pads)	No	No	No	Danger: 0 Warning: 0 Good: 0
Trace width (Trace width information)	No	No	No	Danger: 0 Warning: 0 Good: 0
Fiducial (Detect fiducial marks on the board)	No	No	No	Danger: 0 Warning: 0 Good: 0
Pad to board edge (Measure distance of pads from the board edge)	0.23mm Good		Gerber_BottomLayer.GBL Gerber_TopLayer.GTL	Danger: 0 Warning: 0 Good: 52
Pad spacing (Measure pad to pad spacing)	0.14mm Warning		Gerber_BottomLayer.GBL Gerber_TopLayer.GTL	Danger: 0 Warning: 1 Good: 18
Plated through-hole to trace clearance (Measure clearance of plated through-holes to traces)	0.26mm Good		Gerber_BottomLayer.GBL Gerber_TopLayer.GTL	Danger: 0 Warning: 0 Good: 100
Annular ring (Annular ring width of pads compared to holes)	0.15mm <mark>Warning</mark>		Gerber_BottomLayer.GBL Gerber_TopLayer.GTL	Danger: 0 Warning: 100 Good: 0
tht to smd Detect clearance of vias to pads)	1.39mm Danger		Gerber_BottomLayer.GBL Gerber_TopLayer.GTL	Danger: 9 Warning: 4 Good: 45
Via to pad	0.09mm		Gerber BottomLaver.GBL	Danger: 2 Warning: 2

Analyze project	Analysis results	PCB screenshot	Layer distribution	Statistics
	РСВ	DFM>Silkscreen layer ana	ılysis	
Negative soldermask expansion (Detect solder mask openings smaller than their corresponding pads)	No	No	No	Danger: 0 Warning: 0 Good: 0
Soldermask opening with multiple segments (Check if solder mask openings are constructed from multiple geometric shapes)	null Warning		Gerber_BottomSolderMaskLayer.GB S	Danger: 0 Warning: 6 Good: 0
Solder mask opening exposing trace (Detect clearance of solder mask openings to nearby traces)	0.09mm <b>Warning</b>		Gerber_BottomSolderMaskLayer.GB S Gerber_TopSolderMaskLayer.GTS	Danger: 0 Warning: 56 Good: 0
Soldermask bridge (Detect distance between parallel soldermask opening edges)	0.1mm Danger		Gerber_TopSolderMaskLayer.GTS	Danger: 11 Warning: 0 Good: 0

PCB DFM>Soldermask layer analysis

PCB screenshot

Gerber\_BottomLayer.GBL

Layer distribution

Warning: 2

Good: 0

Statistics

Danger

Analysis results

(Detect clearance of vias to pads)

Analyze project

pads)			Gerber_TopSilkscreenLayer.GTO	Good: 0
Silkscreen to hole (Detect clearance of silkscreen to holes)	0mm <mark>Dange</mark> r		Gerber_BottomSilkscreenLayer.GB O Gerber_TopSilkscreenLayer.GTO	Danger: 100 Warning: 0 Good: 0
Silkscreen line width (Check silkscreen line width)	0.06mm Danger	•	Gerber_BottomSilkscreenLayer.GB O Gerber_TopSilkscreenLayer.GTO	Danger: 50 Warning: 50 Good: 0
PCB DFM>Drill layer analysis  Analysis results  PCB screenshot  Layer distribution  Statistics				

Analyze project	Analysis results	PCB screenshot	Layer distribution	Statistics
Unconnected via (Detect isolated unconnected vias)	No	No	No	Danger: 0 Warning: 0 Good: 0
Missing plated through-hole (Detect top and bottom pads at the same location without plated through-holes)	No	No	No	Danger: 0 Warning: 0 Good: 0
Unconnected via (Detect isolated unconnected vias)	No	No	No	Danger: 0 Warning: 0 Good: 0
Plated through-hole spacing (Measure spacing between plated through-holes)	No	No	No	Danger: 0 Warning: 0 Good: 0
Short slot detection (Detect slots shorter than twice their width)	No	No	No	Danger: 0 Warning: 0 Good: 0
Slot width check (Measure slot width)	0.6mm Danger		Drill_PTH_Through.DRL	Danger: 4 Warning: 0 Good: 0
Via to PTH spacing (Measure spacing of vias to plated through-holes)	No	No	No	Danger: 0 Warning: 0 Good: 0
Unconnected via				Danger: 0

No

No

Warning: 0

Good: 0

No

(Detect isolated unconnected

vias)